## **Purchase Order**

Brigham Young University
BRIGHAM YOUNG UNIVERSITY

BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 United States

> Supplier: 0000017743 TEAC AMERICA TASCAM ATTN: FACTORY SERVICE 7733 TELEGRAPH RD MONTEBELLO CA 90640

Purchase Order Date Revision Page

BYU-0000034100 01/29/1999 1

Payment Terms Freight Terms Ship Via

NET 30 FOB Origin, Buyer Bears Frt. UPS Ground

Buyer Phone/Email Currency
Whitney, Kristina R. USD

Ship To: RECEIVING

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 United States

Attention: Not Specified

BIII To: BRIGHAM YOUNG UNIVERSITY

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

**United States** 

Tax Exempt? Y Tax Exempt ID: N10020 Replenishment Option: Standard
Line-Sch Item/Description Mfg ID Quantity UOM PO Price Extended Amt Due Date

1- 1 REPAIR TASCAM PORTASTUDIO 424MKII MIXER/CASSETTE DECK.

1.00EA

0.00

0.00 CLOSED

0.00

Schedule Total \_\_\_\_

PROBLEM: CASSETTE PORTION IS NOT FUNCTIONING. WON'T PLAY, FF, RW, ETC WITH ANY RELIABILITY- GETS STUCK IN VARIOUS STATES.

THIS UNIT WAS FIXED UNDER WARRANTY AND FOR SOME REASON THE VENDOR SENT IT BACK DIRECTLY TO THE ORIGINAL PURCHASER RATHER THAN THROUGH RECEIVING. IT SHOULD HAVE GONE THROUGH RECEIVING AND THEN TO ITSERVICES. HAROLD VAIL TO CONTACT JOHN CALL X7065 TO FIND OUT IF HE DOES HAVE THE MACHINE AND IF IT IS WORKING PROPERLY. 3/10/99 KRW JOHN CALL DOES HAVE MACHINE. HAROLD VAIL TO SEND A MEMO TO CLEAR RECEIVING. 3/12/99 KRW

Item Total 0.00

PLEASE RUSH!!! ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING SHIP UPS GROUND IF UPS CHARGES ARE UNDER \$44.00 FOR TOTAL SHIPMENT. IF OVER \$44.00 SHIP FOB ORIGIN-COLLECT LESS THAN TRUCKLOAD (LTL) ONLY VIA ROADWAY EXPRESS. THE USE OF ANY OTHER METHOD WILL RESULT IN A CHARGE BACK FOR ANY ADDITIONAL FREIGHT COSTS INCURRED. VENDOR ACCEPTS LIABILITY FOR DAMAGES IF ABOVE DIRECTIONS ARE NOT FOLLOWED.

Total PO Amount 0.00