## **Purchase Order**

Brigham Young University
BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 **United States** 

> **Supplier:** 0000013733 RANE CORPORATION\* 10802 47TH AVE WEST **MUKILTEO WA 98275**

**Dispatch via Print Purchase Order** Date Revision Page BYU-0000017036 02/19/1998 **Payment Terms Freight Terms** Ship Via

PAY NOW F.O.B. Dest, Seller Bears Frt. UPS Ground

**Buyer** Phone/Email Currency USD

Neitzel,Janae P

RECEIVING Ship To: **BRIGHAM YOUNG UNIVERSITY** 

**CENTRAL RECEIVING** 685 E UNIVERSITY PKWY PROVO UT 84602-1830

**United States** 

Attention: Not Specified

Bill To: **BRIGHAM YOUNG UNIVERSITY** 

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

**United States** 

Tax Exempt? Y Tax Exempt ID: N10020 Replenishment Option: Standard Line-Sch Item/Description Quantity UOM PO Price Extended Amt Due Date Mfg ID

1- 1 REPAIR RANE MA-6S S/N155064 Χ 1.00EA 0.01 0.00 CLOSED

> **Schedule Total** 0.00

PROBLEM: SHOWS CLIP LIMIT LIGHT AND BLOWS INTERNAL FUSES WITH NO INPUT OF OUTPUT CONNECTED. (NOTE: AMPW AS BOUGHT 2/20/97 MAY BE UNDER WARRANTY ORIGINAL PO Y91554)

> Item Total 0.00

WARRANTY REPAIR

**Total PO Amount** 0.00