Purchase Order

Brigham Young University
BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 **United States**

> Supplier: 0000002505 **ELECTRO-VOICE / EVI AUDIO*** ATTN: MICROPHONE REPAIR REPAIR DEPT 600-T CECIL ST **BUCHANAN MI 49107**

Dispatch via Print **Purchase Order** Date Revision

BYU-0000039950 07/02/1999 1 - 07/02/1999 Payment Terms **Freight Terms** Ship Via NET 30 FOB Origin, Buyer Bears Frt. UPS Ground **Buyer** Phone/Email Currency Whitney, Kristina R USD

RECEIVING Ship To:

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 **United States**

Attention: Not Specified

Bill To: **BRIGHAM YOUNG UNIVERSITY**

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

United States

Tax Exempt? Y Tax Exempt ID: N10020 Replenishment Option: Standard Line-Sch Item/Description PO Price Mfa ID Quantity UOM Extended Amt Due Date

1- 1 REPAIR & REBUILD EV RE18 MIC PROBLEM: SCREENS FALL OFF

2.00EA

27.15

0.00 CLOSED

Schedule Total

0.00

Item Total

0.00

ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING

SHIP UPS GROUND IF UPS CHARGES ARE UNDER \$44.00 FOR TOTAL SHIPMENT. IF OVER \$44.00 SHIP FOB ORIGIN-COLLECT LESS THAN TRUCKLOAD (LTL) ONLY VIA ROADWAY EXPRESS. THE USE OF ANY OTHER METHOD WILL RESULT IN A CHARGE BACK FOR ANY ADDITIONAL FREIGHT COSTS INCURRED. VENDOR ACCEPTS LIABILITY FOR DAMAGES IF ABOVE DIRECTIONS ARE NOT FOLLOWED.

CHANGE ORDER #1

CHANGED PRICE TO REPAIR PRICE ON INVOICE. PREVIOUS PRICE WAS \$0 UNTIL WE RECEIVED ACTUAL PRICE. KKN 7/2/99

> **Total PO Amount** 0.00