Feature importance by mean F1 score decrease, CNC data

Index mass quantile, sub-cut 4 — **0.5**

FFT coef. 4 (real), sub-cut 5 — **0.35**

FFT coef. 87 (abs), sub-cut 6 — **0.15**

Partial autocorrelation, sub-cut 5 — **0.13**

Change quantiles, (agg. by mean), sub-cut 5 — **0.087**

FFT coef. 57 (real), sub-cut 5 — **0.076**

FFT coef. 28 (abs), sub-cut 1 — **0.064**

FFT coef. 35 (abs), sub-cut 1 — **0.048**

FFT coef. 46 (abs), sub-cut 1 — **0.041**

Large standard deviation, sub-cut 6 — **-8.3e-05**

Increasing Importance