## Working on UART using Bare Metal

19 June 2025 09:53

First things first, need to be clear about registers.

So for getting the info, go through: (1) stm32f427vg pdf (2) rm-stm32f429

- (1) look for the block diagram, figure 4, to know about the bus connected to the peripheral
- (2) Go through each and every register needed to configure the uart (USART), section 30

The word length can be changed to 8 or 9 bits, in the USART\_CR1 register Mth bit.

Procedure to start communication is given in detail in pg 974, rm-stm32f429

Also understand the usart block diagram.