

A

A

B


B

C




C

D


D




Title		
Size A3	Number	Revision
Date: 1/14/2026	Sheet of File: Block_Diagram.SchDoc	Drawn By:



A





All the Sensors are getting connected with the below connectors like IMU, PPG Sensors and Further More if there are anything




TCA9548 has clock frequency constraint of 400kHz, Currently TCA9548 is in use. This design will continue until the release of PCA9847(VQFN Package), until use TCA9548 with 400kHz Clock frequency



**Address of TCA9548 : 0x71h or 113d**




Title		
Size	Number	Revision
A3		
Date:	1/14/2026	Sheet of
File:	TCA9847_PCA9847.SchDoc	Drawn By:




**Haptics Protection  
Battery Isolation**



**Fire Buttons**



**Fire Button Pullup**








Title

Size  
A3

Date: 1/14/2026  
File: Haptics and Fire Buttons.SchDoc

Number  
Sheet of  
Drawn By:



Title		
Size A3	Number	Revision
Date: 1/14/2026	Sheet of	
File: Power Supply SchDoc	Drawn By:	

A

1

B



10

6

1

D

1



Title	
Size A3	Number
Date: 1/14/2026	Sheet of
File: USP_Inputs_SchDoc	Drawn By: