

Harry Lo <harrykhlo@gmail.com>

## Fwd: 2 rapare street

1 message

Harry Lo <harrykhlo@gmail.com>

Mon, Oct 31, 2022 at 12:48 PM

To: Ricky Wong <jsrconstruction.nz@gmail.com>

Cc: tom.ashwin@hagley.co.nz, Sze Ping Jessica Lo <jlee2609@yahoo.com.hk>

Hi Ricky,

The photos of white aluminium frames you sent Tom were not for our house.

On the photos of the black aluminium frames, the layer marked thermal broken is a strip of alumunium but not the thermal broken layer.

Please have a further investigation. Thanks.

Harry

On Mon, 31 Oct 2022, 11:00 Ricky Wong, <jsrconstruction.nz@gmail.com> wrote:

----- Forwarded message -----From: Tom Ashwin <tom.ashwin@hagley.co.nz> Date: Mon, 31 Oct 2022, 10:12 Subject: RE: 2 rapare street To: Ricky Wong <jsrconstruction.nz@gmail.com> Hi Ricky

I can see the thermal break in both those photos so no need to go to site.

Cheers Tom

Gmail - Fwd: 2 rapare street

5/7/23, 11:14 PM

**Project Manager Hagley Windows & Doors** 

0274 800 208 tom.ashwin@hagley.co.nz www.hagley.co.nz На gle Wi nd ow s & Do ors Yo utu

**Waterloo Business Park** 926 Halswell Junction Road Christchurch 8042 New Zealand

The content of this email may contain information that is confidential to the named recipient and/or subject to legal privilege. If you are not the intended recipient, you must not use, distribute or copy this email. If you have received this email in error, please notify the sender immediately and delete the email. Any views expressed in this email do not

be

necessarily reflect those of the Hagley & Thermaseal group of companies. Sustainability | Please consider the environment before printing this email.

From: Ricky Wong <jsrconstruction.nz@gmail.com>

Sent: Monday, 31 October 2022 9:56 AM To: Tom Ashwin <tom.ashwin@hagley.co.nz>

Subject: Re: 2 rapare street

I had covid, you can get in lockbox and gate 1988

On Mon, 31 Oct 2022, 08:18 Tom Ashwin, <tom.ashwin@hagley.co.nz> wrote:

What time will you be on site?

Tom Ashwin	03 33 88 235
Project Manager	0274 800 208
Hagley Windows & Doors	tom.ashwin@hagley.co.nz
	www.hagley.co.nz
	Waterloo Business Park
	926 Halswell Junction Road
	Christchurch 8042
	New Zealand

The content of this email may contain information that is confidential to the named recipient and/or subject to legal privilege. If you are not the intended recipient, you must not use, distribute or copy this email. If you have received this email in error, please notify the sender immediately and delete the email. Any views expressed in this email do not necessarily reflect those of the Hagley & Thermaseal group of companies.

Sustainability | Please consider the environment before printing this email.

From: Ricky Wong <jsrconstruction.nz@gmail.com>

Sent: Monday, 31 October 2022 8:14 AM To: Tom Ashwin <tom.ashwin@hagley.co.nz>

Subject: Re: 2 rapare street

Papers yes, but what onsite is different stories, please come to have a look

On Mon, 31 Oct 2022, 08:01 Tom Ashwin, <tom.ashwin@hagley.co.nz> wrote:

Hi Ricky

I have just checked our paperwork here and all items are thermally broken as requested.

The client didn't want Argon Gas to the Double Glazed Units so this was not provided.

**Tom Ashwin** 03 33 88 235

0274 800 208 **Project Manager** 

**Hagley Windows & Doors** tom.ashwin@hagley.co.nz

www.hagley.co.nz

## **Waterloo Business Park**

926 Halswell Junction Road

Christchurch 8042

New Zealand

The content of this email may contain information that is confidential to the named recipient and/or subject to legal privilege. If you are not the intended recipient, you must not use, distribute or copy this email. If you have received this email in error, please notify the sender immediately and delete the email. Any views expressed in this email do not necessarily reflect those of the Hagley & Thermaseal group of companies.

**Sustainability** | Please consider the environment before printing this email.

From: Ricky Wong < jsrconstruction.nz@gmail.com >

Sent: Sunday, 30 October 2022 5:07 PM To: Tom Ashwin < tom.ashwin@hagley.co.nz >

Subject: 2 rapare street

Hi Tom go see why some doors are not thermal broken

## 13 attachments



image001.png 391K



image002.png 469K

- image770833.png
- image049301.png 1K
- image653555.png
- image165781.png 1K
- image771661.png
- image532643.png



image932747.png



image001.png 391K



IMG-20221029-WA0010.jpg 153K



IMG-20221029-WA0009.jpg 157K