

MRPL - SOP-CRU-401 (Revision v1.0) - [SUPERSEDED - DO NOT USE]

ARCHIVED FLANGE MAINTENANCE PROCEDURE (SUPERSEDED 2021)

Section 3.0: E-204 flange torque requirement: Tighten bolts to 220 Nm.

Asbestos-filled gaskets may be reused if undamaged.