

STANDARD OPERATING PROCEDURE

Title: Overhead Crane Inspection

Document ID: SOP-CRN-001

Procedure

1. Inspect wire rope.
2. Verify brake operation.
3. Inspect hooks.
4. Test limit switches.
5. Inspect hoist gearbox.
6. Verify lubrication.
7. Record defects.

Critical Findings

- Rope strand breakage
- Brake malfunction
- Hook deformation

Action

Immediate shutdown if critical defects are found.