

STANDARD OPERATING PROCEDURE

Title: Industrial Exhaust Fan Inspection

Document ID: SOP-FAN-001

Procedure

1. Measure vibration.
2. Verify blade condition.
3. Inspect bearings.
4. Check motor current.
5. Verify airflow.

Failure Indicators

- Imbalance
- Bearing wear
- Blade damage
- Motor overload