

STANDARD OPERATING PROCEDURE

Title: Industrial Motor Inspection

Document ID: SOP-MTR-001

Purpose

To detect electrical and mechanical degradation in motors.

Procedure

1. Isolate equipment.
2. Inspect terminal connections.
3. Measure insulation resistance.
4. Verify winding temperatures.
5. Measure current imbalance.
6. Inspect bearings.
7. Verify cooling fan condition.
8. Record findings.

Acceptance Criteria

- Insulation resistance above 1 M Ω
- Current imbalance below 10%
- Bearing temperature below 85°C

Failure Indicators

- High current
- Overheating
- Bearing noise
- Insulation degradation