

STANDARD OPERATING PROCEDURE

Title: Rolling Mill Shaft Alignment

Document ID: SOP-ALIGN-001

Procedure

1. Stop equipment.
2. Verify LOTO.
3. Mount laser alignment system.
4. Measure angular misalignment.
5. Measure offset misalignment.
6. Adjust shims.
7. Re-measure alignment.
8. Verify final tolerance.

Acceptance Criteria

- Offset below 0.05 mm
- Angular deviation below specification

Failure Indicators

- Excessive vibration
- Bearing failures
- Coupling wear