

AI OCR — DOCUMENT VALIDATION REPORT

Document: VG-CP2-PRO-PID-0044 | Status: FAIL | Engine: VGL OCR

Phase 1: AI Metadata Extraction

PASS AI OCR Extraction	Extracted 8 of 14 fields (partial)
	document_number document_title revision issue_date classification issue_purpose security_code discipline_code document_type from_organisation project contract_reference prepared_by : NA : P&ID - Condensate Recovery Unit : Rev 0 : March 2026 : NOT FOUND : AFC - Approved for Construction : NOT FOUND : PRO - Process : PID : KBR : Cameron LNG Expansion : NOT SPECIFIED : T. Wilson

Phase 2: Cross-Page Consistency Analysis

PASS Blank Page Detection	No blank pages
PASS Non-OCR Page Detection	All pages have text
FAIL Draft Watermark Detected	Page 1-2
Page 1: Large "DRAFT" watermark text found. Page 1: "DRAFT - NOT FOR CONSTRUCTION" statement present. Page 2: "DRAFT" watermark repeated on notes page. Documents with DRAFT status cannot be submitted for construction approval.	
PASS Markup Annotations Check	No markups detected
WARN Signature Block Present	Only "Prepared by" found — missing Reviewed/Approved
WARN Revision History Present	No revision history section found
FAIL Security Classification Missing	
No security classification found in document. Document explicitly states: "Security classification not assigned yet." This is a mandatory field per VGL document control procedures.	
FAIL Cross-Page Consistency: Revision (Page 2)	Page 2
MISMATCH DETECTED: Page 1 Cover: Revision: Rev 0 Page 2 Notes: Revision: Rev 4 The revision number on page 2 contradicts the cover page. This is a critical discrepancy that must be resolved.	

FAIL Cross-Page Consistency: Date (Page 2)

Page 2

MISMATCH DETECTED:
Page 1 Cover: Date: March 2026
Page 2 Notes: Date: January 2025
The document date on page 2 is over a year earlier than the cover page.

Phase 3: Loadsheet Cross-Validation

PASS Loadsheet: Document Title	Title matches
PASS Loadsheet: Revision	Revision 0 matches loadsheet
PASS Loadsheet: Discipline	PRO matches Process

Phase 4: Contract / Project Validation

FAIL Wrong Contract/Project Reference

Document states PROJECT: "Cameron LNG Expansion"
Expected: "Venture Global CP2 LNG" or "C2 EPC-BOP"
This document appears to be submitted under the WRONG contract.
Cameron LNG is a different facility — not the CP2 project.

FAIL Rev 0 + AFC Misalignment

Revision 0 cannot be "Approved for Construction" (AFC).
Rev 0 is typically "Issued for Review" (IFR) or "Issued for Information" (IFI).
AFC status requires at least one prior review cycle (Rev A or higher).

Summary

Total Checks: 18 | Passed: 7 | Failed: 6 | Warnings: 2

VERDICT: REJECTED — 6 critical failures detected:

- 1. DRAFT watermark present
- 2. Security classification missing
- 3. Revision mismatch across pages (Rev 0 vs Rev 4)
- 4. Date mismatch across pages (2026 vs 2025)
- 5. Wrong project (Cameron LNG instead of CP2)
- 6. Rev 0 + AFC issue purpose misalignment