

Precise Aerial Measurement Report

Prepared for you by Beacon



2925 Katie Ct, Arnold, MO 63010




Beacon Roofing Supply, Inc.

Beacon
Beacon
Peabody, MA 01960

Master Account
tel. 555-555-5555
email: Beacon@eagleview.com
beacon.com

2925 Katie Ct, Arnold, MO 63010

Report: 64043072



In this 3D model, facets appear as semi-transparent to reveal overhangs.

Claim Information

Claim Info: 577150

PREPARED FOR

Contact: Keith Brigman
 Company: Roof Depot - O'FALLON
 Address: 1441 N. Warson Rd.
 St. Louis, MO 63132
 Phone: 314-473-1904

TABLE OF CONTENTS

Images	1
Length Diagram	4
Pitch Diagram	5
Area Diagram	6
Notes Diagram	7
Report Summary	8

MEASUREMENTS

Total Roof Area =1,925 sq ft
 Total Roof Facets =8
 Predominant Pitch =5/12
 Number of Stories <=1
 Total Ridges/Hips =82 ft
 Total Valleys =23 ft
 Total Rakes =75 ft
 Total Eaves =149 ft
 Estimated Attic=1,600 sq ft

Measurements provided by www.eagleview.com


Certified Accurate

www.eagleview.com/Guarantee.aspx

2925 Katie Ct, Arnold, MO 63010

Report: 64043072

IMAGES

The following aerial images show different angles of this structure for your reference.

Top View



2925 Katie Ct, Arnold, MO 63010

Report: 64043072

IMAGES

North Side



South Side



2925 Katie Ct, Arnold, MO 63010


Report: 64043072

IMAGES

East Side



West Side




2925 Katie Ct, Arnold, MO 63010

Report: 64043072

LENGTH DIAGRAM


Total Line Lengths:

Ridges = 54 ft
Hips = 28 ft
Valleys = 23 ft
Rakes = 75 ft
Eaves = 149 ft
Flashing = 21 ft
Step flashing = 9 ft
Parapets = 0 ft


Note: This diagram contains segment lengths (rounded to the nearest whole number) over 5.0 Feet. In some cases, segment labels have been removed for readability. Plus signs preface some numbers to avoid confusion when rotated (e.g. +6 and +9).

PITCH DIAGRAM

Pitch values are shown in inches per foot, and arrows indicate slope direction. The predominant pitch on this roof is 5/12



Note: This diagram contains labeled pitches for facet areas larger than 20.0 square feet. In some cases, pitch labels have been removed for readability. Blue shading indicates a pitch of 3/12 and greater. Gray shading indicates flat, 1/12 or 2/12 pitches. If present, a value of "F" indicates a flat facet (no pitch).

2925 Katie Ct, Arnold, MO 63010

Report: 64043072

AREA DIAGRAM


Total Area = 1,925 sq ft, with 8 facets.



Note: This diagram shows the square feet of each roof facet (rounded to the nearest Foot). The total area in square feet, at the top of this page, is based on the non-rounded values of each roof facet (rounded to the nearest square foot after being totaled).

NOTES DIAGRAM

Roof facets are labeled from smallest to largest (A to Z) for easy reference.



2925 Katie Ct, Arnold, MO 63010

Report: 64043072

REPORT SUMMARY

All Structures

Areas per Pitch

Roof Pitches	0/12	4/12	5/12	6/12
Area (sq ft)	194.8	116.0	1570.8	42.8
% of Roof	10.1%	6%	81.6%	2.2%

The table above lists each pitch on this roof and the total area and percent (both rounded) of the roof with that pitch.

Structure Complexity

Simple	Normal	Complex
--------	--------	---------

Waste Calculation


NOTE: This waste calculation table is for asphalt shingle roofing applications. All values in table below only include roof areas of 3/12 pitch or greater. For total measurements of all pitches, please refer to the **Lengths, Areas, and Pitches** section below.

Waste %	0%	2%	7%	10%	12%	14%	17%	22%	27%
Area (Sq ft)	1730	1765	1852	1904	1938	1973	2025	2111	2198
Squares *	17.33	17.66	18.66	19.33	19.66	20.00	20.33	21.33	22.00
	Measured				Suggested				

* Squares are rounded up to the 1/3 of a square

Additional materials needed for ridge, hip, and starter lengths are not included in the above table. The provided suggested waste factor is intended to serve as a guide—actual waste percentages may differ based upon several variables that EagleView does not control. These waste factor variables include, but are not limited to, individual installation techniques, crew experiences, asphalt shingle material subtleties, and potential salvage from the site. Individual results may vary from the suggested waste factor that EagleView has provided. The suggested waste is not to replace or substitute for experience or judgment as to any given replacement or repair work.

All Structures Totals



Total Roof Facets = 8

Lengths, Areas and Pitches

Ridges = 54 ft (2 Ridges)
 Hips = 28 ft (2 Hips)
 Valleys = 23 ft (2 Valleys)
 Rakes† = 75 ft (6 Rakes)
 Eaves/Starter‡ = 149 ft (11 Eaves)
 Drip Edge (Eaves + Rakes) = 224 ft (17 Lengths)
 Parapet Walls = 0 (0 Lengths)
 Flashing = 21 ft (1 Lengths)
 Step flashing = 9 ft (2 Lengths)
 Predominant Pitch = 5/12
Total Area (All Pitches) = 1,925 sq ft

Property Location

Longitude = -90.4070822
 Latitude = 38.4180525

Notes

This was ordered as a residential property. There were no changes to the structure in the past four years.

† Rakes are defined as roof edges that are sloped (not level).
 ‡ Eaves are defined as roof edges that are not sloped and level.

2925 Katie Ct, Arnold, MO 63010

Report: 64043072

Online Maps

Online map of property

http://maps.google.com/maps?f=g&source=s_q&hl=en&geocode=&q=2925+Katie+Ct,Arnold,MO,63010

Directions from Roof Depot - O'FALLON to this property

http://maps.google.com/maps?f=d&source=s_d&saddr=1441+N.+Warson+Rd.,St.+Louis,MO,63132&daddr=2925+Katie+Ct,Arnold,MO,63010

2925 Katie Ct, Arnold, MO 63010

Report: 64043072

IMPORTANT LEGAL NOTICE AND DISCLAIMER**Notice and Disclaimer**

No Warranty: The Copyrighted Materials are provided to you "as is," and you agree to use it at your own risk.

EagleView Technologies makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise, including but not limited to, content, quality, accuracy, completeness, effectiveness, reliability, fitness for a particular purpose, usefulness, use or results to be obtained from the Copyrighted Materials.

Contractors agree to always conduct a preliminary site survey to verify Roof Report ordered. In the event of an error in a Report, your sole remedy will be a refund of the fees paid by you to obtain this Report.