Adaptive Dehydrator

Team ID: - MH045
Shivam Rana
Harshil Sheth
Kedar Kale
Jay Suthar

Problem Statement:

• FOOD SPOILAGE DUE TO POOR STORAGE AND PROCESSING FACILITIES.

Wooden structure

Aluminum foil covered on thermocol

ESP 32 WROOM module





Peltier module

DHT 11 sensor

Grill

Initial





Final

Date & Time	Temperature (°C)	Humidity (%)
06/09/2024 – 00:20	30.80	55
06/09/2024 – 00:23	32.20	49
06/09/2024 – 00:37	34.70	41
06/09/2024 – 00:49	35.60	38