

## **BELDEN'S AUTOMOTIVE MC**

8825 FREDERICKSBURG ROAD

San Antonio, TX. 78240

Phone: 210-690-1100 Fax: 210-690-4747

\*\*\* WE KEEP YOU ROLLING\*\*\*

INVOICE

41654

Org. Est. # 136293

## **Invoice from History**

KABB 4335 NW LOOP 410

San Antonio, TX 78229

Spouse 210-559-9046 PABLO -- Cell No Text 210-559-9044

Work Completed: 05/18/2020 Date: 06/04/2020 2013 Subaru - Forester X - 2.5L, H4 (152CI) VIN(Not Available)

Lic #: BTK9773

Odometer In: 100295

Unit #: #8

VIN #: JF2SHABC5 DH407593

LÜIS	1,50,500, 100,000, 10				
Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
BG PLUS OIL CHANGE KIT BG6579	1.00	27.00	27.00	Beldens Multi-Point Inspection is a thorough review of	n/c
OIL FILTER PO4615	1.00	6.40	6.40	all major systems on the vehicle. Inspection of any safety concerns and check to make sure vehicle is completely up to date on recommended factory	
0W-20 FULL SYNTHETIC DEXOS SPL67283	5.50	7.25	39.88	maintenance. Symptoms: Beldens Automotive & Tires Multi-Point Inspection i	is
VALEO BEAM TITANIUM WIPER BLADE Size: 18" 604481	1.00	17.95	17.95	CUSTOMERS CONCERNS: REPLACE WIPER n/c   BLADE, DRIVE SIDE IS MISSING REPLACE BOTH.	
VALEO BEAM TITANIUM WIPER BLADE Size: 24" 604486	1.00	17.95	17.95	BRAKE INSPECTION LITTLE SQUEAKY Symptoms: PERFORM PRELIMINARY INSPECTIONS ON CUSTOMER CONCERNS. REPLACE BOTH WIPER BLADES, PERFORM OIL CHANGE,	
Air Filter	1.00	25.08	25.08		
MGA49012 Shop Supplies/Environ. Fees			8.95	Tech Check List: Customer Concerns AddressedTech Bus. CardFloor MatWindows? Vehicle CleanFluids FullOil Reminder StickerTire PSILug Nuts TightTech Sign -OffMgr Sign Off Symptoms: Tech Check List:	n/c
				BG ENGINE OIL CHANGE PLUS  **DRIVERRICARDO 210-559-9061***WORK 210-993-7795**  ***HAD CHECK ENGINE LIGHT ONPO455 EVAP EMISSION CONTROL SYSTEM*** NEEDS DIAGNOSTIC TIME***  ** HAD CO057-VDC CONTROL INTERRUPTION** TRACTIO CONTROL LIGHT IS ON	
				[ Recommendations ] Perform Lube, Oil & Filter Exchange on 8/14/2020 or 103300 Miles. 05-18-20	
				* RECOMMEND WHEEL ALIGNMENT AND ROTATE AND BALANCEMAINTENANCE	



## **BELDEN'S AUTOMOTIVE MC**

8825 FREDERICKSBURG ROAD San Antonio, TX. 78240

Phone: 210-690-1100 Fax: 210-690-4747

\*\*\* WE KEEP YOU ROLLING\*\*\*

INVOICE

41654

Org. Est. # 136293

## Invoice from History

Work Completed:

05/18/2020

Date: 06/04/2020

KABB

2013 Subaru - Forester X - 2.5L, H4 (152Cl) VIN(Not Available)

4335 NW LOOP 410

Lic #: BTK9773

Odometer In: 100295

San Antonio, TX 78229

Unit #: #8

Spouse 210-559-9046 PABLO -- Cell No Text 210-559-9044

VIN #: JF2SHABC5 DH407593

Part Description / Number	Qty	Sale	Ext Labor Description	Ext

Org. Estimate 93.52 Revisions 0.00 Current Estimate 93.52

Labor: 14.95 Parts: 143.21

Customer Number: 6585

SubTotal: Tax:

158.16 0.00 158.16

Total: Bal Due:

\$0.00

[ Payments - Elec - Credit Card - \$158.16 ]

Service Advisor: DE HOYOS, ALEX, Tech: OLIVAREZ, ALEXANDER

Vehicle Received: 5/18/2020

I authorized the above repair work to be done along with the necessary material and granted you and/or your employees permission to operate the car or truck herein described on street, highways, or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto, 24 MONTH 24,000 MILE LOCAL WARRANTY ON PARTS AND LABOR FROM ORIGINAL DATE OF REPAIRS. I have read and understand the above statements.

KABB Paid \$ 158.16 Card#: xxxxxxxxxxxxxxxxx1006 Transaction: 1500042768-Amex-1006 Approval:

SALE:801469:162000936::1500042768::: Date/Time: 6/4/2020 11:18:52AM

TRANSACTIONTYPE: SALE TRANSACTIONRESULT: APPROVED TIMESTAMP: 6/4/2020 11: 18: 37 AM MERCHANTORDERNUMBER; 0604206585 AMOUNT: 158.16 ENTRYMETHOD: C NAME: ALLAN MCMAHAN ACCOUNTTYPE: AMEX ACCOUNT: XXXXXXXXXXXXX1006 ORDERID: 1216214070 TRANSACTIONID: 1500042768 AUTHCODE: 801469

APPLABEL:AMERICAN EXPRESS AID:A000000025010801 TVR:0080008000 IAD:06490103A02002 TSI:E800 ARQC:7A2911A90FBB510C ARC:00 CVM:S

Signature x

06/04/2020

Buyer agrees to pay total amount above according to cardholder's agreement with issuer.