

Synthetic Scanned Inspection Report

Equipment ID: SCAN-A01

Inspection date: 2026-09-01

Bearing temperature: 82 C

Vibration: 6.4 mm/s

Finding: Bearing temperature is slightly elevated.

Recommendation: Inspect lubrication system.