
No synchronization
Classical reference
QCS (preamble only)
QCS, batch re-sync (prior-art style)
QCS (preamble + pilot tracking)
Perfect synchronization
(a)
(b)
(c)
Timing capture (%)
Initial clock offset (ns)
Clock drift (ppm), offset = 0
Arrival-time jitter σ (ns)