




Copyright @ 2007 CustomPartNet

Copyright @ 2007 CustomPartNet



CNC Axes






CNC Lathe



First NC Machine at MIT (1952)



CNC Machines & Programming

CNC stands for "Computer Numerically Controlled".

In using CNC machines one has to prepare a computer program to manufacture the part.

Preparation of CNC programs and proving them is first step to machine the part.


CNC programs are also called part programs.

There are two types of codes are used in CNC programming:


preparatory codes (G Codes)

miscellaneous codes (M codes)


Milling Machine



Milling Machine Axes



Milling Process



Copyright @ 2007 CustomPartNet

CNC Programming

Motion Statements


G00 Linear Movement (rapid)

G01 Linear Movement (feed)


G02 Circular Movement (cw feed)

G03 Circular Movement (ccw feed)


CNC System



CNC System









Hip Implant




Impeller



Five Axis Machining



Industry 4.0 (Machines)



Designing for Cyber-Physical Systems

Sensors Internet + **Data** ΑI