
HRS (SET sweep)
HRS (RESET sweep)
LRS (SET sweep)
LRS (RESET sweep)
R at 0.1 V (Ω)
SET
RESET
R_{HRS}/R_{LRS}
Cycle