



# Agile Product Collaboration

 IBM  
maximo

AUTODESK  
Tandem



Wawan Hartawan

Operational Director

PT. Anagile Kharisma Utama


[harta@agile.co.id](mailto:harta@agile.co.id)





IBM  
maximo

*Support CM and PM*



IoT  
EDGE



IoT  
Sensor



AUTODESK  
Tandem



Maximo  
Mobile for Technician

1

## IoT Sensor

The sensor will pick up various activities that occur on the device, if something happens the sensor will send a signal to the APCO server

2

## Command Center


The command center is a place to monitor all activities that occur throughout the place which are connected to various sensors. If something happens to the device, the command center will get information via screen and email

3

## Technician

The technician will get information and work orders to inspect or repair the device


# APCO Use Case in Manufacture Industry






# Asset Visualization with Autodesk Tandem

# Asset State – Normal






# Asset State – Conveyor Stopped




# Asset State – Main Unit Warning Overheat






# Asset State – Main Unit Danger Overheat





# Asset Management with IBM Maximo

# Asset Monitoring





agile  
solution



# Mas Manage – Work Order Tracking Detail



IBM Maximo Application Suite | Manage

Work Order Tracking

Find navigation item

X

Common Actions

New Work Order

Save Work Order

Clear Changes

Change Status

Select Owner

Take Ownership

Approve Work Order

Initiate Work Order

Complete Work Order

Close Work Order

Create Report

Work Order

Plans

Assignments

Related Records

Actuals

Safety Plan

Log

Data Sheet

Failure Reporting

Specifi

Work Order

1264

Location

BR230

Asset

11230

Configuration Item

WO Total Work Units

1.00

Parent WO

Classification

DANGER Current Device Temperature is 31.5 with Humidity 80 <

Boiler Room Emergency Generator

Emergency Generator

Site

BEDFORD

Class

WORKORDER

Work Type

CM

GL Account

6210-327-???

Failure Class

Problem Code

Storeroom Material Status

Attachments

View attachments

Status

WAPPR

Status Date

12/12/24 6:05 AM

Inherit Status Changes?





Accepts Charges?

Is Task?

Under Flow Control?



# Maximo Mobile (Technician Access)





# APCO Email Notification



Inboxes > My Inbox > [URGENT] Create Work Order - Asset Need to Repair

W Wawan Hartawan

Search...

[URGENT] Create Work Order - Asset Need to Repair  
to: <harta@agile.co.id> 2 minutes ago

[URGENT] Create Work Order - Asset Need to Repair  
to: <harta@agile.co.id> 16 minutes ago

[INFO] Task Has Been Created  
to: <asri@agile.co.id> 17 days ago

[INFO] Task Has Been Created  
to: <asri@agile.co.id> 18 days ago

[INFO] Task Has Been Created  
to: <asri@agile.co.id> 18 days ago

[INFO] Task Has Been Created  
to: <asri@agile.co.id> 18 days ago

[INFO] Task Has Been Created  
to: <asri@agile.co.id> 18 days ago

[INFO] Task Has Been Created  
to: <asri@agile.co.id> 2 months ago

[INFO] Task Has Been Created  
to: <asri@agile.co.id> 2 months ago

[INFO] Task Has Been Created  
to: <asri@agile.co.id> 2 months ago

## [URGENT] Create Work Order - Asset Need to Repair

2024-11-10 11:27, 2.3 KB

From: APCO <hello@example.com>  
To: <harta@agile.co.id>

Show Headers

HTML HTML Source Text Raw Spam Analysis HTML Check 7 Tech Info



Greeting

There has been a problem with some of Asset Number : **SPT-IOT-004** on PLTS IKN

Work Order Has been Created, and send to Technician Maximo Mobile

**error message as follows Asset Down Need to Be Repair it hapen on 10-11-2024 18:11:27**

*These email generate automatically by APCO Middleware, don't need to reply*

[An Agile Kharisma Utama](#)



# Thank You