FLoc=251175298 AJPSBcnt= 90 DLBLK S=31 D=21 BEPts=20010911 11:11:00 DL MsgLen= 59 DBI= 9 DlIndicator= 1 DINumStns= 1 BepStnName = BOSB3 SSV=88 (0x58)
<SOH>2.N334AA<NAK>QE<STX>M39AAA0011BOS<NUL><NUL><NUL><NUL><NUL><NUL><NUL><TSTRE T>
<NUL><NUL>0764LAXOS LAX /M5300764<ETX>

FLoc=251175388 AJPSBcnt= 182 DLMSG S=31 D=21 BEPts=20010911 11:11:00 ADNS MsgLen= 142 Tail Number= .N334AA SMI= DEP FttId= AA0011 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA ANPDMXA TULDDAA <CR><LF>
.DDLXCXA 111111
<STX>DEP<CR><LF>
FI AA11/AN N334AA/DA BOS/FB 764/DS LAX<CR><LF>
DT DDL BOS 111111 M39A<CR><LF>
- OS LAX /M5300764<CR><LF>
<ETX><ETX><EOT>

FLoc=251219039 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 11:11:05 UL MsgLen= 14 Stn= BOSB3 StnDelivType= 2 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA9_W<ETX>

FLoc=251241743 AJPSBcnt= 69 DLBLK S=31 D=21 BEPts=20010911 11:11:07 DL MsgLen= 38 DBI= 0 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=89 (0x59) <SOH>2.N334AA<NAK>5D<STX>M40AAA0011OS LAX /TISBOS<ETX>

FLoc=251241812 AJPSBcnt= 167 DLMSG S=31 D=21 BEPts=20010911 11:11:07 ADNS MsgLen= 127 Tail Number= .N334AA SMI= TIS FItId= AA0011 AgyNum= 1 (0x0001) <CR><LF> <SOH>QU RURDLXA ATSA5XA ATSAAXA TULDDAA <CR><LF> .DDLXCXA 111111</F> <CR><LF> <STX>TIS<CR><LF> FI AA11/AN N334AA</F> CR><LF> DT DDL BOS 111111 M40A</F> <CR><LF> - OS LAX /TISBOS</F> <ETX><EOT>

FLoc=251259707 AJPSBcnt= 69 DLBLK S=31 D=21 BEPts=20010911 11:11:08 DL MsgLen= 38 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=63 (0x3F) <SOH>2.N334AA<NAK>5D<STX>M40AAA0011OS LAX /TISBOS<ETX>

FLoc=251274928 AJPSBcnt= 545 ULMSG S=31 D=21 BEPts=20010911 11:11:10 ADNS MsgLen= 488 Org Addr= ATSAAXA Org TimeStamp= 20010911 11:10:00 Smi= AGM AgyNum= 65535 Tail Number= .N334AA FltId= AA0011 Target Stn= <00><00><00><00> Target Method= 0 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .ATSAAXA 111110<CR><LF> <STX>AGM<CR><LF> AN N334AA<CR><LF> BOS ATIS INFO N 1054Z. 32008KT 10SM<CR><LF> FEW250 18/14 A3005 (THREE ZERO ZERO<CR><LF> FIVE). ILS 4R, VA 4L, DEP 9. READBACK<CR><LF> ALL HOLD SHORT INSTRUCTIONS. HVY BIRD<CR><LF> ACTVTY IN ALL AREAS. RY 15R/33L CLSD., <CR><LF> AVBL FOR TAXI., RY 15L/33R CLSD., AVBL<CR><LF> FOR TAXI., TWY P , CLSD, TWY E CLSD<CR><LF> BTWN 22R AND 22L. UPON RECEIPT OF YOUR<CR><LF> ATC CLEARANCE READ BACK ONLY YOUR CALL<CR><LF> SIGN AND TRANSPONDER CODE UNLESS YOU<CR><LF> HAVE EIGH QUESTION. ...ADVS you have<CR><LF> INFO N.<CR><LF> <ETX><EOT>

FLoc=251293558 AJPSBcnt= 152 ULBLK S=31 D=21 BEPts=20010911 11:11:12 UL MsgLen= 111 Stn= BOSB3 StnDelivType= 2 Tail= .N334AA Fid= AA0011
<SOH>2.N334AA0C1X<STX>.ATSA5XA 111110<CR><LF> AGM<CR><LF> AN N334AA<CR><LF> - KBOS 1108<CR><LF> TDWR TERMINAL WX INFO<CR><LF> NO STORMS WITHIN 15NM<CR><LF> <CR><LF> <CR><CR><CF> <CR><CF> <CR><CF> <CR><CF> <CR><CF> <CR><CF> <CETX> <CR><CR><CETX> <CR >CETX <

FLoc=251309668 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:11:13 DL MsgLen= 24 DBI= 1 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=89 (0x59) <SOH>2.N334AAX_<STX>S41AAA0011<ETX>

FLoc=251331840 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:11:15 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=64 (0x40)
<SOH>2.N334AAX_<STX>S41AAA0011<ETX>

FLoc=251363159 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:11:18 UL MsgLen= 235 Stn= BOSB3 StnDelivType= 1 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA<NAK>C1Y<STX>.ATSAAXA 111110<CR><LF>

AGM<CR><LF>
AN N334AA<CR><LF>
- BOS ATIS INFO N 1054Z. 32008KT 10SM<CR><LF>
FEW250 18/14 A3005 (THREE ZERO ZERO<CR><LF>
FIVE). ILS 4R, VA 4L, DEP 9. READBACK<CR><LF>
ALL HOLD SHORT INSTRUCTIONS. HVY BIRD<CR><LF>
ACTVTY IN ALL AREAS. RY 15R/33L <ETB>

FLoc=251447743 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:11:28 UL MsgLen= 235 Stn= BOSB3 StnDelivType= 1 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA<NAK>C1Y<STX>.ATSAAXA 111110<CR><LF>AGM<CR><LF>AN N334AA<CR><LF>- BOS ATIS INFO N 1054Z. 32008KT 10SM<CR><LF>FEW250 18/14 A3005 (THREE ZERO ZERO<CR><LF>FIVE). ILS 4R, VA 4L, DEP 9. READBACK<CR><LF>ALL HOLD SHORT INSTRUCTIONS. HVY BIRD<CR><LF>ACTVTY IN ALL AREAS. RY 15R/33L <ETB>

FLoc=251463224 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:11:29 DL MsgLen= 24 DBI= 3 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=89 (0x59) <SOH>2.N334AAY_<STX>S43AAA0011<ETX>

FLoc=251476551 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:11:31 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=63 (0x3F) <SOH>2.N334AAY_<STX>S43AAA0011<ETX>

FLoc=251491179 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:11:34 UL MsgLen= 235 Stn= BOSB3 StnDelivType= 1 Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>C1Z<STX>CLSD.,<CR><LF> AVBL FOR TAXI., RY 15L/33R CLSD., AVBL<CR><LF> FOR TAXI., TWY P , CLSD, TWY E CLSD<CR><LF> BTWN 22R AND 22L. UPON RECEIPT OF YOUR<CR><LF> ATC CLEARANCE READ BACK ONLY YOUR CALL<CR><LF> SIGN AND TRANSPONDER CODE UNLESS YOU<CR><LF> HAVE EIGH QUESTIO<ETB>

FLoc=251506653 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:11:35 DL MsgLen= 24 DBI= 4 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=89 (0x59) <SOH>2.N334AAZ <STX>S44AAA0011<ETX>

FLoc=251519008 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:11:37 DL MsgLen= 24 DBI= 4 DIIndicator= 2 DINumStns= 1 BepStnName = BOSA3 SSV=63 (0x3F) <SOH>2.N334AAZ_<STX>S44AAA0011<ETX>

FLoc=251545655 AJPSBcnt= 86 ULBLK S=31 D=21 BEPts=20010911 11:11:40 UL MsgLen= 45 Stn= BOSB3 StnDelivType= 1 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA<NAK>C1A<STX>N. ...ADVS you have<CR><LF>INFO N.<CR><LF>

FLoc=251637416 AJPSBcnt= 86 ULBLK S=31 D=21 BEPts=20010911 11:11:50 UL MsgLen= 45 Stn= BOSB3 StnDelivType= 1 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA<NAK>C1A<STX>N. ...ADVS you have<CR><LF>INFO N.<CR><LF><ETX>

FLoc=251650802 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:11:51 DL MsgLen= 24 DBI= 6 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=90 (0x5A) <SOH>2.N334AAA_<STX>S46AAA0011<ETX>

FLoc=251678650 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:11:54 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=64 (0x40) <SOH>2.N334AAA_<STX>S46AAA0011<ETX>

FLoc=260024234 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 11:28:00 DL MsgLen= 35 DBI= 7 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=87 (0x57) <SOH>2.N334AA<NAK>5Z<STX>M47AAA0011OS LAX /CLR<ETX>

FLoc=260024300 AJPSBcnt= 148 DLMSG S=31 D=21 BEPts=20010911 11:28:00 ADNS MsgLen= 108 Tail Number= .N334AA SMI= AGM FltId= AA0011 AgyNum= 1 (0x0001) <CR><LF> <SOH>QU RURDLXA TULDDAA <CR><LF> .DDLXCXA 111128<CR><LF> <STX>AGM<CR><LF> FI AA11/AN N334AA<CR><LF> DT DDL BOS 111128 M47A<CR><LF> - OS LAX /CLR<CR><LF> <ETX><ETX><EOT>

FLoc=260040232 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 11:28:02 DL MsgLen= 35 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=59 (0x3B) <SOH>2.N334AA<NAK>5Z<STX>M47AAA0011OS LAX /CLR<ETX>

FLoc=260055431 AJPSBcnt= 407 ULMSG S=31 D=21 BEPts=20010911 11:28:03 ADNS MsgLen= 350 Org Addr= TULDDAA Org TimeStamp= 20010911 11:27:00 Smi= M40 AgyNum= 65535 Tail Number= .N334AA FltId= AA0011 Target Stn= BOS<00><00> Target Method= 1 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111127 FROM <CR><LF> <STX>M40<CR><LF> AN N334AA/AP BOS<CR><LF> - FLIGHT 0011/11 BOS -LAX <CR><LF> PDC<CR><LF> AAL11 XPNDR 1443<CR><LF> B/B762/E P1145 350<CR><LF> <CR><LF>

FLoc=260077112 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:28:05 UL MsgLen= 235 Stn= BOSB3 StnDelivType= 2 Tail= .N334AA Fid= AA0011
<SOH>2.N334AA740B<STX>FLIGHT 0011/11 BOS -LAX <CR><LF> PDC<CR><LF> AAL11 XPNDR 1443<CR><LF> B/B762/E P1145 350<CR><LF> <CR><LF> BOS GLYDE CTR HNK ULW JHW<CR><LF> CXR PIA J96 SLN J102***LAX<CR><LF> @NRP@<CR><LF> <CR><LF> CR><LF> DOS GLYDE CTR FIRM OF TOO OO OF TOO OF TOO OF TOO OF TOO OF TOO OT OO OT OOT OO OT OOT OO OT OOT OO OT OOT

FLoc=260088724 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:28:06 DL MsgLen= 24 DBI= 8 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=87 (0x57) <SOH>2.N334AAB_<STX>S48AAA0011<ETX>

FLoc=260105335 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:28:08 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=60 (0x3C) <SOH>2.N334AAB_<STX>S48AAA0011<ETX>

FLoc=260130412 AJPSBcnt= 109 ULBLK S=31 D=21 BEPts=20010911 11:28:11 UL MsgLen= 68 Stn= BOSB3 StnDelivType= 1 Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40C<STX>RTURE<CR><LF> CONTACT 121.65 WHEN READY TO PUSH<CR><LF> <CR><LF> <CR><LF> <CR><LF> <END<CR><LF> <END<CR><LF> <ETX> <

FLoc=260141252 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:28:12 DL MsgLen= 24 DBI= 9 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=88 (0x58) <SOH>2.N334AAC_<STX>S49AAA0011<ETX>

FLoc=260168237 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:28:14 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DINumStns= 1

BepStnName = BOSA3 SSV=59 (0x3B) <SOH>2.N334AAC <STX>S49AAA0011<ETX>

FLoc=261189576 AJPSBcnt= 75 DLBLK S=31 D=21 BEPts=20010911 11:30:02 DL MsgLen= 44 DBI= 0 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=86 (0x56) <SOH>2.N334AA<NAK>5Z<STX>M50AAA0011OS LAX /TPS09 15018<ETX>

FLoc=261189651 AJPSBcnt= 157 DLMSG S=31 D=21 BEPts=20010911 11:30:02 ADNS MsgLen= 117 Tail Number= .N334AA SMI= AGM FltId= AA0011 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA TULDDAA <CR><LF>
.DDLXCXA 111130 <CR><LF>
<STX>AGM <CR><LF>
FI AA11/AN N334AA <CR><LF>
DT DDL BOS 111130 M50A <CR><LF>
- OS LAX /TPS09 15018 <CR><LF>
<ETX><EOT>

FLoc=261205777 AJPSBcnt= 75 DLBLK S=31 D=21 BEPts=20010911 11:30:04 DL MsgLen= 44 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=60 (0x3C) <SOH>2.N334AA<NAK>5Z<STX>M50AAA0011OS LAX /TPS09 15018<ETX>

FLoc=261216636 AJPSBcnt=1633 ULMSG S=31 D=21 BEPts=20010911 11:30:05 ADNS MsgLen= 1576 Org Addr= TULDDAA Org TimeStamp= 20010911 11:29:00 Smi= M40 AgyNum= 65535 Tail Number= .N334AA FitId= AA0011 Target Stn= BOS<00><00> Target Method= 1 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111129 FROM <CR><LF> <STX>M40<CR><LF> AN N334AA/AP BOS<CR><LF> - FLT 0011 BOS- <CR><LF> STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF> BOS -90 0011/11 334 11/1129Z<CR><LF> <CR><LF> *** 767/767ER CF6-80A ENG ***<CR><LF> <CR><LF> TEMP PTOW ATOW ZFW FUEL <CR><LF> 18C 294.1 297.1 218.5 76.4A<CR><LF> <CR><LF> ******* THRUST / V-SPEED ******** <CR><LF> <CR><LF> *MAX* N1 TOW CG<CR><LF> A/C ON 103.4 27.2<CR><LF> A/C OFF 103.7<CR><LF> <CR><LF> RWY FLAP STAB A/C N1 V1 VR V2<CR><LF> 09 15 3.6 ON 100.4 132 136 141<CR><LF> <CR><LF> RWY AT MTOW <CR><LF>

09 45C 324.7T <CR><LF>

<CR><LF>

```
********* AIRPORT NOTES ***********************
<CR><LF>
SPECIAL ENGINE-FAILURE PROCEDURES<CR><LF>
EXIST RWY 27.<CR><LF>
.<CR><LF>
   * USE /S/ AFTER RUNWAY NUMBER FOR *<CR><LF>
* TAKEOFF WEIGHTS WHEN TOWER *<CR><LF>
* CONFIRMS SHIPS IN CHANNEL. *<CR><LF>
     EXAMPLE - 04RS
                     *<CR><LF>
<CR><LF>
****** AIRPORT ANALYSIS DATA *********CR><LF>
<CR><LF>
 STRUCT WT LIMIT 351.0<CR><LF>
 <CR><LF>
   CLIMB TEMP RWY <CR><LF>
FLAP A/C LIMIT C 09 <CR><LF>
             ---<CR><LF>
  ON 327.1 18 324.7 <CR><LF>
15 ON 327.0 20 323.8 <CR><LF>
OFF 329.8 18 326.2 <CR><LF>
  OFF 329.8 20 325.3 <CR><LF>
  HDWND ADD / KT 0 < CR > < LF >
  TLWND SUB / KT 2720 < CR><LF>
   E/O ACCEL /AFL/ FT 600 <CR><LF>
    /MSL/ FT 620 <CR><LF>
 ------CR><LF>
  IMPROVED PERFORMANCE<CR><LF>
  OFF 18 326.1 <CR><LF>
15 OFF
          20 325.2 <CR><LF>
 PLANNED WIND KT H0 <CR><LF>
          -----<CR><LF>
 LENGTH - FT 7000 <CR><LF>
 SLOPE - PCT
             .0 <CR><LF>
         -----<CR><LF>
<CR><LF>
<CR><LF>
<LF>
<CR><LF>
<LF>
<| F>
<ETX><EOT>
FLoc=261230585 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:30:07
UL MsgLen= 235 Stn= BOSB3 StnDelivType= 2
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA040D<STX>FLT 0011 BOS- <CR><LF>
STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF>
BOS -90 0011/11 334 11/1129Z<CR><LF>
<CR><LF>
*** 767/767ER CF6-80A ENG ***<CR><LF>
<CR><LF>
 TEMP PTOW ATOW ZFW FUEL <CR><LF>
 18C 294.1 297.1 218.5 76.4A<CR><LF>
```

```
FLoc=261333447 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:30:17 UL MsgLen= 235 Stn= BOSB3 StnDelivType= 2 Tail= .N334AA Fid= AA0011  
<SOH>2.N334AA040D<STX>FLT 0011 BOS- <CR><LF> STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF> BOS -90 0011/11 334 11/1129Z<CR><LF> <CR><LF> **** 767/767ER CF6-80A ENG ***<CR><LF> CR><LF> TEMP PTOW ATOW ZFW FUEL <CR><LF> 18C 294.1 297.1 218.5 76.4A<CR><LF> <CR><ETB>
```

FLoc=261557302 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:30:37 UL MsgLen= 235 Stn= BOSB3 StnDelivType= 2 Tail= .N334AA Fid= AA0011
<SOH>2.N334AA040D<STX>FLT 0011 BOS- <CR><LF> STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF> BOS -90 0011/11 334 11/1129Z<CR><LF> <CR><LF> *** 767/767ER CF6-80A ENG ***<CR><LF> TEMP PTOW ATOW ZFW FUEL <CR><LF> 18C 294.1 297.1 218.5 76.4A<CR><LF> <CR><ETB>

FLoc=261672448 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:30:47 UL MsgLen= 235 Stn= BOSB3 StnDelivType= 2 Tail= .N334AA Fid= AA0011
<SOH>2.N334AA040D<STX>FLT 0011 BOS- <CR><LF> STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF> BOS -90 0011/11 334 11/1129Z<CR><LF> <CR><LF> *** 767/767ER CF6-80A ENG ***<CR><LF> TEMP PTOW ATOW ZFW FUEL <CR><LF> 18C 294.1 297.1 218.5 76.4A<CR><LF> <CR><ETB>

FLoc=261765612 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:30:57 UL MsgLen= 235 Stn= BOSB3 StnDelivType= 2

Tail= .N334AA Fid= AA0011
<SOH>2.N334AA040D<STX>FLT 0011 BOS- <CR><LF>
STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF>
BOS -90 0011/11 334 11/1129Z<CR><LF>
<CR><LF>
*** 767/767ER CF6-80A ENG ***<CR><LF>
CR><LF>
TEMP PTOW ATOW ZFW FUEL <CR><LF>
18C 294.1 297.1 218.5 76.4A<CR><LF>
<CR><ETB>

FLoc=261853118 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:31:07 UL MsgLen= 235 Stn= BOSA3 StnDelivType= 3 Tail= .N334AA Fid= AA0011
<SOH>>2.N334AA040D<STX>FLT 0011 BOS- <CR><LF> STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF> BOS -90 0011/11 334 11/1129Z<CR><LF> <CR><LF> **** 767/767ER CF6-80A ENG ***<CR><LF> CR><LF> TEMP PTOW ATOW ZFW FUEL <CR><LF> 18C 294.1 297.1 218.5 76.4A<CR><LF> <CR><ETB>

FLoc=261946489 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:31:17 UL MsgLen= 235 Stn= BOSA3 StnDelivType= 3 Tail= .N334AA Fid= AA0011
<SOH>2.N334AA040D<STX>FLT 0011 BOS- <CR><LF> STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF> BOS -90 0011/11 334 11/1129Z<CR><LF> <CR><LF> *** 767/767ER CF6-80A ENG ***<CR><LF> CR><LF> TEMP PTOW ATOW ZFW FUEL <CR><LF> 18C 294.1 297.1 218.5 76.4A<CR><LF> <CR><ETB>

FLoc=262042760 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:31:27 UL MsgLen= 235 Stn= BOSA3 StnDelivType= 3 Tail= .N334AA Fid= AA0011
<SOH>2.N334AA040D<STX>FLT 0011 BOS- <CR><LF> STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF> BOS -90 0011/11 334 11/1129Z<CR><LF> <CR><LF> **** 767/767ER CF6-80A ENG ***<CR><LF> CR><LF> TEMP PTOW ATOW ZFW FUEL <CR><LF> 18C 294.1 297.1 218.5 76.4A<CR><LF> <CR><ETB>

FLoc=262140606 AJPSBcnt=1708 ICPUL S=31 D=21 BEPts=20010911 11:31:37 Intercept MsgLen=1576 Addressee= .N334AA Num MediaTypes=1 Blk Num=1 Ul Code=0

***lcpHdr: Reason Code= 311 AgyNum= 65535

***IcpHdr: Tail Number= .N334AA

```
Dumping Media type #1 of 1

Media Type = 0 Num Stns= 2 Num History= 9

Stn Score Card # 1 of 2; EntryType= 2 (0x0002) Stn=BOSB3

Stn Score Card # 2 of 2; EntryType= 3 (0x0003) Stn=BOSA3

History Card # 1 of 9; Reason= 311 (0x0137) Stn=BOSB3

History Card # 2 of 9; Reason= 311 (0x0137) Stn=BOSB3

History Card # 3 of 9; Reason= 311 (0x0137) Stn=BOSB3

History Card # 4 of 9; Reason= 311 (0x0137) Stn=BOSB3

History Card # 5 of 9; Reason= 311 (0x0137) Stn=BOSB3

History Card # 6 of 9; Reason= 311 (0x0137) Stn=BOSB3

History Card # 7 of 9; Reason= 311 (0x0137) Stn=BOSB3

History Card # 8 of 9; Reason= 311 (0x0137) Stn=BOSA3

History Card # 9 of 9; Reason= 311 (0x0137) Stn=BOSA3

History Card # 9 of 9; Reason= 311 (0x0137) Stn=BOSA3

CR><LF>

SOH>OU DDLXCXA<CR><LF>
```

<CR><LF> <SOH>QU DDLXCXA<CR><LF> <CR><LF> .TULDDAA 111129 FROM <STX>M40<CR><LF> AN N334AA/AP BOS<CR><LF> - FLT 0011 BOS- <CR><LF> STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF> BOS -90 0011/11 334 11/1129Z<CR><LF> <CR><LF> *** 767/767ER CF6-80A ENG ***<CR><LF> <CR><LF> TEMP PTOW ATOW ZFW FUEL <CR><LF> 18C 294.1 297.1 218.5 76.4A<CR><LF> <CR><LF> ******* THRUST / V-SPEED ******** < CR > < LF > <CR><LF> *MAX* N1 TOW CG<CR><L A/C ON 103.4 27.2<CR><LF> A/C OFF 103.7<CR><LF> TOW CG<CR><LF> <CR><LF> RWY FLAP STAB A/C N1 V1 VR V2<CR><LF> 09 15 3.6 ON 100.4 132 136 141<CR><LF> <CR><LF> RWY AT MTOW <CR><LF> 09 45C 324.7T <CR><LF> <CR><LF> ******* AIRPORT NOTES ******************** <CR><LF> SPECIAL ENGINE-FAILURE PROCEDURES<CR><LF> EXIST RWY 27.<CR><LF> .<CR><LF> * USE /S/ AFTER RUNWAY NUMBER FOR *<CR><LF> TAKEOFF WEIGHTS WHEN TOWER *<CR><LF> CONFIRMS SHIPS IN CHANNEL. *<CR><LF> *<CR><LF> EXAMPLE - 04RS <CR><LF>

****** AIRPORT ANALYSIS DATA *********CR><LF>

```
<CR><LF>
 STRUCT WT LIMIT 351.0<CR><LF>
 <CR><LF>
CLIMB TEMP RWY <CR><LF>FLAP A/C LIMIT C 09 <CR><LF>
              ----<CR><LF>
  ON 327.1 18 324.7 <CR><LF>
15 ON 327.0 20 323.8 <CR><LF> OFF 329.8 18 326.2 <CR><LF>
  OFF 329.8 20 325.3 <CR><LF>
   HDWND ADD / KT 0 < CR > < LF >
   TLWND SUB / KT 2720 <CR><LF>
       - - - - - - - - < CR><LF>
 E/O ACCEL /AFL/ FT 600 <CR><LF>
    /MSL/ FT 620 <CR><LF>
 -----CR><LF>
  IMPROVED PERFORMANCE<CR><LF>
        18 326.1 <CR><LF>
  OFF
           20 325.2 <CR><LF>
15 OFF
 PLANNED WIND KT H0 <CR><LF>
           -----<CR><LF>
 LENGTH - FT 7000 <CR><LF>
 SLOPE - PCT
                 .0 <CR><LF>
         -----<CR><LF>
<CR><LF>
<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX><EOT>
FLoc=263023054 AJPSBcnt= 75 DLBLK S=31 D=21 BEPts=20010911 11:33:09
DL MsgLen= 44 DBI= 2 DlIndicator= 1 DlNumStns= 1
BepStnName = BOSB3 SSV=87 (0x57)
<SOH>2.N334AA<NAK>H1<STX>F52AAA0000#M1ALIF/DAKBOS/RD090<ETX>
FLoc=263023129 AJPSBcnt= 168 DLMSG S=31 D=21 BEPts=20010911 11:33:09
ADNS MsgLen= 128 Tail Number= .N334AA SMI= FML
FltId= AA0000 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA DCABFXA DCAGFXA TULDDAA <CR><LF>
.DDLXCXA 111133<CR><LF>
<STX>FML<CR><LF>
FI AA0/AN N334AA<CR><LF>
DT DDL BOS 111133 F52A<CR><LF>
- LIF/DAKBOS/RD090<CR><LF>
<ETX><EOT>
FLoc=263041054 AJPSBcnt= 75 DLBLK S=31 D=21 BEPts=20010911 11:33:11
DL MsgLen= 44 DBI= 2 DlIndicator= 2 DlNumStns= 1
BepStnName = BOSA3 SSV=58 (0x3A)
<SOH>2.N334AA<NAK>H1<STX>F52AAA0000#M1ALIF/DAKBOS/RD090<ETX>
```

FLoc=263047158 AJPSBcnt= 255 ULMSG S=31 D=21 BEPts=20010911 11:33:11 ADNS MsgLen= 198 Org Addr= TULDDAA Org TimeStamp= 20010911 11:32:00

Smi= M40 AgyNum= 65535

Tail Number= .N334AA FItId= AA0011

Target Stn= BOS<00><00> Target Method= 1

<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111132 FROM <CR><LF>
<STX>M40<CR><LF>
AN N334AA/AP BOS<CR><LF>
- ***** LIF RUNWAY REQUEST *********** <CR><LF>
RUNWAY 09 NOT AVAILABLE<CR><LF>
LOAD AGENT NOTIFIED <ETX><EOT>

FLoc=263090882 AJPSBcnt= 75 DLBLK S=31 D=21 BEPts=20010911 11:33:17 DL MsgLen= 44 DBI= 3 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=86 (0x56) <SOH>2.N334AAE5Z<STX>M53AAA0011OS LAX /TPS09 15018<ETX>

FLoc=263090957 AJPSBcnt= 157 DLMSG S=31 D=21 BEPts=20010911 11:33:17 ADNS MsgLen= 117 Tail Number= .N334AA SMI= AGM FitId= AA0011 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA TULDDAA <CR><LF>
.DDLXCXA 111133 <CR><LF>
<STX>AGM <CR><LF>
FI AA11/AN N334AA <CR><LF>
DT DDL BOS 111133 M53A <CR><LF>
- OS LAX /TPS09 15018 <CR><LF>
<ETX><EOT>

FLoc=263113326 AJPSBcnt= 75 DLBLK S=31 D=21 BEPts=20010911 11:33:20 DL MsgLen= 44 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=58 (0x3A) <SOH>2.N334AAE5Z<STX>M53AAA0011OS LAX /TPS09 15018<ETX>

FLoc=263123520 AJPSBcnt=1633 ULMSG S=31 D=21 BEPts=20010911 11:33:21 ADNS MsgLen= 1576 Org Addr= TULDDAA Org TimeStamp= 20010911 11:33:00 Smi= M40 AgyNum= 65535
Tail Number= .N334AA FltId= AA0011
Target Stn= BOS<00><00> Target Method= 1
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111133 FROM <CR><LF>
AN N334AA/AP BOS<CR><LF>
AN N334AA/AP BOS<CR><LF>
-FLT 0011 BOS- <CR><LF>
STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF>
BOS -90 0011/11 334 11/1133Z<CR><LF>
<CR><LF>
<CR><LF>
<CR><LF>
<CR><LF>
</CR></LF>

```
*** 767/767ER CF6-80A ENG ***<CR><LF>
<CR><LF>
 TEMP PTOW ATOW ZFW FUEL <CR><LF>
 18C 294.1 297.1 218.5 76.4A<CR><LF>
<CR><LF>
*********** THRUST / V-SPEED ********* < CR > < LF >
<CR><LF>
*MAX* N1
            TOW CG<CR><LF>
A/C ON 103.4 27.2<CR><LF>
A/C OFF 103.7<CR><LF>
<CR><LF>
RWY FLAP STAB A/C N1 V1 VR V2<CR><LF>
09 15 3.6 ON 100.4 132 136 141<CR><LF>
<CR><LF>
RWY AT
          MTOW <CR><LF>
09 45C 324.7T <CR><LF>
<CR><LF>
****** AIRPORT NOTES ********* < CR > < LF >
<CR><LF>
SPECIAL ENGINE-FAILURE PROCEDURES<CR><LF>
EXIST RWY 27.<CR><LF>
.<CR><LF>
   * USE /S/ AFTER RUNWAY NUMBER FOR *<CR><LF>
* TAKEOFF WEIGHTS WHEN TOWER *<CR><LF>
  CONFIRMS SHIPS IN CHANNEL. *<CR><LF>
    EXAMPLE - 04RS
                     *<CR><LF>
<CR><LF>
****** AIRPORT ANALYSIS DATA ******** < CR > < LF >
<CR><LF>
 STRUCT WT LIMIT 351.0<CR><LF>
 <CR><LF>
   CLIMB TEMP RWY <CR><LF>
FLAP A/C LIMIT C 09 <CR><LF>
        -----CR><l F>
  ON 327.1 18 324.7 <CR><LF>
15 ON 327.0 20 323.8 <CR><LF>
  OFF 329.8 18 326.2 <CR><LF>
  OFF 329.8 20 325.3 <CR><LF>
  HDWND ADD / KT 0 < CR><LF>
  TLWND SUB / KT 2720 <CR><LF>
  ------CR><LF>
E/O ACCEL /AFL/ FT 600 <CR><LF>
   /MSL/ FT 620 <CR><LF>
IMPROVED PERFORMANCE<CR><LF>
       18 326.1 <CR><LF>
  OFF
15 OFF
          20 325.2 <CR><LF>
PLANNED WIND KT H0 <CR><LF>
           -----<CR><LF>
 LENGTH - FT
              7000 <CR><LF>
 SLOPE - PCT
               .0 <CR><LF>
             --<CR><LF>
<CR><I F>
<CR><LF>
```

```
<| F>
<CR><LF>
<LF>
<LF>
<ETX><EOT>
FLoc=263128643 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:33:22
UL MsgLen= 235 Stn= BOSB3 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA340F<STX>FLT 0011 BOS- <CR><LF>
STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF>
BOS -90 0011/11 334 11/1133Z<CR><LF>
<CR><LF>
*** 767/767ER CF6-80A ENG ***<CR><LF>
<CR><LF>
 TEMP PTOW ATOW ZFW FUEL <CR><LF>
 18C 294.1 297.1 218.5 76.4A<CR><LF>
<CR><ETB>
FLoc=263243232 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:33:32
UL MsgLen= 235 Stn= BOSB3 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA340F<STX>FLT 0011 BOS- <CR><LF>
STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF>
BOS -90 0011/11 334 11/1133Z<CR><LF>
<CR><LF>
*** 767/767ER CF6-80A ENG ***<CR><LF>
<CR><LF>
 TEMP PTOW ATOW ZFW FUEL <CR><LF>
 18C 294.1 297.1 218.5 76.4A<CR><LF>
<CR><ETB>
FLoc=263330475 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:33:42
UL MsgLen= 235 Stn= BOSB3 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA340F<STX>FLT 0011 BOS- <CR><LF>
STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF>
BOS -90 0011/11 334 11/1133Z<CR><LF>
<CR><LF>
*** 767/767ER CF6-80A ENG ***<CR><LF>
<CR><LF>
 TEMP PTOW ATOW ZFW FUEL <CR><LF>
 18C 294.1 297.1 218.5 76.4A<CR><LF>
<CR><ETB>
FLoc=263429082 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:33:52
UL MsgLen= 235 Stn= BOSB3 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA340F<STX>FLT 0011 BOS- <CR><LF>
STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF>
BOS -90 0011/11 334 11/1133Z<CR><LF>
<CR><LF>
*** 767/767ER CF6-80A ENG ***<CR><LF>
```

<CR><LF>

TEMP PTOW ATOW ZFW FUEL <CR><LF>
18C 294.1 297.1 218.5 76.4A<CR><LF>

```
<CR><ETB>
FLoc=263518992 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:34:02
UL MsgLen= 235 Stn= BOSB3 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA340F<STX>FLT 0011 BOS- <CR><LF>
STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF>
BOS -90 0011/11 334 11/1133Z<CR><LF>
<CR><LF>
*** 767/767ER CF6-80A ENG ***<CR><LF>
<CR><LF>
 TEMP PTOW ATOW ZFW FUEL <CR><LF>
 18C 294.1 297.1 218.5 76.4A<CR><LF>
<CR><ETB>
FLoc=263607251 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:34:12
UL MsgLen= 235 Stn= BOSB3 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA340F<STX>FLT 0011 BOS- <CR><LF>
STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF>
BOS -90 0011/11 334 11/1133Z<CR><LF>
<CR><LF>
*** 767/767ER CF6-80A ENG ***<CR><LF>
<CR><LF>
 TEMP PTOW ATOW ZFW FUEL <CR><LF>
 18C 294.1 297.1 218.5 76.4A<CR><LF>
<CR><ETB>
FLoc=263712207 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:34:22
UL MsqLen= 235 Stn= BOSB3 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA340F<STX>FLT 0011 BOS- <CR><LF>
STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF>
BOS -90 0011/11 334 11/1133Z<CR><LF>
<CR><LF>
*** 767/767ER CF6-80A ENG ***<CR><LF>
<CR><LF>
       PTOW ATOW ZFW FUEL <CR><LF>
 TEMP
 18C 294.1 297.1 218.5 76.4A<CR><LF>
<CR><ETB>
```

FLoc=263909539 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:34:42 UL MsgLen= 235 Stn= BOSA3 StnDelivType= 3

Tail= .N334AA Fid= AA0011

<SOH>2.N334AA340F<STX>FLT 0011 BOS- <CR><LF>
STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF>
BOS -90 0011/11 334 11/1133Z<CR><LF>
<CR><LF>
*** 767/767ER CF6-80A ENG ***<CR><LF>
CR><LF>
TEMP PTOW ATOW ZFW FUEL <CR><LF>
18C 294.1 297.1 218.5 76.4A<CR><LF>
<CR><ETB>

FLoc=263997028 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:34:52 UL MsgLen= 235 Stn= BOSA3 StnDelivType= 3 Tail= .N334AA Fid= AA0011
<SOH>>2.N334AA340F<STX>FLT 0011 BOS- <CR><LF> STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF> BOS -90 0011/11 334 11/1133Z<CR><LF> <CR><LF> *** 767/767ER CF6-80A ENG ***<CR><LF> CR><LF> TEMP PTOW ATOW ZFW FUEL <CR><LF> 18C 294.1 297.1 218.5 76.4A<CR><LF> <CR><ETB>

FLoc=264084939 AJPSBcnt=1715 ICPUL S=31 D=21 BEPts=20010911 11:35:02 Intercept MsgLen=1576 Addressee= N334AA Num MediaTypes=1 Blk Num=1 UI Code=0

***IcpHdr: Reason Code= 311 AgyNum= 65535

***IcpHdr: Tail Number= .N334AA

***IcpHdr: FltId= <FF><00><00><00><00>

Dumping Media type #1 of 1

Media Type = 0 Num Stns= 2 Num History= 10
Stn Score Card # 1 of 2; EntryType= 1 (0x0001) Stn= BOSB3
Stn Score Card # 2 of 2; EntryType= 3 (0x0003) Stn= BOSA3
History Card # 1 of 10; Reason= 311 (0x0137) Stn= BOSB3
History Card # 2 of 10; Reason= 311 (0x0137) Stn= BOSB3
History Card # 3 of 10; Reason= 311 (0x0137) Stn= BOSB3
History Card # 4 of 10; Reason= 311 (0x0137) Stn= BOSB3
History Card # 5 of 10; Reason= 311 (0x0137) Stn= BOSB3
History Card # 6 of 10; Reason= 311 (0x0137) Stn= BOSB3
History Card # 7 of 10; Reason= 311 (0x0137) Stn= BOSB3
History Card # 8 of 10; Reason= 311 (0x0137) Stn= BOSB3
History Card # 9 of 10; Reason= 311 (0x0137) Stn= BOSA3
History Card # 10 of 10; Reason= 311 (0x0137) Stn= BOSA3

```
<CR><LF>
*** 767/767ER CF6-80A ENG ***<CR><LF>
<CR><LF>
 TEMP PTOW ATOW ZFW FUEL <CR><LF>
 18C 294.1 297.1 218.5 76.4A<CR><LF>
<CR><LF>
*********** THRUST / V-SPEED *********CR><LF>
<CR><LF>
*MAX* N1
             TOW CG<CR><LF>
A/C ON 103.4 27.2<Cl
A/C OFF 103.7<CR><LF>
              27.2<CR><LF>
<CR><LF>
RWY FLAP STAB A/C N1 V1 VR V2<CR><LF>
09 15 3.6 ON 100.4 132 136 141<CR><LF>
<CR><LF>
RWY AT MTOW <CR><LF>
09 45C 324.7T <CR><LF>
<CR><LF>
********* AIRPORT NOTES *************CR><LF>
<CR><LF>
SPECIAL ENGINE-FAILURE PROCEDURES<CR><LF>
EXIST RWY 27.<CR><LF>
<CR><I F>
  * USE /S/ AFTER RUNWAY NUMBER FOR *<CR><LF>
* TAKEOFF WEIGHTS WHEN TOWER *<CR><LF>
  CONFIRMS SHIPS IN CHANNEL. *<CR><LF>
                      *<CR><LF>
    FXAMPLE - 04RS
            <CR><LF>
****** AIRPORT ANALYSIS DATA *********CR><LF>
<CR><LF>
 STRUCT WT LIMIT 351.0<CR><LF>
 <CR><LF>
   CLIMB TEMP RWY <CR><LF>
FLAP A/C LIMIT C 09 <CR><LF>
             ----<CR><LF>
  ON 327.1 18 324.7 <CR><LF>
15 ON 327.0 20 323.8 <CR><LF>
OFF 329.8 18 326.2 <CR><LF>
OFF 329.8 20 325.3 <CR><LF>
  HDWND ADD / KT 0 < CR > < LF >
  TLWND SUB / KT 2720 <CR><LF>
  E/O ACCEL /AFL/ FT 600 <CR><LF>
    /MSL/ FT 620 <CR><LF>
------CR><LF>
  IMPROVED PERFORMANCE<CR><LF>
  OFF
        18 326.1 <CR><LF>
15 OFF
          20 325.2 <CR><LF>
 PLANNED WIND KT H0 <CR><LF>
         -----<CR><LF>
 LENGTH - FT 7000 <CR><LF>
 SLOPE - PCT
               .0 <CR><LF>
          -----<CR><LF>
<CR><LF>
```

<CR><LF><LF><LF><CR><LF><CR><LF><<LF><LF><LF><LF><

FLoc=264809611 AJPSBcnt= 75 DLBLK S=31 D=21 BEPts=20010911 11:36:24 DL MsgLen= 44 DBI= 5 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=90 (0x5A) <SOH>2.N334AA<NAK>5Z<STX>M55AAA0011OS LAX /TPS09 15018<ETX>

FLoc=264809686 AJPSBcnt= 157 DLMSG S=31 D=21 BEPts=20010911 11:36:24 ADNS MsgLen= 117 Tail Number= .N334AA SMI= AGM FltId= AA0011 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA TULDDAA <CR><LF>
.DDLXCXA 111136<CR><LF>
<STX>AGM<CR><LF>
FI AA11/AN N334AA<CR><LF>
DT DDL BOS 111136 M55A<CR><LF>
- OS LAX /TPS09 15018<CR><LF>
<ETX><EOT>

FLoc=264821950 AJPSBcnt= 75 DLBLK S=31 D=21 BEPts=20010911 11:36:26 DL MsgLen= 44 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=62 (0x3E) <SOH>2.N334AA<NAK>5Z<STX>M55AAA0011OS LAX /TPS09 15018<ETX>

FLoc=264832000 AJPSBcnt=1633 ULMSG S=31 D=21 BEPts=20010911 11:36:27 ADNS MsgLen= 1576 Org Addr= TULDDAA Org TimeStamp= 20010911 11:36:00 Smi= M40 AgyNum= 65535 Tail Number= .N334AA FltId= AA0011 Target Stn= BOS<00><00> Target Method= 1 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111136 FROM <CR><LF> <STX>M40<CR><LF> AN N334AA/AP BOS<CR><LF> - FLT 0011 BOS- <CR><LF> STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF> BOS -100 0011/11 334 11/1136Z<CR><LF> <CR><LF> *** 767/767ER CF6-80A ENG ***<CR><LF> <CR><LF> TEMP PTOW ATOW ZFW FUEL <CR><LF> 18C 294.1 297.1 218.5 76.4A<CR><LF> <CR><LF> ******* THRUST / V-SPEED ******** < CR><LF> <CR><LF> *MAX* N1 TOW CG<CR><LF> A/C ON 103.4 27.2<C A/C OFF 103.7<CR><LF> 27.2<CR><LF> <CR><LF> RWY FLAP STAB A/C N1 V1 VR V2<CR><LF> 09 15 3.6 ON 100.4 132 136 141<CR><LF>

```
<CR><LF>
RWY AT
          MTOW <CR><LF>
09 45C 324.7T <CR><LF>
<CR><LF>
********* AIRPORT NOTES ********************
SPECIAL ENGINE-FAILURE PROCEDURES<CR><LF>
EXIST RWY 27.<CR><LF>
.<CR><LF>
   * USE /S/ AFTER RUNWAY NUMBER FOR *<CR><LF>
* TAKEOFF WEIGHTS WHEN TOWER *<CR><LF>
  CONFIRMS SHIPS IN CHANNEL. *<CR><LF>
                      *<CR><LF>
    EXAMPLE - 04RS
          ***** AIRPORT ANALYSIS DATA ********CR><LF>
<CR><LF>
 STRUCT WT LIMIT 351.0<CR><LF>
 <CR><LF>
   CLIMB TEMP RWY <CR><LF>
FLAP A/C LIMIT C 09 <CR><LF>
              --<CR><LF>
ON 327.1 18 324.7 <CR><LF>
15 ON 327.0 20 323.8 <CR><LF>
  OFF 329.8 18 326.2 <CR><LF>
  OFF 329.8 20 325.3 <CR><LF>
  HDWND ADD / KT 0 <CR><LF>
  TLWND SUB / KT 2720 <CR><LF>
    E/O ACCEL /AFL/ FT 600 <CR><LF>
   /MSL/ FT 620 <CR><LF>
------CR><LF>
  IMPROVED PERFORMANCE<CR><LF>
  OFF
        18 326.1 <CR><LF>
15 OFF
          20 325.2 <CR><LF>
PLANNED WIND KT H0 <CR><LF>
     -----<CR><LF>
             7000 <CR><LF>
 LENGTH - FT
 SLOPE - PCT
               .0 <CR><LF>
            -----<CR><LF>
<CR><LF>
<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX><EOT>
FLoc=264848744 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:36:29
UL MsgLen= 235 Stn= BOSB3 StnDelivType= 2
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA540G<STX>FLT 0011 BOS- <CR><LF>
STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF>
BOS -100 0011/11 334 11/1136Z<CR><LF>
<CR><LF>
```

```
*** 767/767ER CF6-80A ENG ***<CR><LF>
<CR><LF>
 TEMP PTOW ATOW ZFW FUEL <CR><LF>
 18C 294.1 297.1 218.5 76.4A<CR><LF>
<CR><ETB>
FLoc=264857600 AJPSBcnt=1633 ULMSG S=31 D=21 BEPts=20010911 11:36:29
ADNS MsgLen= 1576 Org Addr= TULDDAA Org TimeStamp= 20010911 11:36:00
Smi= M40 AgyNum= 65535
Tail Number= .N334AA FltId= AA0011
Target Stn= BOS<00><00> Target Method= 1
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111136 FROM L003
                         <CR><LF>
<STX>M40<CR><LF>
AN N334AA/AP BOS<CR><LF>
- FLT 0011 BOS- <CR><LF>
STA PRES ALT FLT/DTE AIRPL DTE/TIME<CR><LF>
BOS -100 0011/11 334 11/1136Z<CR><LF>
<CR><I F>
*** 767/767ER CF6-80A ENG ***<CR><LF>
<CR><LF>
 TEMP PTOW ATOW ZFW FUEL <CR><LF>
 19C 294.1 297.1 218.5 76.4A<CR><LF>
<CR><LF>
<CR><LF>
*MAX* N1 TOW CG<CR><L
A/C ON 103.6 27.2<CR><LF>
            TOW CG<CR><LF>
A/C OFF 103.9<CR><LF>
<CR><LF>
RWY FLAP STAB A/C N1 V1 VR V2<CR><LF>
09 15 3.6 ON 100.5 132 136 141<CR><LF>
<CR><LF>
RWY AT
          MTOW <CR><LF>
09 45C 324.2T <CR><LF>
<CR><LF>
****** AIRPORT NOTES ************************
<CR><LF>
SPECIAL ENGINE-FAILURE PROCEDURES<CR><LF>
EXIST RWY 27.<CR><LF>
.<CR><LF>
* USE /S/ AFTER RUNWAY NUMBER FOR *<CR><LF>
* TAKEOFF WEIGHTS WHEN TOWER *<CR><LF>
  CONFIRMS SHIPS IN CHANNEL. *<CR><LF>
     EXAMPLE - 04RS
                      *<CR><LF>
      <CR><LF>
***** AIRPORT ANALYSIS DATA ******* < CR><LF>
<CR><LF>
 STRUCT WT LIMIT 351.0<CR><LF>
 <CR><LF>
    CLIMB TEMP RWY <CR><LF>
FLAP A/C LIMIT C 09 <CR><LF>
            -----<CR><LF>
```

```
ON 327.1 19 324.2 <CR><LF>
15 ON 327.0 21 323.3 <CR><LF>
  OFF 329.8 19 325.7 <CR><LF>
  OFF 329.7 21 324.8 <CR><LF>
   HDWND ADD / KT 0 < CR><LF>
   TLWND SUB / KT 2720 <CR><LF>
   E/O ACCEL /AFL/ FT 600 <CR><LF>
     /MSL/ FT 620 <CR><LF>
 ------CR><LF>
   IMPROVED PERFORMANCE<CR><LF>
  OFF
         19 325.6 <CR><LF>
15 OFF
           21 324.7 <CR><LF>
 PLANNED WIND KT H0 <CR><LF>
           -----<CR><LF>
  LENGTH - FT 7000 < CR > < LF >
  SLOPE - PCT
                 .0 <CR><LF>
             -----<CR><LF>
<CR><LF>
<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX><EOT>
FLoc=264874615 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:36:31
DL MsgLen= 24 DBI= 6 DlIndicator= 1 DlNumStns= 1
BepStnName = BOSB3 SSV=90 (0x5A)
<SOH>2.N334AAG_<DEL><STX>S56AAA0011<ETX>
FLoc=264898722 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:36:34
DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1
BepStnName = BOSA3 SSV=61 (0x3D)
<SOH>2.N334AAG_<DEL><STX>S56AAA0011<ETX>
FLoc=264910360 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:36:36
UL MsgLen= 235 Stn= BOSB3 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40H<STX><LF>
 ********** THRUST / V-SPEED **********CR><LF>
<CR><LF>
*MAX* N1 TOW CG<CR><LF>
A/C ON 103.4 27.2<CR><LF>
A/C OFF 103.7<CR><LF>
<CR><LF>
RWY FLAP STAB A/C N1 V1 VR V2<CR><LF>
09 15 3.6 ON 100.4 132 136 141<CR><LF>
<CR><LF>
RWY AT
            <ETB>
FLoc=264982749 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:36:43
DL MsgLen= 24 DBI= 7 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=90 (0x5A)
```

<SOH>2.N334AAH_<STX>S57AAA0011<ETX>

FLoc=265003585 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 11:36:45 DL MsgLen= 35 DBI= 8 DIIndicator= 1 DINumStns= 1 BepStnName = BOSB3 SSV=90 (0x5A) <SOH>2.N334AA<NAK>5Z<STX>M58AAA0011OS LAX /CLR<ETX>

FLoc=265003651 AJPSBcnt= 148 DLMSG S=31 D=21 BEPts=20010911 11:36:45 ADNS MsgLen= 108 Tail Number= .N334AA SMI= AGM FitId= AA0011 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA TULDDAA <CR><LF>
.DDLXCXA 111136<CR><LF>
<STX>AGM<CR><LF>
FI AA11/AN N334AA<CR><LF>
DT DDL BOS 111136 M58A<CR><LF>
- OS LAX /CLR<CR><LF>
<ETX><EOT>

FLoc=265008788 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:36:46 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=61 (0x3D) <SOH>2.N334AAH_<STX>S57AAA0011<ETX>

FLoc=265018528 AJPSBcnt= 407 ULMSG S=31 D=21 BEPts=20010911 11:36:47 ADNS MsgLen= 350 Org Addr= TULDDAA Org TimeStamp= 20010911 11:36:00 Smi= M40 AgyNum= 65535 Tail Number= .N334AA FltId= AA0011 Target Stn= BOS<00><00> Target Method= 1 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111136 FROM <CR><LF> <STX>M40<CR><LF> AN N334AA/AP BOS<CR><LF> FLIGHT 0011/11 BOS -LAX <CR><LF> PDC<CR><LF> AAL11 XPNDR 1443<CR><LF> B/B762/E P1145 350<CR><LF> <CR><LF> BOS GLYDE CTR HNK ULW JHW<CR><LF> CXR PIA J96 SLN J102***LAX<CR><LF> @NRP@<CR><LF> <CR><LF> MAINT 5000 EXPCT REQ ALT 10 MIN AFT T/O<CR><LF> DEPARTURE FREQ 133.0<CR><LF> LOGAN TWO DEPARTURE<CR><LF> CONTACT 121.65 WHEN READY TO PUSH<CR><LF> <CR><LF> <CR><LF> END<CR><LF> <ETX><EOT>

FLoc=265022698 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:36:48 UL MsgLen= 235 Stn= BOSB3 StnDelivType= 1 Tail= .N334AA Fid= AA0011
<SOH>2.N334AA840I<STX>MTOW <CR><LF>
09 45C 324.7T <CR><LF>
<CR><LF>

******* AIRPORT NOTES *************CR><LF> <CR><LF> SPECIAL ENGINE-FAILURE PROCEDURES<CR><LF> EXIST RWY 27.<CR><LF> .<CR><LF> * USE /S/ AFTER RUNWAY NUMBER FOR *<CR><LF> * TAKE<ETB>

FLoc=265025334 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 11:36:48 DL MsgLen= 35 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=61 (0x3D)

<SOH>2.N334AA<NAK>5Z<STX>M58AAA0011OS LAX /CLR<ETX>

FLoc=265042259 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:36:49 DL MsgLen= 24 DBI= 9 DIIndicator= 1 DINumStns= 1 BepStnName = BOSB3 SSV=90 (0x5A) <SOH>2.N334AAI_<STX>S59AAA0011<ETX>

FLoc=265064346 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:36:52 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=60 (0x3C) <SOH>2.N334AAI <STX>S59AAA0011<ETX>

FLoc=265081663 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:36:54 UL MsgLen= 235 Stn= BOSB3 StnDelivType= 1 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA<NAK>40J<STX>OFF WEIGHTS WHEN TOWER *<CR><LF> CONFIRMS SHIPS IN CHANNEL. *<CR><LF>

EXAMPLE - 04RS *<CR><LF>

<CR><LF> ***** AIRPORT ANALYSIS DATA ******* < CR><LF> <CR><LF> STRUCT WT LIMIT 351.0<CR><LF> <CR><ETB>

FLoc=265093208 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:36:55 DL MsgLen= 24 DBI= 0 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=90 (0x5A)<SOH>2.N334AAJ_<STX>\$60AÁA0011<ETX>

FLoc=265106020 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:36:57 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=62 (0x3E) <SOH>2.N334AAJ <STX>S60AAA0011<ETX>

FLoc=265127834 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:37:00 UL MsgLen= 235 Stn= BOSB3 StnDelivType= 1 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA<NAK>40K<STX><LF> CLIMB TEMP RWY <CR><LF>FLAP A/C LIMIT C 09 <CR><LF> ----<CR><LF> ON 327.1 18 324.7 <CR><LF> 15 ON 327.0 20 323.8 <CR><LF>

```
OFF 329.8 20 325.3 <CR><LF>
   HDWND ADD <ETB>
FLoc=265139862 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:37:01
DL MsgLen= 24 DBI= 1 DlIndicator= 1 DlNumStns= 1
BepStnName = BOSB3 SSV=90 (0x5A)
<SOH>2.N334AAK_<DEL><STX>S61AAA0011<ETX>
FLoc=265159231 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:37:03
DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1
BepStnName = BOSA3 SSV=60 (0x3C)
<SOH>2.N334AAK_<DEL><STX>S61AAA0011<ETX>
FLoc=265184205 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:37:06
UL MsgLen= 235 Stn= BOSB3 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40L<STX>/ KT
                                 0 <CR><LF>
  TLWND SUB / KT 2720 <CR><LF>
      E/O ACCEL /AFL/ FT 600 <CR><LF>
     /MSL/ FT 620 <CR><LF>
 IMPROVED PERFORMANCE<CR><LF>
  OFF 18 326.1 <CR><LF>
15 <ETB>
FLoc=265199181 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:37:07
DL MsgLen= 24 DBI= 2 DlIndicator= 1 DlNumStns= 1
BepStnName = BOSB3 SSV=90 (0x5A)
<SOH>2.N334AAL_<DEL><STX>S62AAA0011<ETX>
FLoc=265217897 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:37:10
DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1
BepStnName = BOSA3 SSV=61 (0x3D)
<SOH>2.N334AAL_<DEL><STX>S62AAA0011<ETX>
FLoc=265235687 AJPSBcnt= 236 ULBLK S=31 D=21 BEPts=20010911 11:37:12
UL MsgLen= 195 Stn= BOSB3 StnDelivType= 1
Tail= .N334AA Fid= AA0011
                                    20 325.2 <CR><LF>
<SOH>2.N334AA<NAK>40M<STX>OFF
 PLANNED WIND KT H0 <CR><LF>
            -----<CR><LF>
 LENGTH - FT 7000 <CR><LF>
SLOPE - PCT .0 <CR><LF>
             -----<CR><LF>
<CR><LF>
<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
```

FLoc=265248482 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:37:13

DL MsgLen= 24 DBI= 3 DlIndicator= 1 DlNumStns= 1

OFF 329.8 18 326.2 <CR><LF>

<ETX>

BepStnName = BOSB3 SSV=90 (0x5A) <SOH>2.N334AAM_<STX>S63AAA0011<ETX>

FLoc=265289961 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:37:16 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=60 (0x3C) <SOH>2.N334AAM_<STX>S63AAA0011<ETX>

FLoc=265342465 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:37:20 DL MsgLen= 24 DBI= 4 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=90 (0x5A) <SOH>2.N334AAN_<STX>S64AAA0011<ETX>

FLoc=265368441 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:37:23 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=57 (0x39) <SOH>2.N334AAN_<STX>S64AAA0011<ETX>

RWY FLAP STAB A/C N1 V1 VR V2<CR><LF>
09 15 3.6 ON 100.5 132 136 141<CR><LF>
<CR><LF>
RWY AT <ETB>

FLoc=265491595 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:37:37 DL MsgLen= 24 DBI= 6 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=90 (0x5A) <SOH>2.N334AAO_<STX>S66AAA0011<ETX>

FLoc=265518118 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:37:40 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=61 (0x3D) <SOH>2.N334AAO_<STX>S66AAA0011<ETX>

* USE /S/ AFTER RUNWAY NUMBER FOR *<CR><LF>
* TAKE<ETB>

FLoc=265642131 AJPSBcnt= 276 ULBLK S=31 D=2

* USE /S/ AFTER RUNWAY NUMBER FOR *<CR><LF>
* TAKE<ETB>

FLoc=265660878 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:37:53 DL MsgLen= 24 DBI= 8 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=90 (0x5A) <SOH>2.N334AAP_<STX>S68AAA0011<ETX>

FLoc=265676277 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:37:55 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=61 (0x3D)
<SOH>2.N334AAP_<STX>S68AAA0011<ETX>

FLoc=265700848 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:37:58

```
UL MsgLen= 235 Stn= BOSB3 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40Q<STX>OFF WEIGHTS WHEN TOWER *<CR><LF>
  CONFIRMS SHIPS IN CHANNEL. *<CR><LF>
     EXAMPLE - 04RS
                       *<CR><LF>
            <CR><LF>
****** AIRPORT ANALYSIS DATA *********CR><LF>
<CR><LF>
 STRUCT WT LIMIT 351.0<CR><LF>
 <CR><ETB>
FLoc=265717754 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:37:59
DL MsgLen= 24 DBI= 9 DlIndicator= 1 DlNumStns= 1
BepStnName = BOSB3 SSV=90 (0x5A)
<SOH>2.N334AAQ <DEL><STX>S69AAA0011<ETX>
FLoc=265732101 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:38:01
DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1
BepStnName = BOSA3 SSV=62 (0x3E)
<SOH>2.N334AAQ <DEL><STX>S69AAA0011<ETX>
FLoc=265755570 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:38:04
UL MsgLen= 235 Stn= BOSB3 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40R<STX><LF>
CLIMB TEMP RWY <CR><LF>FLAP A/C LIMIT C 09 <CR><LF>
             -----<CR><LF>
  ON 327.1 19 324.2 <CR><LF>
15 ON 327.0 21 323.3 <CR><LF>
  OFF 329.8 19 325.7 <CR><LF> OFF 329.7 21 324.8 <CR><LF>
  HDWND ADD <ETB>
FLoc=265770571 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:38:05
DL MsgLen= 24 DBI= 0 DlIndicator= 1 DlNumStns= 1
BepStnName = BOSB3 SSV=89 (0x59)
<SOH>2.N334AAR_<DEL><STX>S70AAA0011<ETX>
FLoc=265793781 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:38:08
DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1
BepStnName = BOSA3 SSV=63 (0x3F)
<SOH>2.N334AAR_<DEL><STX>S70AAA0011<ETX>
FLoc=265808042 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:38:10
UL MsgLen= 235 Stn= BOSB3 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40S<STX>/ KT
                                  0 <CR><LF>
  TLWND SUB / KT 2720 <CR><LF>
     E/O ACCEL /AFL/ FT 600 <CR><LF>
     /MSL/ FT 620 <CR><LF>
     -----CR><LF>
```

IMPROVED PERFORMANCE<CR><LF>
OFF 19 325.6 < CR><LF>

```
FLoc=265891625 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:38:20
UL MsgLen= 235 Stn= BOSB3 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40S<STX>/ KT
                                  0 <CR><LF>
  TLWND SUB / KT 2720 <CR><LF>
      E/O ACCEL /AFL/ FT 600 <CR><LF>
     /MSL/ FT 620 <CR><LF>
    IMPROVED PERFORMANCE<CR><LF>
         19 325.6 <CR><LF>
15 <ETB>
FLoc=265910377 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:38:21
DL MsgLen= 24 DBI= 2 DIIndicator= 1 DINumStns= 1
BepStnName = BOSB3 SSV=90 (0x5A)
<SOH>2.N334AAS_<DEL><STX>S72AAA0011<ETX>
FLoc=265931874 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:38:23
DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1
BepStnName = BOSA3 SSV=62 (0x3E)
<SOH>2.N334AAS_<DEL><STX>S72AAA0011<ETX>
FLoc=265947868 AJPSBcnt= 236 ULBLK S=31 D=21 BEPts=20010911 11:38:26
UL MsgLen= 195 Stn= BOSB3 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40T<STX>OFF
                                     21 324.7 <CR><LF>
 PLANNED WIND KT H0 <CR><LF>
             -----<CR><LF>
  LENGTH - FT 7000 <CR><LF>
  SLOPE - PCT
                 .0 <CR><LF>
             -----<CR><LF>
<CR><I F>
<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX>
FLoc=265985475 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:38:30
DL MsgLen= 24 DBI= 3 DlIndicator= 1 DlNumStns= 1
BepStnName = BOSB3 SSV=90 (0x5A)
<SOH>2.N334AAT_<DEL><STX>S73AAA0011<ETX>
FLoc=266005964 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:38:32
DL MsgLen= 24 DBI= 3 DIIndicator= 2 DINumStns= 1
BepStnName = BOSA3 SSV=62 (0x3E)
<SOH>2.N334AAT_<DEL><STX>S73AAA0011<ETX>
FLoc=266026484 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:38:35 UL MsgLen= 235 Stn= BOSB3 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40U<STX>FLIGHT 0011/11 BOS -LAX <CR><LF>
```

PDC<CR><LF>
AAL11 XPNDR 1443<CR><LF>
B/B762/E P1145 350<CR><LF>
<CR><LF>
<CR><LF>
BOS GLYDE CTR HNK ULW JHW<CR><LF>
CXR PIA J96 SLN J102***LAX<CR><LF>
@NRP@<CR><LF>
<CR><LF>
<CR><LF>
LDEPARTURE FREQ 133.0<CR><LF>
LOGAN TWO DEPA<ETB>

FLoc=266041889 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:38:36 DL MsgLen= 24 DBI= 4 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=90 (0x5A) <SOH>2.N334AAU <STX>S74AAA0011<ETX>

FLoc=266071362 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:38:39 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=62 (0x3E) <SOH>2.N334AAU_<STX>S74AAA0011<ETX>

FLoc=266087385 AJPSBcnt= 109 ULBLK S=31 D=21 BEPts=20010911 11:38:41 UL MsgLen= 68 Stn= BOSB3 StnDelivType= 1 Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40V<STX>RTURE<CR><LF> CONTACT 121.65 WHEN READY TO PUSH<CR><LF> <CR><LF> <CR><LF> <END<CR><LF> <END<CR><LF> <END<ENTAGE | STREET | STRE

FLoc=266098628 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:38:42 DL MsgLen= 24 DBI= 5 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=89 (0x59) <SOH>2.N334AAV_<STX>S75AAA0011<ETX>

FLoc=266131333 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:38:45 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=62 (0x3E) <SOH>2.N334AAV_<STX>S75AAA0011<ETX>

FLoc=267146288 AJPSBcnt= 74 DLBLK S=31 D=21 BEPts=20010911 11:40:40 DL MsgLen= 43 DBI= 6 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=90 (0x5A) <SOH>2.N334AA<NAK>QE<STX>M76AAA0011BOS1140<NUL><NUL><NUL><NUL><NUL><TSTRET> 0764LAX<ETX>

FLoc=267146362 AJPSBcnt= 169 DLMSG S=31 D=21 BEPts=20010911 11:40:40 ADNS MsgLen= 129 Tail Number= .N334AA SMI= DEP FItId= AA0011 AgyNum= 1 (0x0001) <CR><LF> <SOH>QU RURDLXA ANPDMXA TULDDAA <CR><LF> .DDLXCXA 111140<CR><LF> <STX>DEP<CR><LF> FI AA11/AN N334AA/DA BOS/OT 1140/FB 764/DS LAX<CR><LF> DT DDL BOS 111140 M76A<CR><LF>
<ETX><EOT>

FLoc=267159205 AJPSBcnt= 74 DLBLK S=31 D=21 BEPts=20010911 11:40:42 DL MsgLen= 43 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=61 (0x3D) <SOH>2.N334AA<NAK>QE<STX>M76AAA0011BOS1140<NUL><NUL><NUL><NUL><NUL><NUL><TSTRET> 0764LAX<ETX>

FLoc=267182541 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 11:40:45 UL MsgLen= 14 Stn= BOSB3 StnDelivType= 2 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA6_W<ETX>

FLoc=270878726 AJPSBcnt= 358 ULMSG S=31 D=21 BEPts=20010911 11:47:28 ADNS MsgLen= 301 Org Addr= TULDDAA Org TimeStamp= 20010911 11:47:00 Smi= M40 AgyNum= 65535 Tail Number= .N334AA FltId= AA0011 Target Stn= BOS<00><00> Target Method= 1 <CR><I F> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111147 FROM L003 <CR><LF> <STX>M40<CR><LF> AN N334AA/AP BOS<CR><LF> - LOAD CLOSEOUT RVSN 00 0747L<CR><LF> 0011 BOS-LAX N334<CR><LF> TOW 287126<CR><LF> FOB 75680A<CR><LF> ZFW 211446<CR><LF> STAB 3.8<CR><LF> R/A F-3 A-0 <CR><LF> CG 24.6 PCT <CR><LF> PSGR 81 W0 X0<CR><LF> PSGR WGT 14580<CR><LF> CGO WGT 9122 <CR><LF> EOW 187744<CR><LF> SECOK<CR><LF> <CR><LF> <CR><LF> <LF> <CR><LF> <LF> <LF> <ETX><EOT>

FLoc=270892234 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:47:30 DL MsgLen= 24 DBI= 7 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=90 (0x5A) <SOH>2.N334AAX_<STX>S77AAA0011<ETX>

FLoc=270901162 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:47:31 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=63 (0x3F) <SOH>2.N334AAX_<STX>S77AAA0011<ETX>

FLoc=270927256 AJPSBcnt= 61 ULBLK S=31 D=21 BEPts=20010911 11:47:35 UL MsgLen= 20 Stn= BOSB3 StnDelivType= 1 Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40Y<STX><LF>
<CR><LF>
<LF>
<LF>
<ETX>

FLoc=270935029 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:47:35 DL MsgLen= 24 DBI= 8 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=90 (0x5A) <SOH>2.N334AAY_<STX>S78AAA0011<ETX>

FLoc=270961792 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:47:38 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=65 (0x41) <SOH>2.N334AAY_<STX>S78AAA0011<ETX>

FLoc=278709653 AJPSBcnt= 183 DLBLK S=31 D=21 BEPts=20010911 12:00:15 DL MsgLen= 152 DBI= 9 DIIndicator= 1 DINumStns= 1 BepStnName = BOSB3 SSV=90 (0x5A)
<SOH>2.N334AA<NAK>H1<STX>D79AAA0000#DFBEDA/E4FFD,193,09D,09A,,<TSTRET>65965E,67066F,6A0697,85E861,040049,27436D,1<CR><LF>7E1C1,28F2EC,10011040,381,0C10C1,013,000,0,4684F3,0B3B27<ETX>

FLoc=278709836 AJPSBcnt= 276 DLMSG S=31 D=21 BEPts=20010911 12:00:15 ADNS MsgLen= 236 Tail Number= .N334AA SMI= DFD FltId= AA0000 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA BDROOXA DCABFXA TULDDAA <CR><LF>
.DDLXCXA 111200<CR><LF>
<STX>DFD<CR><LF>
FI AA0/AN N334AA<CR><LF>
DT DDL BOS 111200 D79A<CR><LF>
- EDA/E4FFD,193,09D,09A,,65965E,67066F,6A0697,85E861,040049,2<TSTRET> 7436D,1<CR><LF>

7E1C1,28F2EC,10011040,381,0C10C1,013,000,0,4684F3,0B3B27<CR><LF><ETX><EOT>

FLoc=278750417 AJPSBcnt= 183 DLBLK S=31 D=21 BEPts=20010911 12:00:18 DL MsgLen= 152 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=79 (0x4F) <SOH>2.N334AA<NAK>H1<STX>D79AAA0000#DFBEDA/E4FFD,193,09D,09A,,<TSTRET>65965E,67066F,6A0697,85E861,040049,27436D,1<CR><LF>7E1C1,28F2EC,10011040,381,0C10C1,013,000,0,4684F3,0B3B27<ETX>

FLoc=278772397 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:00:20 UL MsgLen= 14 Stn= BOSB3 StnDelivType= 2 Tail= .N334AA Fid= AA0000 <SOH>2.N334AA9 Z<ETX>

FLoc=278826010 AJPSBcnt= 65 DLBLK S=31 D=21 BEPts=20010911 12:00:23 DL MsgLen= 34 DBI= 0 DIIndicator= 1 DINumStns= 1 BepStnName = BOSB3 SSV=90 (0x5A) <SOH>2.N334AA<NAK>QF<STX>M80AAA0011BOS1159LAX<ETX>

FLoc=278826075 AJPSBcnt= 154 DLMSG S=31 D=21 BEPts=20010911 12:00:23 ADNS MsgLen= 114 Tail Number= .N334AA SMI= DEP FltId= AA0011 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA TULDDAA <CR><LF>
.DDLXCXA 111200<CR><LF>
<STX>DEP<CR><LF>
FI AA11/AN N334AA/DA BOS/OF 1159/DS LAX<CR><LF>
DT DDL BOS 111200 M80A<CR><LF>
<ETX><EOT>

FLoc=278846666 AJPSBcnt= 65 DLBLK S=31 D=21 BEPts=20010911 12:00:25 DL MsgLen= 34 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=76 (0x4C) <SOH>2.N334AA<NAK>QF<STX>M80AAA0011BOS1159LAX<ETX>

FLoc=278875361 AJPSBcnt= 62 ULBLK S=31 D=21 BEPts=20010911 12:00:28 UL MsgLen= 21 Stn= BOSB3 StnDelivType= 2 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA0:;A<STX>130025<ETX>

FLoc=278887079 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:00:28 DL MsgLen= 24 DBI= 1 DlIndicator= 1 DlNumStns= 1 BepStnName = BOSB3 SSV=86 (0x56) <SOH>2.N334AAA_<STX>S81AAA0011<ETX>

FLoc=278919412 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:00:31 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA3 SSV=73 (0x49) <SOH>2.N334AAA <STX>S81AAA0011<ETX>

FLoc=278926891 AJPSBcnt= 71 DLBLK S=31 D=21 BEPts=20010911 12:00:31 DL MsgLen= 40 DBI= 2 DlIndicator= 1 DlNumStns= 1 BepStnName = MHTA2 SSV=45 (0x2D) <SOH>2.N334AA<NAK>10<STX>M82AAA0011OS LAX /FQY30025<ETX>

FLoc=278926962 AJPSBcnt= 71 DLBLK S=31 D=21 BEPts=20010911 12:00:31 DL MsgLen= 40 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = PVDA2 SSV=48 (0x30) <SOH>2.N334AA<NAK>10<STX>M82AAA0011OS LAX /FQY30025<ETX>

FLoc=278927033 AJPSBcnt= 153 DLMSG S=31 D=21 BEPts=20010911 12:00:31 ADNS MsgLen= 113 Tail Number= .N334AA SMI= M10 FltId= AA0011 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA TULDDAA <CR><LF>
.DDLXCXA 111200<CR><LF>
<STX>M10<CR><LF>
FI AA11/AN N334AA<CR><LF>
DT DDL MHT 111200 M82A<CR><LF>
- OS LAX /FQY30025<CR><LF>
<ETX><ETX><ETX><ETX><ETX><ETX><ETX><ETX</ED>

FLoc=278927379 AJPSBcnt= 71 DLBLK S=31 D=21 BEPts=20010911 12:00:31 DL MsgLen= 40 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSB2 SSV=74 (0x4A) <SOH>2.N334AA<NAK>10<STX>M82AAA0011OS LAX /FQY30025<ETX>

FLoc=278961744 AJPSBcnt= 71 DLBLK S=31 D=21 BEPts=20010911 12:00:34 DL MsgLen= 40 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA2 SSV=83 (0x53) <SOH>2.N334AA<NAK>10<STX>M82AAA0011OS LAX /FQY30025<ETX>

FLoc=278988800 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:00:36 UL MsgLen= 14 Stn= BOSA2 StnDelivType= 2 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA2_B<ETX>

FLoc=279187925 AJPSBcnt= 71 DLBLK S=31 D=21 BEPts=20010911 12:00:51 DL MsgLen= 40 DBI= 2 DlIndicator= 3 DlNumStns= 1 BepStnName = MHTA2 SSV=42 (0x2A) <SOH>2.N334AA<NAK>10<STX>M82AAA0011OS LAX /FQY30025<ETX>

FLoc=279187996 AJPSBcnt= 71 DLBLK S=31 D=21 BEPts=20010911 12:00:51 DL MsgLen= 40 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = PVDA2 SSV=50 (0x32) <SOH>2.N334AA<NAK>10<STX>M82AAA0011OS LAX /FQY30025<ETX>

FLoc=279188224 AJPSBcnt= 71 DLBLK S=31 D=21 BEPts=20010911 12:00:51 DL MsgLen= 40 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSB2 SSV=70 (0x46) <SOH>2.N334AA<NAK>10<STX>M82AAA0011OS LAX /FQY30025<ETX>

FLoc=279216553 AJPSBcnt= 71 DLBLK S=31 D=21 BEPts=20010911 12:00:53 DL MsgLen= 40 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA2 SSV=77 (0x4D) <SOH>2.N334AA<NAK>10<STX>M82AAA0011OS LAX /FQY30025<ETX>

FLoc=279248134 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:00:56 UL MsgLen= 14 Stn= BOSA2 StnDelivType= 2 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA2_C<ETX>

```
FLoc=280931578 AJPSBcnt=1366 ULMSG S=31 D=21 BEPts=20010911 12:03:02
ADNS MsgLen= 1309 Org Addr= TULDDAA Org TimeStamp= 20010911 12:03:00
Smi= M40 AgyNum= 65535
Tail Number= .N334AA FltId= AA0011
Target Stn= BOS<00><00> Target Method= 2
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111203 FROM
                          <CR><LF>
<STX>M40<CR><LF>
AN N334AA/GL BOS<CR><LF>
- FLT 0011 BOS-LAX SKD ARR 1059L<CR><LF>
         PLN
              1055L<CR><LF>
OUT 1140
OFF 1159
            0764<CR><LF>
            0756<CR><LF>
GLYDE 1208
            0729<CR><LF>
CTR 1216
HNK 1232
            0691<CR><LF>
            0660<CR><LF>
ULW
     1243
            0641<CR><LF>
     1256
            0618<CR><LF>
JHW
CXR 1311
            0593<CR><LF>
PIA 1408
           0496<CR><LF>
IRK 1427
           0466<CR><LF>
AGENT 1443
             0440<CR><LF>
SLN 1502
RYLIE 1531
           0410<CR><LF>
            0364<CR><LF>
LAA
            0355<CR><LF>
     1537
ALS
     1600
            0320<CR><LF>
FMN
     1617
            0294<CR><LF>
TBC
     1640
            0259<CR><LF>
PGS
     1657
            0234<CR><LF>
HEC 1719
            0201<CR><LF>
CIVET 1734
             0189<CR><LF>
 ON 1746
            0179<CR><LF>
           0175<CR><LF>
 IN 1755
          <CR><LF>
- FLT 0011 BOS-LAX SKD ARR 1059L<CR><LF>
         PLN
              1055L<CR><LF>
 OUT 1140
OFF 1159
            0764<CR><LF>
            0756<CR><LF>
GLYDE 1208
             0729<CR><LF>
            0691<CR><LF>
CTR 1216
            0660<CR><LF>
HNK
     1232
ULW
      1243
             0641<CR><LF>
```

1256

JHW

0618<CR><LF>

```
PIA 1408
           0496<CR><LF>
IRK 1427
           0466<CR><LF>
AGENT 1443
             0440<CR><LF>
SLN 1502
           0410<CR><LF>
RYLIE 1531
            0364<CR><LF>
LAA 1537
            0355<CR><LF>
ALS 1600
            0320<CR><LF>
FMN 1617
            0294<CR><LF>
TBC
     1640
            0259<CR><LF>
PGS
     1657
            0234<CR><LF>
HEC 1719
            0201<CR><LF>
CIVET 1734
            0189<CR><LF>
 ON 1746
           0179<CR><LF>
 IN 1755
          0175<CR><LF>
          <CR><LF>
<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX><EOT>
FLoc=280932944 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:03:02
UL MsgLen= 235 Stn= BOSA2 StnDelivType= 2
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40D<STX>FLT 0011 BOS-LAX SKD ARR 1059L<CR><LF>
         PLN
              1055L<CR><LF>
OUT 1140
OFF 1159
            0764<CR><LF>
            0756<CR><LF>
GLYDE 1208
             0729<CR><LF>
            0691<CR><LF>
CTR 1216
HNK
     1232
            0660<CR><LF>
ULW
     1243
            0641<CR><LF>
JHW 1256
            <ETB>
FLoc=280938389 AJPSBcnt= 292 ULMSG S=31 D=21 BEPts=20010911 12:03:02
ADNS MsgLen= 235 Org Addr= TULDDAA Org TimeStamp= 20010911 12:03:00
Smi= M40 AgyNum= 65535
Tail Number= .N334AA FltId= AA0011
Target Stn= BOS<00><00> Target Method= 2
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111203 FROM
                         <CR><LF>
<STX>M40<CR><LF>
AN N334AA/GL BOS<CR><LF>
--/FLT 0011 BOS-LAX<CR><LF>
LAX KLAX 111203<CR><LF>
111155<CR><LF>
111150Z 00000KT 9SM FEW014 18/16 A2991 RMK AO2 SLP124 <CR><LF>
  T01780156 10189 20178 53001 <CR><LF>
END DATA <CR><LF>
<CR><LF>
<LF>
<CR><LF>
<LF>
```

CXR 1311

0593<CR><LF>

```
<LF>
<ETX><EOT>
```

FLoc=281053588 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:03:12 UL MsgLen= 235 Stn= BOSA2 StnDelivType= 2 Tail= .N334AA Fid= AA0011

<SOH>2.N334AA<NAK>40D<STX>FLT 0011 BOS-LAX SKD ARR 1059L<CR><LF>PLN 1055L<CR><LF>

OUT 1140 0764<CR><LF> OFF 1159 0756<CR><LF> GLYDE 1208 0729<CR><LF> CTR 1216 0691<CR><LF> HNK 1232 0660<CR><LF> ULW 1243 0641<CR><LF> JHW 1256 <ETB>

FLoc=281086566 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:14 DL MsgLen= 24 DBI= 3 DlIndicator= 1 DlNumStns= 1 BepStnName = MHTA2 SSV=56 (0x38) <SOH>2.N334AAD_<STX>S83AAA0011<ETX>

FLoc=281086621 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:14 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = PVDA2 SSV=51 (0x33) <SOH>2.N334AAD_<STX>S83AAA0011<ETX>

FLoc=281087393 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:14 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSB2 SSV=64 (0x40) <SOH>2.N334AAD_<STX>S83AAA0011<ETX>

FLoc=281104911 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:16 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA2 SSV=78 (0x4E) <SOH>2.N334AAD <STX>S83AAA0011<ETX>

FLoc=281146230 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:03:19 UL MsgLen= 235 Stn= BOSA2 StnDelivType= 1 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA<NAK>40E<STX> 0618<CR><LF> CXR 1311 0593<CR><LF> PIA 1408 0496<CR><LF> IRK 1427 0466<CR><LF> AGENT 1443 0440<CR><LF> SLN 1502 0410<CR><LF> **RYLIE 1531** 0364<CR><LF> LAA 1537 0355<CR><LF> ALS 1600 0320<CR><LF> FMN 1617 0294<CR><LF> TBC <ETB>

FLoc=281216559 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:23 DL MsgLen= 24 DBI= 4 DIIndicator= 1 DINumStns= 1 BepStnName = BOSA2 SSV=79 (0x4F) <SOH>2.N334AAE_<STX>S84AAA0011<ETX>

```
FLoc=281245895 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:03:26
UL MsgLen= 235 Stn= BOSA2 StnDelivType= 1
Tail= .N334AA Fid= AA0011
PGS 1657
HEC 1719
            0234<CR><LF>
            0201<CR><LF>
CIVET 1734 0189<CR><LF>
ON 1746 0179<CR><LF>
 IN 1755 0175<CR><LF>
          <CR><LF>
- FLT 0011 BOS-LAX SKD ARR 1059L<ETB>
FLoc=281290907 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:29
DL MsgLen= 24 DBI= 5 DlIndicator= 1 DlNumStns= 1
BepStnName = MHTA2 SSV=51 (0x33)
<SOH>2.N334AAF_<DEL><STX>S85AAA0011<ETX>
FLoc=281290962 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:29
DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1
BepStnName = PVDA2 SSV=50 (0x32)
<SOH>2.N334AAF_<DEL><STX>S85AAA0011<ETX>
FLoc=281291688 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:29
DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1
BepStnName = BOSB2 SSV=64 (0x40)
<SOH>2.N334AAF_<DEL><STX>S85AAA0011<ETX>
FLoc=281291858 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:29
DL MsgLen= 24 DBI= 5 DIIndicator= 2 DINumStns= 1
BepStnName = BDLA2 SSV=29 (0x1D)
<SOH>2.N334AAF_<DEL><STX>S85AAA0011<ETX>
FLoc=281311692 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:31
DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1
BepStnName = SWFA2 SSV=29 (0x1D)
<SOH>2.N334AAF_<DEL><STX>S85AAA0011<ETX>
FLoc=281315771 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:31
DL MsgLen= 24 DBI= 5 DIIndicator= 2 DINumStns= 1
BepStnName = BOSA2 SSV=76 (0x4C)
<SOH>2.N334AAF_<DEL><STX>S85AAA0011<ETX>
FLoc=281340441 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:03:34
UL MsgLen= 235 Stn= BOSA2 StnDelivType= 1
```

Tail= .N334AA Fid= AA0011

```
PLN 1055L<CR><LF>
 OUT 1140 0764<CR><LF>
 OFF 1159
           0756<CR><LF>
GLYDE 1208 0729<CR><LF>
CTR 1216
           0691<CR><LF>
HNK
ULW
     1232
            0660<CR><LF>
     1243
            0641<CR><LF>
JHW 1256
            0618<CR><LF>
CXR 1311
            0593<CR><LF>
<ETB>
FLoc=281375433 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:36
DL MsgLen= 24 DBI= 6 DlIndicator= 1 DlNumStns= 1
BepStnName = MHTA2 SSV=51 (0x33)
<SOH>2.N334AAG_<DEL><STX>S86AAA0011<ETX>
FLoc=281375488 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:36
DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1
BepStnName = PVDA2 SSV=51 (0x33)
<SOH>2.N334AAG_<DEL><STX>S86AAA0011<ETX>
FLoc=281376311 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:36
DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1
BepStnName = BOSB2 SSV=65 (0x41)
<SOH>2.N334AAG <DEL><STX>S86AAA0011<ETX>
FLoc=281376775 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:36
DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1
BepStnName = BDLA2 SSV=31 (0x1F)
<SOH>2.N334AAG_<DEL><STX>S86AAA0011<ETX>
FLoc=281404273 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:38
DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1
BepStnName = BOSA2 SSV=75 (0x4B)
<SOH>2.N334AAG_<DEL><STX>S86AAA0011<ETX>
FLoc=281431301 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:03:41
UL MsgLen= 235 Stn= BOSA2 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40H<STX>PIA 1408 0496<CR><LF>
IRK 1427
           0466<CR><LF>
AGENT 1443
             0440<CR><LF>
          0410<CR><LF>
SLN 1502
RYLIE 1531
           0364<CR><LF>
            0355<CR><LF>
LAA 1537
ALS
     1600
            0320<CR><LF>
FMN 1617
            0294<CR><LF>
           0259<CR><LF>
TBC
     1640
PGS
     1657 <ETB>
FLoc=281485328 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:45
DL MsgLen= 24 DBI= 7 DlIndicator= 1 DlNumStns= 1 BepStnName = PVDA2 SSV=51 (0x33)
<SOH>2.N334AAH_<DEL><STX>S87AAA0011<ETX>
```

<SOH>2.N334AA<NAK>40G<STX><CR><LF>

```
FLoc=281486105 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:45
DL MsgLen= 24 DBI= 7 DIIndicator= 2 DINumStns= 1
BepStnName = BDLA2 SSV=29 (0x1D)
<SOH>2.N334AAH_<DEL><STX>S87AAA0011<ETX>
FLoc=281486225 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:45
DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1
BepStnName = BOSB2 SSV=66 (0x42)
<SOH>2.N334AAH_<DEL><STX>S87AAA0011<ETX>
FLoc=281493589 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:46
DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1
BepStnName = SWFA2 SSV=30 (0x1E)
<SOH>2.N334AAH_<DEL><STX>S87AAA0011<ETX>
FLoc=281509062 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:03:47
DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1
BepStnName = BOSA2 SSV=74 (0x4A)
<SOH>2.N334AAH_<DEL><STX>S87AAA0011<ETX>
FLoc=281532142 AJPSBcnt= 189 ULBLK S=31 D=21 BEPts=20010911 12:03:50
UL MsgLen= 148 Stn= BOSA2 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40I<STX> 0234<CR><LF>
HEC 1719 0201<CR><LF>
CIVET 1734 0189<CR><LF>
ON 1746 0179<CR><LF>
IN 1755 0175<CR><LF>
           <CR><LF>
 <CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX>
FLoc=281650780 AJPSBcnt= 189 ULBLK S=31 D=21 BEPts=20010911 12:04:00
UL MsgLen= 148 Stn= BOSA2 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40I<STX> 0234<CR><LF>
HEC 1719 0201<CR><LF>
CIVET 1734 0189<CR><LF>
 ON 1746 0179<CR><LF>
 IN 1755
           0175<CR><LF>
           <CR><LF>
<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX>
FLoc=281678962 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:04:02
DL MsgLen= 24 DBI= 8 DlIndicator= 1 DlNumStns= 1
BepStnName = MHTA2 SSV=47 (0x2F)
<SOH>2.N334AAI_<DEL><STX>S88AAA0011<ETX>
```

FLoc=281679017 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:04:02 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = PVDA2 SSV=53 (0x35) <SOH>2.N334AAI <STX>S88AAA0011<ETX>

FLoc=281680188 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:04:02 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = BDLA2 SSV=31 (0x1F) <SOH>2.N334AAI_<STX>S88AAA0011<ETX>

FLoc=281680243 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:04:02 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSB2 SSV=64 (0x40) <SOH>2.N334AAI_<STX>S88AAA0011<ETX>

FLoc=281712122 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:04:04 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA2 SSV=76 (0x4C) <SOH>2.N334AAI_<STX>S88AAA0011<ETX>

FLoc=281782710 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:04:09 DL MsgLen= 24 DBI= 9 DlIndicator= 1 DlNumStns= 1 BepStnName = MHTA2 SSV=50 (0x32) <SOH>2.N334AAJ_<STX>S89AAA0011<ETX>

FLoc=281782765 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:04:09 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = PVDA2 SSV=54 (0x36) <SOH>2.N334AAJ_<STX>S89AAA0011<ETX>

FLoc=281783433 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:04:09 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = BDLA2 SSV=32 (0x20) <SOH>2.N334AAJ_<STX>S89AAA0011<ETX>

FLoc=281783695 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:04:09 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSB2 SSV=67 (0x43) <SOH>2.N334AAJ <STX>S89AAA0011<ETX>

FLoc=281803639 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:04:11 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSA2 SSV=76 (0x4C) <SOH>2.N334AAJ_<STX>S89AAA0011<ETX>

FLoc=284139025 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 12:07:30 DL MsgLen= 35 DBI= 0 DlIndicator= 1 DlNumStns= 1 BepStnName = PVDA2 SSV=46 (0x2E) <SOH>2.N334AA<NAK>5Z<STX>M90AAA0011OS LAX /M26<ETX>

FLoc=284139091 AJPSBcnt= 148 DLMSG S=31 D=21 BEPts=20010911 12:07:30 ADNS MsgLen= 108 Tail Number= .N334AA SMI= AGM FltId= AA0011 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA TULDDAA <CR><LF>
.DDLXCXA 111207 <CR><LF>
<STX>AGM<CR><LF>
FI AA11/AN N334AA <CR><LF>
DT DDL PVD 111207 M90A <CR><LF>
- OS LAX /M26 <CR><LF>
<ETX><ETX><ETX><EOT>

FLoc=284139239 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 12:07:30 DL MsgLen= 35 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = MHTA2 SSV=56 (0x38) <SOH>2.N334AA<NAK>5Z<STX>M90AAA0011OS LAX /M26<ETX>

FLoc=284139548 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 12:07:30 DL MsgLen= 35 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = JFKB2 SSV=35 (0x23) <SOH>2.N334AA<NAK>5Z<STX>M90AAA0011OS LAX /M26<ETX>

FLoc=284139614 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 12:07:30 DL MsgLen= 35 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = BDLA2 SSV=44 (0x2C) <SOH>2.N334AA<NAK>5Z<STX>M90AAA0011OS LAX /M26<ETX>

FLoc=284139741 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 12:07:30 DL MsgLen= 35 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSB2 SSV=65 (0x41) <SOH>2.N334AA<NAK>5Z<STX>M90AAA0011OS LAX /M26<ETX>

FLoc=284151553 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 12:07:31 DL MsgLen= 35 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = ISPA2 SSV=33 (0x21) <SOH>2.N334AA<NAK>5Z<STX>M90AAA0011OS LAX /M26<ETX>

FLoc=284153218 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 12:07:31 DL MsgLen= 35 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = SWFA2 SSV=44 (0x2C) <SOH>2.N334AA<NAK>5Z<STX>M90AAA0011OS LAX /M26<ETX>

FLoc=284154559 AJPSBcnt= 72 DLBLK S=31 D=21 BEPts=20010911 12:07:31 DL MsgLen= 35 DBI= 0 DlIndicator= 2 DlNumStns= 2 BepStnName = BOSA2 SSV=76 (0x4C)

BepStnName = LGAA2 SSV=47 (0x2F) <SOH>2.N334AA<NAK>5Z<STX>M90AAA0011OS LAX /M26<ETX>

FLoc=284194913 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:07:35 UL MsgLen= 14 Stn= BOSA2 StnDelivType= 2 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA0_K<ETX>

FLoc=284536991 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 12:08:05 DL MsgLen= 35 DBI= 0 DlIndicator= 3 DlNumStns= 1 BepStnName = PVDA2 SSV=54 (0x36) <SOH>2.N334AA<NAK>5Z<STX>M90AAA0011OS LAX /M26<ETX>

FLoc=284537580 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 12:08:05 DL MsgLen= 35 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = MHTA2 SSV=60 (0x3C) <SOH>2.N334AA<NAK>5Z<STX>M90AAA0011OS LAX /M26<ETX>

FLoc=284537646 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 12:08:05 DL MsgLen= 35 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = ALBA2 SSV=43 (0x2B) <SOH>2.N334AA<NAK>5Z<STX>M90AAA0011OS LAX /M26<ETX>

FLoc=284537773 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 12:08:05 DL MsgLen= 35 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = BDLA2 SSV=45 (0x2D) <SOH>2.N334AA<NAK>5Z<STX>M90AAA0011OS LAX /M26<ETX>

FLoc=284537839 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 12:08:05 DL MsgLen= 35 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = JFKB2 SSV=37 (0x25) <SOH>2.N334AA<NAK>5Z<STX>M90AAA0011OS LAX /M26<ETX>

FLoc=284537905 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 12:08:05 DL MsgLen= 35 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSB2 SSV=65 (0x41) <SOH>2.N334AA<NAK>5Z<STX>M90AAA0011OS LAX /M26<ETX>

FLoc=284550645 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 12:08:06 DL MsgLen= 35 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = SWFA2 SSV=46 (0x2E) <SOH>2.N334AA<NAK>5Z<STX>M90AAA0011OS LAX /M26<ETX>

FLoc=284552979 AJPSBcnt= 72 DLBLK S=31 D=21 BEPts=20010911 12:08:06 DL MsgLen= 35 DBI= 0 DlIndicator= 2 DlNumStns= 2 BepStnName = ISPA2 SSV=35 (0x23) BepStnName = HPNA2 SSV=34 (0x22) <SOH>2.N334AA<NAK>5Z<STX>M90AAA0011OS LAX /M26<ETX>

FLoc=284564296 AJPSBcnt= 72 DLBLK S=31 D=21 BEPts=20010911 12:08:07 DL MsgLen= 35 DBI= 0 DlIndicator= 2 DlNumStns= 2 BepStnName = BOSA2 SSV=75 (0x4B) BepStnName = LGAA2 SSV=48 (0x30) <SOH>2.N334AA<NAK>5Z<STX>M90AAA0011OS LAX /M26<ETX>

FLoc=284591764 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:08:10

UL MsgLen= 14 Stn= BOSA2 StnDelivType= 2 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA0 L<ETX>

FLoc=291277760 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:18:12 DL MsgLen= 24 DBI= 1 DlIndicator= 1 DlNumStns= 1 BepStnName = PVDA2 SSV=59 (0x3B) <SOH>2.N334AA<NAK>Q0<STX>S91AAA0011<ETX>

FLoc=291277815 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:18:12 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = MHTA2 SSV=56 (0x38) <SOH>2.N334AA<NAK>Q0<STX>S91AAA0011<ETX>

FLoc=291277925 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:18:12 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = ALBA2 SSV=63 (0x3F) <SOH>2.N334AA<NAK>Q0<STX>S91AAA0011<ETX>

FLoc=291278062 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:18:12 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = JFKB2 SSV=47 (0x2F) <SOH>2.N334AA<NAK>QO<STX>S91AAA0011<ETX>

FLoc=291278317 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:18:12 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = BDLA2 SSV=51 (0x33) <SOH>2.N334AA<NAK>Q0<STX>S91AAA0011<ETX>

FLoc=291278372 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:18:12 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSB2 SSV=58 (0x3A) <SOH>2.N334AA<NAK>QO<STX>S91AAA0011<ETX>

FLoc=291291212 AJPSBcnt= 67 DLBLK S=31 D=21 BEPts=20010911 12:18:13 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 3 BepStnName = SWFA2 SSV=50 (0x32) BepStnName = ACYA2 SSV=47 (0x2F) BepStnName = AVPA2 SSV=33 (0x21) <SOH>2.N334AA<NAK>Q0<STX>S91AAA0011<ETX>

FLoc=291292463 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:18:13 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 2 BepStnName = ISPA2 SSV=44 (0x2C) BepStnName = HPNA2 SSV=43 (0x2B) <SOH>2.N334AA<NAK>Q0<STX>S91AAA0011<ETX>

FLoc=291298976 AJPSBcnt= 67 DLBLK S=31 D=21 BEPts=20010911 12:18:14 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 3 BepStnName = BOSA2 SSV=68 (0x44) BepStnName = LGAA2 SSV=56 (0x38) BepStnName = EWRA2 SSV=43 (0x2B) <SOH>2.N334AA<NAK>QO<STX>S91AAA0011<ETX>

FLoc=291325115 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:18:17 UL MsgLen= 14 Stn= BOSA2 StnDelivType= 2

Tail= .N334AA Fid= AA0011 <SOH>2.N334AA1_M<ETX>

FLoc=291643162 AJPSBcnt= 66 ULBLK S=31 D=21 BEPts=20010911 12:18:51 UL MsgLen= 25 Stn= BOSA2 StnDelivType= 2 Tail= .N334AA Fid= AA0011
<SOH>2.AA0011<NAK>54N<STX>129400<CR><LF>
<CR><LF>
<ETX>

FLoc=291655154 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:18:52 DL MsgLen= 24 DBI= 2 DlIndicator= 1 DlNumStns= 1 BepStnName = PVDA2 SSV=60 (0x3C) <SOH>2.N334AANF3<STX>S92AAA0011<ETX>

FLoc=291655209 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:18:52 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = MHTA2 SSV=56 (0x38) <SOH>2.N334AANF3<STX>S92AAA0011<ETX>

FLoc=291655264 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:18:52 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = ALBA2 SSV=62 (0x3E) <SOH>2.N334AANF3<STX>S92AAA0011<ETX>

FLoc=291655319 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:18:52 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = ROCA2 SSV=42 (0x2A) <SOH>2.N334AANF3<STX>S92AAA0011<ETX>

FLoc=291655484 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:18:52 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = JFKB2 SSV=48 (0x30) <SOH>2.N334AANF3<STX>S92AAA0011<ETX>

FLoc=291655594 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:18:52 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = BDLA2 SSV=50 (0x32) <SOH>2.N334AANF3<STX>S92AAA0011<ETX>

FLoc=291655649 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:18:52 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1

BepStnName = BOSB2 SSV=58 (0x3A) <SOH>2.N334AANF3<STX>S92AAA0011<ETX>

FLoc=291669951 AJPSBcnt= 73 DLBLK S=31 D=21 BEPts=20010911 12:18:54

DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 4

BepStnName = YULA2 SSV=54 (0x36)

BepStnName = YULB2 SSV=54 (0x36)

BepStnName = ACYA2 SSV=49 (0x31) BepStnName = SWFA2 SSV=48 (0x30)

<SOH>2.N334AANF3<STX>S92AAA0011<ETX>

FLoc=291671022 AJPSBcnt= 67 DLBLK S=31 D=21 BEPts=20010911 12:18:54

DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 3

BepStnName = ISPA2 SSV=45 (0x2D)
BepStnName = HPNA2 SSV=44 (0x2C)
BepStnName = ABEA2 SSV=43 (0x2B)

<SOH>2.N334AANF3<STX>S92AAA0011<ETX>

FLoc=291671461 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:18:54

DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 2

BepStnName = BOSA2 SSV=67 (0x43) BepStnName = EWRA2 SSV=42 (0x2A)

<SOH>2.N334AANF3<STX>S92AAA0011<ETX>

FLoc=293213655 AJPSBcnt= 183 DLBLK S=31 D=21 BEPts=20010911 12:21:41

DL MsgLen= 152 DBI= 3 DIIndicator= 1 DINumStns= 1

BepStnName = MHTA2 SSV=50 (0x32)

<SOH>2.N334AA<NAK>H1<STX>D93AAA0000#DFBEDA/E138A,515,342,EEB,,<TSTRET>

5E25EC,619620,59058E,31E333,03D046,0900FD,1<CR><LF>

65174,0671E0,10011003,369,0E50E4,013,000,0,48F49E,0C1519<ETX>

FLoc=293213838 AJPSBcnt= 276 DLMSG S=31 D=21 BEPts=20010911 12:21:41

ADNS MsgLen= 236 Tail Number= .N334AA SMI= DFD

FitId= AA0000 AgyNum= 1 (0x0001)

<CR><LF>

<SOH>QU RURDLXA BDROOXA DCABFXA TULDDAA <CR><LF>

.DDLXCXA 111221<CR><LF>

<STX>DFD<CR><LF>

FI AA0/AN N334AA<CR><LF>

DT DDL MHT 111221 D93A<CR><LF>

EDA/E138A,515,342,EEB,,5E25EC,619620,59058E,31E333,03D046,0<TSTRET>

900FD.1<CR><LF>

65174,0671E0,10011003,369,0E50E4,013,000,0,48F49E,0C1519<CR><LF>

<ETX><EOT>

FLoc=293214114 AJPSBcnt= 183 DLBLK S=31 D=21 BEPts=20010911 12:21:41

DL MsgLen= 152 DBI= 3 DlIndicator= 2 DlNumStns= 1

BepStnName = ALBA2 SSV=70 (0x46)

<SOH>2.N334AA<NAK>H1<STX>D93AAA0000#DFBEDA/E138A,515,342,EEB,,<TSTRET>

5E25EC,619620,59058E,31E333,03D046.0900FD,1<CR><LF>

65174,0671E0,10011003,369,0E50E4,013,000,0,48F49E,0C1519<ETX>

FLoc=293214297 AJPSBcnt= 183 DLBLK S=31 D=21 BEPts=20010911 12:21:41 DL MsgLen= 152 DBI= 3 DlIndicator= 2 DlNumStns= 1

BepStnName = ROCA2 SSV=49 (0x31)

<SOH>2.N334AA<NAK>H1<STX>D93AAA0000#DFBEDA/E138A,515,342,EEB,,<TSTRET>

5E25EC,619620,59058E,31E333,03D046,0900FD,1<CR><LF>65174,0671E0,10011003,369,0E50E4,013,000,0,48F49E,0C1519<ETX>

FLoc=293214793 AJPSBcnt= 183 DLBLK S=31 D=21 BEPts=20010911 12:21:41 DL MsgLen= 152 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = JFKB2 SSV=49 (0x31) <SOH>2.N334AA<NAK>H1<STX>D93AAA0000#DFBEDA/E138A,515,342,EEB,,<TSTRET> 5E25EC,619620,59058E,31E333,03D046,0900FD,1<CR><LF>65174,0671E0,10011003,369,0E50E4,013,000,0,48F49E,0C1519<ETX>

FLoc=293215159 AJPSBcnt= 183 DLBLK S=31 D=21 BEPts=20010911 12:21:41 DL MsgLen= 152 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSB2 SSV=56 (0x38)
<SOH>2.N334AA<NAK>H1<STX>D93AAA0000#DFBEDA/E138A,515,342,EEB,,<TSTRET> 5E25EC,619620,59058E,31E333,03D046,0900FD,1<CR><LF>65174,0671E0,10011003,369,0E50E4,013,000,0,48F49E,0C1519<ETX>

FLoc=293220058 AJPSBcnt= 195 DLBLK S=31 D=21 BEPts=20010911 12:21:42 DL MsgLen= 152 DBI= 3 DlIndicator= 2 DlNumStns= 3 BepStnName = SYRA2 SSV=59 (0x3B) BepStnName = ACYA2 SSV=46 (0x2E) BepStnName = AVPA2 SSV=34 (0x22) <SOH>2.N334AA<NAK>H1<STX>D93AAA0000#DFBEDA/E138A,515,342,EEB,,<TSTRET> 5E25EC,619620,59058E,31E333,03D046,0900FD,1<CR><LF>65174,0671E0,10011003,369,0E50E4,013,000,0,48F49E,0C1519<ETX>

FLoc=293229164 AJPSBcnt= 183 DLBLK S=31 D=21 BEPts=20010911 12:21:43 DL MsgLen= 152 DBI= 3 DlIndicator= 2 DINumStns= 1 BepStnName = BOSA2 SSV=68 (0x44) <SOH>>2.N334AA<NAK>H1<STX>D93AAA0000#DFBEDA/E138A,515,342,EEB,,<TSTRET> 5E25EC,619620,59058E,31E333,03D046,0900FD,1<CR>><LF>65174,0671E0,10011003,369,0E50E4,013,000,0,48F49E,0C1519<ETX>

FLoc=293233796 AJPSBcnt= 189 DLBLK S=31 D=21 BEPts=20010911 12:21:43 DL MsgLen= 152 DBI= 3 DlIndicator= 2 DlNumStns= 2 BepStnName = ISPA2 SSV=44 (0x2C) BepStnName = ABEA2 SSV=42 (0x2A) <SOH>2.N334AA<NAK>H1<STX>D93AAA0000#DFBEDA/E138A,515,342,EEB,,<TSTRET> 5E25EC,619620,59058E,31E333,03D046,0900FD,1<CR><LF>65174,0671E0,10011003,369,0E50E4,013,000,0,48F49E,0C1519<ETX>

FLoc=293255474 AJPSBcnt= 62 ULBLK S=31 D=21 BEPts=20010911 12:21:45 UL MsgLen= 21 Stn= ALBA2 StnDelivType= 2 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA3:;O<STX>136800<ETX>

FLoc=293262130 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:21:45 DL MsgLen= 24 DBI= 4 DIIndicator= 1 DINumStns= 1 BepStnName = PHLC2 SSV=45 (0x2D)

FLoc=293262397 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:21:45 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = MHTA2 SSV=51 (0x33) <SOH>2.N334AAO <STX>S94AAA0011<ETX>

FLoc=293262452 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:21:45 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = PVDA2 SSV=58 (0x3A) <SOH>2.N334AAO <STX>S94AAA0011<ETX>

FLoc=293262562 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:21:45 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = ALBA2 SSV=70 (0x46) <SOH>2.N334AAO_<STX>S94AAA0011<ETX>

FLoc=293262617 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:21:45 DL MsgLen= 24 DBI= 4 DIIndicator= 2 DINumStns= 1 BepStnName = ROCA2 SSV=48 (0x30) <SOH>2.N334AAO_<STX>S94AAA0011<ETX>

FLoc=293262961 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:21:45 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = JFKB2 SSV=49 (0x31) <SOH>2.N334AAO_<STX>S94AAA0011<ETX>

FLoc=293263016 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:21:45 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = BDLA2 SSV=46 (0x2E) <SOH>2.N334AAO_<STX>S94AAA0011<ETX>

FLoc=293263329 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:21:45 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = BOSB2 SSV=56 (0x38) <SOH>2.N334AAO_<STX>S94AAA0011<ETX>

FLoc=293268692 AJPSBcnt= 73 DLBLK S=31 D=21 BEPts=20010911 12:21:46 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 4 BepStnName = YULA2 SSV=53 (0x35) BepStnName = SWFA2 SSV=47 (0x2F) BepStnName = ACYA2 SSV=47 (0x2F) BepStnName = AVPA2 SSV=36 (0x24) <SOH>2.N334AAO_<STX>S94AAA0011<ETX>

FLoc=293276755 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:21:47 DL MsgLen= 24 DBI= 4 DIIndicator= 2 DINumStns= 2 BepStnName = ISPA2 SSV=44 (0x2C) BepStnName = ABEA2 SSV=41 (0x29) <SOH>2.N334AAO <STX>S94AAA0011<ETX>

FLoc=293276871 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:21:47 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 2 BepStnName = BOSA2 SSV=67 (0x43) BepStnName = PHLA2 SSV=49 (0x31) <SOH>2.N334AAO_<STX>S94AAA0011<ETX>

FLoc=293298406 AJPSBcnt= 71 DLBLK S=31 D=21 BEPts=20010911 12:21:50 DL MsgLen= 40 DBI= 5 DlIndicator= 1 DlNumStns= 1 BepStnName = SYRA6 SSV=59 (0x3B) <SOH>2.N334AA<NAK>10<STX>M95AAA0011OS LAX /FQY36800<ETX>

FLoc=293298477 AJPSBcnt= 153 DLMSG S=31 D=21 BEPts=20010911 12:21:50 ADNS MsgLen= 113 Tail Number= .N334AA SMI= M10 FltId= AA0011 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA TULDDAA <CR><LF>
.DDLXCXA 111221<CR><LF>
<STX>M10<CR><LF>
FI AA11/AN N334AA<CR><LF>
DT DDL SYR 111221 M95A<CR><LF>
- OS LAX /FQY36800<CR><LF>
<ETX><EOT>

FLoc=293309495 AJPSBcnt= 71 DLBLK S=31 D=21 BEPts=20010911 12:21:51 DL MsgLen= 40 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = LGAA6 SSV=55 (0x37) <SOH>2.N334AA<NAK>10<STX>M95AAA0011OS LAX /FQY36800<ETX>

FLoc=293322054 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:21:53 UL MsgLen= 14 Stn= SYRA6 StnDelivType= 2 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA5_P<ETX>

FLoc=294350402 AJPSBcnt= 230 ULMSG S=31 D=21 BEPts=20010911 12:23:36 ADNS MsgLen= 173 Org Addr= TULDDAA Org TimeStamp= 20010911 12:23:00 Smi= M40 AgyNum= 65535 Tail Number= .N334AA FltId= AA0011 Target Stn= ALB<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111223 FROM FD23 <CR><LF> <STX>M40<CR><LF> AN N334AA/GL ALB<CR><LF> --/<CR><LF> GOOD MORNING...ATC LOOKING<CR><LF> FOR YOU ON 135.32<CR><LF> FD23/PEGGY<CR><LF> PLZ ACK MSG NO. 2337<CR><LF> END<CR><LF> <LF> <CR><LF>

<LF>

<ETX><EOT>

FLoc=294350632 AJPSBcnt= 153 ULBLK S=31 D=21 BEPts=20010911 12:23:36 UL MsgLen= 112 Stn= SYRA6 StnDelivType= 2 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA<NAK>40Q<STX>- /<CR><LF> GOOD MORNING...ATC LOOKING<CR><LF> FOR YOU ON 135.32<CR><LF>

```
FD23/PEGGY<CR><LF>
PLZ ACK MSG NO. 2337<CR><LF>
END<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX>
FLoc=294449635 AJPSBcnt= 153 ULBLK S=31 D=21 BEPts=20010911 12:23:46
UL MsgLen= 112 Stn= SYRA6 StnDelivType= 2
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40Q<STX>-/<CR><LF>
GOOD MORNING...ATC LOOKING<CR><LF>
FOR YOU ON 135.32<CR><LF>
FD23/PEGGY<CR><LF>
PLZ ACK MSG NO. 2337<CR><LF>
END<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX>
FLoc=294513726 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:23:54
DL MsgLen= 24 DBI= 6 DIIndicator= 1 DINumStns= 1
BepStnName = LGAC6 SSV=60 (0x3C)
<SOH>2.N334AAQ_<DEL><STX>S96AAA0011<ETX>
FLoc=294521552 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:23:55
DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1
BepStnName = SYRA6 SSV=61 (0x3D)
<SOH>2.N334AAQ <DEL><STX>S96AAA0011<ETX>
FLoc=294530684 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:23:56
DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1
BepStnName = LGAA6 SSV=58 (0x3A)
<SOH>2.N334AAQ_<DEL><STX>S96AAA0011<ETX>
FLoc=295272214 AJPSBcnt= 272 ULMSG S=31 D=21 BEPts=20010911 12:25:11
ADNS MsgLen= 215 Org Addr= TULDDAA Org TimeStamp= 20010911 12:25:00
Smi= M40 AgyNum= 65535
Tail Number= .N334AA FltId= AA0011
Target Stn= ALB<00><00> Target Method= 2
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111225 FROM EQP5
                              <CR><LF>
<STX>M40<CR><LF>
AN N334AA/GL ALB<CR><LF>
- <CR><LF>
PLZ CONTACT BOS CTR ASAP...<CR><LF>
```

THEY HAVE LOST RADIO CONTACT AND YOUR TRANSPONDER SIGNAL<CR><LF>

FTWDP BOBMARINO<CR><LF>PLZ ACK MSG NO. 2511<CR><LF>

END<CR><LF>

<LF>

```
<CR><LF>
<LF>
<LF>
<ETX><EOT>
FLoc=295272486 AJPSBcnt= 195 ULBLK S=31 D=21 BEPts=20010911 12:25:11
UL MsgLen= 154 Stn= SYRA6 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40R<STX><CR><LF>
PLZ CONTACT BOS CTR ASAP...<CR><LF>
THEY HAVE LOST RADIO CONTACT AND YOUR TRANSPONDER SIGNAL<CR><LF>
FTWDP BOBMARINO<CR><LF>
PLZ ACK MSG NO. 2511<CR><LF>
END<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX>
FLoc=295297922 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:14
DL MsgLen= 24 DBI= 7 DlIndicator= 1 DlNumStns= 1
BepStnName = LGAC6 SSV=60 (0x3C)
<SOH>2.N334AAR <DEL><STX>S97AAA0011<ETX>
FLoc=295309905 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:15
DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1
BepStnName = SYRA6 SSV=61 (0x3D)
<SOH>2.N334AAR <DEL><STX>S97AAA0011<ETX>
FLoc=295323352 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:16
DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1
BepStnName = LGAA6 SSV=55 (0x37)
<SOH>2.N334AAR_<DEL><STX>S97AAA0011<ETX>
FLoc=299192994 AJPSBcnt= 154 ULMSG S=31 D=21 BEPts=20010911 12:31:49
ADNS MsgLen= 97 Org Addr= TULDDAA Org TimeStamp= 20010911 12:31:00
Smi= DFD AgyNum= 65535
Tail Number= .N334AA FltId= AA0011
Target Stn= ALB<00><00> Target Method= 2
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111231 FROM FD23
                             <CR><LF>
<STX>DFD<CR><LF>
AN N334AA/GL ALB<CR><LF>
- XRP 151 0<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<EOT> 535<ETX><EOT>
FLoc=299193148 AJPSBcnt= 137 ULBLK S=31 D=21 BEPts=20010911 12:31:49
UL MsgLen= 96 Stn= SYRA6 StnDelivType= 2
```

Tail= .N334AA Fid= AA0011

<SOH>2.N334AA<NAK>H1S<STX>.TULDDAA 111231 FROM FD23

<CR><LF>

FLoc=299215401 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:31:51 DL MsgLen= 24 DBI= 8 DlIndicator= 1 DlNumStns= 1 BepStnName = LGAC6 SSV=62 (0x3E) <SOH>2.N334AAS_<STX>S98AAA0011<ETX>

FLoc=299222843 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:31:52 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = SYRA6 SSV=60 (0x3C) <SOH>2.N334AAS_<STX>S98AAA0011<ETX>

FLoc=299237127 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:31:53 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 2 BepStnName = LGAA6 SSV=52 (0x34) BepStnName = BWIA6 SSV=48 (0x30) <SOH>2.N334AAS <STX>S98AAA0011<ETX>

FLoc=300288198 AJPSBcnt= 141 ULMSG S=31 D=21 BEPts=20010911 12:33:50 ADNS MsgLen= 84 Org Addr= SFOXGXA Org TimeStamp= 20010911 12:33:00 Smi= GVR AgyNum= 1 Tail Number= .N334AA FltId= AA0011 Target Stn= BOS<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .SFOXGXA 111233<CR><LF> <STX>GVR<CR><LF> FI AA11/GL BOS<CR><LF> - 129400<CR><LF> CONTACT SFOXA<CR><LF> <CR><LF> <CR><LF> <CR><LF> <CR><LF> <CR><LF> <CR><LF> <CR><LF> <CONTACT SFOXA<CR><LF> <CR><LF> <CR><CR><LF> <CR><CR><LF> <CR><CR><CR><CR><CF> <CR><CF> <CR><CF> <CR><CF> <CR><CF> <CR><CF> <CTX><CETX><CETX><CETX><CETX><CETX><CETX><CETX><CETX><CETX <CETX <C

FLoc=300288339 AJPSBcnt= 81 ULBLK S=31 D=21 BEPts=20010911 12:33:50 UL MsgLen= 40 Stn= LGAC6 StnDelivType= 2 Tail= .N334AA Fid= AA0011
<SOH>2.AA0011<NAK>54T<STX>129400<CR><LF> CONTACT SFOXA<CR><LF> <CR><LF> <ETX>

FLoc=300371621 AJPSBcnt= 81 ULBLK S=31 D=21 BEPts=20010911 12:34:00 UL MsgLen= 40 Stn= LGAC6 StnDelivType= 2 Tail= .N334AA Fid= AA0011
<SOH>2.AA0011<NAK>54T<STX>129400<CR><LF> CONTACT SFOXA<CR><LF> <CR><LF> <ETX>

FLoc=300378382 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:34:00 DL MsgLen= 24 DBI= 9 DIIndicator= 1 DINumStns= 1 BepStnName = LGAC6 SSV=62 (0x3E) <SOH>2.N334AATF3<STX>S99AAA0011<ETX>

FLoc=300398343 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:34:02 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 2 BepStnName = LGAA6 SSV=56 (0x38) BepStnName = BWIA6 SSV=51 (0x33) <SOH>2.N334AATF3<STX>S99AAA0011<ETX>

FLoc=300403826 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:34:03 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = SYRA6 SSV=60 (0x3C) <SOH>2.N334AATF3<STX>S99AAA0011<ETX>

FLoc=302176045 AJPSBcnt= 154 ULMSG S=31 D=21 BEPts=20010911 12:36:49 ADNS MsgLen= 97 Org Addr= TULDDAA Org TimeStamp= 20010911 12:36:00 Smi= DFD AgyNum= 65535 Tail Number= .N334AA FltId= AA0011 Target Stn= ALB<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111236 FROM EQP6 <CR><LF> <STX>DFD<CR><LF> AN N334AA/GL ALB<CR><LF> - XRP 151 0<CR><LF> <| F> <CR><LF> <LF> <LF> <EOT> 840<ETX><EOT>

FLoc=302192890 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:36:51 DL MsgLen= 24 DBI= 0 DlIndicator= 1 DlNumStns= 1 BepStnName = LGAC6 SSV=76 (0x4C) <SOH>2.N334AAU_<STX>S01AAA0011<ETX>

FLoc=302203632 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:36:52 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = SYRA6 SSV=54 (0x36) <SOH>2.N334AAU_<STX>S01AAA0011<ETX> FLoc=302223060 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:36:53 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 2 BepStnName = LGAA6 SSV=56 (0x38) BepStnName = BWIA6 SSV=52 (0x34) <SOH>2.N334AAU_<STX>S01AAA0011<ETX>

FLoc=302973356 AJPSBcnt= 154 ULMSG S=31 D=21 BEPts=20010911 12:38:00 ADNS MsgLen= 97 Org Addr= TULDDAA Org TimeStamp= 20010911 12:37:00 Smi= DFD AgyNum= 65535 Tail Number= .N334AA FltId= AA0011 Target Stn= ALB<00><00> Target Method= 2 <CR>><LF> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111237 FROM FD21 <CR><LF> <STX>DFD<CR><LF> AN N334AA/GL ALB<CR><LF> - XRP 151 0<CR><LF> <| F> <CR><LF> <LF> <LF> <EOT> 895<ETX><EOT>

FLoc=302991848 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:38:01 DL MsgLen= 24 DBI= 1 DlIndicator= 1 DlNumStns= 1 BepStnName = LGAC6 SSV=77 (0x4D) <SOH>2.N334AAV_<STX>S02AAA0011<ETX>

FLoc=303018297 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:38:03 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = SYRA6 SSV=54 (0x36) <SOH>2.N334AAV <STX>S02AAA0011<ETX>

FLoc=303025576 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:38:03 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = LGAA6 SSV=58 (0x3A) <SOH>2.N334AAV_<STX>S02AAA0011<ETX>

FLoc=303510131 AJPSBcnt= 251 ULMSG S=31 D=21 BEPts=20010911 12:38:50 ADNS MsgLen= 194 Org Addr= TULDDAA Org TimeStamp= 20010911 12:38:00 Smi= M40 AgyNum= 65535 Tail Number= .N334AA FltId= AA0011 Target Stn= BUF<00><00> Target Method= 2

```
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111238 FROM FD19
                             <CR><LF>
<STX>M40<CR><LF>
AN N334AA/GL BUF<CR><LF>
--/<CR><LF>
HALLO AND GOOD MORNING <CR><LF>
ATC RQST YR PRESENCE ON FREQ 123.87<CR><LF>
HV A GRAND DAY......XOX- MISTY ATWELL<CR><LF>
END<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX><EOT>
FLoc=303510382 AJPSBcnt= 174 ULBLK S=31 D=21 BEPts=20010911 12:38:50
UL MsgLen= 133 Stn= LGAC6 StnDelivType= 1
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40W<STX>-/<CR><LF>
HALLO AND GOOD MORNING <CR><LF>
ATC RQST YR PRESENCE ON FREQ 123.87<CR><LF>
HV A GRAND DAY......XOX- MISTY ATWELL<CR><LF>
END<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX>
FLoc=303537498 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:38:53
DL MsgLen= 24 DBI= 2 DlIndicator= 1 DlNumStns= 1
BepStnName = SYRA6 SSV=52 (0x34)
<SOH>2.N334AAW_<DEL><STX>S03AAA0011<ETX>
FLoc=303546267 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:38:54
DL MsgLen= 24 DBI= 2 DIIndicator= 2 DINumStns= 1
BepStnName = BWIA6 SSV=51 (0x33)
<SOH>2.N334AAW_<DEL><STX>S03AAA0011<ETX>
FLoc=306005326 AJPSBcnt= 154 ULMSG S=31 D=21 BEPts=20010911 12:42:53
ADNS MsgLen= 97 Org Addr= TULDDAA Org TimeStamp= 20010911 12:42:00
Smi= DFD AgyNum= 65535
Tail Number= .N334AA FltId= AA0011
Target Stn= BUF<00><00> Target Method= 2
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111242 FROM FD04
                            <CR><LF>
<STX>DFD<CR><LF>
AN N334AA/GL BUF<CR><LF>
- XRP 151 0<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<EOT> 233<ETX><EOT>
```

FLoc=306005480 AJPSBcnt= 137 ULBLK S=31 D=21 BEPts=20010911 12:42:53 UL MsgLen= 96 Stn= LGAC6 StnDelivType= 2 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA<NAK>H1X<STX>.TULDDAA 111242 FROM FD04 CR><LF> DFD<CR><LF> AN N334AA/GL BUF<CR><LF> - #DFXRP 151 0<CR><LF> <LF> <CR><LF> <LF> <LF> 233<ETX> FLoc=306099388 AJPSBcnt= 137 ULBLK S=31 D=21 BEPts=20010911 12:43:03 UL MsgLen= 96 Stn= LGAC6 StnDelivType= 2 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA<NAK>H1X<STX>.TULDDAA 111242 FROM FD04 CR><LF> DFD<CR><LF> AN N334AA/GL BUF<CR><LF> - #DFXRP 151 0<CR><LF> <LF> <CR><LF> <LF> <LF> 233<ETX> FLoc=306121165 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:43:05 DL MsgLen= 24 DBI= 3 DlIndicator= 1 DlNumStns= 1 BepStnName = LGAC6 SSV=86 (0x56) <SOH>2.N334AAXQ5<STX>S04AAA0011<ETX> FLoc=306146474 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:43:07 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = LGAA6 SSV=70 (0x46) <SOH>2.N334AAXQ5<STX>S04AAA0011<ETX>

FLoc=306359285 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:43:28 DL MsgLen= 24 DBI= 4 DlIndicator= 1 DlNumStns= 1 BepStnName = LGAC6 SSV=86 (0x56) <SOH>2.N334AAY_<STX>S05AAA0011<ETX>

FLoc=306390972 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:43:31

DL MsgLen= 24 DBI= 4 DIIndicator= 2 DINumStns= 1 BepStnName = LGAA6 SSV=71 (0x47) <SOH>2.N334AAY_<STX>S05AAA0011<ETX> FLoc=308836862 AJPSBcnt= 154 ULMSG S=31 D=21 BEPts=20010911 12:47:32 ADNS MsgLen= 97 Org Addr= TULDDAA Org TimeStamp= 20010911 12:47:00 Smi= DFD AgyNum= 65535 Tail Number= .N334AA FltId= AA0011 Target Stn= BUF<00><00> Target Method= 2 <CR>><LF> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111247 FROM 2SEC <CR><LF> <STX>DFD<CR><LF> AN N334AA/GL BUF<CR><LF> - XRP 151 0<CR><LF> <LF> <CR><LF> <| F> <LF> <EOT> 528<ETX><EOT> FLoc=308837016 AJPSBcnt= 137 ULBLK S=31 D=21 BEPts=20010911 12:47:32 UL MsgLen= 96 Stn= LGAC6 StnDelivType= 2 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA<NAK>H1Z<STX>.TULDDAA 111247 FROM 2SEC CR><LF> DFD<CR><LF> AN N334AA/GL BUF<CR><LF> - #DFXRP 151 0<CR><LF> <LF> <CR><LF> <| F> <LF> 528<ETX> FLoc=308926577 AJPSBcnt= 137 ULBLK S=31 D=21 BEPts=20010911 12:47:42 UL MsgLen= 96 Stn= LGAC6 StnDelivType= 2 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA<NAK>H1Z<STX>.TULDDAA 111247 FROM 2SEC CR><LF> DFD<CR><LF> AN N334AA/GL BUF<CR><LF> - #DFXRP 151 0<CR><LF> <LF> <CR><LF> <| F> <LF> 528<ETX> FLoc=309032362 AJPSBcnt= 137 ULBLK S=31 D=21 BEPts=20010911 12:47:52 UL MsgLen= 96 Stn= LGAC6 StnDelivType= 2 Tail= .N334AA Fid= AA0011 <SOH>2.N334AA<NAK>H1Z<STX>.TULDDAA 111247 FROM 2SEC CR><LF> DFD<CR><LF> AN N334AA/GL BUF<CR><LF> - #DFXRP 151 0<CR><LF>

<LF>
<CR><LF>

```
<LF>
<| F>
528<ETX>
FLoc=309124458 AJPSBcnt= 137 ULBLK S=31 D=21 BEPts=20010911 12:48:02
UL MsgLen= 96 Stn= LGAC6 StnDelivType= 2
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>H1Z<STX>.TULDDAA 111247 FROM 2SEC
                                                         <CR><LF>
DFD<CR><LF>
AN N334AA/GL BUF<CR><LF>
- #DFXRP 151 0<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
528<ETX>
FLoc=309211851 AJPSBcnt= 137 ULBLK S=31 D=21 BEPts=20010911 12:48:12
UL MsgLen= 96 Stn= LGAC6 StnDelivType= 2
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>H1Z<STX>.TULDDAA 111247 FROM 2SEC
                                                        <CR><LF>
DFD<CR><LF>
AN N334AA/GL BUF<CR><LF>
- #DFXRP 151 0<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
528<ETX>
FLoc=309288079 AJPSBcnt= 137 ULBLK S=31 D=21 BEPts=20010911 12:48:22
UL MsgLen= 96 Stn= LGAC6 StnDelivType= 2
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>H1Z<STX>.TULDDAA 111247 FROM 2SEC
                                                          <CR><LF>
DFD<CR><LF>
AN N334AA/GL BUF<CR><LF>
- #DFXRP 151 0<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
528<ETX>
FLoc=309380087 AJPSBcnt= 137 ULBLK S=31 D=21 BEPts=20010911 12:48:32
UL MsgLen= 96 Stn= LGAA6 StnDelivType= 3
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>H1Z<STX>.TULDDAA 111247 FROM 2SEC
                                                          <CR><LF>
DFD<CR><LF>
AN N334AA/GL BUF<CR><LF>
- #DFXRP 151 0<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
```

528<ETX>

```
FLoc=309456979 AJPSBcnt= 137 ULBLK S=31 D=21 BEPts=20010911 12:48:42
UL MsgLen= 96 Stn= LGAA6 StnDelivType= 3
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>H1Z<STX>.TULDDAA 111247 FROM 2SEC CR><LF>
DFD<CR><LF>
AN N334AA/GL BUF<CR><LF>
- #DFXRP 151 0<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
528<ETX>
FLoc=309462153 AJPSBcnt= 224 ULMSG S=31 D=21 BEPts=20010911 12:48:42
ADNS MsgLen= 167 Org Addr= TULDDAA Org TimeStamp= 20010911 12:48:00
Smi= M40 AgyNum= 65535
Tail Number= .N334AA FltId= AA0011
Target Stn= BUF<00><00> Target Method= 2
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111248 FROM FD04
                            <CR><LF>
<STX>M40<CR><LF>
AN N334AA/GL BUF<CR><LF>
- /<CR><LF>
GOOD MORNING...BOS CTR<CR><LF>
LOOKING FOR YOU. FD04/PEGGY<CR><LF>
PLZ ACK MSG NO. 4821<CR><LF>
END<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX><EOT>
FLoc=309550329 AJPSBcnt= 137 ULBLK S=31 D=21 BEPts=20010911 12:48:52
UL MsgLen= 96 Stn= LGAA6 StnDelivType= 3
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>H1Z<STX>.TULDDAA 111247 FROM 2SEC CR><LF>
DFD<CR><LF>
AN N334AA/GL BUF<CR><LF>
- #DFXRP 151 0<CR><LF>
<LF>
<CR><LF>
<| F>
<LF>
528<ETX>
FLoc=309653842 AJPSBcnt= 147 ULBLK S=31 D=21 BEPts=20010911 12:49:02
UL MsgLen= 106 Stn= LGAC6 StnDelivType= 2
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40A<STX>-/<CR><LF>
GOOD MORNING...BOS CTR<CR><LF>
LOOKING FOR YOU. FD04/PEGGY<CR><LF>
PLZ ACK MSG NO. 4821<CR><LF>
END<CR><LF>
<LF>
```

```
<CR><LF>
<LF>
<LF>
<ETX>
FLoc=309654084 AJPSBcnt= 229 ICPUL S=31 D=21 BEPts=20010911 12:49:02
Intercept MsgLen=97 Addressee= .N334AA Num MediaTypes=1
Blk Num=1 UI Code=0
***IcpHdr: Reason Code= 311 AgyNum= 65535
***IcpHdr: Tail Number= .N334AA
***IcpHdr: FltId= <FF><00><00><00><00>
Dumping Media type #1 of 1
  Media Type = 0 Num Stns= 2 Num History= 9
  Stn Score Card # 1 of 2; EntryType= 2 (0x0002) Stn= LGAC6
 Stn Score Card # 2 of 2; EntryType= 3 (0x0003) Stn= LGAA6
History Card # 1 of 9; Reason= 311 (0x0137) Stn= LGAC6
  History Card # 2 of 9; Reason= 311 (0x0137) Stn= LGAC6
 History Card # 3 of 9; Reason= 311 (0x0137) Stn= LGAC6
History Card # 4 of 9; Reason= 311 (0x0137) Stn= LGAC6
  History Card # 5 of 9; Reason= 311 (0x0137) Stn= LGAC6
  History Card # 6 of 9; Reason= 311 (0x0137) Stn= LGAC6
 History Card # 7 of 9; Reason= 311 (0x0137) Stn= LGAA6
History Card # 8 of 9; Reason= 311 (0x0137) Stn= LGAA6
 History Card # 9 of 9; Reason= 311 (0x0137) Stn= LGAA6
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111247 FROM 2SEC
                                  <CR><LF>
<STX>DFD<CR><LF>
AN N334AA/GL BUF<CR><LF>
- XRP 151 0<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<EOT> 528<ETX><EOT>
FLoc=309758948 AJPSBcnt= 147 ULBLK S=31 D=21 BEPts=20010911 12:49:12
UL MsgLen= 106 Stn= LGAC6 StnDelivType= 2
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40A<STX>-/<CR><LF>
GOOD MORNING...BOS CTR<CR><LF>
LOOKING FOR YOU. FD04/PEGGY<CR><LF>
PLZ ACK MSG NO. 4821<CR><LF>
END<CR><LF>
<I F>
<CR><LF>
<LF>
<| F>
<ETX>
FLoc=309874903 AJPSBcnt= 147 ULBLK S=31 D=21 BEPts=20010911 12:49:22
```

UL MsgLen= 106 Stn= LGAC6 StnDelivType= 2

```
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40A<STX>-/<CR><LF>
GOOD MORNING...BOS CTR<CR><LF>
LOOKING FOR YOU. FD04/PEGGY<CR><LF>
PLZ ACK MSG NO. 4821<CR><LF>
END<CR><LF>
<| F>
<CR><LF>
<LF>
<LF>
<ETX>
FLoc=309966407 AJPSBcnt= 147 ULBLK S=31 D=21 BEPts=20010911 12:49:32
UL MsgLen= 106 Stn= LGAC6 StnDelivType= 2
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40A<STX>-/<CR><LF>
GOOD MORNING...BOS CTR<CR><LF>
LOOKING FOR YOU. FD04/PEGGY<CR><LF>
PLZ ACK MSG NO. 4821<CR><LF>
END<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX>
FLoc=310065784 AJPSBcnt= 147 ULBLK S=31 D=21 BEPts=20010911 12:49:42
UL MsgLen= 106 Stn= LGAC6 StnDelivType= 2
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40A<STX>-/<CR><LF>
GOOD MORNING...BOS CTR<CR><LF>
LOOKING FOR YOU. FD04/PEGGY<CR><LF>
PLZ ACK MSG NO. 4821<CR><LF>
END<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX>
FLoc=310167937 AJPSBcnt= 147 ULBLK S=31 D=21 BEPts=20010911 12:49:52
UL MsgLen= 106 Stn= LGAC6 StnDelivType= 2
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40A<STX>-/<CR><LF>
GOOD MORNING...BOS CTR<CR><LF>
LOOKING FOR YOU. FD04/PEGGY<CR><LF>
PLZ ACK MSG NO. 4821<CR><LF>
END<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
FLoc=310261392 AJPSBcnt= 147 ULBLK S=31 D=21 BEPts=20010911 12:50:02
```

UL MsgLen= 106 Stn= LGAA6 StnDelivType= 3

```
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40A<STX>-/<CR><LF>
GOOD MORNING...BOS CTR<CR><LF>
LOOKING FOR YOU. FD04/PEGGY<CR><LF>
PLZ ACK MSG NO. 4821<CR><LF>
END<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX>
FLoc=310362825 AJPSBcnt= 147 ULBLK S=31 D=21 BEPts=20010911 12:50:12
UL MsgLen= 106 Stn= LGAA6 StnDelivType= 3
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40A<STX>-/<CR><LF>
GOOD MORNING...BOS CTR<CR><LF>
LOOKING FOR YOU. FD04/PEGGY<CR><LF>
PLZ ACK MSG NO. 4821<CR><LF>
END<CR><LF>
<LF>
<CR><LF>
<| F>
<LF>
<ETX>
FLoc=310477028 AJPSBcnt= 147 ULBLK S=31 D=21 BEPts=20010911 12:50:22
UL MsgLen= 106 Stn= LGAA6 StnDelivType= 3
Tail= .N334AA Fid= AA0011
<SOH>2.N334AA<NAK>40A<STX>-/<CR><LF>
GOOD MORNING...BOS CTR<CR><LF>
LOOKING FOR YOU. FD04/PEGGY<CR><LF>
PLZ ACK MSG NO. 4821<CR><LF>
END<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX>
FLoc=310575483 AJPSBcnt= 299 ICPUL S=31 D=21 BEPts=20010911 12:50:32
Intercept MsgLen=167 Addressee= .N334AA Num MediaTypes=1
Blk Num=1 UI Code=0
***IcpHdr: Reason Code= 311 AgyNum= 65535
***IcpHdr: Tail Number= .N334AA
***IcpHdr: FltId= <FF><00><00><00><00>
Dumping Media type #1 of 1
 Media Type = 0 Num Stns= 2 Num History= 9
 Stn Score Card # 1 of 2; EntryType= 2 (0x0002) Stn= LGAC6
Stn Score Card # 2 of 2; EntryType= 3 (0x0003) Stn= LGAA6
 History Card # 1 of 9; Reason= 311 (0x0137) Stn= LGAC6
 History Card # 2 of 9; Reason= 311 (0x0137) Stn= LGAC6
 History Card # 3 of 9; Reason= 311 (0x0137) Stn= LGAC6
 History Card # 4 of 9; Reason= 311 (0x0137) Stn= LGAC6
```

```
History Card # 5 of 9; Reason= 311 (0x0137) Stn= LGAC6
History Card # 6 of 9; Reason= 311 (0x0137) Stn= LGAC6
History Card # 7 of 9; Reason= 311 (0x0137) Stn= LGAA6
History Card # 8 of 9; Reason= 311 (0x0137) Stn= LGAA6
History Card # 9 of 9; Reason= 311 (0x0137) Stn= LGAA6
```

<CR><LF> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111248 FROM FD04 <CR><LF> <STX>M40<CR><LF> AN N334AA/GL BUF<CR><LF> --/<CR><LF> GOOD MORNING...BOS CTR<CR><LF> LOOKING FOR YOU. FD04/PEGGY<CR><LF> PLZ ACK MSG NO. 4821<CR><LF> END<CR><LF> <LF> <CR><LF> <LF> <LF> <ETX><EOT>

FLoc=311938604 AJPSBcnt= 73 ULBLK S=31 D=21 BEPts=20010911 12:52:43 UL MsgLen= 32 Stn= LGAC6 StnDelivType= 2 Tail= .N334AA Fid= AA0011
<SOH>2.AA0011<NAK>54B<STX>129350<CR><LF> SFOXA<CR><LF> <CR><LF> <ETX>

FLoc=312039877 AJPSBcnt= 73 ULBLK S=31 D=21 BEPts=20010911 12:52:53 UL MsgLen= 32 Stn= LGAC6 StnDelivType= 2 Tail= .N334AA Fid= AA0011 <SOH>2.AA0011<NAK>54B<STX>129350<CR><LF> SFOXA<CR><LF> <CR><LF> <ETX>

FLoc=312153424 AJPSBcnt= 73 ULBLK S=31 D=21 BEPts=20010911 12:53:03 UL MsgLen= 32 Stn= LGAC6 StnDelivType= 2

Tail= .N334AA Fid= AA0011 <SOH>2.AA0011<NAK>54B<STX>129350<CR><LF> SFOXA<CR><LF> <CR><LF> <ETX>

FLoc=312260686 AJPSBcnt= 73 ULBLK S=31 D=21 BEPts=20010911 12:53:13 UL MsgLen= 32 Stn= LGAC6 StnDelivType= 2 Tail= .N334AA Fid= AA0011
<SOH>2.AA0011<NAK>54B<STX>129350<CR><LF> SFOXA<CR><LF> <CR><LF> <ETX>

FLoc=312362344 AJPSBcnt= 73 ULBLK S=31 D=21 BEPts=20010911 12:53:23 UL MsgLen= 32 Stn= LGAC6 StnDelivType= 2 Tail= .N334AA Fid= AA0011 <SOH>2.AA0011<NAK>54B<STX>129350<CR><LF> SFOXA<CR><LF> <CR><LF> <ETX>

FLoc=312462403 AJPSBcnt= 73 ULBLK S=31 D=21 BEPts=20010911 12:53:33 UL MsgLen= 32 Stn= LGAC6 StnDelivType= 2 Tail= .N334AA Fid= AA0011
<SOH>2.AA0011<NAK>54B<STX>129350<CR><LF> SFOXA<CR><LF> <CR><LF> <ETX>

FLoc=312542331 AJPSBcnt= 73 ULBLK S=31 D=21 BEPts=20010911 12:53:43 UL MsgLen= 32 Stn= LGAA6 StnDelivType= 3 Tail= .N334AA Fid= AA0011 <SOH>2.AA0011<NAK>54B<STX>129350<CR><LF> SFOXA<CR><LF> <CR><LF> <ETX>

FLoc=312641016 AJPSBcnt= 73 ULBLK S=31 D=21 BEPts=20010911 12:53:53 UL MsgLen= 32 Stn= LGAA6 StnDelivType= 3 Tail= .N334AA Fid= AA0011 <SOH>2.AA0011<NAK>54B<STX>129350<CR><LF> SFOXA<CR><LF> <CR><LF> <ETX>

FLoc=312742908 AJPSBcnt= 73 ULBLK S=31 D=21 BEPts=20010911 12:54:03 UL MsgLen= 32 Stn= LGAA6 StnDelivType= 3 Tail= .N334AA Fid= AA0011 <SOH>2.AA0011<NAK>54B<STX>129350<CR><LF> SFOXA<CR><LF> <CR><LF> <ETX>

FLoc=314680979 AJPSBcnt= 154 ULMSG S=31 D=21 BEPts=20010911 12:56:44 ADNS MsgLen= 97 Org Addr= TULDDAA Org TimeStamp= 20010911 12:56:00

```
Smi= DFD AgyNum= 65535
Tail Number= .N334AA FltId= AA0011
Target Stn= BUF<00><00> Target Method= 2
<CR><I F>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111256 FROM CC04
                             <CR><LF>
<STX>DFD<CR><LF>
AN N334AA/GL BUF<CR><LF>
- XRP 151 0<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<EOT> 034<ETX><EOT>
FLoc=314681133 AJPSBcnt= 152 ICPUL S=31 D=21 BEPts=20010911 12:56:44
Intercept MsgLen=97 Addressee= .N334AA Num MediaTypes=1
Blk Num=1 UI Code=0
***IcpHdr: Reason Code= 231 AgyNum= 65535
***IcpHdr: Tail Number= .N334AA
***lcpHdr: FltId= <FF><00><00><00><00>
Dumping Media type #1 of 1
 Media Type = 0 Num Stns= 0 Num History= 0
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111256 FROM CC04
                             <CR><LF>
<STX>DFD<CR><LF>
AN N334AA/GL BUF<CR><LF>
- XRP 151 0<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<EOT> 034<ETX><EOT>
FLoc=321754450 AJPSBcnt= 154 ULMSG S=31 D=21 BEPts=20010911 13:06:31
ADNS MsgLen= 97 Org Addr= TULDDAA Org TimeStamp= 20010911 13:06:00
Smi= DFD AgyNum= 65535
Tail Number= .N334AA FltId= AA0011
Target Stn= CLE<00><00> Target Method= 2
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111306 FROM FD04
                             <CR><LF>
<STX>DFD<CR><LF>
AN N334AA/GL CLE<CR><LF>
- XRP 151 0<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<EOT> 732<ETX><EOT>
```

FLoc=321754604 AJPSBcnt= 152 ICPUL S=31 D=21 BEPts=20010911 13:06:31 Intercept MsgLen=97 Addressee= .N334AA Num MediaTypes=1 Blk Num=1 Ul Code=0

***IcpHdr: Reason Code= 231 AgyNum= 65535

***IcpHdr: Tail Number= .N334AA

***lcpHdr: FltId= <FF><00><00><00><00>

Dumping Media type #1 of 1 Media Type = 0 Num Stns= 0 Num History= 0

FLoc=265527364 AJPSBcnt= 80 DLBLK S=31 D=21 BEPts=20010911 11:37:41 DL MsgLen= 49 DBI= 3 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=80 (0x50) <SOH>2.N591UA<NAK>B9<STX>M64AUA0093/ATSUAXA.TI2/024EWR D90D7<ETX>

FLoc=265527444 AJPSBcnt= 162 DLMSG S=31 D=21 BEPts=20010911 11:37:41 ADNS MsgLen= 122 Tail Number= .N591UA SMI= RAI FltId= UA0093 AgyNum= 60 (0x003C)
<CR><LF>
<SOH>QU RURDLXA ATSUAXA DPADUUA <CR><LF>
.DDLXCXA 111137<CR><LF>
<STX>RAI<CR><LF>
FI UAL93/AN N591UA<CR><LF>
DT DDL EWR 111137 M64A<CR><LF>
- TI2/024EWR D90D7<CR><LF>
<ETX><EOT>

FLoc=265551817 AJPSBcnt= 80 DLBLK S=31 D=21 BEPts=20010911 11:37:44 DL MsgLen= 49 DBl= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=70 (0x46) <SOH>2.N591UA<NAK>B9<STX>M64AUA0093/ATSUAXA.TI2/024EWR D90D7<ETX>

FLoc=265557940 AJPSBcnt= 611 ULMSG S=31 D=21 BEPts=20010911 11:37:44 ADNS MsgLen= 554 Org Addr= ATSUAXA Org TimeStamp= 20010911 11:37:00 Smi= CMD AgyNum= 65535 Tail Number= .N591UA FItId= UA0093 Target Stn= <00><00><00><00> Target Method= 0 <CR><I F> <SOH>QU DDLXCXA<CR><LF> .ATSUAXA 111137<CR><LF> <STX>CMD<CR><LF> AN N591UA<CR><LF> - QUATSUAXA~1EWR ATIS INFO D 1051Z.<CR><LF> 34005KT 10SM CLR 18/14<CR><LF> A3011 (THREE ZERO ONE<CR><LF> ONE). ILS RWY 4R APCH IN<CR><LF> USE. DEPARTING RWY 4L.<CR><LF> RWY 29 AVAILABLE FOR ALL<CR><LF> PROPS, AND STAGE 3 JETS<CR><LF> OVR WHITE, DIXIE DEP<CR><LF> FIXES. DEP FLOW MGT PROC<CR><LF> IN EFFECT, DEP DELAYS<CR><LF> LESS THAN 15 MIN. RY 4<CR><LF> DEPARTURES, USE UPPER<CR><LF> ANTENNA FOR ATC<CR><LF> COMMUNICATIONS. COA RAMP<CR><LF> PROCEDURES IN EFFECT.<CR><LF> READBACK ALL RUNWAY HOLD<CR><LF> SHORT INSTRUCTIONS. USE<CR><LF> CAUTION FOR BIRDS AND<CR><LF> CRANES IN THE VICINITY<CR><LF> OF EWR. ...ADVS YOU HAVE<CR><LF> INFO D.<CR><LF> <ETX><EOT>

FLoc=265573923 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:37:46

UL MsgLen= 235 Stn= EWRB5 StnDelivType= 2
Tail= .N591UA Fid= UA0093
<SOH>2.N591UA3RAR<STX>QUATSUAXA~1EWR ATIS INFO D 1051Z.<CR><LF>
34005KT 10SM CLR 18/14<CR><LF>
A3011 (THREE ZERO ONE<CR><LF>
ONE). ILS RWY 4R APCH IN<CR><LF>
USE. DEPARTING RWY 4L.<CR><LF>
RWY 29 AVAILABLE FOR ALL<CR><LF>
PROPS, AND STAGE 3 JETS<CR><LF>
OVR WHITE, DIXIE DEP<CR><LF>
FIXES. DEP FLOW<ETB>

FLoc=265679413 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:37:56 UL MsgLen= 235 Stn= EWRB5 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA3RAR<STX>QUATSUAXA~1EWR ATIS INFO D 1051Z.<CR><LF> 34005KT 10SM CLR 18/14<CR><LF> A3011 (THREE ZERO ONE<CR><LF> ONE). ILS RWY 4R APCH IN<CR><LF> USE. DEPARTING RWY 4L.<CR><LF> RWY 29 AVAILABLE FOR ALL<CR><LF> PROPS, AND STAGE 3 JETS<CR><LF> OVR WHITE, DIXIE DEP<CR><LF> FIXES. DEP FLOW<ETB>

FLoc=265734610 AJPSBcnt= 65 DLBLK S=31 D=21 BEPts=20010911 11:38:01 DL MsgLen= 34 DBI= 4 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=80 (0x50) <SOH>2.N591UAR5Z<STX>M65AUA0093/CD EWRSFO<ETX>

FLoc=265734675 AJPSBcnt= 148 DLMSG S=31 D=21 BEPts=20010911 11:38:01 ADNS MsgLen= 108 Tail Number= .N591UA SMI= AGM FltId= UA0093 AgyNum= 60 (0x003C)
<CR><LF>
<SOH>QU RURDLXA HDQDLUA <CR><LF>
.DDLXCXA 111138<CR><LF>
<STX>AGM<CR><LF>
FI UAL93/AN N591UA<CR><LF>
DT DDL EWR 111138 M65A<CR><LF>
- /CD EWRSFO<CR><LF>
<ETX><ETX><EOT>

FLoc=265759605 AJPSBcnt= 65 DLBLK S=31 D=21 BEPts=20010911 11:38:04 DL MsgLen= 34 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=70 (0x46) <SOH>2.N591UAR5Z<STX>M65AUA0093/CD EWRSFO<ETX>

FLoc=265768584 AJPSBcnt= 529 ULMSG S=31 D=21 BEPts=20010911 11:38:05 ADNS MsgLen= 472 Org Addr= ATCCDUA Org TimeStamp= 20010911 11:37:00 Smi= CMD AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= EWR<00><00> Target Method= 1 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .ATCCDUA 111137/<CR><LF> <STX>CMD<CR><LF> <STX>CMD<CR><LF> <

AN N591UA/AP EWR<CR><LF> - QUATCCDUA~1**DPTR CLRNC**<CR><LF> FLT 93-11 EWR - SFO<CR><LF> UAL93 EWR<CR><LF> L/B752/E P1200 RQ350<CR><LF> XPDR 1527<CR><LF> <CR><I F> ***FILED ROUTE****** <CR><LF> EWR ELIOT J60<CR><LF> DJB***SFO <CR><LF> ?NRP <CR><LF> ************ <CR><LF> <CR><LF> ***REVISED SEGMENT*** <CR><LF> NONE<CR><LF> ************** <CR><LF> <CR><LF> ***REMARKS******* <CR><LF> NEWARK SIX DEPARTURE <CR><LF> EXPECT REQ ALT 10 MIN<CR><LF> AFTER TAKE-OFF <CR><LF> DEPARTURE FREQUENCY<CR><LF> 119.2 <CR><LF> CONTACT FLOW CONTROL<CR><LF> NOW 126.15 <CR><LF> ******************************* <CR><LF> <ETX><EOT>

FLoc=265772624 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:38:06 UL MsgLen= 235 Stn= EWRB5 StnDelivType= 1
Tail= .N591UA Fid= UA0093
<SOH>2.N591UA4RAS<STX> MGT PROC<CR><LF>
IN EFFECT, DEP DELAYS<CR><LF>
LESS THAN 15 MIN. RY 4<CR><LF>
DEPARTURES, USE UPPER<CR><LF>
ANTENNA FOR ATC<CR><LF>
COMMUNICATIONS. COA RAMP<CR><LF>
PROCEDURES IN EFFECT.<CR><LF>
READBACK ALL RUNWAY HOLD<CR><LF>
SHORT INSTRUCTIONS. USE<CR><ETB>

FLoc=265810083 AJPSBcnt= 65 DLBLK S=31 D=21 BEPts=20010911 11:38:10 DL MsgLen= 34 DBI= 5 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=80 (0x50) <SOH>2.N591UAS5Z<STX>M66AUA0093/RL EWRSFO<ETX>

FLoc=265810148 AJPSBcnt= 148 DLMSG S=31 D=21 BEPts=20010911 11:38:10 ADNS MsgLen= 108 Tail Number= .N591UA SMI= AGM FltId= UA0093 AgyNum= 60 (0x003C) <CR><LF> <SOH>QU RURDLXA HDQDLUA <CR><LF> .DDLXCXA 111138<CR><LF> <STX>AGM<CR><LF> FI UAL93/AN N591UA<CR><LF> <

DT DDL EWR 111138 M66A<CR><LF>
- /RL EWRSFO<CR><LF>
<ETX><EOT>

FLoc=265827776 AJPSBcnt= 65 DLBLK S=31 D=21 BEPts=20010911 11:38:12 DL MsgLen= 34 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=70 (0x46) <SOH>2.N591UAS5Z<STX>M66AUA0093/RL EWRSFO<ETX>

FLoc=265837046 AJPSBcnt= 138 ULMSG S=31 D=21 BEPts=20010911 11:38:13 ADNS MsgLen= 81 Org Addr= HDQWDUA Org TimeStamp= 20010911 11:37:00 Smi= CMD AgyNum= 65535
Tail Number= .N591UA FltId= UA0093
Target Stn= EWR<00><00> Target Method= 2
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.HDQWDUA 111137/<CR><LF>
.HDQWDUA 111137/<CR><LF>
AN N591UA/GL EWR<CR><LF>
- QUHDQWDUA~1RLS 01<CR><LF>
<ETX><EOT>

FLoc=265850529 AJPSBcnt= 116 ULBLK S=31 D=21 BEPts=20010911 11:38:15 UL MsgLen= 75 Stn= EWRB5 StnDelivType= 1 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA5RAT<STX><LF> CRANES IN THE VICINITY<CR><LF> OF EWR. ...ADVS YOU HAVE<CR><LF> INFO D.<CR><LF> <ETX>

FLoc=265890035 AJPSBcnt= 65 DLBLK S=31 D=21 BEPts=20010911 11:38:19 DL MsgLen= 34 DBI= 6 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=80 (0x50) <SOH>2.N591UAT5Z<STX>M67AUA0093/CG EWRSFO<ETX>

FLoc=265917299 AJPSBcnt= 65 DLBLK S=31 D=21 BEPts=20010911 11:38:22 DL MsgLen= 34 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=70 (0x46) <SOH>2.N591UAT5Z<STX>M67AUA0093/CG EWRSFO<ETX>

FLoc=265920110 AJPSBcnt= 355 ULMSG S=31 D=21 BEPts=20010911 11:38:22 ADNS MsgLen= 298 Org Addr= HDQWDUA Org TimeStamp= 20010911 11:37:00 Smi= CMD AgyNum= 65535

Tail Number= .N591UA FltId= UA0093 Target Stn= EWR<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .HDQWDUA 111137/<CR><LF> <STX>CMD<CR><LF> AN N591UA/GL EWR<CR><LF> QUHDQWDUA~1CXN GATE CHGS<CR><LF> UA93 EWRSFO<CR><LF> FLT 93-11 SFO<CR><LF> EON 1800Z/ETA 1107L<CR><LF> GATE 88 <CR><LF> FREQ 119.22<CR><LF> APU OFF <CR><LF> -----FLT--GATE--ETD-<CR><LF> KIX 809 INTL 1250 <CR><LF> LAS 2310 76 1215 <CR><LF> RNO 2432 73A 1222 <CR><LF> SAN 2163 77A 1230 <CR><LF> <ETX><EOT>

FLoc=265934333 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:38:24 UL MsgLen= 235 Stn= EWRB5 StnDelivType= 1 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA6RAU<STX>QUATCCDUA~1**DPTR CLRNC**<CR><LF> FLT 93-11 EWR - SFO<CR><LF> UAL93 EWR<CR><LF> L/B752/E P1200 RQ350<CR><LF> XPDR 1527<CR><LF> <CR><LF> ***FILED ROUTE****** <CR><LF> EWR ELIOT J60<CR><LF> DJB***SFO <CR><LF> ?NRP <CR><LF> ****************** <CR><LF> <CR><I F> ***REVISED SEGMENT*** <CR><LF> NONE<CR><LF> **********

FLoc=265959568 AJPSBcnt= 65 DLBLK S=31 D=21 BEPts=20010911 11:38:27 DL MsgLen= 34 DBI= 7 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=80 (0x50) <SOH>2.N591UAU5Z<STX>M68AUA0093/C3 EWRSFO<ETX>

FLoc=265959633 AJPSBcnt= 148 DLMSG S=31 D=21 BEPts=20010911 11:38:27 ADNS MsgLen= 108 Tail Number= .N591UA SMI= AGM FitId= UA0093 AgyNum= 60 (0x003C)
<CR><LF>
<SOH>QU RURDLXA HDQDLUA <CR><LF>
.DDLXCXA 111138 <CR><LF>
<STX>AGM<CR><LF>
FI UAL93/AN N591UA <CR><LF>
DT DDL EWR 111138 M68A <CR><LF>
- /C3 EWRSFO <CR><LF>
<ETX><EOT>

FLoc=265979470 AJPSBcnt= 201 ULMSG S=31 D=21 BEPts=20010911 11:38:29 ADNS MsgLen= 144 Org Addr= HDQWDUA Org TimeStamp= 20010911 11:38:00 Smi= CMD AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= EWR<00><00> Target Method= 2 <CR>><LF> <SOH>QU DDLXCXA<CR><LF> .HDQWDUA 111138/<CR><LF> <STX>CMD<CR><LF> AN N591UA/GL EWR<CR><LF> - QUHDQWDUA~1GATE ASSIGN<CR><LF> UA93 EWRSFO<CR><LF> GATE 88 FREQ 119.22 <CR><LF> EON 1800 APU OFF <CR><LF> <CR><LF> <CR><LF> <ETX><EOT>

FLoc=266056996 AJPSBcnt= 69 DLBLK S=31 D=21 BEPts=20010911 11:38:38 DL MsgLen= 38 DBI= 8 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=80 (0x50) <SOH>2.N591UAV5Z<STX>M69AUA0093/W1 EWRSFO SFO<ETX>

FLoc=266057065 AJPSBcnt= 152 DLMSG S=31 D=21 BEPts=20010911 11:38:38 ADNS MsgLen= 112 Tail Number= .N591UA SMI= AGM FltId= UA0093 AgyNum= 60 (0x003C)
<CR><LF>
<SOH>QU RURDLXA HDQDLUA <CR><LF>
.DDLXCXA 111138</CR><LF>
<STX>AGM<CR><LF>
FI UAL93/AN N591UA<CR><LF>
DT DDL EWR 111138 M69A<CR><LF>
- /W1 EWRSFO SFO<CR><LF>
<ETX><ETX><EOT>

FLoc=266080853 AJPSBcnt= 69 DLBLK S=31 D=21 BEPts=20010911 11:38:40 DL MsgLen= 38 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=70 (0x46)

<SOH>2.N591UAV5Z<STX>M69AUA0093/W1 EWRSFO SFO<ETX>

FLoc=266099271 AJPSBcnt= 240 ULMSG S=31 D=21 BEPts=20010911 11:38:42 ADNS MsgLen= 183 Org Addr= HDQWDUA Org TimeStamp= 20010911 11:38:00 Smi= CMD AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= EWR<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .HDQWDUA 111138/<CR><LF> <STX>CMD<CR><LF> AN N591UA/GL EWR<CR><LF> - QUHDQWDUA~1HRLY WEATHER<CR><LF> UA93 EWRSFO<CR><LF> SFO 1102 111056Z <CR><LF> 32004KT 10SM BKN200 <CR><LF> 17/12 A2991 RMK AO2 <CR><LF> SLP128 T01720122<CR><LF> <CR><LF> <ETX><EOT>

FLoc=266109215 AJPSBcnt= 75 ULBLK S=31 D=21 BEPts=20010911 11:38:43 UL MsgLen= 34 Stn= EWRB5 StnDelivType= 1 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA8RAW<STX>QUHDQWDUA~1RLS 01<CR><LF> <ETX>

FLoc=266131846 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:38:45 DL MsgLen= 24 DBI= 9 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=80 (0x50) <SOH>2.N591UAW_<STX>S29AUA0093<ETX>

FLoc=266155828 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:38:47 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=70 (0x46) <SOH>2.N591UAW_<STX>S29AUA0093<ETX>

FLoc=266258322 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:39:00 UL MsgLen= 235 Stn= EWRB5 StnDelivType= 1 Tail= .N591UA Fid= UA0093

<SOH>2.N591UA<NAK>RAX<STX>QUHDQWDUA~1CXN GATE CHGS<CR><LF>
UA93 EWRSFO<CR><LF>
FLT 93-11 SFO<CR><LF>
EON 1800Z/ETA 1107L<CR><LF>
GATE 88 <CR><LF>
FREQ 119.22<CR><LF>
APU OFF <CR><LF>
-----FLT--GATE--ETD-<CR><LF>
KIX 809 INTL 1250 <CR><LF>
LAS 2310 76 1215 <CR><LF>
RNO 2432 73A 1222 <CR><LF>
SAN 21<ETB>

FLoc=266382528 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:39:14 DL MsgLen= 24 DBI= 2 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRA5 SSV=70 (0x46) <SOH>2.N591UAX_<STX>S32AUA0093<ETX>

FLoc=266401353 AJPSBcnt= 72 ULBLK S=31 D=21 BEPts=20010911 11:39:17 UL MsgLen= 31 Stn= EWRB5 StnDelivType= 1 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAY<STX>63 77A 1230 <CR><LF><ETX>

FLoc=266492135 AJPSBcnt= 72 ULBLK S=31 D=21 BEPts=20010911 11:39:27 UL MsgLen= 31 Stn= EWRB5 StnDelivType= 1 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAY<STX>63 77A 1230 <CR><LF><ETX>

FLoc=266500113 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:39:27 DL MsgLen= 24 DBI= 3 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=80 (0x50) <SOH>2.N591UAY <STX>S33AUA0093<ETX>

FLoc=266519323 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:39:30 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=70 (0x46) <SOH>2.N591UAY_<STX>S33AUA0093<ETX>

FLoc=266554571 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:39:33 DL MsgLen= 24 DBI= 4 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=80 (0x50) <SOH>2.N591UAZ_<STX>S34AUA0093<ETX>

FLoc=266576883 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:39:36 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=70 (0x46) <SOH>2.N591UAZ_<STX>S34AUA0093<ETX>

FLoc=266590463 AJPSBcnt= 177 ULBLK S=31 D=21 BEPts=20010911 11:39:38 UL MsgLen= 136 Stn= EWRB5 StnDelivType= 1 Tail= .N591UA Fid= UA0093
<SOH>2.N591UA<NAK>RAA<STX>QUHDQWDUA~1HRLY WEATHER<CR><LF> UA93 EWRSFO<CR><LF> SFO 1102 111056Z <CR><LF> 32004KT 10SM BKN200 <CR><LF> 17/12 A2991 RMK AO2 <CR><LF> SLP128 T01720122<CR><LF> <CR><LF> <CR><LF> <ETX>

FLoc=266607061 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:39:39 DL MsgLen= 24 DBI= 5 DIIndicator= 1 DINumStns= 1 BepStnName = EWRB5 SSV=80 (0x50) <SOH>2.N591UAA_<STX>S35AUA0093<ETX>

FLoc=266631377 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:39:42 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=70 (0x46) <SOH>2.N591UAA_<STX>S35AUA0093<ETX>

FLoc=277385494 AJPSBcnt= 75 DLBLK S=31 D=21 BEPts=20010911 11:58:26 DL MsgLen= 44 DBI= 6 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=80 (0x50) <SOH>2.N591UA<NAK>5Z<STX>M70AUA0093/B3 EWRSFO 11 R4L F5<ETX>

FLoc=277385569 AJPSBcnt= 158 DLMSG S=31 D=21 BEPts=20010911 11:58:26 ADNS MsgLen= 118 Tail Number= .N591UA SMI= AGM FltId= UA0093 AgyNum= 60 (0x003C) <CR><LF> <SOH>QU RURDLXA HDQDLUA <CR><LF> .DDLXCXA 111158<CR><LF> <STX>AGM<CR><LF> FI UAL93/AN N591UA<CR><LF> <

DT DDL EWR 111158 M70A<CR><LF>
- /B3 EWRSFO 11 R4L F5<CR><LF>
<ETX><EOT>

FLoc=277410100 AJPSBcnt= 515 ULMSG S=31 D=21 BEPts=20010911 11:58:28 ADNS MsgLen= 458 Org Addr= HDQWDUA Org TimeStamp= 20010911 11:58:00 Smi= CMD AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= EWR<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .HDQWDUA 111158/<CR><LF> <STX>CMD<CR><LF> AN N591UA/GL EWR<CR><LF> QUHDQWDUA~1RNWY DATA-4L<CR><LF> UA93 EWRSFO<CR><LF> *F5 BLEED-NORMAL*<CR><LF> TOG 192.8P ZFW 144.1P<CR><LF> REDUCED THRUST OPTIONS<CR><LF> TW EPR N1 ATGW ATEMP<CR><LF> 0 1.33 83 207.6 120/48<CR><LF> 5 1.33 83 202.5 120/48<CR><LF> 10 1.33 83 197.3 120/48<CR><LF> MAX EPR: 1.41 N1: 88<CR><LF> R247.5 P251.6 S240.0<CR><LF> T66(18) ALTM 3012I<CR><LF> WIND 3408M 4KT HW<CR><LF> (4L) RWY 4L/R ENGINE <CR><LF> FAILURE PROCEDURE: <CR><LF> NON-STANDARD <CR><LF> ACCELERATION <CR><LF> ALTITUDE: 1020 FT <CR><LF> MSL.<CR><LF> <CR><LF> <CR><LF> <ETX><EOT>

FLoc=277416991 AJPSBcnt= 81 DLBLK S=31 D=21 BEPts=20010911 11:58:29 DL MsgLen= 44 DBI= 6 DlIndicator= 2 DlNumStns= 2 BepStnName = EWRA5 SSV=70 (0x46) BepStnName = LGAA5 SSV=41 (0x29) <SOH>2.N591UA<NAK>5Z<STX>M70AUA0093/B3 EWRSFO 11 R4L F5<ETX>

FLoc=277435456 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:58:31 UL MsgLen= 235 Stn= EWRB5 StnDelivType= 2 Tail= .N591UA Fid= UA0093
<SOH>2.N591UA6RAB<STX>QUHDQWDUA~1RNWY DATA-4L<CR><LF> UA93 EWRSFO<CR><LF> *F5 BLEED-NORMAL*<CR><LF> TOG 192.8P ZFW 144.1P<CR><LF> REDUCED THRUST OPTIONS<CR><LF> TW EPR N1 ATGW ATEMP<CR><LF> 0 1.33 83 207.6 120/48<CR><LF> 5 1.33 83 202.5 120/48<CR><LF> MAX EPR: 1.41<ETB>

FLoc=277454655 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:58:33 DL MsgLen= 24 DBI= 7 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=80 (0x50) <SOH>2.N591UAB_<STX>S36AUA0093<ETX>

FLoc=277477331 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:58:35 DL MsgLen= 24 DBI= 7 DIIndicator= 2 DINumStns= 1 BepStnName = EWRA5 SSV=70 (0x46) <SOH>2.N591UAB_<STX>S36AUA0093<ETX>

FLoc=277512003 AJPSBcnt= 232 ULBLK S=31 D=21 BEPts=20010911 11:58:38 UL MsgLen= 191 Stn= EWRB5 StnDelivType= 1 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAC<STX> N1: 88<CR><LF> R247.5 P251.6 S240.0<CR><LF> T66(18) ALTM 3012I<CR><LF> WIND 3408M 4KT HW<CR><LF> (4L) RWY 4L/R ENGINE <CR><LF> FAILURE PROCEDURE: <CR><LF> NON-STANDARD <CR><LF> ACCELERATION <CR><LF> ALTITUDE: 1020 FT <CR><LF> MSL.<CR><LF> <CR><LF> <CR><LF> <ETX>

FLoc=277535638 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:58:40 DL MsgLen= 24 DBI= 8 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=79 (0x4F) <SOH>2.N591UAC_<STX>S37AUA0093<ETX>

FLoc=277557589 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 11:58:42 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 2 BepStnName = EWRA5 SSV=70 (0x46) BepStnName = LGAA5 SSV=42 (0x2A) <SOH>2.N591UAC_<STX>S37AUA0093<ETX>

FLoc=279459340 AJPSBcnt= 71 DLBLK S=31 D=21 BEPts=20010911 12:01:11 DL MsgLen= 40 DBI= 9 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=79 (0x4F) <SOH>2.N591UA<NAK>QA<STX>M71AUA0093EWR1201060970498<ETX>

FLoc=279459547 AJPSBcnt= 179 DLMSG S=31 D=21 BEPts=20010911 12:01:11 ADNS MsgLen= 139 Tail Number= .N591UA SMI= DEP FItId= UA0093 AgyNum= 60 (0x003C)
<CR><LF>
<SOH>QU RURDLXA ANPDMXA HDQDLUA IADDTXA <CR><LF>
.DDLXCXA 111201</F>
<STX>DEP<CR><LF>
FI UAL93/AN N591UA/DA EWR/OT 1201/FB 498/BF 6097</F>
DT DDL EWR 111201 M71A</F>
<ETX><EOT>

FLoc=279493131 AJPSBcnt= 71 DLBLK S=31 D=21 BEPts=20010911 12:01:13

DL MsgLen= 40 DBI= 9 DIIndicator= 2 DINumStns= 1
BepStnName = LGAA5 SSV=42 (0x2A)
<SOH>2.N591UA<NAK>QA<STX>M71AUA0093EWR1201060970498<ETX>

FLoc=279526173 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:01:16 UL MsgLen= 14 Stn= EWRB5 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA9 D<ETX>

FLoc=282156381 AJPSBcnt= 250 ULMSG S=31 D=21 BEPts=20010911 12:04:39 ADNS MsgLen= 193 Org Addr= HDQWDUA Org TimeStamp= 20010911 12:04:00 Smi= CMD AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= EWR<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .HDQWDUA 111204/VIL<CR><LF> <STX>CMD<CR><LF> AN N591UA/GL EWR<CR><LF> - QUHDQWDUA~1WEIGHT MANIFEST<CR><LF> UA93 EWRSFO<CR><LF> EWR<CR><LF> ZFW 143938<CR><LF> TOG 192638<CR><LF> MAC 17.9<CR><LF> TRIM 05.1<CR><LF> PSGRS 038<CR><LF> CREW 02/05<CR><LF> <ETX><EOT>

FLoc=282156631 AJPSBcnt= 184 ULBLK S=31 D=21 BEPts=20010911 12:04:39 UL MsgLen= 143 Stn= EWRB5 StnDelivType= 2 Tail= .N591UA Fid= UA0093
<SOH>2.N591UA<NAK>RAE<STX>QUHDQWDUA~1WEIGHT MANIFEST<CR><LF> UA93 EWRSFO<CR><LF> EWR<CR><LF> ZFW 143938<CR><LF> TOG 192638<CR><LF> MAC 17.9<CR><LF> TRIM 05.1<CR><LF> PSGRS 038<CR><LF> CREW 02/05<CR><LF> CREW 02/05<CR><LF> <<ETX></ETX

FLoc=282178616 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:04:41 DL MsgLen= 24 DBI= 0 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=82 (0x52) <SOH>2.N591UAE_<STX>S38AUA0093<ETX>

FLoc=282214550 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:04:43 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=68 (0x44) <SOH>2.N591UAE_<STX>S38AUA0093<ETX>

FLoc=291638609 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:18:51 DL MsgLen= 39 DBI= 1 DlIndicator= 1 DlNumStns= 1

FLoc=291638679 AJPSBcnt= 153 DLMSG S=31 D=21 BEPts=20010911 12:18:51 ADNS MsgLen= 113 Tail Number= .N591UA SMI= DLA FltId= UA0093 AgyNum= 60 (0x003C)
<CR><LF>
<SOH>QU RURDLXA HDQDLUA <CR><LF>
.DDLXCXA 111218</CR><LF>
<STX>DLA<CR><LF>
FI UAL93/AN N591UA<CR><LF>
DT DDL EWR 111218 M72A<CR><LF>
- /ED EWRSFO 1230</CR><LF>
<ETX><EOT>

FLoc=291661665 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:18:53 DL MsgLen= 39 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=76 (0x4C) <SOH>2.N591UA<NAK>Q7<STX>M72AUA0093/ED EWRSFO 1230<ETX>

FLoc=291686247 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:18:56 UL MsgLen= 14 Stn= EWRB5 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA1 F<ETX>

FLoc=292181746 AJPSBcnt= 77 DLBLK S=31 D=21 BEPts=20010911 12:19:45 DL MsgLen= 46 DBI= 2 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=84 (0x54) <SOH>2.N591UA<NAK>5Z<STX>M73AUA0093/R3 EWRSFO 1569-07 MCO<ETX>

FLoc=292181823 AJPSBcnt= 160 DLMSG S=31 D=21 BEPts=20010911 12:19:45 ADNS MsgLen= 120 Tail Number= .N591UA SMI= AGM FltId= UA0093 AgyNum= 60 (0x003C)
<CR><LF>
<SOH>QU RURDLXA HDQDLUA <CR><LF>
.DDLXCXA 111219<CR><LF>
<STX>AGM<CR><LF>
FI UAL93/AN N591UA<CR><LF>
DT DDL EWR 111219 M73A<CR><LF>
- /R3 EWRSFO 1569-07 MCO<CR><LF>
<ETX><EOT>

FLoc=292208857 AJPSBcnt= 77 DLBLK S=31 D=21 BEPts=20010911 12:19:48 DL MsgLen= 46 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=76 (0x4C) <SOH>2.N591UA<NAK>5Z<STX>M73AUA0093/R3 EWRSFO 1569-07 MCO<ETX>

FLoc=292210734 AJPSBcnt= 368 ULMSG S=31 D=21 BEPts=20010911 12:19:48 ADNS MsgLen= 311 Org Addr= HDQWDUA Org TimeStamp= 20010911 12:19:00 Smi= CMD AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= EWR<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .HDQWDUA 111219/<CR><LF> <STX>CMD<CR><LF> <STX>CMD<CR><LF> <

AN N591UA/GL EWR<CR><LF>
- QUHDQWDUA~11569-07 HOWGOZIT<CR><LF>
UA93 EWRSFO<CR><LF>
MCO 1319/1329 324A<CR><LF>
CTY 1347 35 280-<CR><LF>
JOHNN 1403 35 262-<CR><LF>
ATL 1419 35 243-<CR><LF>
BNA 1443 39 215-<CR><LF>
STL 1514 39 181-<CR><LF>
MAGOO 1522 39 172-<CR><LF>
BDF 1536 39 164-<CR><LF>
ORD 1559/1605 106A<CR><LF>
<ETX><EOT>

FLoc=292218971 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:19:50 UL MsgLen= 235 Stn= EWRB5 StnDelivType= 2 Tail= .N591UA Fid= UA0093
<SOH>2.N591UA2RAG<STX>QUHDQWDUA~11569-07 HOWGOZIT<CR><LF> UA93 EWRSFO<CR><LF> MCO 1319/1329 324A<CR><LF> CTY 1347 35 280-<CR><LF> JOHNN 1403 35 262-<CR><LF> ATL 1419 35 243-<CR><LF> BNA 1443 39 215-<CR><LF> STL 1514 39 181-<CR><LF> MAGOO 1522 39 172-<CR><LF> BDF 1536 39 <ETB>

FLoc=292231953 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:19:51 DL MsgLen= 24 DBl= 3 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=83 (0x53) <SOH>2.N591UAG_<STX>S39AUA0093<ETX>

FLoc=292251970 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:19:54 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=76 (0x4C) <SOH>2.N591UAG_<STX>S39AUA0093<ETX>

FLoc=292264613 AJPSBcnt= 85 ULBLK S=31 D=21 BEPts=20010911 12:19:56 UL MsgLen= 44 Stn= EWRB5 StnDelivType= 1 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAH<STX>164-<CR><LF>ORD 1559/1605 106A<CR><LF><ETX>

FLoc=292271939 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:19:57 DL MsgLen= 24 DBI= 4 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=83 (0x53) <SOH>2.N591UAH_<STX>S40AUA0093<ETX>

FLoc=292282029 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:19:58 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=76 (0x4C) <SOH>2.N591UAH_<STX>S40AUA0093<ETX>

FLoc=293594699 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:22:23

DL MsgLen= 39 DBI= 5 DIIndicator= 1 DINumStns= 1
BepStnName = EWRB5 SSV=83 (0x53)
<SOH>2.N591UA<NAK>Q7<STX>M74AUA0093/ED EWRSFO 1230<ETX>

FLoc=293594824 AJPSBcnt= 153 DLMSG S=31 D=21 BEPts=20010911 12:22:23 ADNS MsgLen= 113 Tail Number= .N591UA SMI= DLA FItId= UA0093 AgyNum= 60 (0x003C)
<CR><LF>
<SOH>QU RURDLXA HDQDLUA <CR><LF>
.DDLXCXA 111222<CR><LF>
<STX>DLA<CR><LF>
FI UAL93/AN N591UA<CR><LF>
DT DDL EWR 111222 M74A<CR><LF>
- /ED EWRSFO 1230<CR><LF>
<ETX><ETX><EOT>

FLoc=293620577 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:22:25 DL MsgLen= 39 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=76 (0x4C) <SOH>2.N591UA<NAK>Q7<STX>M74AUA0093/ED EWRSFO 1230<ETX>

FLoc=293645369 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:22:28 UL MsgLen= 14 Stn= EWRB5 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA5_I<ETX>

FLoc=298529195 AJPSBcnt= 80 DLBLK S=31 D=21 BEPts=20010911 12:30:44 DL MsgLen= 49 DBI= 6 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=83 (0x53) <SOH>2.N591UA<NAK>B9<STX>M75AUA0093/ATSUAXA.TI2/024EWR D90D7<ETX>

FLoc=298529275 AJPSBcnt= 162 DLMSG S=31 D=21 BEPts=20010911 12:30:44 ADNS MsgLen= 122 Tail Number= .N591UA SMI= RAI FItId= UA0093 AgyNum= 60 (0x003C)
<CR><LF>
<SOH>QU RURDLXA ATSUAXA DPADUUA <CR><LF>
.DDLXCXA 111230<CR><LF>
<STX>RAI<CR><LF>
FI UAL93/AN N591UA<CR><LF>
DT DDL EWR 111230 M75A<CR><LF>
- TI2/024EWR D90D7<CR><LF>
<ETX><EOT>

FLoc=298558266 AJPSBcnt= 611 ULMSG S=31 D=21 BEPts=20010911 12:30:47 ADNS MsgLen= 554 Org Addr= ATSUAXA Org TimeStamp= 20010911 12:30:00 Smi= CMD AgyNum= 65535
Tail Number= .N591UA FltId= UA0093
Target Stn= <00><00><00><00> Target Method= 0
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.ATSUAXA 111230<CR><LF>
AN N591UA<CR><LF>
AN N591UA<CR><LF>
- QUATSUAXA~1EWR ATIS INFO E 1151Z.<CR><LF>
34007KT 10SM CLR 19/13<CR><LF>
A3012 (THREE ZERO ONE<CR><LF>

TWO). ILS RWY 4R APCH IN<CR><LF> USE. DEPARTING RWY 4L.<CR><LF> RWY 29 AVAILABLE FOR ALL<CR><LF> PROPS, AND STAGE 3 JETS<CR><LF> OVR WHITE, DIXIE DEP<CR><LF> FIXES. DEP FLOW MGT PROC<CR><LF> IN EFFECT, DEP DELAYS<CR><LF> LESS THAN 15 MIN. RY 4<CR><LF> DEPARTURES, USE UPPER<CR><LF> ANTENNA FOR ATC<CR><LF> COMMUNICATIONS. COA RAMP<CR><LF> PROCEDURES IN EFFECT.<CR><LF> READBACK ALL RUNWAY HOLD<CR><LF> SHORT INSTRUCTIONS. USE<CR><LF> CAUTION FOR BIRDS AND<CR><LF> CRANES IN THE VICINITY<CR><LF> OF EWR. ...ADVS YOU HAVE<CR><LF> INFO E.<CR><LF> <ETX><EOT>

FLoc=298562578 AJPSBcnt= 80 DLBLK S=31 D=21 BEPts=20010911 12:30:47 DL MsgLen= 49 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=71 (0x47) <SOH>2.N591UA<NAK>B9<STX>M75AUA0093/ATSUAXA.TI2/024EWR D90D7<ETX>

FLoc=298575984 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:30:49 UL MsgLen= 235 Stn= EWRB5 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA6RAJ<STX>QUATSUAXA~1EWR ATIS INFO E 1151Z.<CR><LF> 34007KT 10SM CLR 19/13<CR><LF> A3012 (THREE ZERO ONE<CR><LF> TWO). ILS RWY 4R APCH IN<CR><LF> USE. DEPARTING RWY 4L.<CR><LF> RWY 29 AVAILABLE FOR ALL<CR><LF> PROPS, AND STAGE 3 JETS<CR><LF> OVR WHITE, DIXIE DEP<CR><LF> FIXES. DEP FLOW<ETB>

FLoc=298595643 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:30:51 DL MsgLen= 24 DBI= 7 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=83 (0x53) <SOH>2.N591UAJ <STX>S41AUA0093<ETX>

FLoc=298626532 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:30:54 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=73 (0x49) <SOH>2.N591UAJ_<STX>S41AUA0093<ETX>

FLoc=298639604 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:30:56 UL MsgLen= 235 Stn= EWRB5 StnDelivType= 1 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAK<STX> MGT PROC<CR><LF> IN EFFECT, DEP DELAYS<CR><LF> LESS THAN 15 MIN. RY 4<CR><LF> DEPARTURES, USE UPPER<CR><LF> ANTENNA FOR ATC<CR><LF>

COMMUNICATIONS. COA RAMP<CR><LF>
PROCEDURES IN EFFECT.<CR><LF>
READBACK ALL RUNWAY HOLD<CR><LF>
SHORT INSTRUCTIONS. USE<CR><LF>
CAUTION FOR BIRDS AND<CR><ETB>

FLoc=298662758 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:30:57 DL MsgLen= 24 DBI= 8 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=83 (0x53) <SOH>2.N591UAK <STX>S42AUA0093<ETX>

FLoc=298682108 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:30:59 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=73 (0x49) <SOH>2.N591UAK <STX>S42AUA0093<ETX>

FLoc=298706313 AJPSBcnt= 116 ULBLK S=31 D=21 BEPts=20010911 12:31:02 UL MsgLen= 75 Stn= EWRB5 StnDelivType= 1 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAL<STX><LF> CRANES IN THE VICINITY<CR><LF> OF EWR. ...ADVS YOU HAVE<CR><LF> INFO E.<CR><LF> <ETX>

FLoc=298719961 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:31:03 DL MsgLen= 24 DBI= 9 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=83 (0x53) <SOH>2.N591UAL_<STX>S43AUA0093<ETX>

FLoc=298751810 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:31:06 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=72 (0x48) <SOH>2.N591UAL_<STX>S43AUA0093<ETX>

FLoc=299919188 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:33:06 DL MsgLen= 39 DBI= 0 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=83 (0x53) <SOH>2.N591UA<NAK>Q7<STX>M76AUA0093/ED EWRSFO 1240<ETX>

FLoc=299919258 AJPSBcnt= 153 DLMSG S=31 D=21 BEPts=20010911 12:33:06 ADNS MsgLen= 113 Tail Number= .N591UA SMI= DLA FItId= UA0093 AgyNum= 60 (0x003C)
<CR><LF>
<SOH>QU RURDLXA HDQDLUA <CR><LF>
.DDLXCXA 111233<CR><LF>
<FI UAL93/AN N591UA<CR><LF>
DT DDL EWR 111233 M76A<CR><LF>
- /ED EWRSFO 1240<CR><LF>
<ETX><EOT>

FLoc=299944682 AJPSBcnt= 76 DLBLK S=31 D=21 BEPts=20010911 12:33:09 DL MsgLen= 39 DBI= 0 DlIndicator= 2 DlNumStns= 2 BepStnName = EWRA5 SSV=73 (0x49) BepStnName = LGAA5 SSV=41 (0x29)

<SOH>2.N591UA<NAK>Q7<STX>M76AUA0093/ED EWRSFO 1240<ETX>

FLoc=299963505 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:33:11 UL MsgLen= 14 Stn= EWRB5 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA0_M<ETX>

FLoc=305820824 AJPSBcnt= 65 DLBLK S=31 D=21 BEPts=20010911 12:42:36 DL MsgLen= 34 DBI= 1 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=88 (0x58) <SOH>2.N591UA<NAK>QF<STX>M77AUA0093EWR1242SFO<ETX>

FLoc=305820944 AJPSBcnt= 171 DLMSG S=31 D=21 BEPts=20010911 12:42:36 ADNS MsgLen= 131 Tail Number= .N591UA SMI= DEP FltId= UA0093 AgyNum= 60 (0x003C) <CR><LF> <SOH>QU RURDLXA ANPDMXA HDQDLUA IADDTXA <CR><LF> .DDLXCXA 111242<CR><LF> <STX>DEP<CR><LF> FI UAL93/AN N591UA/DA EWR/OF 1242/DS SFO<CR><LF> DT DDL EWR 111242 M77A<CR><LF> <ETX><EOT>

FLoc=305838934 AJPSBcnt= 65 DLBLK S=31 D=21 BEPts=20010911 12:42:37 DL MsgLen= 34 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA5 SSV=68 (0x44) <SOH>2.N591UA<NAK>QF<STX>M77AUA0093EWR1242SFO<ETX>

FLoc=305871481 AJPSBcnt= 62 ULBLK S=31 D=21 BEPts=20010911 12:42:41 UL MsgLen= 21 Stn= EWRB5 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA1;;N<STX>131125<ETX>

FLoc=305899714 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:42:43 DL MsgLen= 24 DBI= 2 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB5 SSV=84 (0x54) <SOH>2.N591UAN_<STX>S44AUA0093<ETX>

FLoc=305921105 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:42:45 DL MsgLen= 24 DBI= 3 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB4 SSV=90 (0x5A) <SOH>2.N591UA<NAK>Q0<STX>S45AUA0093<ETX>

FLoc=305921734 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:42:45 DL MsgLen= 24 DBI= 3 DIIndicator= 2 DINumStns= 1 BepStnName = JFKB4 SSV=57 (0x39) <SOH>2.N591UA<NAK>Q0<STX>S45AUA0093<ETX>

FLoc=305924369 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:42:45 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 2 BepStnName = EWRA5 SSV=70 (0x46) BepStnName = LGAA5 SSV=52 (0x34) <SOH>2.N591UAN_<STX>S44AUA0093<ETX>

FLoc=305940740 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:42:47 DL MsgLen= 24 DBI= 3 DIIndicator= 2 DINumStns= 1

```
BepStnName = JFKA4 SSV=53 (0x35)
<SOH>2.N591UA<NAK>Q0<STX>S45AUA0093<ETX>
```

FLoc=305942184 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:42:47 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 2 BepStnName = EWRA4 SSV=73 (0x49) BepStnName = LGAA4 SSV=58 (0x3A) <SOH>2.N591UA<NAK>QO<STX>S45AUA0093<ETX>

FLoc=305966772 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:42:50 UL MsgLen= 14 Stn= EWRB4 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA3_O<ETX>

FLoc=306297490 AJPSBcnt= 265 DLBLK S=31 D=21 BEPts=20010911 12:43:21 DL MsgLen= 234 DBI= 4 DIIndicator= 1 DINumStns= 1 BepStnName = LGAC4 SSV=63 (0x3F)

<SOH>2.N591UA<NAK>H1<STX>D74AUA0093#DFBEDA/E4 05 <CR><LF><CR><LF>
UA0093 1 89 EWR SFO 11 12:42:21 N40.68 W074.2 <CR><LF>
<CR><LF>
192 0473 -0136 1471 222 0229 00 <CR><LF>
<CR><LF>
0701 12112 11768 086 0849 0928 1313 1310 1389 0550 0563 10101V<TSTRET>
<CR><LF>
1529 0227 338 233 000 000 001 000 03<ETB>

FLoc=306299272 AJPSBcnt= 265 DLBLK S=31 D=21 BEPts=20010911 12:43:21 DL MsgLen= 234 DBI= 4 DIIndicator= 2 DINumStns= 1 BepStnName = EWRB4 SSV=86 (0x56)
<SOH>2.N591UA<NAK>H1<STX>D74AUA0093#DFBEDA/E4 05 <CR><LF> CR><LF> UA0093 1 89 EWR SFO 11 12:42:21 N40.68 W074.2 <CR><LF> CR><LF> 192 0473 -0136 1471 222 0229 00 <CR><LF> CR><LF> 0701 12112 11768 086 0849 0928 1313 1310 1389 0550 0563 10101V<TSTRET> <CR><LF> 1529 0227 338 233 000 000 001 000 03<ETB>

FLoc=306322585 AJPSBcnt= 265 DLBLK S=31 D=21 BEPts=20010911 12:43:24 DL MsgLen= 234 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA4 SSV=72 (0x48)

FLoc=306334329 AJPSBcnt= 265 DLBLK S=31 D=21 BEPts=20010911 12:43:25 DL MsgLen= 234 DBI= 4 DIIndicator= 2 DINumStns= 1 BepStnName = JFKA4 SSV=63 (0x3F)
<SOH>2.N591UA<NAK>H1<STX>D74AUA0093#DFBEDA/E4 05 <CR><LF>
CR><LF>
UA0093 1 89 EWR SFO 11 12:42:21 N40.68 W074.2 <CR><LF>
<CR><LF>
192 0473 -0136 1471 222 0229 00 <CR><LF>
<CR><LF>
0701 12112 11768 086 0849 0928 1313 1310 1389 0550 0563 10101V<TSTRET>
<CR><LF>
1529 0227 338 233 000 000 001 000 03<ETB>

FLoc=306340322 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:43:26 UL MsgLen= 14 Stn= EWRB4 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA4_P<ETX>

1528 0221 336 234 002 000 -01 000 034 034 014 14 15R133 <ETB>

1528 0221 336 234 002 000 -01 000 034 034 014 14 15R133 <ETB>

FLoc=306390407 AJPSBcnt= 265 DLBLK S=31 D=21 BEPts=20010911 12:43:31 DL MsgLen= 234 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = JFKA4 SSV=62 (0x3E)

0689 11600 11192 082 0840 0928 1304 1299 1389 0529 0543 10101V<TSTRET> <CR><LF>

1528 0221 336 234 002 000 -01 000 034 034 014 14 15R133 <ETB>

FLoc=306406261 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:43:33 UL MsgLen= 14 Stn= EWRB4 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA5 Q<ETX>

FLoc=306421500 AJPSBcnt= 620 DLMSG S=31 D=21 BEPts=20010911 12:43:34 ADNS MsgLen= 580 Tail Number= .N591UA SMI= DFD FltId= UA0093 AgyNum= 60 (0x003C)
<CR><LF>
<SOH>QU RURDLXA DCABFXA HDQDLUA <CR><LF>
.DDLXCXA 111243<CR><LF>
<STX>DFD<CR><LF>
FI UAL93/AN N591UA<CR><LF>
DT DDL LGA 111243 D74A<CR><LF>
- EDA/E4 05 <CR><LF>
<CR><LF>
UA0093 1 89 EWR SFO 11 12:42:21 N40.68 W074.2 <CR><LF>

<CR><LF>
192 0473 -0136 1471 222 0229 00 <CR><LF>

<CR><LF>

0701 12112 11768 086 0849 0928 1313 1310 1389 0550 0563 10101V<TSTRET> <CR><LF>

1529 0227 338 233 000 000 001 000 039 039 020 17 15R134 <CR><LF>

0689 11600 11192 082 0840 0928 1304 1299 1389 0529 0543 10101V<TSTRET> <CR><LF>

1528 0221 336 234 002 000 -01 000 034 034 014 14 15R133 <CR><LF>

FLoc=306422836 AJPSBcnt= 121 DLBLK S=31 D=21 BEPts=20010911 12:43:34 DL MsgLen= 90 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = JFKB4 SSV=62 (0x3E) <SOH>2.N591UA<NAK>H1<STX>D74CUA0093#DFB<CR><LF>

FLoc=306422957 AJPSBcnt= 121 DLBLK S=31 D=21 BEPts=20010911 12:43:34

FLoc=306471414 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:43:39 UL MsgLen= 14 Stn= EWRB4 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA6_R<ETX>

FLoc=310438565 AJPSBcnt= 77 DLBLK S=31 D=21 BEPts=20010911 12:50:18 DL MsgLen= 46 DBI= 7 DlIndicator= 1 DlNumStns= 1 BepStnName = LGAC4 SSV=60 (0x3C) <SOH>2.N591UA<NAK>5Z<STX>M78AUA0093/R3 EWRSFO 0093-11 EWR<ETX>

FLoc=310438642 AJPSBcnt= 160 DLMSG S=31 D=21 BEPts=20010911 12:50:18 ADNS MsgLen= 120 Tail Number= .N591UA SMI= AGM FltId= UA0093 AgyNum= 60 (0x003C)
<CR><LF>
<SOH>QU RURDLXA HDQDLUA <CR><LF>
.DDLXCXA 111250<CR><LF>
<STX>AGM<CR><LF>
FI UAL93/AN N591UA<CR><LF>
DT DDL LGA 111250 M78A<CR><LF>
- /R3 EWRSFO 0093-11 EWR<CR><LF>
<ETX><ETX><EOT>

FLoc=310463447 AJPSBcnt= 77 DLBLK S=31 D=21 BEPts=20010911 12:50:20 DL MsgLen= 46 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = JFKA4 SSV=58 (0x3A) <SOH>2.N591UA<NAK>5Z<STX>M78AUA0093/R3 EWRSFO 0093-11 EWR<ETX>

FLoc=310464539 AJPSBcnt= 77 DLBLK S=31 D=21 BEPts=20010911 12:50:20 DL MsgLen= 46 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA4 SSV=64 (0x40) <SOH>2.N591UA<NAK>5Z<STX>M78AUA0093/R3 EWRSFO 0093-11 EWR<ETX>

FLoc=310466807 AJPSBcnt= 437 ULMSG S=31 D=21 BEPts=20010911 12:50:20 ADNS MsgLen= 380 Org Addr= HDQWDUA Org TimeStamp= 20010911 12:49:00 Smi= CMD AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= LGA<00><00> Target Method= 2 <CR><LF>

<SOH>QU DDLXCXA<CR><LF> .HDQWDUA 111249/<CR><LF> <STX>CMD<CR><LF> AN N591UA/GL LGA<CR><LF> QUHDQWDUA~10093-11 HOWGOZIT<CR><LF> UA93 EWRSFO<CR><LF> EWR 1201/1242 490A<CR><LF> PSB 1311 35 432 <CR><LF> 1338 35 400 <CR><LF> DJB 1409 35 363 <CR><LF> 1508 35 296 <CR><LF> MCK 1536 39 263 <CR><LF> **FQF** 1603 39 234 <CR><LF> DBL 1618 39 218 <CR><LF> HVE 1646 39 189 <CR><LF> OAL 1734 39 139 <CR><LF> SFO 1814/1821 114 <CR><LF> <ETX><EOT> FLoc=310488348 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:50:23 UL MsgLen= 235 Stn= EWRB4 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA7RAS<STX>QUHDQWDUA~10093-11 HOWGOZIT<CR><LF> UA93 EWRSFO<CR><LF> EWR 1201/1242 490A<CR><LF> PSB 1311 35 432 <CR><LF> 1338 35 400 <CR><LF> DJB IRK 1445 35 322 <CR><LF> PWE 1508 35 300 1409 35 363 <CR><LF> 1508 35 296 <CR><LF> MCK 1536 39 263 <CR><LF> FQF 1603 39 <ETB> FLoc=310516373 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:50:25 DL MsgLen= 24 DBI= 8 DlIndicator= 1 DlNumStns= 1 BepStnName = LGAC4 SSV=60 (0x3C) <SOH>2.N591UAS_<STX>S46AUA0093<ETX> FLoc=310516483 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:50:25 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = JFKB4 SSV=57 (0x39) <SOH>2.N591UAS_<STX>S46AUA0093<ETX> FLoc=310516538 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:50:25 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRB4 SSV=76 (0x4C)

<SOH>2.N591UAS_<STX>S46AUA0093<ETX>
FLoc=310528110 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:50:27
DL MsqLen= 24 DBI= 8 DlIndicator= 2 DINumStns= 1

FLoc=310528110 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:50:27 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = JFKA4 SSV=54 (0x36) <SOH>2.N591UAS_<STX>S46AUA0093<ETX>

FLoc=310528821 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:50:27 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 2

BepStnName = LGAA4 SSV=59 (0x3B)
BepStnName = DCAA4 SSV=46 (0x2E)
<SOH>2.N591UAS_<STX>S46AUA0093<ETX>

FLoc=310552341 AJPSBcnt= 154 ULBLK S=31 D=21 BEPts=20010911 12:50:30 UL MsgLen= 113 Stn= EWRB4 StnDelivType= 1 Tail= .N591UA Fid= UA0093
<SOH>2.N591UA<NAK>RAT<STX>234 <CR><LF> DBL 1618 39 218 <CR><LF> HVE 1646 39 189 <CR><LF> OAL 1734 39 139 <CR><LF> SFO 1814/1821 114 <CR><LF> <ETX>

FLoc=310586462 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:50:33 DL MsgLen= 24 DBI= 9 DlIndicator= 1 DlNumStns= 1 BepStnName = EWRB4 SSV=76 (0x4C) <SOH>2.N591UAT_<STX>S47AUA0093<ETX>

FLoc=310603854 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:50:34 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA4 SSV=66 (0x42) <SOH>2.N591UAT_<STX>S47AUA0093<ETX>

FLoc=317366295 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:00:32 DL MsgLen= 24 DBI= 0 DlIndicator= 1 DlNumStns= 1 BepStnName = LGAC4 SSV=58 (0x3A) <SOH>2.N591UA<NAK>Q0<STX>S48AUA0093<ETX>

FLoc=317366622 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:00:32 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRB4 SSV=61 (0x3D) <SOH>2.N591UA<NAK>Q0<STX>S48AUA0093<ETX>

FLoc=317368097 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:00:32 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = JFKB4 SSV=56 (0x38) <SOH>2.N591UA<NAK>Q0<STX>S48AUA0093<ETX>

FLoc=317411403 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:00:35 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = EWRA4 SSV=60 (0x3C) <SOH>2.N591UA<NAK>Q0<STX>S48AUA0093<ETX>

FLoc=317414035 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:00:35 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = JFKA4 SSV=55 (0x37) <SOH>2.N591UA<NAK>Q0<STX>S48AUA0093<ETX>

FLoc=317431323 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:00:37 UL MsgLen= 14 Stn= EWRB4 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA0_U<ETX>

FLoc=318909205 AJPSBcnt= 62 ULBLK S=31 D=21 BEPts=20010911 13:02:35 UL MsgLen= 21 Stn= EWRB4 StnDelivType= 12

Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>:;V<STX>130025<ETX>

FLoc=319041635 AJPSBcnt= 62 ULBLK S=31 D=21 BEPts=20010911 13:02:45 UL MsgLen= 21 Stn= EWRB4 StnDelivType= 12 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>:;V<STX>130025<ETX>

FLoc=319164312 AJPSBcnt= 62 ULBLK S=31 D=21 BEPts=20010911 13:02:55 UL MsgLen= 21 Stn= EWRB4 StnDelivType= 12 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>:;V<STX>130025<ETX>

FLoc=319172859 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:55 DL MsgLen= 24 DBI= 1 DlIndicator= 1 DlNumStns= 1 BepStnName = DCAB4 SSV=60 (0x3C) <SOH>2.N591UAV_<STX>S49AUA0093<ETX>

FLoc=319173672 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:55 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = JFKB4 SSV=50 (0x32) <SOH>2.N591UAV <STX>S49AUA0093<ETX>

FLoc=319196018 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 13:02:57 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 2 BepStnName = EWRA4 SSV=60 (0x3C) BepStnName = LGAA4 SSV=53 (0x35) <SOH>2.N591UAV_<STX>S49AUA0093<ETX>

FLoc=319203641 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:58 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = JFKA4 SSV=52 (0x34) <SOH>2.N591UAV_<STX>S49AUA0093<ETX>

FLoc=319206467 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:58 DL MsgLen= 24 DBI= 2 DlIndicator= 1 DlNumStns= 1 BepStnName = PHLC2 SSV=60 (0x3C) <SOH>2.N591UA<NAK>Q0<STX>S50AUA0093<ETX>

FLoc=319206522 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:58 DL MsgLen= 24 DBI= 2 DIIndicator= 2 DINumStns= 1 BepStnName = PITC2 SSV=57 (0x39) <SOH>2.N591UA<NAK>Q0<STX>S50AUA0093<ETX>

FLoc=319206577 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:58 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZC2 SSV=56 (0x38) <SOH>2.N591UA<NAK>Q0<STX>S50AUA0093<ETX>

FLoc=319207202 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:58 DL MsgLen= 24 DBI= 2 DIIndicator= 2 DINumStns= 1 BepStnName = ALBA2 SSV=48 (0x30) <SOH>2.N591UA<NAK>Q0<STX>S50AUA0093<ETX>

FLoc=319207257 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:58 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1

BepStnName = ROCA2 SSV=56 (0x38) <SOH>2.N591UA<NAK>Q0<STX>S50AUA0093<ETX>

FLoc=319208173 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:58 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB2 SSV=48 (0x30) <SOH>2.N591UA<NAK>Q0<STX>S50AUA0093<ETX>

FLoc=319208566 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:58 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = RICA2 SSV=47 (0x2F) <SOH>2.N591UA<NAK>Q0<STX>S50AUA0093<ETX>

FLoc=319208621 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:58 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = JFKB2 SSV=47 (0x2F) <SOH>2.N591UA<NAK>Q0<STX>S50AUA0093<ETX>

FLoc=319208676 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:58 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = BUFB2 SSV=52 (0x34) <SOH>2.N591UA<NAK>Q0<STX>S50AUA0093<ETX>

FLoc=319208731 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:58 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = BDLA2 SSV=32 (0x20) <SOH>2.N591UA<NAK>Q0<STX>S50AUA0093<ETX>

FLoc=319209685 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:58 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB2 SSV=47 (0x2F) <SOH>2.N591UA<NAK>Q0<STX>S50AUA0093<ETX>

FLoc=319217197 AJPSBcnt= 73 DLBLK S=31 D=21 BEPts=20010911 13:02:59 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 4 BepStnName = SYRA2 SSV=57 (0x39) BepStnName = ACYA2 SSV=56 (0x38) BepStnName = AVPA2 SSV=53 (0x35) BepStnName = SWFA2 SSV=47 (0x2F) <SOH>2.N591UA<NAK>QO<STX>S50AUA0093<ETX>

FLoc=319220510 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:59 DL MsgLen= 24 DBI= 2 DIIndicator= 2 DINumStns= 1 BepStnName = ABEA2 SSV=51 (0x33) <SOH>2.N591UA<NAK>Q0<STX>S50AUA0093<ETX>

FLoc=319235098 AJPSBcnt= 67 DLBLK S=31 D=21 BEPts=20010911 13:03:00 DL MsgLen= 24 DBI= 2 DIIndicator= 2 DINumStns= 3 BepStnName = DCAA2 SSV=59 (0x3B) BepStnName = BWIA2 SSV=54 (0x36) BepStnName = EWRA2 SSV=47 (0x2F) <SOH>2.N591UA<NAK>QO<STX>S50AUA0093<ETX>

FLoc=319267322 AJPSBcnt= 62 ULBLK S=31 D=21 BEPts=20010911 13:03:03 UL MsgLen= 21 Stn= PHLC2 StnDelivType= 2 Tail= .N591UA Fid= UA0093

<SOH>2.N591UA2:;W<STX>136800<ETX>

FLoc=319286777 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:03:04 DL MsgLen= 24 DBI= 3 DIIndicator= 1 DINumStns= 1 BepStnName = PHLC2 SSV=60 (0x3C) <SOH>2.N591UAW_<STX>S51AUA0093<ETX>

FLoc=319286832 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:03:04 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = PITC2 SSV=57 (0x39) <SOH>2.N591UAW_<STX>S51AUA0093<ETX>

FLoc=319286887 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:03:04 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZC2 SSV=56 (0x38) <SOH>2.N591UAW_<STX>S51AUA0093<ETX>

FLoc=319286942 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:03:04 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = ALBA2 SSV=48 (0x30) <SOH>2.N591UAW_<STX>S51AUA0093<ETX>

FLoc=319287183 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:03:04 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = ROCA2 SSV=55 (0x37) <SOH>2.N591UAW_<STX>S51AUA0093<ETX>

FLoc=319287424 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:03:04 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB2 SSV=47 (0x2F) <SOH>2.N591UAW_<STX>S51AUA0093<ETX>

FLoc=319287627 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:03:04 DL MsgLen= 24 DBI= 3 DIIndicator= 2 DINumStns= 1 BepStnName = JFKB2 SSV=46 (0x2E) <SOH>2.N591UAW_<STX>S51AUA0093<ETX>

FLoc=319287682 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:03:04 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = BUFB2 SSV=52 (0x34) <SOH>2.N591UAW_<STX>S51AUA0093<ETX>

FLoc=319287847 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:03:04 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = BDLA2 SSV=34 (0x22) <SOH>2.N591UAW_<STX>S51AUA0093<ETX>

FLoc=319289355 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:03:04 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB2 SSV=48 (0x30) <SOH>2.N591UAW_<STX>S51AUA0093<ETX>

FLoc=319300318 AJPSBcnt= 67 DLBLK S=31 D=21 BEPts=20010911 13:03:05 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 3 BepStnName = ABEA2 SSV=51 (0x33) BepStnName = HPNA2 SSV=47 (0x2F)

BepStnName = CAKA2 SSV=36 (0x24) <SOH>2.N591UAW_<STX>S51AUA0093<ETX>

FLoc=319300385 AJPSBcnt= 73 DLBLK S=31 D=21 BEPts=20010911 13:03:05 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 4

BepStnName = SYRA2 SSV=58 (0x3A)
BepStnName = ACYA2 SSV=55 (0x37)
BepStnName = AVPA2 SSV=52 (0x34)

BepStnName = SWFA2 SSV=47 (0x2F)

<SOH>2.N591UAW_<STX>S51AUA0093<ETX>

FLoc=319310641 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:03:06 DL MsgLen= 24 DBI= 4 DlIndicator= 1 DlNumStns= 1 BepStnName = LGAC6 SSV=60 (0x3C)

<SOH>2.N591UA<NAK>Q0<STX>S52AUA0093<ETX>

FLoc=319310696 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:03:06 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = IADC6 SSV=56 (0x38) <SOH>2.N591UA<NAK>Q0<STX>S52AUA0093<ETX>

FLoc=319310751 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:03:06 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZC6 SSV=56 (0x38) <SOH>2.N591UA<NAK>Q0<STX>S52AUA0093<ETX>

FLoc=319310916 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:03:06 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB6 SSV=60 (0x3C) <SOH>2.N591UA<NAK>Q0<STX>S52AUA0093<ETX>

FLoc=319311478 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:03:06 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB6 SSV=50 (0x32) <SOH>2.N591UA<NAK>Q0<STX>S52AUA0093<ETX>

FLoc=319317499 AJPSBcnt= 67 DLBLK S=31 D=21 BEPts=20010911 13:03:06 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 3 BepStnName = BWIA2 SSV=55 (0x37) BepStnName = EWRA2 SSV=46 (0x2E) BepStnName = CLEA2 SSV=33 (0x21) <SOH>2.N591UAW_<STX>S51AUA0093<ETX>

FLoc=319327368 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 13:03:07 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 2 BepStnName = BWIA6 SSV=59 (0x3B) BepStnName = LGAA6 SSV=48 (0x30) <SOH>2.N591UA<NAK>Q0<STX>S52AUA0093<ETX>

FLoc=319338265 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:03:08 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = ORFA6 SSV=43 (0x2B) <SOH>2.N591UA<NAK>Q0<STX>S52AUA0093<ETX>

FLoc=319339742 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:03:08 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1

BepStnName = SYRA6 SSV=54 (0x36) <SOH>2.N591UA<NAK>Q0<STX>S52AUA0093<ETX>

FLoc=319369467 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:03:11 UL MsgLen= 14 Stn= LGAC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA4_X<ETX>

FLoc=320309584 AJPSBcnt= 72 DLBLK S=31 D=21 BEPts=20010911 13:04:26 DL MsgLen= 41 DBI= 5 DlIndicator= 1 DlNumStns= 1 BepStnName = LGAC6 SSV=60 (0x3C) <SOH>2.N591UA<NAK>5Z<STX>M79AUA0093/20 EWRSFO 087030<ETX>

FLoc=320309656 AJPSBcnt= 155 DLMSG S=31 D=21 BEPts=20010911 13:04:26 ADNS MsgLen= 115 Tail Number= N591UA SMI= AGM FItId= UA0093 AgyNum= 60 (0x003C)
<CR><LF>
<SOH>QU RURDLXA HDQDLUA <CR><LF>
.DDLXCXA 111304<CR><LF>
<STX>AGM<CR><LF>
FI UAL93/AN N591UA <CR><LF>
DT DDL LGA 111304 M79A<CR><LF>
- /20 EWRSFO 087030<CR><LF>
<ETX><EOT>

FLoc=320309811 AJPSBcnt= 72 DLBLK S=31 D=21 BEPts=20010911 13:04:26 DL MsgLen= 41 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = IADC6 SSV=56 (0x38) <SOH>2.N591UA<NAK>5Z<STX>M79AUA0093/20 EWRSFO 087030<ETX>

FLoc=320310401 AJPSBcnt= 72 DLBLK S=31 D=21 BEPts=20010911 13:04:26 DL MsgLen= 41 DBI= 5 DIIndicator= 2 DINumStns= 1 BepStnName = BWIB6 SSV=60 (0x3C) <SOH>2.N591UA<NAK>5Z<STX>M79AUA0093/20 EWRSFO 087030<ETX>

FLoc=320311678 AJPSBcnt= 72 DLBLK S=31 D=21 BEPts=20010911 13:04:26 DL MsgLen= 41 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB6 SSV=48 (0x30) <SOH>2.N591UA<NAK>5Z<STX>M79AUA0093/20 EWRSFO 087030<ETX>

FLoc=320320700 AJPSBcnt= 72 DLBLK S=31 D=21 BEPts=20010911 13:04:27 DL MsgLen= 41 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = SYRA6 SSV=58 (0x3A) <SOH>2.N591UA<NAK>5Z<STX>M79AUA0093/20 EWRSFO 087030<ETX>

FLoc=320331391 AJPSBcnt= 78 DLBLK S=31 D=21 BEPts=20010911 13:04:28 DL MsgLen= 41 DBI= 5 DlIndicator= 2 DlNumStns= 2 BepStnName = BWIA6 SSV=60 (0x3C) BepStnName = LGAA6 SSV=52 (0x34) <SOH>2.N591UA<NAK>5Z<STX>M79AUA0093/20 EWRSFO 087030<ETX>

FLoc=320342539 AJPSBcnt= 72 DLBLK S=31 D=21 BEPts=20010911 13:04:29 DL MsgLen= 41 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=60 (0x3C) <SOH>2.N591UA<NAK>5Z<STX>M79AUA0093/20 EWRSFO 087030<ETX>

FLoc=320354355 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:04:31 UL MsgLen= 14 Stn= LGAC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA5_Y<ETX>

FLoc=320445264 AJPSBcnt= 72 DLBLK S=31 D=21 BEPts=20010911 13:04:37 DL MsgLen= 41 DBI= 5 DlIndicator= 3 DlNumStns= 1 BepStnName = PITC6 SSV=60 (0x3C) <SOH>2.N591UA<NAK>5Z<STX>M79AUA0093/20 EWRSFO 087030<ETX>

FLoc=320449220 AJPSBcnt= 72 DLBLK S=31 D=21 BEPts=20010911 13:04:38 DL MsgLen= 41 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB6 SSV=60 (0x3C) <SOH>2.N591UA<NAK>5Z<STX>M79AUA0093/20 EWRSFO 087030<ETX>

FLoc=320474114 AJPSBcnt= 72 DLBLK S=31 D=21 BEPts=20010911 13:04:39 DL MsgLen= 41 DBI= 5 DIIndicator= 2 DINumStns= 1 BepStnName = SYRA6 SSV=57 (0x39) <SOH>2.N591UA<NAK>5Z<STX>M79AUA0093/20 EWRSFO 087030<ETX>

FLoc=320481010 AJPSBcnt= 72 DLBLK S=31 D=21 BEPts=20010911 13:04:40 DL MsgLen= 41 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = LGAA6 SSV=49 (0x31) <SOH>2.N591UA<NAK>5Z<STX>M79AUA0093/20 EWRSFO 087030<ETX>

FLoc=320482061 AJPSBcnt= 72 DLBLK S=31 D=21 BEPts=20010911 13:04:40 DL MsgLen= 41 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=60 (0x3C) <SOH>2.N591UA<NAK>5Z<STX>M79AUA0093/20 EWRSFO 087030<ETX>

FLoc=320503603 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:04:42 UL MsgLen= 14 Stn= LGAC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA5_Z<ETX>

FLoc=327636141 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:14:44 DL MsgLen= 24 DBI= 6 DlIndicator= 1 DlNumStns= 1 BepStnName = LGAC6 SSV=44 (0x2C) <SOH>2.N591UA<NAK>Q0<STX>S53AUA0093<ETX>

FLoc=327636273 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:14:44 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = IADC6 SSV=56 (0x38) <SOH>2.N591UA<NAK>Q0<STX>S53AUA0093<ETX>

FLoc=327637272 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:14:44 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB6 SSV=60 (0x3C) <SOH>2.N591UA<NAK>Q0<STX>S53AUA0093<ETX>

FLoc=327638150 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:14:44 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB6 SSV=56 (0x38) <SOH>2.N591UA<NAK>Q0<STX>S53AUA0093<ETX>

FLoc=327649993 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:14:45

DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = SYRA6 SSV=54 (0x36) <SOH>2.N591UA<NAK>Q0<STX>S53AUA0093<ETX>

FLoc=327651356 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:14:45 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=51 (0x33) <SOH>2.N591UA<NAK>Q0<STX>S53AUA0093<ETX>

FLoc=327661382 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 13:14:46 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 2 BepStnName = BWIA6 SSV=55 (0x37) BepStnName = DTWB6 SSV=52 (0x34) <SOH>2.N591UA<NAK>Q0<STX>S53AUA0093<ETX>

FLoc=327689192 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:14:49 UL MsgLen= 14 Stn= BWIB6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA6_A<ETX>

FLoc=332278767 AJPSBcnt= 213 DLBLK S=31 D=21 BEPts=20010911 13:21:20 DL MsgLen= 182 DBI= 7 DIIndicator= 1 DINumStns= 1 BepStnName = PITC6 SSV=76 (0x4C)
<SOH>2.N591UA<NAK>5Z<STX>M80AUA0093/C4 EWRSFO GOOD MORNIN'...N<TSTRET> ICE CLB<CR><LF>
OUTTA EWR AFTER A NICE<CR><LF>
TOUR OF THE APT COURTS<CR><LF>
Y GRND CNTRL. 20 N EWC<CR><LF>
AT 350 OCCL LT CHOP WI<CR><LF>
ND 290/50 AINT HELPIN J<ETX>

FLoc=332278980 AJPSBcnt= 296 DLMSG S=31 D=21 BEPts=20010911 13:21:20 ADNS MsgLen= 256 Tail Number= .N591UA SMI= AGM FltId= UA0093 AgyNum= 60 (0x003C) <CR><LF> <SOH>QU RURDLXA HDQDLUA <CR><LF> .DDLXCXA 111321<CR><LF> <STX>AGM<CR><LF> FI UAL93/AN N591UA<CR><LF> DT DDL PIT 111321 M80A<CR><LF> - /C4 EWRSFO GOOD MORNIN'...NICE CLB<CR><LF> OUTTA EWR AFTER A NICE<CR><LF> TOUR OF THE APT COURTS<CR><LF> Y GRND CNTRL. 20 N EWC<CR><LF> AT 350 OCCL LT CHOP WI<CR><LF> ND 290/50 AINT HELPIN J<CR><LF> <ETX><EOT>

FLoc=332279331 AJPSBcnt= 213 DLBLK S=31 D=21 BEPts=20010911 13:21:20 DL MsgLen= 182 DBI= 7 DlIndicator= 2 DINumStns= 1 BepStnName = IADC6 SSV=52 (0x34) <SOH>2.N591UA<NAK>5Z<STX>M80AUA0093/C4 EWRSFO GOOD MORNIN'...N<TSTRET> ICE CLB<CR><LF> OUTTA EWR AFTER A NICE<CR><LF> TOUR OF THE APT COURTS<CR><LF> Y GRND CNTRL. 20 N EWC<CR><LF>

AT 350 OCCL LT CHOP WI<CR><LF>ND 290/50 AINT HELPIN J<ETX>

FLoc=332282463 AJPSBcnt= 213 DLBLK S=31 D=21 BEPts=20010911 13:21:20 DL MsgLen= 182 DBI= 7 DlIndicator= 2 DINumStns= 1 BepStnName = YYZB6 SSV=57 (0x39)
<SOH>2.N591UA<NAK>5Z<STX>M80AUA0093/C4 EWRSFO GOOD MORNIN'...N<TSTRET> ICE CLB<CR><LF> OUTTA EWR AFTER A NICE<CR><LF> TOUR OF THE APT COURTS<CR><LF> Y GRND CNTRL. 20 N EWC<CR><LF> AT 350 OCCL LT CHOP WI<CR><LF> ND 290/50 AINT HELPIN J<ETX>

FLoc=332293433 AJPSBcnt= 213 DLBLK S=31 D=21 BEPts=20010911 13:21:21 DL MsgLen= 182 DBI= 7 DlIndicator= 2 DINumStns= 1 BepStnName = SYRA6 SSV=48 (0x30)
<SOH>2.N591UA<NAK>5Z<STX>M80AUA0093/C4 EWRSFO GOOD MORNIN'...N<TSTRET> ICE CLB<CR><LF>
OUTTA EWR AFTER A NICE<CR><LF>
TOUR OF THE APT COURTS<CR><LF>
Y GRND CNTRL. 20 N EWC<CR><LF>
AT 350 OCCL LT CHOP WI<CR><LF>
ND 290/50 AINT HELPIN J<ETX>

FLoc=332303041 AJPSBcnt= 213 DLBLK S=31 D=21 BEPts=20010911 13:21:22 DL MsgLen= 182 DBI= 7 DlIndicator= 2 DINumStns= 1 BepStnName = HTSA6 SSV=47 (0x2F)

<SOH>2.N591UA<NAK>5Z<STX>M80AUA0093/C4 EWRSFO GOOD MORNIN'...N<TSTRET> ICE CLB<CR><LF>
OUTTA EWR AFTER A NICE<CR><LF>
TOUR OF THE APT COURTS<CR><LF>
Y GRND CNTRL. 20 N EWC<CR><LF>
AT 350 OCCL LT CHOP WI<CR><LF>
ND 290/50 AINT HELPIN J<ETX>

FLoc=332307095 AJPSBcnt= 219 DLBLK S=31 D=21 BEPts=20010911 13:21:22 DL MsgLen= 182 DBI= 7 DIIndicator= 2 DINumStns= 2 BepStnName = DTWB6 SSV=56 (0x38)
BepStnName = BWIA6 SSV=53 (0x35)
<SOH>2.N591UA<NAK>5Z<STX>M80AUA0093/C4 EWRSFO GOOD MORNIN'...N<TSTRET> ICE CLB<CR><LF>
OUTTA EWR AFTER A NICE<CR><LF>
TOUR OF THE APT COURTS<CR><LF>
Y GRND CNTRL. 20 N EWC<CR><LF>
AT 350 OCCL LT CHOP WI<CR><LF>
ND 290/50 AINT HELPIN J<ETX>

FLoc=332311698 AJPSBcnt= 213 DLBLK S=31 D=21 BEPts=20010911 13:21:23
DL MsgLen= 182 DBI= 7 DlIndicator= 2 DlNumStns= 1
BepStnName = CRWA6 SSV=56 (0x38)
<SOH>2.N591UA<NAK>5Z<STX>M80AUA0093/C4 EWRSFO GOOD MORNIN'...N<TSTRET>
ICE CLB<CR><LF>
OUTTA EWR AFTER A NICE<CR><LF>
TOUR OF THE APT COURTS<CR><LF>
Y GRND CNTRL. 20 N EWC<CR><LF>

AT 350 OCCL LT CHOP WI<CR><LF>ND 290/50 AINT HELPIN J<ETX>

FLoc=332340111 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:21:25 UL MsgLen= 14 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA7_B<ETX>

FLoc=332464446 AJPSBcnt= 213 DLBLK S=31 D=21 BEPts=20010911 13:21:34 DL MsgLen= 182 DBI= 7 DIIndicator= 3 DINumStns= 1 BepStnName = DTWA6 SSV=51 (0x33)
<SOH>2.N591UA<NAK>5Z<STX>M80AUA0093/C4 EWRSFO GOOD MORNIN'...N<TSTRET> ICE CLB<CR><LF>
OUTTA EWR AFTER A NICE<CR><LF>
TOUR OF THE APT COURTS<CR><LF>
Y GRND CNTRL. 20 N EWC<CR><LF>
AT 350 OCCL LT CHOP WI<CR><LF>
ND 290/50 AINT HELPIN J<ETX>

FLoc=332464769 AJPSBcnt= 213 DLBLK S=31 D=21 BEPts=20010911 13:21:34 DL MsgLen= 182 DBI= 7 DlIndicator= 2 DINumStns= 1 BepStnName = IADC6 SSV=48 (0x30) <SOH>2.N591UA<NAK>5Z<STX>M80AUA0093/C4 EWRSFO GOOD MORNIN'...N<TSTRET> ICE CLB<CR><LF> OUTTA EWR AFTER A NICE<CR><LF> TOUR OF THE APT COURTS<CR><LF> Y GRND CNTRL. 20 N EWC<CR><LF> AT 350 OCCL LT CHOP WI<CR><LF> ND 290/50 AINT HELPIN J<ETX>

FLoc=332467974 AJPSBcnt= 213 DLBLK S=31 D=21 BEPts=20010911 13:21:35 DL MsgLen= 182 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB6 SSV=48 (0x30)
<SOH>2.N591UA<NAK>5Z<STX>M80AUA0093/C4 EWRSFO GOOD MORNIN'...N<TSTRET> ICE CLB<CR><LF>
OUTTA EWR AFTER A NICE<CR><LF>
TOUR OF THE APT COURTS<CR><LF>
Y GRND CNTRL. 20 N EWC<CR><LF>
AT 350 OCCL LT CHOP WI<CR><LF>
ND 290/50 AINT HELPIN J<ETX>

FLoc=332468965 AJPSBcnt= 213 DLBLK S=31 D=21 BEPts=20010911 13:21:35 DL MsgLen= 182 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB6 SSV=56 (0x38) <SOH>2.N591UA<NAK>5Z<STX>M80AUA0093/C4 EWRSFO GOOD MORNIN'...N<TSTRET> ICE CLB<CR><LF> OUTTA EWR AFTER A NICE<CR><LF> TOUR OF THE APT COURTS<CR><LF> Y GRND CNTRL. 20 N EWC<CR><LF> AT 350 OCCL LT CHOP WI<CR><LF> ND 290/50 AINT HELPIN J<ETX>

FLoc=332488661 AJPSBcnt= 219 DLBLK S=31 D=21 BEPts=20010911 13:21:36 DL MsgLen= 182 DBI= 7 DIIndicator= 2 DINumStns= 2 BepStnName = IADA6 SSV=58 (0x3A) BepStnName = CRWA6 SSV=55 (0x37)

<SOH>2.N591UA<NAK>5Z<STX>M80AUA0093/C4 EWRSFO GOOD MORNIN'...N<TSTRET> ICE CLB<CR><LF>
OUTTA EWR AFTER A NICE<CR><LF>
TOUR OF THE APT COURTS<CR><LF>
Y GRND CNTRL. 20 N EWC<CR><LF>
AT 350 OCCL LT CHOP WI<CR><LF>
ND 290/50 AINT HELPIN J<ETX>

FLoc=332494082 AJPSBcnt= 213 DLBLK S=31 D=21 BEPts=20010911 13:21:37 DL MsgLen= 182 DBI= 7 DlIndicator= 2 DINumStns= 1 BepStnName = SYRA6 SSV=47 (0x2F)
<SOH>2.N591UA<NAK>5Z<STX>M80AUA0093/C4 EWRSFO GOOD MORNIN'...N<TSTRET> ICE CLB<CR><LF> OUTTA EWR AFTER A NICE<CR><LF> TOUR OF THE APT COURTS<CR><LF> Y GRND CNTRL. 20 N EWC<CR><LF> AT 350 OCCL LT CHOP WI<CR><LF> ND 290/50 AINT HELPIN J<ETX>

FLoc=332497211 AJPSBcnt= 213 DLBLK S=31 D=21 BEPts=20010911 13:21:37 DL MsgLen= 182 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIA6 SSV=54 (0x36)
<SOH>2.N591UA<NAK>5Z<STX>M80AUA0093/C4 EWRSFO GOOD MORNIN'...N<TSTRET> ICE CLB<CR><LF> OUTTA EWR AFTER A NICE<CR><LF> TOUR OF THE APT COURTS<CR><LF> Y GRND CNTRL. 20 N EWC<CR><LF> AT 350 OCCL LT CHOP WI<CR><LF> ND 290/50 AINT HELPIN J<ETX>

FLoc=332510776 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:21:39 UL MsgLen= 14 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA7_C<ETX>

FLoc=333069153 AJPSBcnt= 254 ULMSG S=31 D=21 BEPts=20010911 13:22:26 ADNS MsgLen= 197 Org Addr= JFKFOUA Org TimeStamp= 20010911 13:22:00 Smi= AGM AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= PIT<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .JFKFOUA 111322/TAR<CR><LF> <STX>AGM<CR><LF> AN N591UA/GL PIT<CR><LF> - UA93 EWRSFO<CR><LF> LEROY, MELODY WANTS TO MAKE SURE YOU ARE O.K.!<CR><LF> SEND ME BACK A MESSAGE.<CR><LF> JFKFO TARA CAMPBELL <CR><LF> <ETX><EOT>

FLoc=333069407 AJPSBcnt= 235 ULBLK S=31 D=21 BEPts=20010911 13:22:26 UL MsgLen= 194 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>C1D<STX>.JFKFOUA 111322/TAR<CR><LF> AGM<CR><LF>

AN N591UA/GL PIT<CR><LF>
- UA93 EWRSFO<CR><LF>
LEROY, MELODY WANTS TO MAKE SURE YOU ARE O.K.!<CR><LF>
SEND ME BACK A MESSAGE.<CR><LF>
JFKFO TARA CAMPBELL <CR><LF>
<ETX>

FLoc=333200738 AJPSBcnt= 235 ULBLK S=31 D=21 BEPts=20010911 13:22:36 UL MsgLen= 194 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>C1D<STX>.JFKFOUA 111322/TAR<CR><LF> AGM<CR><LF> AN N591UA/GL PIT<CR><LF> - UA93 EWRSFO<CR><LF> LEROY, MELODY WANTS TO MAKE SURE YOU ARE O.K.!<CR><LF> SEND ME BACK A MESSAGE.<CR><LF> JFKFO TARA CAMPBELL <CR><LF> <ETX>

FLoc=333326928 AJPSBcnt= 235 ULBLK S=31 D=21 BEPts=20010911 13:22:46 UL MsgLen= 194 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>C1D<STX>.JFKFOUA 111322/TAR<CR><LF> AGM<CR><LF> AN N591UA/GL PIT<CR><LF> - UA93 EWRSFO<CR><LF> LEROY, MELODY WANTS TO MAKE SURE YOU ARE O.K.!<CR><LF> SEND ME BACK A MESSAGE.<CR><LF> JFKFO TARA CAMPBELL <CR><LF> <ETX>

FLoc=333442532 AJPSBcnt= 235 ULBLK S=31 D=21 BEPts=20010911 13:22:56 UL MsgLen= 194 Stn= PITC6 StnDelivType= 2
Tail= .N591UA Fid= UA0093
<SOH>2.N591UA<NAK>C1D<STX>.JFKFOUA 111322/TAR<CR><LF>
AGM<CR><LF>
AN N591UA/GL PIT<CR><LF>
- UA93 EWRSFO<CR><LF>
LEROY, MELODY WANTS TO MAKE SURE YOU ARE O.K.!<CR><LF>
SEND ME BACK A MESSAGE.<CR><LF>
JFKFO TARA CAMPBELL <CR><LF>
<ETX>

FLoc=333472431 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:22:58 DL MsgLen= 24 DBI= 8 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=79 (0x4F) <SOH>2.N591UA<NAK>_<STX>S54AUA0093<ETX>

FLoc=333472486 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:22:58 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = DTWA6 SSV=60 (0x3C) <SOH>2.N591UA<NAK>_<STX>S54AUA0093<ETX>

FLoc=333472541 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:22:58 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = IADC6 SSV=48 (0x30)

<SOH>2.N591UA<NAK>_<STX>S54AUA0093<ETX>

FLoc=333472994 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:22:58 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB6 SSV=49 (0x31) <SOH>2.N591UA<NAK>_<STX>S54AUA0093<ETX>

FLoc=333474251 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:22:58 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB6 SSV=56 (0x38) <SOH>2.N591UA<NAK>_<STX>S54AUA0093<ETX>

FLoc=333492799 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:22:59 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = SYRA6 SSV=47 (0x2F) <SOH>2.N591UA<NAK>_<STX>S54AUA0093<ETX>

FLoc=333493019 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:22:59 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=56 (0x38) <SOH>2.N591UA<NAK>_<STX>S54AUA0093<ETX>

FLoc=333495106 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:22:59 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIA6 SSV=53 (0x35) <SOH>2.N591UA<NAK>_<STX>S54AUA0093<ETX>

FLoc=333554394 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:23:05 DL MsgLen= 24 DBI= 9 DIIndicator= 1 DINumStns= 1 BepStnName = IADC6 SSV=48 (0x30) <SOH>2.N591UAD_<STX>S55AUA0093<ETX>

FLoc=333555574 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:23:05 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = PITC6 SSV=78 (0x4E) <SOH>2.N591UAD_<STX>S55AUA0093<ETX>

FLoc=333556670 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:23:05 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB6 SSV=49 (0x31) <SOH>2.N591UAD_<STX>S55AUA0093<ETX>

FLoc=333556904 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:23:05 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DINumStns= 1

BepStnName = YYZA6 SSV=60 (0x3C) <SOH>2.N591UAD_<STX>S55AUA0093<ETX>

<ETX><EOT>

FLoc=333557622 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:23:05 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB6 SSV=58 (0x3A) <SOH>2.N591UAD_<STX>S55AUA0093<ETX>

FLoc=333574559 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:23:06 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = SYRA6 SSV=48 (0x30) <SOH>2.N591UAD_<STX>S55AUA0093<ETX>

FLoc=333575568 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:23:06 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = PITA6 SSV=65 (0x41) <SOH>2.N591UAD_<STX>S55AUA0093<ETX>

FLoc=333592545 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:23:08 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIA6 SSV=53 (0x35) <SOH>2.N591UAD_<STX>S55AUA0093<ETX>

FLoc=334534824 AJPSBcnt= 299 ULMSG S=31 D=21 BEPts=20010911 13:24:24 ADNS MsgLen= 242 Org Addr= CHIAKUA Org TimeStamp= 20010911 13:23:00 Smi= CMD AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= PIT<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .CHIAKUA 111323/ED <CR><LF> <STX>CMD<CR><LF> AN N591UA/GL PIT<CR><LF> - QUCHIAKUA~1UA93 EWRSFO<CR><LF> - MESSAGE FROM CHIDD -<CR><LF> /BEWARE ANY COCKPIT INTROUSION. . TWO AIRCAFT IN NY , HIT TRAD<TSTRET> E C<CR><LF> NTER BUILDS...<CR><LF> CHIDD ED BALLINGER <CR><LF>

FLoc=334535123 AJPSBcnt= 234 ULBLK S=31 D=21 BEPts=20010911 13:24:24 UL MsgLen= 193 Stn= PITC6 StnDelivType= 1 Tail= .N591UA Fid= UA0093
<SOH>2.N591UA<NAK>RAE<STX>QUCHIAKUA~1UA93 EWRSFO<CR><LF> - MESSAGE FROM CHIDD -<CR><LF> /BEWARE ANY COCKPIT INTROUSION. . TWO AIRCAFT IN NY , HIT TRAD<TSTRET> E C<CR><LF> NTER BUILDS...<CR><LF> CHIDD ED BALLINGER <CR><LF> <ETX>

FLoc=334653543 AJPSBcnt= 234 ULBLK S=31 D=21 BEPts=20010911 13:24:34 UL MsgLen= 193 Stn= PITC6 StnDelivType= 1 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAE<STX>QUCHIAKUA~1UA93 EWRSFO<CR><LF>

- MESSAGE FROM CHIDD -<CR><LF>
/BEWARE ANY COCKPIT INTROUSION. . TWO AIRCAFT IN NY , HIT TRAD<TSTRET>
E C<CR><LF>
NTER BUILDS...<CR><LF>
CHIDD ED BALLINGER <CR><LF>
<ETX>

FLoc=334684117 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:24:36 DL MsgLen= 24 DBI= 0 DlIndicator= 1 DlNumStns= 1 BepStnName = BWIB6 SSV=50 (0x32) <SOH>2.N591UAE_<STX>S56AUA0093<ETX>

FLoc=334684444 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:24:36 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB6 SSV=56 (0x38) <SOH>2.N591UAE_<STX>S56AUA0093<ETX>

FLoc=334696664 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:24:37 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = SYRA6 SSV=45 (0x2D) <SOH>2.N591UAE_<STX>S56AUA0093<ETX>

FLoc=334697331 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:24:37 DL MsgLen= 24 DBI= 0 DIIndicator= 2 DINumStns= 1 BepStnName = CRWA6 SSV=56 (0x38) <SOH>2.N591UAE_<STX>S56AUA0093<ETX>

FLoc=334699058 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:24:37 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=51 (0x33) <SOH>2.N591UAE_<STX>S56AUA0093<ETX>

FLoc=334704775 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:24:38 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIA6 SSV=52 (0x34) <SOH>2.N591UAE_<STX>S56AUA0093<ETX>

FLoc=335757925 AJPSBcnt= 103 DLBLK S=31 D=21 BEPts=20010911 13:26:10 DL MsgLen= 72 DBI= 1 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=77 (0x4D) <SOH>2.N591UA<NAK>5Z<STX>M81AUA0093/C4 EWRSFO ED COFIRM LATEST<TSTRET> MSSG P<CR><LF> LZ JASON<CR><LF> <ETX>

FLoc=335758028 AJPSBcnt= 186 DLMSG S=31 D=21 BEPts=20010911 13:26:10 ADNS MsgLen= 146 Tail Number= .N591UA SMI= AGM FltId= UA0093 AgyNum= 60 (0x003C) <CR><LF> <SOH>QU RURDLXA HDQDLUA <CR><LF> .DDLXCXA 111326<CR><LF> <STX>AGM<CR><LF> FI UAL93/AN N591UA<CR><LF> DT DDL PIT 111326 M81A<CR><LF> - /C4 EWRSFO ED COFIRM LATEST MSSG P<CR><LF> LZ JASON<

<CR><LF><ETX><EOT>

FLoc=335758269 AJPSBcnt= 103 DLBLK S=31 D=21 BEPts=20010911 13:26:10 DL MsgLen= 72 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = DTWA6 SSV=60 (0x3C) <SOH>2.N591UA<NAK>5Z<STX>M81AUA0093/C4 EWRSFO ED COFIRM LATEST<TSTRET> MSSG P<CR><LF> LZ JASON<CR><LF> <ETX>

FLoc=335758372 AJPSBcnt= 103 DLBLK S=31 D=21 BEPts=20010911 13:26:10
DL MsgLen= 72 DBI= 1 DlIndicator= 2 DlNumStns= 1
BepStnName = YYZC6 SSV=56 (0x38)
<SOH>2.N591UA<NAK>5Z<STX>M81AUA0093/C4 EWRSFO ED COFIRM LATEST<TSTRET>
MSSG P<CR><LF>
LZ JASON<CR><LF>
<FTX>

FLoc=335758530 AJPSBcnt= 103 DLBLK S=31 D=21 BEPts=20010911 13:26:10 DL MsgLen= 72 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = IADC6 SSV=45 (0x2D) <SOH>2.N591UA<NAK>5Z<STX>M81AUA0093/C4 EWRSFO ED COFIRM LATEST<TSTRET> MSSG P<CR><LF> LZ JASON<CR><LF> <ETX>

FLoc=335759637 AJPSBcnt= 103 DLBLK S=31 D=21 BEPts=20010911 13:26:10 DL MsgLen= 72 DBI= 1 DlIndicator= 2 DINumStns= 1 BepStnName = BWIB6 SSV=43 (0x2B) <SOH>2.N591UA<NAK>5Z<STX>M81AUA0093/C4 EWRSFO ED COFIRM LATEST<TSTRET> MSSG P<CR><LF> LZ JASON<CR><LF> <ETX>

FLoc=335759740 AJPSBcnt= 103 DLBLK S=31 D=21 BEPts=20010911 13:26:10 DL MsgLen= 72 DBI= 1 DlIndicator= 2 DINumStns= 1 BepStnName = YYZA6 SSV=53 (0x35) <SOH>2.N591UA<NAK>5Z<STX>M81AUA0093/C4 EWRSFO ED COFIRM LATEST<TSTRET> MSSG P<CR><LF> LZ JASON<CR><LF> <ETX>

FLoc=335760715 AJPSBcnt= 103 DLBLK S=31 D=21 BEPts=20010911 13:26:10 DL MsgLen= 72 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB6 SSV=57 (0x39) <SOH>2.N591UA<NAK>5Z<STX>M81AUA0093/C4 EWRSFO ED COFIRM LATEST<TSTRET> MSSG P<CR><LF> LZ JASON<CR><LF> <ETX>

FLoc=335774954 AJPSBcnt= 103 DLBLK S=31 D=21 BEPts=20010911 13:26:11 DL MsgLen= 72 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=50 (0x32) <SOH>2.N591UA<NAK>5Z<STX>M81AUA0093/C4 EWRSFO ED COFIRM LATEST<TSTRET> MSSG P<CR><LF>

```
LZ JASON<CR><LF><ETX>
```

FLoc=335778115 AJPSBcnt= 103 DLBLK S=31 D=21 BEPts=20010911 13:26:11 DL MsgLen= 72 DBI= 1 DlIndicator= 2 DiNumStns= 1 BepStnName = SYRA6 SSV=44 (0x2C) <SOH>2.N591UA<NAK>5Z<STX>M81AUA0093/C4 EWRSFO ED COFIRM LATEST<TSTRET> MSSG P<CR><LF> LZ JASON<CR><LF> <ETX>

FLoc=335785826 AJPSBcnt= 115 DLBLK S=31 D=21 BEPts=20010911 13:26:12
DL MsgLen= 72 DBI= 1 DlIndicator= 2 DlNumStns= 3
BepStnName = PITA6 SSV=66 (0x42)
BepStnName = CRWA6 SSV=57 (0x39)
BepStnName = IADA6 SSV=55 (0x37)
<SOH>2.N591UA<NAK>5Z<STX>M81AUA0093/C4 EWRSFO ED COFIRM LATEST<TSTRET>
MSSG P<CR><LF>
LZ JASON<CR><LF>
<ETX>

FLoc=335820529 AJPSBcnt= 109 DLBLK S=31 D=21 BEPts=20010911 13:26:14
DL MsgLen= 72 DBI= 1 DlIndicator= 2 DINumStns= 2
BepStnName = DTWB6 SSV=57 (0x39)
BepStnName = BWIA6 SSV=50 (0x32)
<SOH>2.N591UA<NAK>5Z<STX>M81AUA0093/C4 EWRSFO ED COFIRM LATEST<TSTRET>
MSSG P<CR><LF>
LZ JASON<CR><LF>
<ETX>

FLoc=335822739 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:26:15 UL MsgLen= 14 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA1_F<ETX>

FLoc=337246560 AJPSBcnt= 265 DLBLK S=31 D=21 BEPts=20010911 13:28:16 DL MsgLen= 234 DBI= 2 DlIndicator= 1 DINumStns= 1 BepStnName = DTWA6 SSV=60 (0x3C)
<SOH>2.N591UA<NAK>H1<STX>D75AUA0093#DFBEDA/E1 12 <CR><LF> <CR><LF> UA0093 1 89 EWR SFO 11 13:26:36 N41.20 W080.5 1 <CR><LF> <CR><LF> 184 0405 35000 2808 825 -210 00 <CR><LF> <CR><LF> <CR><LF> 0594 03812 03840 117 0809 0868 1192 1191 1443 0423 10101V<CR><LF> 0539 -204 126 232 000 100 100 001 012 0<ETB>

0594 03812 03840 117 0809 0868 1192 1191 1443 0423 10101V<CR><LF> 0539 -204 126 232 000 100 100 001 012 0<ETB>

FLoc=337252918 AJPSBcnt= 265 DLBLK S=31 D=21 BEPts=20010911 13:28:17 DL MsgLen= 234 DBI= 2 DIIndicator= 2 DINumStns= 1 BepStnName = YYZB6 SSV=56 (0x38)
<SOH>2.N591UA<NAK>H1<STX>D75AUA0093#DFBEDA/E1 12 <CR><LF> <CR><LF> UA0093 1 89 EWR SFO 11 13:26:36 N41.20 W080.5 1 <CR><LF> <CR><LF> 184 0405 35000 2808 825 -210 00 <CR><LF> <CR><LF> <CR><LF> 0594 03812 03840 117 0809 0868 1192 1191 1443 0423 10101V<CR><LF> 0539 -204 126 232 000 100 100 001 012 0<ETB>

FLoc=337296729 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:28:21 UL MsgLen= 14 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA2_G<ETX>

FLoc=337298150 AJPSBcnt= 265 DLBLK S=31 D=21 BEPts=20010911 13:28:21 DL MsgLen= 234 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = DTWB6 SSV=55 (0x37)
<SOH>2.N591UA<NAK>H1<STX>D75AUA0093#DFBEDA/E1 12 <CR><LF> <CR><LF> UA0093 1 89 EWR SFO 11 13:26:36 N41.20 W080.5 1 <CR><LF> <CR><LF> 184 0405 35000 2808 825 -210 00 <CR><LF> <CR><LF> 0594 03812 03840 117 0809 0868 1192 1191 1443 0423 10101V<CR><LF> 0539 -204 126 232 000 100 100 001 012 0<ETB>

FLoc=337328663 AJPSBcnt= 265 DLBLK S=31 D=21 BEPts=20010911 13:28:23 DL MsgLen= 234 DBI= 3 DlIndicator= 2 DlNumStns= 1

FLoc=337375964 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:28:28 UL MsgLen= 14 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA3_H<ETX>

FLoc=337386575 AJPSBcnt= 115 DLBLK S=31 D=21 BEPts=20010911 13:28:29 DL MsgLen= 84 DBI= 4 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=76 (0x4C) <SOH>2.N591UA<NAK>H1<STX>D75CUA0093#DFB020V0020V0000V0000V0000VTSTRET> V0000V0000V0000V0000V0000V0000V0000V <ETX>

FLoc=337386690 AJPSBcnt= 115 DLBLK S=31 D=21 BEPts=20010911 13:28:29 DL MsgLen= 84 DBI= 4 DlIndicator= 2 DINumStns= 1 BepStnName = DTWA6 SSV=60 (0x3C) <SOH>2.N591UA<NAK>H1<STX>D75CUA0093#DFB020V0020V0000V0000V0000VTSTRET> V0000V0000V0000V0000V0000V0000V0000V <ETX>

FLoc=337386921 AJPSBcnt= 614 DLMSG S=31 D=21 BEPts=20010911 13:28:29 ADNS MsgLen= 574 Tail Number= .N591UA SMI= DFD FltId= UA0093 AgyNum= 60 (0x003C)
<CR><LF>
<SOH>QU RURDLXA DCABFXA HDQDLUA <CR><LF>
.DDLXCXA 111328<CR><LF>
<STX>DFD<CR><LF>
FI UAL93/AN N591UA<CR><LF>
DT DDL DTW 111328 D75A<CR><LF>
- EDA/E1 12 <CR><LF>

FLoc=337389011 AJPSBcnt= 115 DLBLK S=31 D=21 BEPts=20010911 13:28:29 DL MsgLen= 84 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZA6 SSV=54 (0x36) <SOH>2.N591UA<NAK>H1<STX>D75CUA0093#DFB020V0020V0000V0000V0000<TSTRET> V0000V0000V0000V0000V0000V0000V <ETX>

FLoc=337389436 AJPSBcnt= 115 DLBLK S=31 D=21 BEPts=20010911 13:28:29 DL MsgLen= 84 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB6 SSV=56 (0x38) <SOH>2.N591UA<NAK>H1<STX>D75CUA0093#DFB020V0020V0000V0000V0000<TSTRET> V0000V0000V0000V0000V0000V0000V <ETX>

FLoc=337409942 AJPSBcnt= 121 DLBLK S=31 D=21 BEPts=20010911 13:28:31 DL MsgLen= 84 DBI= 4 DlIndicator= 2 DlNumStns= 2 BepStnName = PITA6 SSV=66 (0x42) BepStnName = CRWA6 SSV=57 (0x39) <SOH>2.N591UA<NAK>H1<STX>D75CUA0093#DFB020V0020V0000V0000V0000<TSTRET> V0000V0000V0000V0000V0000V0000V <ETX>

FLoc=337415263 AJPSBcnt= 115 DLBLK S=31 D=21 BEPts=20010911 13:28:32 DL MsgLen= 84 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = DTWB6 SSV=54 (0x36) <SOH>2.N591UA<NAK>H1<STX>D75CUA0093#DFB020V0020V0000V0000V0000VTSTRET> V0000V0000V0000V0000V0000V0000V0000V <ETX>

FLoc=337433600 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:28:34 UL MsgLen= 14 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA4_I<ETX>

FLoc=339784708 AJPSBcnt= 253 ULMSG S=31 D=21 BEPts=20010911 13:32:02 ADNS MsgLen= 196 Org Addr= CHIYRUA Org TimeStamp= 20010911 13:31:00 Smi= CMD AgyNum= 65535
Tail Number= .N591UA FltId= UA0093
Target Stn= CAK<00><00> Target Method= 2
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.CHIYRUA 111331/AD <CR><LF>
<STX>CMD<CR><LF>
AN N591UA/GL CAK<CR><LF>
- QUCHIYRUA~1UA93 EWRSFO<CR><LF>

- MESSAGE FROM CHIDD -<CR><LF>
CENTER LOOKIN FOR YA ASAP ON 133.37<CR><LF>
CHIDD AD ROGERS <CR><LF>
<ETX><EOT>

FLoc=339784961 AJPSBcnt= 188 ULBLK S=31 D=21 BEPts=20010911 13:32:02 UL MsgLen= 147 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAJ<STX>QUCHIYRUA~1UA93 EWRSFO<CR><LF>- MESSAGE FROM CHIDD -<CR><LF> CENTER LOOKIN FOR YA ASAP ON 133.37<CR><LF> CHIDD AD ROGERS <CR><LF> <ETX>

FLoc=339848393 AJPSBcnt= 233 ULMSG S=31 D=21 BEPts=20010911 13:32:07 ADNS MsgLen= 176 Org Addr= CHIVNUA Org TimeStamp= 20010911 13:32:00 Smi= CMD AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= CAK<00><00> Target Method= 2 <CR>><LF> <SOH>QU DDLXCXA<CR><LF> .CHIVNUA 111332/ROB<CR><LF> <STX>CMD<CR><LF> AN N591UA/GL CAK<CR><LF> - QUCHIVNUA~1<BEL>UA93 EWRSFO<CR><LF> MESSAGE FROM CHIDD -<CR><LF> CALLL 133.37<CR><LF> <CR><LF> <CR><LF> CHIDD ROBERT BRITTAIN <ETX><EOT>

FLoc=339900732 AJPSBcnt= 188 ULBLK S=31 D=21 BEPts=20010911 13:32:12 UL MsgLen= 147 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAJ<STX>QUCHIYRUA~1UA93 EWRSFO<CR><LF> - MESSAGE FROM CHIDD -<CR><LF> CENTER LOOKIN FOR YA ASAP ON 133.37<CR><LF> CHIDD AD ROGERS <CR><LF> <ETX>

FLoc=339923288 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:32:13 DL MsgLen= 24 DBI= 5 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=76 (0x4C) <SOH>2.N591UAJ_<STX>S57AUA0093<ETX>

FLoc=339923663 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:32:13 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = IADC6 SSV=42 (0x2A) <SOH>2.N591UAJ_<STX>S57AUA0093<ETX>

FLoc=339924179 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:32:13 DL MsgLen= 24 DBI= 5 DIIndicator= 2 DINumStns= 1 BepStnName = CVGA6 SSV=44 (0x2C) <SOH>2.N591UAJ_<STX>S57AUA0093<ETX>

FLoc=339924289 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:32:13

DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = DTWA6 SSV=60 (0x3C) <SOH>2.N591UAJ_<STX>S57AUA0093<ETX>

FLoc=339929600 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:32:14 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB6 SSV=56 (0x38) <SOH>2.N591UAJ_<STX>S57AUA0093<ETX>

FLoc=339940146 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:32:14 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=53 (0x35) <SOH>2.N591UAJ_<STX>S57AUA0093<ETX>

FLoc=339945359 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:32:15 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=56 (0x38) <SOH>2.N591UAJ_<STX>S57AUA0093<ETX>

FLoc=339952817 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:32:15 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGB6 SSV=50 (0x32) <SOH>2.N591UAJ_<STX>S57AUA0093<ETX>

FLoc=339979154 AJPSBcnt= 168 ULBLK S=31 D=21 BEPts=20010911 13:32:18 UL MsgLen= 127 Stn= PITC6 StnDelivType= 1 Tail= .N591UA Fid= UA0093
<SOH>2.N591UA<NAK>RAK<STX>QUCHIVNUA~1<BEL>UA93 EWRSFO<CR><LF>- MESSAGE FROM CHIDD -<CR><LF> CALLL 133.37<CR><LF> <CR><LF> CHIDD ROBERT BRITTAIN <CR><ETX><

FLoc=340104912 AJPSBcnt= 168 ULBLK S=31 D=21 BEPts=20010911 13:32:28 UL MsgLen= 127 Stn= PITC6 StnDelivType= 1 Tail= .N591UA Fid= UA0093
<SOH>2.N591UA<NAK>RAK<STX>QUCHIVNUA~1<BEL>UA93 EWRSFO<CR><LF>- MESSAGE FROM CHIDD -<CR><LF> CALLL 133.37<CR><LF> <CR><LF> CHIDD ROBERT BRITTAIN <CR><ETX>

FLoc=340249083 AJPSBcnt= 168 ULBLK S=31 D=21 BEPts=20010911 13:32:38 UL MsgLen= 127 Stn= PITC6 StnDelivType= 1 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAK<STX>QUCHIVNUA~1<BEL>UA93 EWRSFO<CR><LF>- MESSAGE FROM CHIDD -<CR><LF> CALLL 133.37<CR><LF> <CR><LF> CHIDD ROBERT BRITTAIN <CR><ETX>

FLoc=340266451 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:32:39 DL MsgLen= 24 DBI= 6 DlIndicator= 1 DlNumStns= 1

BepStnName = PITC6 SSV=63 (0x3F) <SOH>2.N591UAK_<STX>S58AUA0093<ETX>

FLoc=340266506 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:32:39 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = DTWA6 SSV=53 (0x35) <SOH>2.N591UAK_<STX>S58AUA0093<ETX>

FLoc=340266561 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:32:39 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZC6 SSV=58 (0x3A) <SOH>2.N591UAK_<STX>S58AUA0093<ETX>

FLoc=340266797 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:32:39 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=44 (0x2C) <SOH>2.N591UAK_<STX>S58AUA0093<ETX>

FLoc=340267853 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:32:39 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZA6 SSV=60 (0x3C) <SOH>2.N591UAK_<STX>S58AUA0093<ETX>

FLoc=340268293 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:32:39 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB6 SSV=52 (0x34) <SOH>2.N591UAK_<STX>S58AUA0093<ETX>

FLoc=340279545 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:32:40 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=54 (0x36) <SOH>2.N591UAK <STX>S58AUA0093<ETX>

FLoc=340285990 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:32:40 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=56 (0x38) <SOH>2.N591UAK <STX>S58AUA0093<ETX>

FLoc=340290617 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:32:41 DL MsgLen= 24 DBI= 6 DIIndicator= 2 DINumStns= 1 BepStnName = CVGB6 SSV=51 (0x33) <SOH>2.N591UAK_<STX>S58AUA0093<ETX>

FLoc=340645953 AJPSBcnt= 254 ULMSG S=31 D=21 BEPts=20010911 13:33:10 ADNS MsgLen= 197 Org Addr= CHIAKUA Org TimeStamp= 20010911 13:32:00 Smi= CMD AgyNum= 65535
Tail Number= .N591UA FltId= UA0093
Target Stn= CAK<00><00> Target Method= 2
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.CHIAKUA 111332/ED <CR><LF>
<STX>CMD<CR><LF>
AN N591UA/GL CAK<CR><LF>
- QUCHIAKUA~1<BEL>UA93 EWRSFO<CR><LF>
- MESSAGE FROM CHIDD -<CR><LF>
HIGH SECURITY ALERT. SECURE COCKPIT<CR><LF>

<CR><LF>

FLoc=340646400 AJPSBcnt= 189 ULBLK S=31 D=21 BEPts=20010911 13:33:10 UL MsgLen= 148 Stn= PITC6 StnDelivType= 1
Tail= .N591UA Fid= UA0093
<SOH>2.N591UA<NAK>RAL<STX>QUCHIAKUA~1<BEL>UA93 EWRSFO<CR><LF>- MESSAGE FROM CHIDD -<CR><LF>
HIGH SECURITY ALERT. SECURE COCKPIT<CR><LF>
CHIDD ED BALLINGER <CR><LF>
<ETX>

FLoc=340676913 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:33:12 DL MsgLen= 24 DBI= 7 DlIndicator= 1 DlNumStns= 1 BepStnName = YYZC6 SSV=56 (0x38) <SOH>2.N591UAL_<STX>S59AUA0093<ETX>

FLoc=340676968 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:33:12 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = PITC6 SSV=62 (0x3E) <SOH>2.N591UAL_<STX>S59AUA0093<ETX>

FLoc=340677023 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:33:12 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = DTWA6 SSV=60 (0x3C) <SOH>2.N591UAL <STX>S59AUA0093<ETX>

FLoc=340677343 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:33:12 DL MsgLen= 24 DBI= 7 DIIndicator= 2 DINumStns= 1 BepStnName = CVGA6 SSV=42 (0x2A) <SOH>2.N591UAL <STX>S59AUA0093<ETX>

FLoc=340679121 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:33:12 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZA6 SSV=60 (0x3C) <SOH>2.N591UAL_<STX>S59AUA0093<ETX>

FLoc=340679298 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:33:12 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB6 SSV=51 (0x33) <SOH>2.N591UAL_<STX>S59AUA0093<ETX>

FLoc=340697371 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:33:13 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=54 (0x36) <SOH>2.N591UAL_<STX>S59AUA0093<ETX>

FLoc=340703429 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:33:14 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=55 (0x37) <SOH>2.N591UAL_<STX>S59AUA0093<ETX>

FLoc=340704084 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:33:14 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGB6 SSV=51 (0x33) <SOH>2.N591UAL_<STX>S59AUA0093<ETX>

FLoc=341543427 AJPSBcnt= 265 DLBLK S=31 D=21 BEPts=20010911 13:34:29 DL MsgLen= 234 DBI= 8 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=76 (0x4C) <SOH>2.N591UA<NAK>H1<STX>D76AUA0093#DFBEDA/E1 12 <CR><LF> <CR><LF> UA0093 1 89 EWR SFO 11 13:33:44 N41.31 W081.6 1 <CR><LF> <CR><LF> 183 0395 35004 2805 825 -213 00 <CR><LF> <CR><LF> 0612 04118 04136 114 0825 0876 1241 1241 1443 0438 10101V<CR><LF> 0538 -208 132 236 000 100 100 001 034 0<ETB> FLoc=341543889 AJPSBcnt= 265 DLBLK S=31 D=21 BEPts=20010911 13:34:29 DL MsgLen= 234 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = DTWA6 SSV=60 (0x3C) <SOH>2.N591UA<NAK>H1<STX>D76AUA0093#DFBEDA/E1 12 <CR><LF> <CR><LF> UA0093 1 89 EWR SFO 11 13:33:44 N41.31 W081.6 1 <CR><LF> <CR><LF> 183 0395 35004 2805 825 -213 00 <CR><LF> <CR><LF> 0612 04118 04136 114 0825 0876 1241 1241 1443 0438 10101V<CR><LF> 0538 -208 132 236 000 100 100 001 034 0<ETB> FLoc=341544209 AJPSBcnt= 265 DLBLK S=31 D=21 BEPts=20010911 13:34:29 DL MsgLen= 234 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=48 (0x30) <SOH>2.N591UA<NAK>H1<STX>D76AUA0093#DFBEDA/E1 12 <CR><LF> <CR><LF> UA0093 1 89 EWR SFO 11 13:33:44 N41.31 W081.6 1 <CR><LF> <CR><LF> 183 0395 35004 2805 825 -213 00 <CR><LF> <CR><LF> 0612 04118 04136 114 0825 0876 1241 1241 1443 0438 10101V<CR><LF> 0538 -208 132 236 000 100 100 001 034 0<ETB> FLoc=341571375 AJPSBcnt= 265 DLBLK S=31 D=21 BEPts=20010911 13:34:31 DL MsgLen= 234 DBI= 8 DIIndicator= 2 DINumStns= 1 BepStnName = HTSA6 SSV=53 (0x35) <SOH>2.N591UA<NAK>H1<STX>D76AUA0093#DFBEDA/E1 12 <CR><LF> <CR><LF> UA0093 1 89 EWR SFO 11 13:33:44 N41.31 W081.6 1 <CR><LF> <CR><LF> 183 0395 35004 2805 825 -213 00 <CR><LF> <CR><LF> 0612 04118 04136 114 0825 0876 1241 1241 1443 0438 10101V<CR><LF> 0538 -208 132 236 000 100 100 001 034 0<ETB> FLoc=341579750 AJPSBcnt= 265 DLBLK S=31 D=21 BEPts=20010911 13:34:32 DL MsgLen= 234 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=55 (0x37) <SOH>2.N591UA<NAK>H1<STX>D76AUA0093#DFBEDA/E1 12 <CR><LF> <CR><LF>

EWR SFO 11 13:33:44 N41.31 W081.6 1 <CR><LF>

UA0093 1 89

<CR><LF>

183 0395 35004 2805 825 -213 00 <CR><LF> <CR><LF> 0612 04118 04136 114 0825 0876 1241 1241 1443 0438 10101V<CR><LF> 0538 -208 132 236 000 100 100 001 034 0<ETB>

FLoc=341581424 AJPSBcnt= 271 DLBLK S=31 D=21 BEPts=20010911 13:34:32 DL MsgLen= 234 DBI= 8 DlIndicator= 2 DlNumStns= 2 BepStnName = DTWB6 SSV=58 (0x3A) BepStnName = CVGB6 SSV=52 (0x34) <SOH>2.N591UA<NAK>H1<STX>D76AUA0093#DFBEDA/E1 12 <CR><LF> UA0093 1 89 EWR SFO 11 13:33:44 N41.31 W081.6 1 <CR><LF> <CR><LF> 183 0395 35004 2805 825 -213 00 <CR><LF> <CR><LF> 0612 04118 04136 114 0825 0876 1241 1241 1443 0438 10101V<CR><LF> 0538 -208 132 236 000 100 100 001 034 0<ETB>

FLoc=341601656 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:34:34 UL MsgLen= 14 Stn= PITC6 StnDelivType= 1 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA8_M<ETX>

FLoc=341640675 AJPSBcnt= 265 DLBLK S=31 D=21 BEPts=20010911 13:34:37 DL MsgLen= 234 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=56 (0x38)

0562 03261 03208 113 0773 0852 1104 1104 1443 0381 10101V<CR><LF> 0538 -220 115 228 002 100 100 000 020 017 020 22 19R136 <CR><LF> 4040V0<ETB>

FLoc=341645053 AJPSBcnt= 265 DLBLK S=31 D=21 BEPts=20010911 13:34:38 DL MsgLen= 234 DBI= 9 DlIndicator= 2 DINumStns= 1

BepStnName = HTSA6 SSV=54 (0x36)

0562 03261 03208 113 0773 0852 1104 1104 1443 0381 10101V<CR><LF> 0538 -220 115 228 002 100 100 000 020 017 020 22 19R136 <CR><LF> 4040V0<ETB>

FLoc=341656203 AJPSBcnt= 271 DLBLK S=31 D=21 BEPts=20010911 13:34:39

DL MsgLen= 234 DBI= 9 DlIndicator= 2 DlNumStns= 2

BepStnName = DTWB6 SSV=57 (0x39)

BepStnName = CVGB6 SSV=52 (0x34)

0562 03261 03208 113 0773 0852 1104 1104 1443 0381 10101V<CR><LF> 0538 -220 115 228 002 100 100 000 020 017 020 22 19R136 <CR><LF> 4040V0<ETB>

FLoc=341679955 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:34:41 UL MsgLen= 14 Stn= PITC6 StnDelivType= 1 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA9 N<ETX>

FLoc=341815892 AJPSBcnt= 265 DLBLK S=31 D=21 BEPts=20010911 13:34:54 DL MsgLen= 234 DBI= 9 DlIndicator= 3 DlNumStns= 1

BepStnName = PITC6 SSV=61 (0x3D)

0562 03261 03208 113 0773 0852 1104 1104 1443 0381 10101V<CR><LF> 0538 -220 115 228 002 100 100 000 020 017 020 22 19R136 <CR><LF> 4040V0<ETB>

FLoc=341816896 AJPSBcnt= 265 DLBLK S=31 D=21 BEPts=20010911 13:34:54 DL MsgLen= 234 DBI= 9 DIIndicator= 2 DINumStns= 1

BepStnName = CVGA6 SSV=44 (0x2C)

0562 03261 03208 113 0773 0852 1104 1104 1443 0381 10101V<CR><LF> 0538 -220 115 228 002 100 100 000 020 017 020 22 19R136 <CR><LF> 4040V0<ETB>

FLoc=341817735 AJPSBcnt= 265 DLBLK S=31 D=21 BEPts=20010911 13:34:54 DL MsgLen= 234 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB6 SSV=51 (0x33)

0562 03261 03208 113 0773 0852 1104 1104 1443 0381 10101V<CR><LF> 0538 -220 115 228 002 100 100 000 020 017 020 22 19R136 <CR><LF> 4040V0<ETB>

FLoc=341858470 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:34:59 UL MsgLen= 14 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA9 O<ETX>

FLoc=341876954 AJPSBcnt= 115 DLBLK S=31 D=21 BEPts=20010911 13:35:00 DL MsgLen= 84 DBI= 0 DlIndicator= 1 DiNumStns= 1 BepStnName = DTWA6 SSV=60 (0x3C) <SOH>2.N591UA<NAK>H1<STX>D76CUA0093#DFB020V0020V0000V0000V0000<TSTRET> V0000V0000V0000V0000V0000V0000V <ETX>

FLoc=341877069 AJPSBcnt= 614 DLMSG S=31 D=21 BEPts=20010911 13:35:00 ADNS MsgLen= 574 Tail Number= .N591UA SMI= DFD FltId= UA0093 AgyNum= 60 (0x003C) <CR><LF> <SOH>QU RURDLXA DCABFXA HDQDLUA <CR><LF> .DDLXCXA 111335<CR><LF> <STX>DFD<CR><LF> FI UAL93/AN N591UA<CR><LF> <

DT DDL PIT 111335 D76A<CR><LF> - EDA/E1 12 <CR><LF> <CR><LF> UA0093 1 89 EWR SFO 11 13:33:44 N41.31 W081.6 1 <CR><LF> <CR><LF> 183 0395 35004 2805 825 -213 00 <CR><LF> <CR><LF> 0612 04118 04136 114 0825 0876 1241 1241 1443 0438 10101V<CR><LF> 0538 -208 132 236 000 100 100 001 034 033 008 24 19R142 <CR><LF> <CR><LF> 0562 03261 03208 113 0773 0852 1104 1104 1443 0381 10101V<CR><LF> 0538 -220 115 228 002 100 100 000 020 017 020 22 19R136 <CR><LF> <CR><LF>

<ETX><EOT>

FLoc=341877683 AJPSBcnt= 115 DLBLK S=31 D=21 BEPts=20010911 13:35:00 DL MsgLen= 84 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=44 (0x2C) <SOH>2.N591UA<NAK>H1<STX>D76CUA0093#DFB020V0020V0000V0000V0000VTSTRET> V0000V0000V0000V0000V0000V0000V <ETX>

FLoc=341881222 AJPSBcnt= 115 DLBLK S=31 D=21 BEPts=20010911 13:35:01 DL MsgLen= 84 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZA6 SSV=60 (0x3C) <SOH>2.N591UA<NAK>H1<STX>D76CUA0093#DFB020V0020V0000V0000V0000VTSTRET> V0000V0000V0000V0000V0000V0000V0000V <ETX>

FLoc=341882187 AJPSBcnt= 115 DLBLK S=31 D=21 BEPts=20010911 13:35:01 DL MsgLen= 84 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB6 SSV=52 (0x34) <SOH>2.N591UA<NAK>H1<STX>D76CUA0093#DFB020V0020V0000V0000V0000<TSTRET> V0000V0000V0000V0000V0000V000V <ETX>

FLoc=341888863 AJPSBcnt= 115 DLBLK S=31 D=21 BEPts=20010911 13:35:02 DL MsgLen= 84 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=53 (0x35) <SOH>2.N591UA<NAK>H1<STX>D76CUA0093#DFB020V0020V0000V0000V0000<TSTRET> V0000V0000V0000V0000V0000V000V <ETX>

FLoc=341896618 AJPSBcnt= 121 DLBLK S=31 D=21 BEPts=20010911 13:35:02 DL MsgLen= 84 DBI= 0 DlIndicator= 2 DlNumStns= 2 BepStnName = DTWB6 SSV=57 (0x39) BepStnName = CVGB6 SSV=51 (0x33) <SOH>2.N591UA<NAK>H1<STX>D76CUA0093#DFB020V0020V0000V0000V0000<TSTRET> V0000V0000V0000V0000V0000V0000V <ETX>

FLoc=341904108 AJPSBcnt= 115 DLBLK S=31 D=21 BEPts=20010911 13:35:03 DL MsgLen= 84 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = PITA6 SSV=61 (0x3D) <SOH>2.N591UA<NAK>H1<STX>D76CUA0093#DFB020V0020V0000V0000V0000VTSTRET> V0000V0000V0000V0000V0000V0000V0000V <ETX>

FLoc=341920380 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:35:05 UL MsgLen= 14 Stn= PITC6 StnDelivType= 2

Tail= .N591UA Fid= UA0093 <SOH>2.N591UA0_P<ETX>

FLoc=342619008 AJPSBcnt= 266 ULMSG S=31 D=21 BEPts=20010911 13:36:07 ADNS MsgLen= 209 Org Addr= CHIALUA Org TimeStamp= 20010911 13:35:00 Smi= CMD AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= CLE<00><00> Target Method= 2 <CR>><LF> <SOH>QU DDLXCXA<CR><LF> .CHIALUA 111335/CHA<CR><LF> <STX>CMD<CR><LF> AN N591UA/GL CLE<CR><LF> - QUCHIALUA~1UA93 EWRSFO<CR><LF> - MESSAGE FROM CHIDD -<CR><LF> HOWS THE WX. CAN DISPATCH BE OF<CR><LF> ANY ASSISTANCE?<CR><LF> CHIDD CHAD MCCURDY <CR><LF> <ETX><EOT>

FLoc=342633930 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:36:08 DL MsgLen= 24 DBI= 1 DlIndicator= 1 DlNumStns= 1 BepStnName = YYZA6 SSV=60 (0x3C) <SOH>2.N591UAQ_<STX>S60AUA0093<ETX>

FLoc=342634224 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:36:08 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB6 SSV=56 (0x38) <SOH>2.N591UAQ_<STX>S60AUA0093<ETX>

FLoc=342635575 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:36:08 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZC6 SSV=56 (0x38) <SOH>2.N591UAQ_<STX>S60AUA0093<ETX>

FLoc=342648141 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:36:09 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DINumStns= 1 BepStnName = PITA6 SSV=61 (0x3D) <SOH>2.N591UAQ_<STX>S60AUA0093<ETX>

FLoc=342648726 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:36:09 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=53 (0x35) <SOH>2.N591UAQ_<STX>S60AUA0093<ETX>

FLoc=345838201 AJPSBcnt= 413 ULMSG S=31 D=21 BEPts=20010911 13:41:10

ADNS MsgLen= 356 Org Addr= CHIAKUA Org TimeStamp= 20010911 13:40:00 Smi= CMD AgyNum= 65535

Tail Number= .N591UA FltId= UA0093

Target Stn= CLE<00><00> Target Method= 2

<CR><LF>

<SOH>QU DDLXCXA<CR><LF>

.CHIAKUA 111340/ED <CR><LF>

<STX>CMD<CR><LF>

AN N591UA/GL CLE<CR><LF>

- QUCHIAKUA~1<BEL>UA93 EWRSFO<CR><LF>
- MESSAGE FROM CHIDD -<CR><LF>

/HIGH SECURITY ALERT. SECURE COCKPIT, ADMIT NO ONE IN TO COCKPI<TSTRET> T.<CR><LF>

TWO AIRLINER HIT NY, TRADE CENTER, AND 1 AIRCAFT IN IAD MIS<TSTRET> SIN<CR><LF>

G AND ONE IN EWR MISSING...TOO

UAL 175/93- MISSING<CR><LF>

<CR><LF>

CHIDD ED BALLINGER

<CR><LF>

<ETX><EOT>

FLoc=345838614 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 13:41:10 UL MsgLen= 235 Stn= PITC6 StnDelivType= 2

Tail= .N591UA Fid= UA0093

<SOH>2.N591UA<NAK>RAR<STX>QUCHIAKUA~1<BEL>UA93 EWRSFO<CR><LF>

- MESSAGE FROM CHIDD -<CR><LF>

/HIGH SECURITY ALERT. SECURE COCKPIT, ADMIT NO ONE IN TO COCKPI<TSTRET> T.<CR><LF>

TWO AIRLINER HIT NY , TRADE CENTER, AND 1 AIRCAFT IN IAD MIS<TSTRET> SIN<CR><LF>

G AND ONE IN EWR MISSING...TOO <ETB>

FLoc=345860292 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:12 DL MsgLen= 24 DBI= 2 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=78 (0x4E) <SOH>2.N591UAR <STX>S61AUA0093<ETX>

FLoc=345860347 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:12 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = IADC6 SSV=42 (0x2A) <SOH>2.N591UAR <STX>S61AUA0093<ETX>

FLoc=345860932 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:12 DL MsgLen= 24 DBI= 2 DIIndicator= 2 DINumStns= 1 BepStnName = YYZA6 SSV=60 (0x3C) <SOH>2.N591UAR_<STX>S61AUA0093<ETX>

FLoc=345861186 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:12 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB6 SSV=56 (0x38) <SOH>2.N591UAR_<STX>S61AUA0093<ETX>

FLoc=345869857 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:14 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=55 (0x37) <SOH>2.N591UAR_<STX>S61AUA0093<ETX> FLoc=345874318 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 13:41:14 DL MsgLen= 24 DBI= 2 DIIndicator= 2 DINumStns= 2 BepStnName = CRWA6 SSV=57 (0x39) BepStnName = ORDA6 SSV=44 (0x2C) <SOH>2.N591UAR_<STX>S61AUA0093<ETX>

FLoc=345879870 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:15 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = DTWB6 SSV=57 (0x39) <SOH>2.N591UAR_<STX>S61AUA0093<ETX>

FLoc=345907200 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:18 DL MsgLen= 24 DBI= 3 DlIndicator= 1 DlNumStns= 1 BepStnName = YYZC6 SSV=56 (0x38) <SOH>2.N591UAS_<STX>S62AUA0093<ETX>

FLoc=345907255 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:18 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=50 (0x32) <SOH>2.N591UAS_<STX>S62AUA0093<ETX>

FLoc=345908003 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:18 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZA6 SSV=60 (0x3C) <SOH>2.N591UAS_<STX>S62AUA0093<ETX>

FLoc=345908239 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:18 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB6 SSV=50 (0x32) <SOH>2.N591UAS_<STX>S62AUA0093<ETX>

FLoc=345921407 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:20 DL MsgLen= 24 DBI= 3 DIIndicator= 2 DINumStns= 1 BepStnName = HTSA6 SSV=55 (0x37) <SOH>2.N591UAS_<STX>S62AUA0093<ETX>

FLoc=345925100 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 13:41:20 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 2 BepStnName = DTWB6 SSV=60 (0x3C) BepStnName = CVGB6 SSV=52 (0x34) <SOH>2.N591UAS_<STX>S62AUA0093<ETX>

FLoc=345925632 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:20 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = PITA6 SSV=63 (0x3F) <SOH>2.N591UAS_<STX>S62AUA0093<ETX>

FLoc=345988175 AJPSBcnt= 409 ULMSG S=31 D=21 BEPts=20010911 13:41:27

ADNS MsgLen= 352 Org Addr= CHIAKUA Org TimeStamp= 20010911 13:41:00 Smi= CMD AgyNum= 65535
Tail Number= .N591UA FltId= UA0093
Target Stn= CLE<00><00> Target Method= 2
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.CHIAKUA 111341/ED <CR><LF>
<STX>CMD<CR><LF>
AN N591UA/GL CLE<CR><LF>

- QUCHIAKUA~1<BEL>UA93 EWRSFO<CR><LF>

- MESSAGE FROM CHIDD -<CR><LF>

/HIGH SECURITY ALERT. SECURE COCKPIT, ADMIT NO ONE IN TO COCKPI<TSTRET> T.<CR><LF>

TWO AIRLINER HIT NY , TRADE CENTER, AND 1 AIRCAFT IN IAD MIS<TSTRET> SIN<CR><LF>

G AND ONE IN EWR MISSING...TOO

UAL 175<CR><LF>

93 FOUND<CR><LF>

CHIDD ED BALLINGER

<CR><LF>

<ETX><EOT>

FLoc=345988584 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 13:41:27 UL MsgLen= 235 Stn= PITC6 StnDelivType= 1

Tail= .N591UA Fid= UA0093

<SOH>2.N591UA<NAK>RAT<STX>QUCHIAKUA~1<BEL>UA93 EWRSFO<CR><LF>

- MESSAGE FROM CHIDD -<CR><LF>

/HIGH SECURITY ALERT. SECURE COCKPIT, ADMIT NO ONE IN TO COCKPI<TSTRET> T.<CR><LF>

TWO AIRLINER HIT NY , TRADE CENTER, $\,$ AND 1 AIRCAFT IN IAD MIS<TSTRET> SIN<CR><LF>

G AND ONE IN EWR MISSING...TOO <ETB>

FLoc=346001716 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:29 DL MsgLen= 24 DBI= 4 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=76 (0x4C) <SOH>2.N591UAT <STX>S63AUA0093<ETX>

FLoc=346001826 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:29 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZC6 SSV=56 (0x38) <SOH>2.N591UAT <STX>S63AUA0093<ETX>

FLoc=346001881 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:29 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = IADC6 SSV=42 (0x2A) <SOH>2.N591UAT_<STX>S63AUA0093<ETX>

FLoc=346001936 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:29 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=48 (0x30) <SOH>2.N591UAT_<STX>S63AUA0093<ETX>

FLoc=346002046 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:29 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZA6 SSV=60 (0x3C) <SOH>2.N591UAT_<STX>S63AUA0093<ETX> FLoc=346003001 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:29 DL MsgLen= 24 DBI= 4 DIIndicator= 2 DINumStns= 1 BepStnName = YYZB6 SSV=47 (0x2F) <SOH>2.N591UAT_<STX>S63AUA0093<ETX>

FLoc=346010633 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:30 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=55 (0x37) <SOH>2.N591UAT_<STX>S63AUA0093<ETX>

FLoc=346021648 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:31 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGB6 SSV=51 (0x33)
<SOH>2.N591UAT_<STX>S63AUA0093<ETX>

FLoc=346030479 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:31 DL MsgLen= 24 DBI= 4 DIIndicator= 2 DINumStns= 1 BepStnName = PITA6 SSV=62 (0x3E) <SOH>2.N591UAT_<STX>S63AUA0093<ETX>

FLoc=346053662 AJPSBcnt= 124 ULBLK S=31 D=21 BEPts=20010911 13:41:34 UL MsgLen= 83 Stn= PITC6 StnDelivType= 1 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAU<STX> UAL 175<CR><LF> 93 FOUND<CR><LF> CHIDD ED BALLINGER <CR><LF> <ETX>

FLoc=346081135 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:36 DL MsgLen= 24 DBI= 5 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=77 (0x4D) <SOH>2.N591UAU_<STX>S64AUA0093<ETX>

FLoc=346081190 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:36 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = IADC6 SSV=42 (0x2A) <SOH>2.N591UAU_<STX>S64AUA0093<ETX>

FLoc=346081859 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:36 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=48 (0x30) <SOH>2.N591UAU_<STX>S64AUA0093<ETX>

FLoc=346098151 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:38 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=55 (0x37) <SOH>2.N591UAU_<STX>S64AUA0093<ETX>

FLoc=346104340 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 13:41:38 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 2 BepStnName = PITA6 SSV=62 (0x3E) BepStnName = CRWA6 SSV=57 (0x39) <SOH>2.N591UAU_<STX>S64AUA0093<ETX>

FLoc=346107518 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:41:38 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1

BepStnName = CVGB6 SSV=52 (0x34) <SOH>2.N591UAU_<STX>S64AUA0093<ETX>

FLoc=349589943 AJPSBcnt= 253 ULMSG S=31 D=21 BEPts=20010911 13:47:18
ADNS MsgLen= 196 Org Addr= SFOLMUA Org TimeStamp= 20010911 13:46:00
Smi= CMD AgyNum= 65535
Tail Number= .N591UA FItId= UA0093
Target Stn= TOL<00><00> Target Method= 2
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.SFOLMUA 111346/PRI<CR><LF>
.SFOLMUA 111346/PRI<CR><LF>
- QUSFOLMUA~1<BEL>UA93 EWRSFO<CR><LF>
HEARD REPORT OF INCIDENT...PLZ CONFIRM ALL IS NML......THX<CR><LF>
SFOLM PRICE DAVID

<CR><ETX><EOT>

FLoc=349590196 AJPSBcnt= 188 ULBLK S=31 D=21 BEPts=20010911 13:47:18 UL MsgLen= 147 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAV<STX>QUSFOLMUA~1<BEL>UA93 EWRSFO<CR><LF>HEARD REPORT OF INCIDENT...PLZ CONFIRM ALL IS NML......THX<CR><LF>SFOLM PRICE DAVID <CR><LF><ETX>

FLoc=349697380 AJPSBcnt= 188 ULBLK S=31 D=21 BEPts=20010911 13:47:28 UL MsgLen= 147 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAV<STX>QUSFOLMUA~1<BEL>UA93 EWRSFO<CR><LF>HEARD REPORT OF INCIDENT...PLZ CONFIRM ALL IS NML.....THX<CR><LF>SFOLM PRICE DAVID <CR><LF><ETX>

FLoc=349736519 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:47:31 DL MsgLen= 24 DBI= 6 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=80 (0x50) <SOH>2.N591UAV_<STX>S65AUA0093<ETX>

FLoc=349736574 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:47:31 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = DTWA6 SSV=60 (0x3C) <SOH>2.N591UAV <STX>S65AUA0093<ETX>

FLoc=349736629 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:47:31 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = IADC6 SSV=41 (0x29) <SOH>2.N591UAV_<STX>S65AUA0093<ETX>

FLoc=349738701 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:47:31 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = YYZB6 SSV=43 (0x2B) <SOH>2.N591UAV <STX>S65AUA0093<ETX>

FLoc=349757304 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:47:32 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1

BepStnName = CRWA6 SSV=55 (0x37) <SOH>2.N591UAV_<STX>S65AUA0093<ETX>

FLoc=349759608 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:47:33 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = DTWB6 SSV=54 (0x36) <SOH>2.N591UAV_<STX>S65AUA0093<ETX>

FLoc=349773796 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:47:34 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=49 (0x31) <SOH>2.N591UAV_<STX>S65AUA0093<ETX>

FLoc=351703471 AJPSBcnt= 296 ULMSG S=31 D=21 BEPts=20010911 13:50:35 ADNS MsgLen= 239 Org Addr= CHIAKUA Org TimeStamp= 20010911 13:50:00 Smi= AGM AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= TOL<00><00> Target Method= 2 <CR>><LF> <SOH>QU DDLXCXA<CR><LF> .CHIAKUA 111350/ED <CR><LF> <STX>AGM<CR><LF> AN N591UA/GL TOL<CR><LF> - UA93 EWRSFO<CR><LF> - MESSAGE FROM CHIDD -<CR><LF> LAND ASP AT NEAREST UAL AIRPORT.. ORD<CR><LF> TERRORIST . NO ONE IN TO COCKPIT LAND ASP<CR><LF> <CR><LF> CHIDD ED BALLINGER <CR><LF> <ETX><EOT>

FLoc=351703767 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 13:50:35 UL MsgLen= 235 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093
<SOH>2.N591UA<NAK>C1W<STX>.CHIAKUA 111350/ED <CR><LF> AGM<CR><LF> AN N591UA/GL TOL<CR><LF> - UA93 EWRSFO<CR><LF> - MESSAGE FROM CHIDD -<CR><LF> LAND ASP AT NEAREST UAL AIRPORT.. ORD<CR><LF> TERRORIST . NO ONE IN TO COCKPIT..... LAND ASP</CR><CR><LF> CHIDD ED BALLINGER <CR><ETB>

FLoc=351727811 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:50:37 DL MsgLen= 24 DBI= 7 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=87 (0x57) <SOH>2.N591UAW <STX>S66AUA0093<ETX>

FLoc=351754551 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:50:39 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = PITA6 SSV=72 (0x48) <SOH>2.N591UAW_<STX>S66AUA0093<ETX>

FLoc=351778486 AJPSBcnt= 57 ULBLK S=31 D=21 BEPts=20010911 13:50:42 UL MsgLen= 16 Stn= PITC6 StnDelivType= 1

Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>C1X<STX><LF> <ETX>

FLoc=351792429 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:50:43 DL MsgLen= 24 DBI= 8 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=86 (0x56) <SOH>2.N591UAX_<STX>S67AUA0093<ETX>

FLoc=351802834 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:50:44 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=48 (0x30) <SOH>2.N591UAX_<STX>S67AUA0093<ETX>

FLoc=351807901 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:50:44 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=53 (0x35) <SOH>2.N591UAX_<STX>S67AUA0093<ETX>

FLoc=351814009 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:50:45 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = DTWB6 SSV=52 (0x34) <SOH>2.N591UAX_<STX>S67AUA0093<ETX>

FLoc=352064272 AJPSBcnt= 271 ULMSG S=31 D=21 BEPts=20010911 13:51:08 ADNS MsgLen= 214 Org Addr= CHIAKUA Org TimeStamp= 20010911 13:50:00 Smi= AGM AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= TOL<00><00> Target Method= 2 <CR>><LF> <SOH>QU DDLXCXA<CR><LF> .CHIAKUA 111350/ED <CR><LF> <STX>AGM<CR><LF> AN N591UA/GL TOL<CR><LF> - UA93 EWRSFO<CR><LF> - MESSAGE FROM CHIDD -<CR><LF> LAND ASP AT NEAREST -- NEAREST AIRPORT. ASP . ASP ON GROND. ANYWER < TSTRET>

E.<CR><LF> CHIDD ED BALLINGER <CR><LF>

<ETX><EOT>

FLoc=352064543 AJPSBcnt= 252 ULBLK S=31 D=21 BEPts=20010911 13:51:08 UL MsgLen= 211 Stn= PITC6 StnDelivType= 1 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>C1Y<STX>.CHIAKUA 111350/ED <CR><LF> AGM<CR><LF> AN N591UA/GL TOL<CR><LF> - UA93 EWRSFO<CR><LF>

- MESSAGE FROM CHIDD -<CR><LF> LAND ASP AT NEAREST -- NEAREST AIRPORT. ASP ON GROND. ANYWER < TSTRET> E.<CR><LF>

CHIDD ED BALLINGER

<CR><LF>

<ETX>

FLoc=352083389 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:51:10 DL MsgLen= 24 DBI= 9 DlIndicator= 1 DlNumStns= 1

BepStnName = PITC6 SSV=86 (0x56) <SOH>2.N591UAY_<STX>S68AUA0093<ETX>

<ETX><EOT>

FLoc=352083617 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:51:10 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = DTWA6 SSV=50 (0x32) <SOH>2.N591UAY_<STX>S68AUA0093<ETX>

FLoc=352093843 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:51:11 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=47 (0x2F) <SOH>2.N591UAY_<STX>S68AUA0093<ETX>

FLoc=352110701 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:51:12 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = PITA6 SSV=73 (0x49) <SOH>2.N591UAY_<STX>S68AUA0093<ETX>

FLoc=352114433 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:51:13 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = DTWB6 SSV=52 (0x34) <SOH>2.N591UAY <STX>S68AUA0093<ETX>

FLoc=352484425 AJPSBcnt= 273 ULMSG S=31 D=21 BEPts=20010911 13:51:48 ADNS MsgLen= 216 Org Addr= CHIAKUA Org TimeStamp= 20010911 13:51:00 Smi= AGM AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= FWA<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .CHIAKUA 111351/ED <CR><LF> <STX>AGM<CR><LF> AN N591UA/GL FWA<CR><LF> - UA93 EWRSFO<CR><LF> - MESSAGE FROM CHIDD -<CR><LF> LAND ASP AT NEAREST -- NEAREST AIRPORT. ASP . ASP ON GROND. ANYWER < TSTRET> E.<CR><LF> <CR><LF> CHIDD ED BALLINGER <CR><LF>

FLoc=352512869 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:51:51

DL MsgLen= 24 DBI= 0 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=88 (0x58) <SOH>2.N591UAZ_<STX>S69AUA0093<ETX>

FLoc=352538978 AJPSBcnt= 273 ULMSG S=31 D=21 BEPts=20010911 13:51:53 ADNS MsgLen= 216 Org Addr= CHIAKUA Org TimeStamp= 20010911 13:51:00 Smi= AGM AgyNum= 65535

Tail Number= .N591UA FltId= UA0093

Target Stn= FWA<00><00> Target Method= 2

<CR><LF>

<SOH>QU DDLXCXA<CR><LF>

.CHIAKUA 111351/ED <CR><LF>

<STX>AGM<CR><LF>

AN N591UA/GL FWA<CR><LF>

- UA93 EWRSFO<CR><LF>

- MESSAGE FROM CHIDD -<CR><LF>

LAND ASP AT NEAREST --NEAREST AIRPORT.ASP .ASP ON GROND.ANYWER<TSTRET> E.<CR><LF>

E. CRACLI

<CR><LF>

CHIDD ED BALLINGER

<CR><LF>

<ETX><EOT>

FLoc=352542704 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:51:53 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = PITA6 SSV=75 (0x4B) <SOH>2.N591UAZ <STX>S69AUA0093<ETX>

FLoc=352565664 AJPSBcnt= 254 ULBLK S=31 D=21 BEPts=20010911 13:51:56 UL MsgLen= 213 Stn= PITC6 StnDelivType= 1 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>C1A<STX>.CHIAKUA 111351/ED <CR><LF>

AGM<CR><LF> AN N591UA/GL FWA<CR><LF>

- UA93 EWRSFO<CR><LF>

- MESSAGE FROM CHIDD -<CR><LF>

LAND ASP AT NEAREST --NEAREST AIRPORT.ASP .ASP ON GROND.ANYWER<TSTRET> E.<CR><LF>

<CR><LF>

CHIDD ED BALLINGER

<CR><LF>

<ETX>

FLoc=352588800 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:51:58 DL MsgLen= 24 DBI= 1 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=86 (0x56) <SOH>2.N591UAA <STX>S70AUA0093<ETX>

FLoc=352588855 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:51:58 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = DTWA6 SSV=43 (0x2B) <SOH>2.N591UAA_<STX>S70AUA0093<ETX>

FLoc=352597513 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:51:59 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=44 (0x2C) <SOH>2.N591UAA_<STX>S70AUA0093<ETX>

FLoc=352602438 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:52:00 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=53 (0x35) <SOH>2.N591UAA_<STX>S70AUA0093<ETX>

FLoc=352604683 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:52:00 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = DTWB6 SSV=51 (0x33) <SOH>2.N591UAA_<STX>S70AUA0093<ETX>

FLoc=359963300 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 14:01:57 DL MsgLen= 24 DBI= 2 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=76 (0x4C) <SOH>2.N591UA<NAK>Q0<STX>S71AUA0093<ETX>

FLoc=359963355 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 14:01:57 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = IADC6 SSV=44 (0x2C) <SOH>2.N591UA<NAK>Q0<STX>S71AUA0093<ETX>

FLoc=359981238 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 14:01:59 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=53 (0x35) <SOH>2.N591UA<NAK>Q0<STX>S71AUA0093<ETX>

FLoc=360007844 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 14:02:02 UL MsgLen= 14 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA2 B<ETX>

FLoc=364376761 AJPSBcnt= 243 ULMSG S=31 D=21 BEPts=20010911 14:10:59 ADNS MsgLen= 186 Org Addr= CHIAKUA Org TimeStamp= 20010911 14:10:00 Smi= CMD AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= CMI<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .CHIAKUA 111410/ED <CR><LF> <STX>CMD<CR><LF> AN N591UA/GL CMI<CR><LF> - QUCHIAKUA~1UA93 EWRSFO<CR><LF> - MESSAGE FROM CHIDD -<CR><LF> DO NOT DIVERT TO DC AREA<CR><LF> CHIDD ED BALLINGER <CR><LF> <ETX><EOT>

FLoc=364377004 AJPSBcnt= 178 ULBLK S=31 D=21 BEPts=20010911 14:10:59 UL MsgLen= 137 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAC<STX>QUCHIAKUA~1UA93 EWRSFO<CR><LF> - MESSAGE FROM CHIDD -<CR><LF> DO NOT DIVERT TO DC AREA<CR><LF> CHIDD ED BALLINGER <CR><ETX>

FLoc=364414154 AJPSBcnt= 244 ULMSG S=31 D=21 BEPts=20010911 14:11:04

ADNS MsgLen= 187 Org Addr= CHIAKUA Org TimeStamp= 20010911 14:10:00 Smi= CMD AgyNum= 65535
Tail Number= .N591UA FitId= UA0093
Target Stn= CMI<00><00> Target Method= 2
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.CHIAKUA 111410/ED <CR><LF>
<STX>CMD<CR><LF>
AN N591UA/GL CMI<CR><LF>
- QUCHIAKUA~1</BEL>UA93 EWRSFO<CR><LF>
- MESSAGE FROM CHIDD -<CR><LF>
DO NOT DIVERT TO DC AREA<CR><LF>
CHIDD ED BALLINGER <CR><ETX><ETX><EOT>

FLoc=364444200 AJPSBcnt= 178 ULBLK S=31 D=21 BEPts=20010911 14:11:09 UL MsgLen= 137 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAC<STX>QUCHIAKUA~1UA93 EWRSFO<CR><LF> - MESSAGE FROM CHIDD -<CR><LF> DO NOT DIVERT TO DC AREA<CR><LF> CHIDD ED BALLINGER <CR><LF> <ETX>

FLoc=364509548 AJPSBcnt= 178 ULBLK S=31 D=21 BEPts=20010911 14:11:19 UL MsgLen= 137 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAC<STX>QUCHIAKUA~1UA93 EWRSFO<CR><LF> - MESSAGE FROM CHIDD -<CR><LF> DO NOT DIVERT TO DC AREA<CR><LF> CHIDD ED BALLINGER <CR><LF> <ETX>

FLoc=364582400 AJPSBcnt= 178 ULBLK S=31 D=21 BEPts=20010911 14:11:29 UL MsgLen= 137 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAC<STX>QUCHIAKUA~1UA93 EWRSFO<CR><LF> - MESSAGE FROM CHIDD -<CR><LF> DO NOT DIVERT TO DC AREA<CR><LF> CHIDD ED BALLINGER <CR><LF> <ETX>

FLoc=364644886 AJPSBcnt= 178 ULBLK S=31 D=21 BEPts=20010911 14:11:39 UL MsgLen= 137 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAC<STX>QUCHIAKUA~1UA93 EWRSFO<CR><LF> - MESSAGE FROM CHIDD -<CR><LF> DO NOT DIVERT TO DC AREA<CR><LF> CHIDD ED BALLINGER <CR><ETX>

FLoc=364707606 AJPSBcnt= 263 ULMSG S=31 D=21 BEPts=20010911 14:11:48 ADNS MsgLen= 206 Org Addr= CHIAKUA Org TimeStamp= 20010911 14:11:00 Smi= CMD AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= CMI<00><00> Target Method= 2

FLoc=364717563 AJPSBcnt= 178 ULBLK S=31 D=21 BEPts=20010911 14:11:50 UL MsgLen= 137 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAC<STX>QUCHIAKUA~1UA93 EWRSFO<CR><LF> - MESSAGE FROM CHIDD -<CR><LF> DO NOT DIVERT TO DC AREA<CR><LF> CHIDD ED BALLINGER <CR><ETX>

FLoc=364793973 AJPSBcnt= 178 ULBLK S=31 D=21 BEPts=20010911 14:12:00 UL MsgLen= 137 Stn= IADA6 StnDelivType= 3
Tail= .N591UA Fid= UA0093
<SOH>2.N591UA<NAK>RAC<STX>QUCHIAKUA~1UA93 EWRSFO<CR><LF>
- MESSAGE FROM CHIDD -<CR><LF>
DO NOT DIVERT TO DC AREA<CR><LF>
CHIDD ED BALLINGER <CR><LF>
<FTX>

FLoc=364860965 AJPSBcnt= 178 ULBLK S=31 D=21 BEPts=20010911 14:12:10 UL MsgLen= 137 Stn= IADA6 StnDelivType= 3
Tail= .N591UA Fid= UA0093
<SOH>2.N591UA<NAK>RAC<STX>QUCHIAKUA~1UA93 EWRSFO<CR><LF>
- MESSAGE FROM CHIDD -<CR><LF>
DO NOT DIVERT TO DC AREA<CR><LF>
CHIDD ED BALLINGER <CR><LF>
<ETX>

FLoc=364917445 AJPSBcnt= 178 ULBLK S=31 D=21 BEPts=20010911 14:12:20 UL MsgLen= 137 Stn= IADA6 StnDelivType= 3 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAC<STX>QUCHIAKUA~1UA93 EWRSFO<CR><LF> - MESSAGE FROM CHIDD -<CR><LF> DO NOT DIVERT TO DC AREA<CR><LF> CHIDD ED BALLINGER <CR><LF> <ETX>

FLoc=364988118 AJPSBcnt= 318 ICPUL S=31 D=21 BEPts=20010911 14:12:30 Intercept MsgLen=186 Addressee= .N591UA Num MediaTypes=1 Blk Num=1 UI Code=0

***IcpHdr: Reason Code= 311 AgyNum= 65535
***IcpHdr: Tail Number= .N591UA

***lcpHdr: FltId= <FF><00><00><00><00>

Dumping Media type #1 of 1

Media Type = 0 Num Stns= 2 Num History= 9
Stn Score Card # 1 of 2; EntryType= 2 (0x0002) Stn= PITC6
Stn Score Card # 2 of 2; EntryType= 3 (0x0003) Stn= IADA6
History Card # 1 of 9; Reason= 311 (0x0137) Stn= PITC6
History Card # 2 of 9; Reason= 311 (0x0137) Stn= PITC6
History Card # 3 of 9; Reason= 311 (0x0137) Stn= PITC6
History Card # 4 of 9; Reason= 311 (0x0137) Stn= PITC6
History Card # 5 of 9; Reason= 311 (0x0137) Stn= PITC6
History Card # 6 of 9; Reason= 311 (0x0137) Stn= PITC6
History Card # 7 of 9; Reason= 311 (0x0137) Stn= IADA6
History Card # 8 of 9; Reason= 311 (0x0137) Stn= IADA6
History Card # 9 of 9; Reason= 311 (0x0137) Stn= IADA6

<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.CHIAKUA 111410/ED <CR><LF>
.CHIAKUA 111410/ED <CR><LF>
<STX>CMD<CR><LF>
AN N591UA/GL CMI<CR><LF>
- QUCHIAKUA~1UA93 EWRSFO<CR><LF>
- MESSAGE FROM CHIDD -<CR><LF>
DO NOT DIVERT TO DC AREA<CR><LF>
CHIDD ED BALLINGER <CR><LF>
<ETX><EOT>

FLoc=365214130 AJPSBcnt= 179 ULBLK S=31 D=21 BEPts=20010911 14:13:00 UL MsgLen= 138 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAD<STX>QUCHIAKUA~1<BEL>UA93 EWRSFO<CR><LF> - MESSAGE FROM CHIDD -<CR><LF>
DO NOT DIVERT TO DC AREA<CR><LF>
CHIDD ED BALLINGER <CR><LF>
<FTX>

FLoc=365302744 AJPSBcnt= 179 ULBLK S=31 D=21 BEPts=20010911 14:13:10 UL MsgLen= 138 Stn= PITC6 StnDelivType= 2 Tail= .N591UA Fid= UA0093 <SOH>2.N591UA<NAK>RAD<STX>QUCHIAKUA~1<BEL>UA93 EWRSFO<CR><LF>- MESSAGE FROM CHIDD -<CR><LF>DO NOT DIVERT TO DC AREA<CR><LF>CHIDD ED BALLINGER <CR><LF></TX>

FLoc=365464105 AJPSBcnt= 179 ULBLK S=31 D=21 BEPts=20010911 14:13:30 UL MsgLen= 138 Stn= IADA6 StnDelivType= 3
Tail= .N591UA Fid= UA0093
<SOH>2.N591UA<NAK>RAD<STX>QUCHIAKUA~1<BEL>UA93 EWRSFO<CR><LF>- MESSAGE FROM CHIDD -<CR><LF>DO NOT DIVERT TO DC AREA<CR><LF>CHIDD ED BALLINGER <CR><LF><ETX>

FLoc=365550345 AJPSBcnt= 179 ULBLK S=31 D=21 BEPts=20010911 14:13:40 UL MsgLen= 138 Stn= IADA6 StnDelivType= 3
Tail= .N591UA Fid= UA0093
<SOH>2.N591UA<NAK>RAD<STX>QUCHIAKUA~1<BEL>UA93 EWRSFO<CR><LF>- MESSAGE FROM CHIDD -<CR><LF>
DO NOT DIVERT TO DC AREA<CR><LF>
CHIDD ED BALLINGER <CR><LF>
<ETX>

FLoc=365612804 AJPSBcnt= 179 ULBLK S=31 D=21 BEPts=20010911 14:13:50 UL MsgLen= 138 Stn= IADA6 StnDelivType= 3
Tail= .N591UA Fid= UA0093
<SOH>2.N591UA<NAK>RAD<STX>QUCHIAKUA~1<BEL>UA93 EWRSFO<CR><LF>- MESSAGE FROM CHIDD -<CR><LF>DO NOT DIVERT TO DC AREA<CR><LF>CHIDD ED BALLINGER <CR><LF><ETX>

FLoc=365678382 AJPSBcnt= 319 ICPUL S=31 D=21 BEPts=20010911 14:14:00 Intercept MsgLen=187 Addressee= .N591UA Num MediaTypes=1 Blk Num=1 UI Code=0

***IcpHdr: Reason Code= 311 AgyNum= 65535

***IcpHdr: Tail Number= .N591UA

***lcpHdr: FltId= <FF><00><00><00><00><00>

Dumping Media type #1 of 1

Media Type = 0 Num Stns= 2 Num History= 9

Stn Score Card #1 of 2; EntryType= 2 (0x0002) Stn= PITC6

Stn Score Card #2 of 2; EntryType= 3 (0x0003) Stn= IADA6

History Card # 1 of 9; Reason= 311 (0x0137) Stn= PITC6

History Card # 2 of 9; Reason= 311 (0x0137) Stn= PITC6

History Card # 3 of 9; Reason= 311 (0x0137) Stn= PITC6

History Card # 4 of 9; Reason= 311 (0x0137) Stn= PITC6

History Card # 5 of 9; Reason= 311 (0x0137) Stn= PITC6

History Card # 6 of 9; Reason= 311 (0x0137) Stn= PITC6

History Card # 7 of 9; Reason= 311 (0x0137) Stn= IADA6

History Card # 8 of 9; Reason= 311 (0x0137) Stn= IADA6

History Card # 9 of 9; Reason= 311 (0x0137) Stn= IADA6

<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.CHIAKUA 111410/ED <CR><LF>
.CHIAKUA 111410/ED <CR><LF>
<STX>CMD<CR><LF>
AN N591UA/GL CMI<CR><LF>
- QUCHIAKUA~1<BEL>UA93 EWRSFO<CR><LF>
- MESSAGE FROM CHIDD -<CR><LF>
DO NOT DIVERT TO DC AREA<CR><LF>
CHIDD ED BALLINGER <CR><LF>
<ETX><EOT>

FLoc=365678701 AJPSBcnt= 261 ICPUL S=31 D=21 BEPts=20010911 14:14:00 Intercept MsgLen=206 Addressee= .N591UA Num MediaTypes=1 Blk Num=1 Ul Code=0

***lcpHdr: Reason Code= 231 AgyNum= 65535

***IcpHdr: Tail Number= .N591UA

***lcpHdr: FltId= <FF><00><00><00><00>

Dumping Media type #1 of 1 Media Type = 0 Num Stns= 0 Num History= 0

FLoc=367059755 AJPSBcnt= 134 ULMSG S=31 D=21 BEPts=20010911 14:17:39 ADNS MsgLen= 77 Org Addr= CHIAOUA Org TimeStamp= 20010911 14:17:00 Smi= CMD AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= CMI<00><00> Target Method= 2

<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.CHIAOUA 111417/ROB<CR><LF>
<STX>CMD<CR><LF>
AN N591UA/GL CMI<CR><LF>
- QUCHIAOUA~2<CR><LF>
<ETX><EOT>

FLoc=367059889 AJPSBcnt= 132 ICPUL S=31 D=21 BEPts=20010911 14:17:39 Intercept MsgLen=77 Addressee= .N591UA Num MediaTypes=1 Blk Num=1 Ul Code=0

***IcpHdr: Reason Code= 231 AgyNum= 65535

***IcpHdr: Tail Number= .N591UA

***IcpHdr: FltId= <FF><00><00><00><00>

Dumping Media type #1 of 1
Media Type = 0 Num Stns= 0 Num History= 0

<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.CHIAOUA 111417/ROB<CR><LF>
<STX>CMD<CR><LF>
AN N591UA/GL CMI<CR><LF>
- QUCHIAOUA~2<CR><LF>
<ETX><EOT>

FLoc=367187539 AJPSBcnt= 134 ULMSG S=31 D=21 BEPts=20010911 14:18:03 ADNS MsgLen= 77 Org Addr= CHIYRUA Org TimeStamp= 20010911 14:17:00 Smi= CMD AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= CMI<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .CHIYRUA 111417/TOM<CR><LF> <STX>CMD<CR><LF> AN N591UA/GL CMI<CR><LF> - QUCHIYRUA~2<CR><LF> <ETX><EOT>

FLoc=367187673 AJPSBcnt= 132 ICPUL S=31 D=21 BEPts=20010911 14:18:03 Intercept MsgLen=77 Addressee= .N591UA Num MediaTypes=1 Blk Num=1 UI Code=0

***IcpHdr: Reason Code= 231 AgyNum= 65535

***IcpHdr: Tail Number= .N591UA

***IcpHdr: FltId= <FF><00><00><00><00>

Dumping Media type #1 of 1 Media Type = 0 Num Stns= 0 Num History= 0

<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.CHIYRUA 111417/TOM<CR><LF>

<STX>CMD<CR><LF>
AN N591UA/GL CMI<CR><LF>
- QUCHIYRUA~2<CR><LF>
<ETX><EOT>

FLoc=367542701 AJPSBcnt= 134 ULMSG S=31 D=21 BEPts=20010911 14:19:04 ADNS MsgLen= 77 Org Addr= CHIAOUA Org TimeStamp= 20010911 14:19:00 Smi= CMD AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= CMI<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .CHIAOUA 111419/ROB<CR><LF> <STX>CMD<CR><LF> AN N591UA/GL CMI<CR><LF> - QUCHIAOUA~2<CR><LF> <ETX><ETX><EOT>

FLoc=367542835 AJPSBcnt= 132 ICPUL S=31 D=21 BEPts=20010911 14:19:04 Intercept MsgLen=77 Addressee= .N591UA Num MediaTypes=1 Blk Num=1 Ul Code=0

***IcpHdr: Reason Code= 231 AgyNum= 65535

***lcpHdr: Tail Number= .N591UA

***IcpHdr: FltId= <FF><00><00><00><00>

Dumping Media type #1 of 1
Media Type = 0 Num Stns= 0 Num History= 0

<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.CHIAOUA 111419/ROB<CR><LF>
<STX>CMD<CR><LF>
AN N591UA/GL CMI<CR><LF>
- QUCHIAOUA~2<CR><LF>
<ETX><EOT>

FLoc=368197741 AJPSBcnt= 134 ULMSG S=31 D=21 BEPts=20010911 14:21:06 ADNS MsgLen= 77 Org Addr= CHIAOUA Org TimeStamp= 20010911 14:20:00 Smi= CMD AgyNum= 65535 Tail Number= .N591UA FltId= UA0093 Target Stn= DEC<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .CHIAOUA 111420/ROB<CR><LF> <STX>CMD<CR><LF> AN N591UA/GL DEC<CR><LF> - QUCHIAOUA~2<CR><LF> <ETX><ETX><EOT>

FLoc=368197875 AJPSBcnt= 132 ICPUL S=31 D=21 BEPts=20010911 14:21:06 Intercept MsgLen=77 Addressee= .N591UA Num MediaTypes=1 Blk Num=1 Ul Code=0

^{***}IcpHdr: Reason Code= 231 AgyNum= 65535

***IcpHdr: Tail Number= .N591UA

***IcpHdr: FltId= <FF><00><00><00><00>

Dumping Media type #1 of 1 Media Type = 0 Num Stns= 0 Num History= 0

<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.CHIAOUA 111420/ROB<CR><LF>
<STX>CMD<CR><LF>
AN N591UA/GL DEC<CR><LF>
- QUCHIAOUA~2<CR><LF>
<ETX><EOT>

FLoc=236469080 AJPSBcnt= 119 DLBLK S=31 D=21 BEPts=20010911 10:39:41 DL MsgLen= 88 DBI= 1 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=73 (0x49)
<SOH>2.N644AA<NAK>B3<STX>M50AAA0077DC1/RCD 039<CR><LF>AAL77-KIAD-GATE -KLAX<CR><LF>ATIS <CR><LF>-TYP/A300<CR><LF>-RMK/0B9A<ETX>

FLoc=236491629 AJPSBcnt= 119 DLBLK S=31 D=21 BEPts=20010911 10:39:44 DL MsgLen= 88 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=66 (0x42)
<SOH>2.N644AA<NAK>B3<STX>M50AAA0077DC1/RCD 039<CR><LF>AAL77-KIAD-GATE -KLAX<CR><LF>ATIS <CR><LF>-TYP/A300<CR><LF>-RMK/0B9A<ETX>

FLoc=236498559 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 10:39:46 UL MsgLen= 14 Stn= IADC6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA1_K<ETX>

FLoc=236505841 AJPSBcnt= 77 DLBLK S=31 D=21 BEPts=20010911 10:39:47 DL MsgLen= 46 DBI= 2 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=72 (0x48) <SOH>2.N644AA<NAK>B9<STX>M51AAA0077/KIAD.TI2/039KIADDCD7D<ETX>

FLoc=236505918 AJPSBcnt= 161 DLMSG S=31 D=21 BEPts=20010911 10:39:47 ADNS MsgLen= 121 Tail Number= .N644AA SMI= RAI FItId= AA0077 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA ATSAAXA TULDDAA <CR><LF>
.DDLXCXA 111039</CR><LF>
<STX>RAI<CR><LF>
FI AA77/AN N644AA</CR><LF>
DT DDL IAD 111039 M51A</CR><LF>
- TI2/039KIADDCD7D</CR><LF>
<ETX><ETX><EOT>

FLoc=236519451 AJPSBcnt= 77 DLBLK S=31 D=21 BEPts=20010911 10:39:49 DL MsgLen= 46 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=67 (0x43) <SOH>2.N644AA<NAK>B9<STX>M51AAA0077/KIAD.TI2/039KIADDCD7D<ETX>

FLoc=236522047 AJPSBcnt= 537 ULMSG S=31 D=21 BEPts=20010911 10:39:50 ADNS MsgLen= 480 Org Addr= ATSAAXA Org TimeStamp= 20010911 10:39:00 Smi= DAI AgyNum= 65535 Tail Number= .N644AA FItId= AA0077 Target Stn= <00><00><00><00> Target Method= 0 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .ATSAAXA 111039<CR><LF> <STX>DAI<CR><LF> AN N644AA<CR><LF> - /ATSAAXA.TI2/KIAD DEP ATIS V<CR><LF> 0951Z IAD ATIS INFO V 0951Z. 00000KT 10SM CLR<CR><LF> 15/13 A3017 (THREE ZERO ONE SEVEN).<CR><LF> APCH IN USE. ILS/VA CONDUCTED<CR><LF> SIMULTANEOUSLY RWY 1R, RWY 1L. DEPG RWY<CR><LF> 30. SINGLE GC FREQ IN USE ON 121.9.<CR><LF> NOTAMS... TWY K CLSD NORTH OF TWY B ;<CR><LF> TWY J CLSD SOUTH OF TWY E; TWY A CLSD<CR><LF> EAST OF TWY J . RUNWAY ONE NINER LEFT<CR><LF> RUNUP BLOCK UNAVAILABLE. BIRD ACTIVITY<CR><LF> VICINITY ARPT. ...ADVS YOU HAVE INFO V.7679<CR><LF> <ETX><EOT>

FLoc=236534051 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 10:39:52 UL MsgLen= 235 Stn= IADC6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA2A9L<STX>/ATSAAXA.TI2/KIAD DEP ATIS V<CR><LF>0951Z IAD ATIS INFO V 0951Z. 00000KT 10SM CLR<CR><LF>15/13 A3017 (THREE ZERO ONE SEVEN).<CR><LF>APCH IN USE. ILS/VA CONDUCTED<CR><LF>SIMULTANEOUSLY RWY 1R, RWY 1L. DEPG RWY<CR><LF>30. SINGLE GC FREQ IN USE ON 121.9<ETB>

FLoc=236587947 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 10:40:02 UL MsgLen= 235 Stn= IADC6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA2A9L<STX>/ATSAAXA.TI2/KIAD DEP ATIS V<CR><LF>0951Z IAD ATIS INFO V 0951Z. 00000KT 10SM CLR<CR><LF>15/13 A3017 (THREE ZERO ONE SEVEN).<CR><LF>APCH IN USE. ILS/VA CONDUCTED<CR><LF>SIMULTANEOUSLY RWY 1R, RWY 1L. DEPG RWY<CR><LF>30. SINGLE GC FREQ IN USE ON 121.9<ETB>

FLoc=236598287 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 10:40:03 DL MsgLen= 24 DBI= 3 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=73 (0x49) <SOH>2.N644AAL_<STX>S29AAA0077<ETX>

FLoc=236607892 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 10:40:05 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=67 (0x43)

<SOH>2.N644AAL <STX>S29AAA0077<ETX>

FLoc=236618083 AJPSBcnt= 262 ULBLK S=31 D=21 BEPts=20010911 10:40:08 UL MsgLen= 221 Stn= IADC6 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>A9M<STX>.<CR><LF> NOTAMS... TWY K CLSD NORTH OF TWY B ;<CR><LF> TWY J CLSD SOUTH OF TWY E ; TWY A CLSD<CR><LF> EAST OF TWY J . RUNWAY ONE NINER LEFT<CR><LF> RUNUP BLOCK UNAVAILABLE. BIRD ACTIVITY<CR><LF> VICINITY ARPT. ...ADVS YOU HAVE INFO V.7679<CR><LF> <ETX>

FLoc=236627545 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 10:40:09 DL MsgLen= 24 DBI= 4 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=72 (0x48) <SOH>2.N644AAM_<STX>S30AAA0077<ETX>

FLoc=236638133 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 10:40:11 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=67 (0x43) <SOH>2.N644AAM_<STX>S30AAA0077<ETX>

FLoc=238564439 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 10:45:14 DL MsgLen= 24 DBI= 5 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=73 (0x49) <SOH>2.N644AA<NAK>51<STX>M52AAA0077<ETX>

FLoc=238576579 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 10:45:16 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=67 (0x43) <SOH>2.N644AA<NAK>51<STX>M52AAA0077<ETX>

FLoc=238587970 AJPSBcnt= 62 ULBLK S=31 D=21 BEPts=20010911 10:45:19 UL MsgLen= 21 Stn= IADC6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA551N<STX>104519<ETX>

FLoc=238595564 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 10:45:20 DL MsgLen= 24 DBI= 6 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=72 (0x48) <SOH>2.N644AAN_<STX>S31AAA0077<ETX>

FLoc=238610926 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 10:45:22 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=67 (0x43) <SOH>2.N644AAN_<STX>S31AAA0077<ETX>

FLoc=252550201 AJPSBcnt= 75 DLBLK S=31 D=21 BEPts=20010911 11:13:29 DL MsgLen= 44 DBI= 7 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=72 (0x48) <SOH>2.N644AA<NAK>H1<STX>F000AA0000#M1AFPR/CRKIADKLAX43<ETX>

FLoc=252550276 AJPSBcnt= 168 DLMSG S=31 D=21 BEPts=20010911 11:13:29 ADNS MsgLen= 128 Tail Number= .N644AA SMI= FML FltId= AA0000 AgyNum= 1 (0x0001)

<CR><LF>
<SOH>QU RURDLXA DCABFXA DCAGFXA TULDDAA <CR><LF>
.DDLXCXA 111113<CR><LF>
<STX>FML<CR><LF>
FI AA0/AN N644AA<CR><LF>
DT DDL IAD 111113 F000<CR><LF>
- FPR/CRKIADKLAX43<CR><LF>
<ETX><EOT>

FLoc=252572383 AJPSBcnt= 244 ULMSG S=31 D=21 BEPts=20010911 11:13:32 ADNS MsgLen= 187 Org Addr= TULDDAA Org TimeStamp= 20010911 11:13:00 Smi= FML AgyNum= 65535
Tail Number= .N644AA FltId= AA0000
Target Stn= IAD<00><00> Target Method= 1
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111113 FROM <CR><LF>
AN N644AA/AP IAD<CR><LF>
- FPR/RTKIADKLAX43:R:RW300:F:LDN.J134.HNN.J134.STL.J110.FMN.J6<TSTRET>
4.PGS.J128.CIVET/ZF1449/CL390/CI050/DGP00/FFM00B081<ETX><EOT>

FLoc=252573264 AJPSBcnt= 341 ULMSG S=31 D=21 BEPts=20010911 11:13:32 ADNS MsgLen= 284 Org Addr= TULDDAA Org TimeStamp= 20010911 11:13:00 Smi= FML AgyNum= 65535 Tail Number= .N644AA FltId= AA0000 Target Stn= IAD<00><00> Target Method= 1 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111113 FROM <CR><LF> .TULDDAA 111113 FROM <CR><LF> AN N644AA/AP IAD<CR><LF> - PWD/ERLDN 310022COLNS280025STEVY280034LAYED290033HNN 29003<TSTRET> 3FLM 300033GBEES300035JUDDI300037CAROL300040STL 290041ELSTO<TSTRET> 280040SCAWT270040BUM 270041FRACA270041PEABO270041GCK 260042<TSTRET>

FLoc=252574358 AJPSBcnt= 75 DLBLK S=31 D=21 BEPts=20010911 11:13:32 DL MsgLen= 44 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=69 (0x45) <SOH>2.N644AA<NAK>H1<STX>F000AA0000#M1AFPR/CRKIADKLAX43<ETX>

ALS 270046FMN 27005282F3<ETX><EOT>

FLoc=252574598 AJPSBcnt= 187 ULMSG S=31 D=21 BEPts=20010911 11:13:32

ADNS MsgLen= 130 Org Addr= TULDDAA Org TimeStamp= 20010911 11:13:00

Smi= FML AgyNum= 65535

Tail Number= .N644AA FitId= AA0000

Target Stn= IAD<00><00> Target Method= 1

<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111113 FROM <CR><LF>
.TULDDAA 111113 FROM <CR><LF>
AN N644AA/AP IAD</CR><LF>
- PWD/ERTBC 270051PGS 250052RUSTT230043CIVET210033C1EA</ETX><EOT><TSTRET>

FLoc=252584191 AJPSBcnt= 172 ULBLK S=31 D=21 BEPts=20010911 11:13:34

UL MsgLen= 131 Stn= IADC6 StnDelivType= 2
Tail= .N644AA Fid= AA0000
<SOH>2.N644AA7H1O<STX>- #M1FPR/RTKIADKLAX43:R:RW300:F:LDN.J134<TSTRET>
.HNN.J134.STL.J110.FMN.J64.PGS.J128.CIVET/ZF1449/CL390/CI050/<TSTRET>
DGP00/FFM00B081<ETX>

FLoc=252607210 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:13:36 DL MsgLen= 24 DBI= 8 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=73 (0x49) <SOH>2.N644AAO_<STX>S32AAA0077<ETX>

FLoc=252626035 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:13:37 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=69 (0x45) <SOH>2.N644AAO_<STX>S32AAA0077<ETX>

FLoc=252652534 AJPSBcnt= 269 ULBLK S=31 D=21 BEPts=20010911 11:13:41 UL MsgLen= 228 Stn= IADC6 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA</BANK>H1P<STX>- #M1PWD/ERLDN 310022COLNS280025STE<TSTRET> VY280034LAYED290033HNN 290033FLM 300033GBEES300035JUDDI3000<TSTRET> 37CAROL300040STL 290041ELSTO280040SCAWT270040BUM 270041FRAC<TSTRET> A270041PEABO270041GCK 260042ALS 270046FMN 27005282F3<ETX>

FLoc=252684036 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:13:44 DL MsgLen= 24 DBI= 9 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=71 (0x47) <SOH>2.N644AAPQ5<STX>S33AAA0077<ETX>

FLoc=252700969 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:13:46 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=70 (0x46) <SOH>2.N644AAPQ5<STX>S33AAA0077<ETX>

FLoc=252850069 AJPSBcnt= 269 ULBLK S=31 D=21 BEPts=20010911 11:14:06 UL MsgLen= 228 Stn= IADC6 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA</BANK>H1Q<STX>-#M1PWD/ERLDN 310022COLNS280025STE<TSTRET> VY280034LAYED290033HNN 290033FLM 300033GBEES300035JUDDI3000<TSTRET> 37CAROL300040STL 290041ELSTO280040SCAWT270040BUM 270041FRAC<TSTRET> A270041PEABO270041GCK 260042ALS 270046FMN 27005282F3<ETX>

FLoc=252927005 AJPSBcnt= 269 ULBLK S=31 D=21 BEPts=20010911 11:14:16 UL MsgLen= 228 Stn= IADC6 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA</BACKSHAQ<STX>-#M1PWD/ERLDN 310022COLNS280025STE<TSTRET> VY280034LAYED290033HNN 290033FLM 300033GBEES300035JUDDI3000<TSTRET> 37CAROL300040STL 290041ELSTO280040SCAWT270040BUM 270041FRAC<TSTRET> A270041PEABO270041GCK 260042ALS 270046FMN 27005282F3<ETX>

FLoc=252955855 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:14:19 DL MsgLen= 24 DBI= 0 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=72 (0x48) <SOH>2.N644AAQ_<STX>S34AAA0077<ETX>

FLoc=252975415 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:14:21

DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=69 (0x45) <SOH>2.N644AAQ <STX>S34AAA0077<ETX>

FLoc=252993927 AJPSBcnt= 115 ULBLK S=31 D=21 BEPts=20010911 11:14:24 UL MsgLen= 74 Stn= IADC6 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>H1R<STX>- #M1PWD/ERTBC 270051PGS 250052RUS<TSTRET> TT230043CIVET210033C1EA<ETX>

FLoc=253011314 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:14:25 DL MsgLen= 24 DBI= 1 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=72 (0x48) <SOH>2.N644AAR_<STX>S35AAA0077<ETX>

FLoc=253024040 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:14:27 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=69 (0x45) <SOH>2.N644AAR_<STX>S35AAA0077<ETX>

FLoc=254233655 AJPSBcnt= 75 DLBLK S=31 D=21 BEPts=20010911 11:16:52 DL MsgLen= 44 DBI= 2 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=72 (0x48) <SOH>2.N644AA<NAK>H1<STX>F001AA0000#M1ALIF/DAKIAD/RD300<ETX>

FLoc=254254064 AJPSBcnt= 189 ULMSG S=31 D=21 BEPts=20010911 11:16:54
ADNS MsgLen= 132 Org Addr= TULDDAA Org TimeStamp= 20010911 11:16:00
Smi= FML AgyNum= 65535
Tail Number= .N644AA FitId= AA0077
Target Stn= IAD<00><00> Target Method= 1
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111116 FROM <CR><LF>
AN N644AA/AP IAD<CR><LF>
- LIF/TT17701221291383000015P451589130134138P63/ZF1449B406<ETX><EOT><TSTRET>

FLoc=254263434 AJPSBcnt= 75 DLBLK S=31 D=21 BEPts=20010911 11:16:55 DL MsgLen= 44 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=71 (0x47) <SOH>2.N644AA<NAK>H1<STX>F001AA0000#M1ALIF/DAKIAD/RD300<ETX>

FLoc=254277433 AJPSBcnt= 117 ULBLK S=31 D=21 BEPts=20010911 11:16:57

UL MsgLen= 76 Stn= IADC6 StnDelivType= 2
Tail= .N644AA Fid= AA0077
<SOH>2.N644AA2H1S<STX>- #M1LIF/TT17701221291383000015P45158913<TSTRET>
0134138P63/ZF1449B406<ETX>

FLoc=254292785 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:16:58 DL MsgLen= 24 DBI= 3 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=72 (0x48) <SOH>2.N644AAS_<STX>S36AAA0077<ETX>

FLoc=254310664 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:17:01 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=71 (0x47) <SOH>2.N644AAS_<STX>S36AAA0077<ETX>

FLoc=264869597 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 11:36:31 DL MsgLen= 35 DBI= 4 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=72 (0x48) <SOH>2.N644AA<NAK>5Z<STX>M53AAA0077OS LAX /CLR<ETX>

FLoc=264869663 AJPSBcnt= 148 DLMSG S=31 D=21 BEPts=20010911 11:36:31 ADNS MsgLen= 108 Tail Number= .N644AA SMI= AGM FltId= AA0077 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA TULDDAA <CR><LF>
.DDLXCXA 111136<CR><LF>
<STX>AGM<CR><LF>
FI AA77/AN N644AA<CR><LF>
DT DDL IAD 111136 M53A<CR><LF>
- OS LAX /CLR<CR><LF>
<ETX><ETX><EOT>

FLoc=264882733 AJPSBcnt= 278 ULMSG S=31 D=21 BEPts=20010911 11:36:32 ADNS MsgLen= 221 Org Addr= TULDDAA Org TimeStamp= 20010911 11:36:00 Smi= AGM AgyNum= 65535 Tail Number= .N644AA FltId= AA0077 Target Stn= IAD<00><00> Target Method= 1 <CR>><LF> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111136 FROM <CR><LF> <STX>AGM<CR><LF> AN N644AA/AP IAD<CR><LF> FLIGHT 0077/11 IAD -LAX <CR><LF> PDC<CR><LF> NO DEPARTURE CLEARANCE MESSAGE ON FILE<CR><LF> CONTACT CLEARANCE DELIVERY VIA VOICE<CR><LF> REQUEST FULL ROUTE CLEARANCE<CR><LF> END<CR><LF> <ETX><EOT>

FLoc=264889566 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 11:36:33 DL MsgLen= 35 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=67 (0x43) <SOH>2.N644AA<NAK>5Z<STX>M53AAA0077OS LAX /CLR<ETX>

FLoc=264909474 AJPSBcnt= 259 ULBLK S=31 D=21 BEPts=20010911 11:36:36

FLoc=264931708 AJPSBcnt= 154 DLMSG S=31 D=21 BEPts=20010911 11:36:38 ADNS MsgLen= 114 Tail Number= .N644AA SMI= DEP FltId= AA0077 AgyNum= 1 (0x0001)

CR><LF>
<SOH>QU RURDLXA ANPDMXA TULDDAA <CR><LF>
.DDLXCXA 111136
CR><LF>
<STX>DEP<CR><LF>
FI AA77/AN N644AA/DA IAD/DS LAX<CR><LF>
DT DDL IAD 111136 M54A<CR><LF>
<ETX><EOT>

FLoc=264972200 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 11:36:43 UL MsgLen= 14 Stn= IADC6 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA5 U<ETX>

FLoc=269246673 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 11:44:24 DL MsgLen= 35 DBI= 6 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=71 (0x47) <SOH>2.N644AA<NAK>5Z<STX>M55AAA0077OS LAX /CLR<ETX>

FLoc=269246739 AJPSBcnt= 148 DLMSG S=31 D=21 BEPts=20010911 11:44:24 ADNS MsgLen= 108 Tail Number= .N644AA SMI= AGM FltId= AA0077 AgyNum= 1 (0x0001) <CR><LF> <SOH>QU RURDLXA TULDDAA <CR><LF> .DDLXCXA 111144<CR><LF> <STX>AGM<CR><LF> FI AA77/AN N644AA<CR><LF> < DT DDL IAD 111144 M55A<CR><LF>
- OS LAX /CLR<CR><LF>
<ETX><EOT>

FLoc=269276336 AJPSBcnt= 66 DLBLK S=31 D=21 BEPts=20010911 11:44:27 DL MsgLen= 35 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=67 (0x43) <SOH>2.N644AA<NAK>5Z<STX>M55AAA0077OS LAX /CLR<ETX>

FLoc=269282780 AJPSBcnt= 384 ULMSG S=31 D=21 BEPts=20010911 11:44:28 ADNS MsgLen= 327 Org Addr= TULDDAA Org TimeStamp= 20010911 11:44:00 Smi= AGM AgyNum= 65535 Tail Number= .N644AA FItId= AA0077 Target Stn= IAD<00><00> Target Method= 1 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111144 FROM <CR><LF> <STX>AGM<CR><LF> AN N644AA/AP IAD<CR><LF> FLIGHT 0077/11 IAD -LAX <CR><LF> PDC<CR><LF> AAL77 XPNDR 6553<CR><LF> L/B752/E P1210 390<CR><LF> <CR><LF> IAD LDN J134 HNN J134 STL<CR><LF> J110 FMN J64 PGS J128<CR><LF> CIVET CIVET4 LAX<CR><LF> <CR><LF> CAPITAL 5 DEPARTURE. MAINTAIN 3000<CR><LF> DEPT FREQ 126.65<CR><LF> <CR><LF> ADZ GROUND CONTROL OF THE ATIS<CR><LF> <CR><LF> <CR><LF> END<CR><LF> <ETX><EOT>

FLoc=269288700 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 11:44:29 UL MsgLen= 235 Stn= IADC6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA6C1V<STX>.TULDDAA 111144 FROM <CR><LF> AGM<CR><LF> AN N644AA/AP IAD<CR><LF> - FLIGHT 0077/11 IAD -LAX <CR><LF> PDC<CR><LF> AAL77 XPNDR 6553<CR><LF> L/B752/E P1210 390<CR><LF> <CR><LF> IAD LDN J134 HNN J134 STL<CR><LF> J110 FMN J64 PGS J128<CR><LF> CIVET CIVET4 LAX<CR><LF> <CR><LF> CAPITAL 5 DE<ETB>

FLoc=269316855 AJPSBcnt= 74 DLBLK S=31 D=21 BEPts=20010911 11:44:32 DL MsgLen= 43 DBI= 7 DlIndicator= 1 DlNumStns= 1

```
BepStnName = IADC6 SSV=71 (0x47)
T>
<NUL><NUL><NUL><NUL><NUL>LAX<ETX>
FLoc=269316929 AJPSBcnt= 154 DLMSG S=31 D=21 BEPts=20010911 11:44:32
ADNS MsgLen= 114 Tail Number= .N644AA SMI= DEP
FltId= AA0077 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA ANPDMXA TULDDAA <CR><LF>
.DDLXCXA 111144<CR><LF>
<STX>DEP<CR><LF>
FI AA77/AN N644AA/DA IAD/DS LAX<CR><LF>
DT DDL IAD 111144 M56A<CR><LF>
<ETX><EOT>
FLoc=269336710 AJPSBcnt= 74 DLBLK S=31 D=21 BEPts=20010911 11:44:34
DL MsgLen= 43 DBI= 7 DlIndicator= 2 DlNumStns= 1
BepStnName = IADA6 SSV=68 (0x44)
T>
<NUL><NUL><NUL><NUL><NUL>LAX<ETX>
FLoc=269357437 AJPSBcnt= 145 ULBLK S=31 D=21 BEPts=20010911 11:44:37
UL MsgLen= 104 Stn= IADC6 StnDelivType= 1
Tail= .N644AA Fid= AA0077
<SOH>2.N644AA7C1W<STX>PARTURE. MAINTAIN 3000<CR><LF>
DEPT FREQ 126.65<CR><LF>
<CR><LF>
ADZ GROUND CONTROL OF THE ATIS<CR><LF>
<CR><LF>
<CR><LF>
END<CR><LF>
<ETX>
FLoc=269377750 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:44:38
DL MsgLen= 24 DBI= 8 DlIndicator= 1 DlNumStns= 1
BepStnName = IADC6 SSV=71 (0x47)
<SOH>2.N644AAW_<DEL><STX>S37AAA0077<ETX>
FLoc=269398636 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 11:44:41
DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1
BepStnName = IADA6 SSV=69 (0x45)
<SOH>2.N644AAW_<DEL><STX>S37AAA0077<ETX>
FLoc=271779765 AJPSBcnt= 74 DLBLK S=31 D=21 BEPts=20010911 11:49:13
DL MsgLen= 43 DBI= 9 DlIndicator= 1 DlNumStns= 1
BepStnName = IADC6 SSV=71 (0x47)
<NUL><NUL>0494LAX<ETX>
FLoc=271779931 AJPSBcnt= 161 DLMSG S=31 D=21 BEPts=20010911 11:49:13
ADNS MsgLen= 121 Tail Number= .N644AA SMI= DEP
```

FltId= AA0077 AgyNum= 1 (0x0001)

<CR><LF>

<SOH>QU RURDLXA ANPDMXA TULDDAA <CR><LF>.DDLXCXA 111149
CR><LF>
<STX>DEP<CR><LF>
FI AA77/AN N644AA/DA IAD/FB 494/DS LAX
CR><LF>
DT DDL IAD 111149 M57A
CR><ETX><EOT>

FLoc=271805168 AJPSBcnt= 74 DLBLK S=31 D=21 BEPts=20010911 11:49:16
DL MsgLen= 43 DBI= 9 DlIndicator= 2 DlNumStns= 1
BepStnName = IADA6 SSV=68 (0x44)
<SOH>2.N644AA<NAK>QE<STX>M57AAA0077IAD<NUL><NUL><NUL><NUL><NUL><NUL><TSTRET
> <NUL><NUL>0494LAX<ETX>

FLoc=271826405 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 11:49:18 UL MsgLen= 14 Stn= IADC6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA9_X<ETX>

FLoc=285131323 AJPSBcnt= 206 DLBLK S=31 D=21 BEPts=20010911 12:09:01 DL MsgLen= 175 DBI= 0 DlIndicator= 1 DINumStns= 1 BepStnName = IADC6 SSV=85 (0x55) <SOH>2.N644AA<NAK>H1<STX>F002AA0000#M1APWDP390HVQ39LAYEDHNN Y<TSTRET> RK13FLM CVG25GBEESMOSEYJUDDICAROLJIGSYSTL TRAKEELSTOSCAWTBU<TSTRET> M FRACAPEABOGCK ALS FMN COCANTBC PGS ETINEABREEDIKESEMM<TSTRET> EY<ETX>

FLoc=285131529 AJPSBcnt= 299 DLMSG S=31 D=21 BEPts=20010911 12:09:01
ADNS MsgLen= 259 Tail Number= .N644AA SMI= FML
FltId= AA0000 AgyNum= 1 (0x0001)

<CR><LF>
<SOH>QU RURDLXA DCABFXA DCAGFXA TULDDAA <CR><LF>
.DDLXCXA 111209<CR><LF>
<STX>FML<CR><LF>
FI AA0/AN N644AA<CR><LF>
DT DDL IAD 111209 F002<CR><LF>
- PWDP390HVQ39LAYEDHNN YRK13FLM CVG25GBEESMOSEYJUDDICAROLJI<TSTRET>
GSYSTL TRAKEELSTOSCAWTBUM FRACAPEABOGCK ALS FMN COCANTBC<TSTRET>
PGS ETINEABREEDIKESEMMEY<CR><LF>
<ETX><EOT>

```
FLM 390 303033<CR><LF>
 GBEES 390 300036<CR><LF>
MOSEY 390 300036<CR><LF>
JUDDI 390 296038<CR><LF>
CAROL 390 293043<CR><LF>
  JIGSY 390 293043<CR><LF>
  STL 390 288041<CR><LF>
  TRAKE 390 282040<CR><LF>
ELSTO 390 276040<CR><LF>
  SCAWT 390 273041<CR><LF>
  BUM 390 270041<CR><LF>FRACA 390 267041<CR><LF>
  PEABO 390 264041<CR><LF>
  GCK 390 260045<CR><LF>
ALS 390 272051<CR><LF>
  FMN 390 275050<CR><LF>
  COCAN 390 267052<CR><LF>
  TBC 390 259054<CR><LF>
 PGS 390 246048<CR><LF>
ETINE 390 239052<CR><LF>
ABREE 390 234057<CR><LF>
DIKES 390 234057<CR><LF>
  EMMEY 390 234057<CR><LF>
 /DESCENT
                    <CR><LF>
      180 199028<CR><LF>
<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX><EOT>
```

FLoc=285192023 AJPSBcnt= 206 DLBLK S=31 D=21 BEPts=20010911 12:09:05 DL MsgLen= 175 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=70 (0x46) <SOH>2.N644AA<NAK>H1<STX>F002AA0000#M1APWDP390HVQ39LAYEDHNN Y<TSTRET> RK13FLM CVG25GBEESMOSEYJUDDICAROLJIGSYSTL TRAKEELSTOSCAWTBU<TSTRET> M FRACAPEABOGCK ALS FMN COCANTBC PGS ETINEABREEDIKESEMM<TSTRET> EY<ETX>

FLoc=285222181 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:09:08

DL MsgLen= 24 DBI= 1 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=72 (0x48) <SOH>2.N644AAY_<STX>S38AAA0077<ETX>

EY<ETX>

FLoc=285248000 AJPSBcnt= 206 DLBLK S=31 D=21 BEPts=20010911 12:09:10 DL MsgLen= 175 DBI= 2 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=73 (0x49) <SOH>2.N644AA<NAK>H1<STX>F003AA0000#M1APWDP350HVQ39LAYEDHNN Y<TSTRET> RK13FLM CVG25GBEESMOSEYJUDDICAROLJIGSYSTL TRAKEELSTOSCAWTBU<TSTRET> M FRACAPEABOGCK ALS FMN COCANTBC PGS ETINEABREEDIKESEMM<TSTRET>

FLoc=285248206 AJPSBcnt= 299 DLMSG S=31 D=21 BEPts=20010911 12:09:10
ADNS MsgLen= 259 Tail Number= .N644AA SMI= FML
FltId= AA0000 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA DCABFXA DCAGFXA TULDDAA <CR><LF>
.DDLXCXA 111209<CR><LF>
<STX>FML<CR><LF>
FI AA0/AN N644AA<CR><LF>
DT DDL IAD 111209 F003<CR><LF>
- PWDP350HVQ39LAYEDHNN YRK13FLM CVG25GBEESMOSEYJUDDICAROLJI<TSTRET>
GSYSTL TRAKEELSTOSCAWTBUM FRACAPEABOGCK ALS FMN COCANTBC<TSTRET>
PGS ETINEABREEDIKESEMMEY<CR><LF>
<ETX><EOT>

FLoc=285250851 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:09:10 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=70 (0x46) <SOH>2.N644AAY_<STX>S38AAA0077<ETX>

FLoc=285280101 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:09:13 UL MsgLen= 235 Stn= IADC6 StnDelivType= 1 Tail= .N644AA Fid= AA0077
<SOH>2.N644AA2C1Z<STX> 390 300036<CR><LF> JUDDI 390 296038<CR><LF> CAROL 390 293043<CR><LF> JIGSY 390 293043<CR><LF> STL 390 288041<CR><LF> TRAKE 390 282040<CR><LF> ELSTO 390 276040<CR><LF> SCAWT 390 273041<CR><LF> SCAWT 390 273041<CR><LF> SCAWT 390 270041<CR><LF> SCAWT SCAWT 390 270041<CR><LF> SCAWT SCAWT

FLoc=285286009 AJPSBcnt= 206 DLBLK S=31 D=21 BEPts=20010911 12:09:13 DL MsgLen= 175 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=70 (0x46) <SOH>2.N644AA<NAK>H1<STX>F003AA0000#M1APWDP350HVQ39LAYEDHNN Y<TSTRET> RK13FLM CVG25GBEESMOSEYJUDDICAROLJIGSYSTL TRAKEELSTOSCAWTBU<TSTRET> M FRACAPEABOGCK ALS FMN COCANTBC PGS ETINEABREEDIKESEMM<TSTRET> EY<ETX>

FLoc=285293826 AJPSBcnt= 870 ULMSG S=31 D=21 BEPts=20010911 12:09:14 ADNS MsgLen= 813 Org Addr= TULDDAA Org TimeStamp= 20010911 12:08:00 Smi= AGM AgyNum= 65535

Tail Number= .N644AA FltId= AA0077 Target Stn= IAD<00><00> Target Method= 1 <CR><LF> <SOH>QU DDLXCXA<CR><LF> <CR><LF> .TULDDAA 111208 FROM <STX>AGM<CR><LF> AN N644AA/AP IAD<CR><LF> - PREDICTED WINDS<CR><LF> /ENROUTE<CR><LF> POINT ALT WINDS <CR><LF> LAYED 350 295031<CR><LF> HNN 350 303031<CR><LF> FLM 350 309032<CR><LF> GBEES 350 309032<CR><LF>
MOSEY 350 309032<CR><LF>
JUDDI 350 305033<CR><LF> CAROL 350 300036<CR><LF>
JIGSY 350 300036<CR><LF>
STL 350 294035<CR><LF> TRAKE 350 282034<CR><LF> ELSTO 350 272034<CR><LF> SCAWT 350 267034<CR><LF> BUM 350 263034<CR><LF>FRACA 350 261033<CR><LF> PEABO 350 258035<CR><LF> GCK 350 255038<CR><LF>
ALS 350 271044<CR><LF>
FMN 350 273043<CR><LF> COCAN 350 266042<CR><LF> TBC 350 258045<CR><LF>PGS 350 242045<CR><LF> ETINE 350 237048<CR><LF> ABREE 350 232053<CR><LF> DIKES 350 232053<CR><LF> EMMEY 350 232053<CR><LF> /DESCENT <CR><LF> 180 199028<CR><LF> <CR><LF> <LF> <CR><LF> <| F> <LF> <ETX><EOT>

FLoc=285304275 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:09:15 DL MsgLen= 24 DBI= 3 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=72 (0x48) <SOH>2.N644AAZ_<STX>S39AAA0077<ETX>

FLoc=285338877 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:09:17 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=70 (0x46) <SOH>2.N644AAZ <STX>S39AAA0077<ETX>

FLoc=285360702 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:09:20 UL MsgLen= 235 Stn= IADC6 StnDelivType= 1

Tail= .N644AA Fid= AA0077

<SOH>2.N644AA<NAK>C1A<STX>FRACA 390 267041<CR><LF>
PEABO 390 264041<CR><LF>
GCK 390 260045<CR><LF>
ALS 390 272051<CR><LF>
FMN 390 275050<CR><LF>
COCAN 390 267052<CR><LF>
TBC 390 259054<CR><LF>
PGS 390 246048<CR><LF>
ETINE 390 239052<ETB>

FLoc=285404131 AJPSBcnt= 206 DLBLK S=31 D=21 BEPts=20010911 12:09:23 DL MsgLen= 175 DBI= 4 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=72 (0x48) <SOH>2.N644AAAH1<STX>F004AA0000#M1APWDP310HVQ39LAYEDHNN YRK13<TSTRET> FLM CVG25GBEESMOSEYJUDDICAROLJIGSYSTL TRAKEELSTOSCAWTBUM F<TSTRET> RACAPEABOGCK ALS FMN COCANTBC PGS ETINEABREEDIKESEMMEY<ETX>

FLoc=285404337 AJPSBcnt= 299 DLMSG S=31 D=21 BEPts=20010911 12:09:23
ADNS MsgLen= 259 Tail Number= .N644AA SMI= FML
FltId= AA0000 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA DCABFXA DCAGFXA TULDDAA <CR><LF>
.DDLXCXA 111209<CR><LF>
<STX>FML<CR><LF>
FI AA0/AN N644AA<CR><LF>
DT DDL IAD 111209 F004<CR><LF>
- PWDP310HVQ39LAYEDHNN YRK13FLM CVG25GBEESMOSEYJUDDICAROLJI<TSTRET>
GSYSTL TRAKEELSTOSCAWTBUM FRACAPEABOGCK ALS FMN COCANTBC<TSTRET>
PGS ETINEABREEDIKESEMMEY<CR><LF>
<ETX><EOT>

FLoc=285439496 AJPSBcnt= 206 DLBLK S=31 D=21 BEPts=20010911 12:09:26 DL MsgLen= 175 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=70 (0x46) <SOH>2.N644AAAH1<STX>F004AA0000#M1APWDP310HVQ39LAYEDHNN YRK13<TSTRET> FLM CVG25GBEESMOSEYJUDDICAROLJIGSYSTL TRAKEELSTOSCAWTBUM F<TSTRET> RACAPEABOGCK ALS FMN COCANTBC PGS ETINEABREEDIKESEMMEY<ETX>

```
MOSEY 310 305028<CR><LF>
 JUDDI 310 308028<CR><LF>
 CAROL 310 304029<CR><LF>
 JIGSY 310 304029<CR><LF>
STL 310 296029<CR><LF>
 TRAKE 310 286028<CR><LF>
 ELSTO 310 272027<CR><LF>
 SCAWT 310 259027<CR><LF>
 BUM 310 251028<CR><LF>
 FRACA 310 246027<CR><LF>
PEABO 310 245029<CR><LF>
 GCK 310 250032<CR><LF>
 ALS 310 273036<CR><LF>FMN 310 279036<CR><LF>
 COCAN 310 272036<CR><LF>
 TBC 310 262036<CR><LF>
 PGS 310 239033<CR><LF>
ETINE 310 231036<CR><LF>
 ABREE 310 224043<CR><LF> DIKES 310 224043<CR><LF>
 EMMEY 310 224043<CR><LF>
 /DESCENT
                 <CR><LF>
     180 199028<CR><LF>
<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX><EOT>
FLoc=285459565 AJPSBcnt= 191 ULBLK S=31 D=21 BEPts=20010911 12:09:28
UL MsgLen= 150 Stn= IADC6 StnDelivType= 1
Tail= .N644AA Fid= AA0077
<SOH>2.N644AA4C1B<STX><CR><LF>
 ABREE 390 234057<CR><LF>
DIKES 390 234057<CR><LF>
 EMMEY 390 234057<CR><LF>
                <CR><LF>
 /DESCENT
     180 199028<CR><LF>
<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX>
FLoc=285474568 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:09:29
DL MsgLen= 24 DBI= 5 DlIndicator= 1 DlNumStns= 1
BepStnName = IADC6 SSV=72 (0x48)
<SOH>2.N644AAB <DEL><STX>S40AAA0077<ETX>
FLoc=285487765 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:09:31
DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1
BepStnName = IADA6 SSV=69 (0x45)
<SOH>2.N644AAB_<DEL><STX>S40AAA0077<ETX>
```

FLoc=285518487 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:09:34 UL MsgLen= 235 Stn= IADC6 StnDelivType= 1 Tail= .N644AA Fid= AA0077
<SOH>2.N644AA<NAK>C1C<STX>.TULDDAA 111208 FROM

CR><LF>
AGM<CR><LF>
AN N644AA/AP IAD<CR><LF>
- PREDICTED WINDS<CR><LF>
/ENROUTE<CR><LF>
POINT ALT WINDS <CR><LF>
LAYED 350 295031<CR><LF>
HNN 350 303031<CR><LF>
FLM 350 309032<CR><LF>
GBEES 350 309032<CR><LF>
MOSEY<ETB>

FLoc=285537877 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:09:35 DL MsgLen= 24 DBI= 6 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=72 (0x48) <SOH>2.N644AAC_<STX>S41AAA0077<ETX>

FLoc=285554477 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:09:37 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=67 (0x43) <SOH>2.N644AAC <STX>S41AAA0077<ETX>

FLoc=285582318 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:09:40 UL MsgLen= 235 Stn= IADC6 StnDelivType= 1 Tail= .N644AA Fid= AA0077
<SOH>2.N644AA<NAK>C1D<STX> 350 309032<CR><LF> JUDDI 350 305033<CR><LF> CAROL 350 300036<CR><LF> JIGSY 350 300036<CR><LF> STL 350 294035<CR><LF> TRAKE 350 282034<CR><LF> ELSTO 350 272034<CR><LF> SCAWT 350 267034<CR><LF> BUM 350 263034<CR><LF> SUM 350 263034<CR><LF> SCAWT 350 263034<CR><LF SCAWT 350 263034<CR

FLoc=285601254 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:09:41 DL MsgLen= 24 DBI= 7 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=70 (0x46) <SOH>2.N644AAD_<STX>S42AAA0077<ETX>

FLoc=285627254 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:09:44 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=67 (0x43) <SOH>2.N644AAD_<STX>S42AAA0077<ETX>

FLoc=285645517 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:09:46 UL MsgLen= 235 Stn= IADC6 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA</NAK>C1E<STX>FRACA 350 261033<CR><LF> PEABO 350 258035<CR><LF> GCK 350 255038<CR><LF> ALS 350 271044<CR><LF>

```
FMN 350 273043<CR><LF>
 COCAN 350 266042<CR><LF>
 TBC 350 258045<CR><LF>PGS 350 242045<CR><LF>ETINE 350 237048<ETB>
FLoc=285663965 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:09:47
DL MsgLen= 24 DBI= 8 DlIndicator= 1 DlNumStns= 1
BepStnName = IADC6 SSV=71 (0x47)
<SOH>2.N644AAE_<DEL><STX>S43AAA0077<ETX>
FLoc=285708390 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:09:51
DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1
BepStnName = IADA6 SSV=67 (0x43)
<SOH>2.N644AAE_<DEL><STX>S43AAA0077<ETX>
FLoc=285719215 AJPSBcnt= 191 ULBLK S=31 D=21 BEPts=20010911 12:09:52
UL MsgLen= 150 Stn= IADC6 StnDelivType= 1
Tail= .N644AA Fid= AA0077
<SOH>2.N644AA<NAK>C1F<STX><CR><LF>
 ABREE 350 232053<CR><LF>
DIKES 350 232053<CR><LF>
 EMMEY 350 232053<CR><LF>
 /DESCENT
                <CR><LF>
     180 199028<CR><LF>
<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX>
FLoc=285752026 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:09:54
DL MsgLen= 24 DBI= 9 DlIndicator= 1 DlNumStns= 1
BepStnName = IADC6 SSV=72 (0x48)
<SOH>2.N644AAF_<DEL><STX>S44AAA0077<ETX>
FLoc=285782403 AJPSBcnt= 74 DLBLK S=31 D=21 BEPts=20010911 12:09:56
DL MsgLen= 43 DBI= 0 DlIndicator= 1 DlNumStns= 1
BepStnName = IADC6 SSV=72 (0x48)
<SOH>2.N644AA<NAK>QE<STX>M58AAA0077IAD1209<NUL><NUL><NUL><NUL><NUL><NUL><TSTRET>
0494LAX<ETX>
FLoc=285782477 AJPSBcnt= 169 DLMSG S=31 D=21 BEPts=20010911 12:09:56
ADNS MsgLen= 129 Tail Number= .N644AA SMI= DEP
FitId= AA0077 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA ANPDMXA TULDDAA <CR><LF>
.DDLXCXA 111209<CR><LF>
<STX>DEP<CR><LF>
FI AA77/AN N644AA/DA IAD/OT 1209/FB 494/DS LAX<CR><LF>
DT DDL IAD 111209 M58A<CR><LF>
<ETX><EOT>
FLoc=285805242 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:09:58
```

DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1

FLoc=285813358 AJPSBcnt= 74 DLBLK S=31 D=21 BEPts=20010911 12:09:59 DL MsgLen= 43 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=68 (0x44) <SOH>2.N644AA<NAK>QE<STX>M58AAA0077IAD1209<NUL><NUL><NUL><NUL><NUL><NUL><TSTRET> 0494LAX<ETX>

FLoc=285834694 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:10:00 DL MsgLen= 24 DBI= 1 DIIndicator= 1 DINumStns= 1 BepStnName = IADC6 SSV=71 (0x47) <SOH>2.N644AAG_<STX>S45AAA0077<ETX>

FLoc=285871139 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:10:03 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=67 (0x43) <SOH>2.N644AAG_<STX>S45AAA0077<ETX>

FLoc=285891151 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:10:05 UL MsgLen= 235 Stn= IADC6 StnDelivType= 1 Tail= .N644AA Fid= AA0077
<SOH>2.N644AA<NAK>C1H<STX> 310 305028<CR><LF> JUDDI 310 308028<CR><LF> CAROL 310 304029<CR><LF> JIGSY 310 304029<CR><LF> STL 310 296029<CR><LF> TRAKE 310 286028<CR><LF> ELSTO 310 272027<CR><LF> SCAWT 310 259027<CR><LF> SCAWT 310 251028<CR><LF> BUM 310 251028<CR><LF> <

FLoc=285906025 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:10:06 DL MsgLen= 24 DBI= 2 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=73 (0x49) <SOH>2.N644AAH_<STX>S46AAA0077<ETX>

FLoc=285940068 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:10:09 DL MsgLen= 24 DBl= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=71 (0x47)

Target Stn= IAD<00><00> Target Method= 1

```
FLoc=285954043 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:10:11
UL MsgLen= 235 Stn= IADC6 StnDelivType= 1
Tail= .N644AA Fid= AA0077
<SOH>2.N644AA<NAK>C1I<STX>FRACA 310 246027<CR><LF>
 PEABO 310 245029<CR><LF>
 GCK 310 250032<CR><LF>
ALS 310 273036<CR><LF>
FMN 310 279036<CR><LF>
 COCAN 310 272036<CR><LF>
 TBC 310 262036<CR><LF>
PGS 310 239033<CR><LF>
ETINE 310 231036<ETB>
FLoc=285969255 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:10:12
DL MsgLen= 24 DBI= 3 DlIndicator= 1 DlNumStns= 1
BepStnName = IADC6 SSV=73 (0x49)
<SOH>2.N644AAI_<DEL><STX>S47AAA0077<ETX>
FLoc=285992780 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:10:14
DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1
BepStnName = IADA6 SSV=68 (0x44)
<SOH>2.N644AAI_<DEL><STX>S47AAA0077<ETX>
FLoc=286032617 AJPSBcnt= 191 ULBLK S=31 D=21 BEPts=20010911 12:10:17
UL MsgLen= 150 Stn= IADC6 StnDelivType= 1
Tail= .N644AA Fid= AA0077
<SOH>2.N644AA<NAK>C1J<STX><CR><LF>
 ABREE 310 224043<CR><LF>
DIKES 310 224043<CR><LF>
 EMMEY 310 224043<CR><LF>
                 <CR><LF>
 /DESCENT
     180 199028<CR><LF>
<CR><LF>
<LF>
<CR><LF>
<LF>
<| F>
<ETX>
FLoc=286055634 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:10:18
DL MsgLen= 24 DBI= 4 DlIndicator= 1 DlNumStns= 1
BepStnName = IADC6 SSV=73 (0x49)
<SOH>2.N644AAJ_<DEL><STX>S48AAA0077<ETX>
FLoc=286090995 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:10:21
DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1
BepStnName = IADA6 SSV=72 (0x48)
<SOH>2.N644AAJ_<DEL><STX>S48AAA0077<ETX>
FLoc=286106835 AJPSBcnt= 341 ULMSG S=31 D=21 BEPts=20010911 12:10:22
ADNS MsgLen= 284 Org Addr= TULDDAA Org TimeStamp= 20010911 12:10:00
Smi= AGM AgyNum= 65535
Tail Number= .N644AA FltId= AA0077
```

```
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111210 FROM L002
                           <CR><LF>
<STX>AGM<CR><LF>
AN N644AA/AP IAD<CR><LF>
- LOAD CLOSEOUT RVSN 00 0810L<CR><LF>
0077 IAD-LAX N5BP<CR><LF>
TOW 193855<CR><LF>
FOB 48800A<CR><LF>
ZFW 145055<CR><LF>
STAB 4.5<CR><LF>
CG 19.5 PCT
               <CR><LF>
PSGR 58 W0 X0<CR><LF>
PSGR WGT 10440<CR><LF>
CGO WGT 2625 <CR><LF>
EOW 131990<CR><LF>
SECOK<CR><LF>
  <CR><LF>
<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX><EOT>
FLoc=286107451 AJPSBcnt= 315 ULMSG S=31 D=21 BEPts=20010911 12:10:22
ADNS MsgLen= 258 Org Addr= TULDDAA Org TimeStamp= 20010911 12:10:00
Smi= FML AgyNum= 65535
Tail Number= .N644AA FltId= AA0077
Target Stn= IAD<00><00> Target Method= 1
<CR>><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111210 FROM
                        <CR><LF>
<STX>FML<CR><LF>
AN N644AA/AP IAD<CR><LF>
- LIF/TT17701231301383000015P451589131134138P63/TT177012313013<TSTRET>
8300X015P451589131134138P63/TT177012213013801L0015P4515891301<TSTRET>
34138P63/TT177012213013819RT015P451589130134138P63/ZF1450803F<TSTRET>
<ETX><EOT>
FLoc=286110915 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:10:23
UL MsgLen= 235 Stn= IADC6 StnDelivType= 1
Tail= .N644AA Fid= AA0077
AGM<CR><LF>
AN N644AA/AP IAD<CR><LF>
- LOAD CLOSEOUT RVSN 00 0810L<CR><LF>
0077 IAD-LAX N5BP<CR><LF>
TOW 193855<CR><LF>
FOB 48800A<CR><LF>
ZFW 145055<CR><LF>
STAB
      4.5<CR><LF>
```

CG 19.5 PCT

CGO WG<ETB>

PSGR 58 W0 X0<CR><LF> PSGR WGT 10440<CR><LF>

<CR><LF>

FLoc=286133121 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:10:25 DL MsgLen= 24 DBI= 5 DIIndicator= 1 DINumStns= 1 BepStnName = IADC6 SSV=72 (0x48) <SOH>2.N644AAK_<STX>S49AAA0077<ETX>

FLoc=286155234 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:10:27 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=70 (0x46) <SOH>2.N644AAK_<STX>S49AAA0077<ETX>

FLoc=286196619 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:10:31 DL MsgLen= 24 DBI= 6 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=72 (0x48) <SOH>2.N644AAL_<STX>S50AAA0077<ETX>

FLoc=286236396 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:10:34 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=70 (0x46) <SOH>2.N644AAL_<STX>S50AAA0077<ETX>

FLoc=286248275 AJPSBcnt= 243 ULBLK S=31 D=21 BEPts=20010911 12:10:36 UL MsgLen= 202 Stn= IADC6 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>H1M<STX>- #M1LIF/TT17701231301383000015P4515<TSTRET> 89131134138P63/TT1770123130138300X015P451589131134138P63/TT17<TSTRET> 7012213013801L0015P451589130134138P63/TT177012213013819RT015P<TSTRET> 451589130134138P63/ZF1450803F<ETX>

FLoc=286288751 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:10:39 DL MsgLen= 24 DBI= 7 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=72 (0x48) <SOH>2.N644AAM_<STX>S51AAA0077<ETX>

FLoc=286316054 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:10:42 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=68 (0x44) <SOH>2.N644AAM_<STX>S51AAA0077<ETX>

FLoc=287418307 AJPSBcnt= 77 DLBLK S=31 D=21 BEPts=20010911 12:12:19 DL MsgLen= 46 DBI= 8 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=72 (0x48)

<SOH>2.N644AA<NAK>B9<STX>M59AAA0077/KIAD.TI2/039KIADDCD7D<ETX>

FLoc=287418384 AJPSBcnt= 161 DLMSG S=31 D=21 BEPts=20010911 12:12:19
ADNS MsgLen= 121 Tail Number= .N644AA SMI= RAI
FitId= AA0077 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA ATSAAXA TULDDAA <CR><LF>
.DDLXCXA 111212<CR><LF>
<STX>RAI<CR><LF>
FI AA77/AN N644AA<CR><LF>
DT DDL IAD 111212 M59A<CR><LF>
- TI2/039KIADDCD7D<CR><LF>
<ETX><EOT>

FLoc=287460895 AJPSBcnt= 77 DLBLK S=31 D=21 BEPts=20010911 12:12:22 DL MsgLen= 46 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=73 (0x49) <SOH>2.N644AA<NAK>B9<STX>M59AAA0077/KIAD.TI2/039KIADDCD7D<ETX>

FLoc=287465876 AJPSBcnt= 535 ULMSG S=31 D=21 BEPts=20010911 12:12:23 ADNS MsgLen= 478 Org Addr= ATSAAXA Org TimeStamp= 20010911 12:11:00 Smi= DAI AgyNum= 65535 Tail Number= .N644AA FltId= AA0077 Target Stn= <00><00><00><00> Target Method= 0 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .ATSAAXA 111211<CR><LF> <STX>DAI<CR><LF> AN N644AA<CR><LF> - /ATSAAXA.TI2/KIAD DEP ATIS X<CR><LF> 1151Z IAD ATIS INFO X 1151Z. 00000KT 10SM CLR<CR><LF> 17/14 A3021 (THREE ZERO TWO ONE), APCH<CR><LF> IN USE. ILS/VA CONDUCTED SIMULTANEOUSLY<CR><LF> RWY 1R, RWY 1L. DEPG RWY 30. SINGLE GC<CR><LF> FREQ IN USE ON 121.9. NOTAMS... TWY K<CR><LF> CLSD NORTH OF TWY B; TWY J CLSD SOUTH<CR><LF> OF TWY E; TWY A CLSD EAST OF TWY J. <CR><LF> RUNWAY ONE NINER LEFT RUNUP BLOCK<CR><LF> UNAVAILABLE. BIRD ACTIVITY VICINITY<CR><LF> ARPT. ...ADVS YOU HAVE INFO X.E4D1<CR><LF> <ETX><EOT>

FLoc=287479779 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:12:24 UL MsgLen= 235 Stn= IADC6 StnDelivType= 2 Tail= .N644AA Fid= AA0077
<SOH>2.N644AA8A9N<STX>/ATSAAXA.TI2/KIAD DEP ATIS X<CR><LF> 1151Z IAD ATIS INFO X 1151Z. 00000KT 10SM CLR<CR><LF> 17/14 A3021 (THREE ZERO TWO ONE). APCH<CR><LF> IN USE. ILS/VA CONDUCTED SIMULTANEOUSLY<CR><LF> RWY 1R, RWY 1L. DEPG RWY 30. SINGLE GC<CR><LF> FREQ IN USE ON 121.9. <ETB>

FLoc=287498405 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:12:25 DL MsgLen= 24 DBI= 9 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=72 (0x48) <SOH>2.N644AAN_<STX>S52AAA0077<ETX> FLoc=287548213 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:12:29 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=70 (0x46) <SOH>2.N644AAN <STX>S52AAA0077<ETX>

FLoc=287555250 AJPSBcnt= 260 ULBLK S=31 D=21 BEPts=20010911 12:12:30 UL MsgLen= 219 Stn= IADC6 StnDelivType= 1 Tail= .N644AA Fid= AA0077
<SOH>2.N644AA<NAK>A9O<STX>NOTAMS... TWY K<CR><LF> CLSD NORTH OF TWY B; TWY J CLSD SOUTH<CR><LF> OF TWY E; TWY A CLSD EAST OF TWY J .<CR><LF> RUNWAY ONE NINER LEFT RUNUP BLOCK<CR><LF> UNAVAILABLE. BIRD ACTIVITY VICINITY<CR><LF> ARPT. ...ADVS YOU HAVE INFO X.E4D1<CR><LF> <ETX>

FLoc=287579627 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:12:31 DL MsgLen= 24 DBI= 0 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=74 (0x4A) <SOH>2.N644AAO <STX>S53AAA0077<ETX>

FLoc=287620390 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:12:34 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=71 (0x47) <SOH>2.N644AAO_<STX>S53AAA0077<ETX>

FLoc=292507902 AJPSBcnt= 65 DLBLK S=31 D=21 BEPts=20010911 12:20:23 DL MsgLen= 34 DBI= 1 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=70 (0x46) <SOH>2.N644AA<NAK>QF<STX>M60AAA0077IAD1220LAX<ETX>

FLoc=292507967 AJPSBcnt= 154 DLMSG S=31 D=21 BEPts=20010911 12:20:23 ADNS MsgLen= 114 Tail Number= .N644AA SMI= DEP FltId= AA0077 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA TULDDAA <CR><LF>
.DDLXCXA 111220 <CR><LF>
<STX>DEP <CR><LF>
FI AA77/AN N644AA/DA IAD/OF 1220/DS LAX<CR><LF>
DT DDL IAD 111220 M60A <CR><LF>
<ETX><EOT>

FLoc=292517406 AJPSBcnt= 65 DLBLK S=31 D=21 BEPts=20010911 12:20:25 DL MsgLen= 34 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=75 (0x4B) <SOH>2.N644AA<NAK>QF<STX>M60AAA0077IAD1220LAX<ETX>

FLoc=292540786 AJPSBcnt= 62 ULBLK S=31 D=21 BEPts=20010911 12:20:28 UL MsgLen= 21 Stn= IADA6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA1;;P<STX>130025<ETX>

FLoc=292558186 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:20:29 DL MsgLen= 24 DBI= 2 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=71 (0x47)

<SOH>2.N644AAP_<STX>S54AAA0077<ETX>

FLoc=292571756 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:20:31 DL MsgLen= 24 DBI= 2 DIIndicator= 2 DINumStns= 1 BepStnName = IADA6 SSV=74 (0x4A) <SOH>2.N644AAP_<STX>S54AAA0077<ETX>

FLoc=292590483 AJPSBcnt= 71 DLBLK S=31 D=21 BEPts=20010911 12:20:33 DL MsgLen= 40 DBI= 3 DlIndicator= 1 DlNumStns= 1 BepStnName = IADA2 SSV=66 (0x42) <SOH>2.N644AA<NAK>10<STX>M61AAA0077OS LAX /FQY30025<ETX>

FLoc=292597281 AJPSBcnt= 71 DLBLK S=31 D=21 BEPts=20010911 12:20:34 DL MsgLen= 40 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = DCAA2 SSV=45 (0x2D) <SOH>2.N644AA<NAK>10<STX>M61AAA0077OS LAX /FQY30025<ETX>

FLoc=292609405 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:20:36 UL MsgLen= 14 Stn= IADA2 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA3_Q<ETX>

FLoc=293064230 AJPSBcnt= 205 DLBLK S=31 D=21 BEPts=20010911 12:21:27 DL MsgLen= 174 DBI= 4 DlIndicator= 1 DlNumStns= 1 BepStnName = BWIB2 SSV=41 (0x29) <SOH>2.N644AA<NAK>H1<STX>D005AA0077#DFBEDA/E4002,197,09C,08F,,<TSTRET> 5C05AC,57D56B,530580,6265E3,059064,374263,3<CR><LF> 724A6,160145,208428C4,25D,08E08D,59E592,0E549464F637,010,000,1<TSTRET> ,5115E4<CR><LF> ,0C1408<ETX>

FLoc=293064435 AJPSBcnt= 307 DLMSG S=31 D=21 BEPts=20010911 12:21:27 ADNS MsgLen= 267 Tail Number= .N644AA SMI= DFD FltId= AA0077 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA ABZDS8X BDROOXA DCABFXA TULDDAA <CR><LF>
.DDLXCXA 111221<CR><LF>
<STX>DFD<CR><LF>
FI AA77/AN N644AA<CR><LF>
DT DDL BWI 111221 D005<CR><LF>
- EDA/E4002,197,09C,08F,,5C05AC,57D56B,530580,6265E3,059064,3<TSTRET> 74263,3<CR><LF>
724A6,160145,208428C4,25D,08E08D,59E592,0E549464F637,010,000,1<TSTRET> ,5115E4<CR><LF>

```
,0C1408<CR><LF><ETX><EOT>
```

FLoc=293100178 AJPSBcnt= 205 DLBLK S=31 D=21 BEPts=20010911 12:21:30 DL MsgLen= 174 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA2 SSV=67 (0x43)
<SOH>2.N644AA<NAK>H1<STX>D005AA0077#DFBEDA/E4002,197,09C,08F,,<TSTRET> 5C05AC,57D56B,530580,6265E3,059064,374263,3<CR><LF> 724A6,160145,208428C4,25D,08E08D,59E592,0E549464F637,010,000,1<TSTRET> ,5115E4<CR><LF> ,0C1408<ETX>

FLoc=293100383 AJPSBcnt= 211 DLBLK S=31 D=21 BEPts=20010911 12:21:30 DL MsgLen= 174 DBI= 4 DlIndicator= 2 DlNumStns= 2 BepStnName = DCAA2 SSV=57 (0x39) BepStnName = BWIA2 SSV=48 (0x30) <SOH>2.N644AA<NAK>H1<STX>D005AA0077#DFBEDA/E4002,197,09C,08F,,<TSTRET> 5C05AC,57D56B,530580,6265E3,059064,374263,3<CR><LF>724A6,160145,208428C4,25D,08E08D,59E592,0E549464F637,010,000,1<TSTRET> ,5115E4<CR><LF>,0C1408<ETX>

FLoc=293115646 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:21:32 UL MsgLen= 14 Stn= IADA2 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA4_R<ETX>

FLoc=294944682 AJPSBcnt=1550 ULMSG S=31 D=21 BEPts=20010911 12:24:40 ADNS MsgLen= 1493 Org Addr= TULDDAA Org TimeStamp= 20010911 12:24:00 Smi= AGM AgyNum= 65535 Tail Number= .N644AA FltId= AA0077 Target Stn= IAD<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111224 FROM <CR><LF> <STX>AGM<CR><LF> AN N644AA/GL IAD<CR><LF> - FLT 0077 IAD-LAX SKD ARR 1036L<CR><LF> PLN 1027L<CR><LF> OUT 1209 0494<CR><LF> OFF 1220 0490<CR><LF> LDN 1228 0474<CR><LF> COLNS 1236 0452<CR><LF> STEVY 1240 0437<CR><LF> 0422<CR><LF> 0405<CR><LF>

```
GCK 1459
            0279<CR><LF>
ALS
    1535
           0240<CR><LF>
    1552
            0222<CR><LF>
FMN
TBC
     1615
            0198<CR><LF>
            0180<CR><LF>
    1632
PGS
RUSTT 1707
             0150<CR><LF>
CIVET 1709
ON 1720
            0149<CR><LF>
           0141<CR><LF>
 IN 1727
          0139<CR><LF>
          <CR><LF>
- FLT 0077 IAD-LAX SKD ARR 1036L<CR><LF>
        PLN 1027L<CR><LF>
 OUT 1209
            0494<CR><LF>
 OFF 1220
            0490<CR><LF>
LDN 1228
            0474<CR><LF>
COLNS 1236
             0452<CR><LF>
STEVY 1240
             0437<CR><LF>
LAYED 1251
             0424<CR><LF>
HNN 1253
FLM 1308
            0422<CR><LF>
            0405<CR><LF>
GBEES 1313
             0398<CR><LF>
JUDDI 1322
            0388<CR><LF>
CAROL 1339
             0369<CR><LF>
STL 1349
           0357<CR><LF>
ELSTO 1400
             0344<CR><LF>
SCAWT 1414
              0329<CR><LF>
BUM 1417
            0326<CR><LF>
FRACA 1433
             0308<CR><LF>
PEABO 1436
             0304<CR><LF>
GCK 1459
            0279<CR><LF>
ALS 1535
            0240<CR><LF>
FMN
    1552
            0222<CR><LF>
            0198<CR><LF>
TBC
     1615
PGS 1632
            0180<CR><LF>
RUSTT 1707
             0150<CR><LF>
CIVET 1709
            0149<CR><LF>
 ON 1720
           0141<CR><LF>
          0139<CR><LF>
 IN 1727
          <CR><LF>
<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
```

<ETX><EOT>

```
FLoc=294946232 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:24:40
UL MsgLen= 235 Stn= IADA2 StnDelivType= 2
Tail= .N644AA Fid= AA0077
<SOH>2.N644AA<NAK>C1S<STX>.TULDDAA 111224 FROM
                                                       <CR><LF>
AGM<CR><LF>
AN N644AA/GL IAD<CR><LF>
- FLT 0077 IAD-LAX SKD ARR 1036L<CR><LF>
         PLN
              1027L<CR><LF>
OUT 1209
           0494<CR><LF>
OFF 1220
            0490<CR><LF>
LDN 1228
          0474<CR><LF>
             0452<CR><LF>
COLNS 1236
STEV<ETB>
FLoc=294948903 AJPSBcnt= 290 ULMSG S=31 D=21 BEPts=20010911 12:24:40
ADNS MsgLen= 233 Org Addr= TULDDAA Org TimeStamp= 20010911 12:24:00
Smi= AGM AgyNum= 65535
Tail Number= .N644AA FltId= AA0077
Target Stn= IAD<00><00> Target Method= 2
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111224 FROM
                          <CR><LF>
<STX>AGM<CR><LF>
AN N644AA/GL IAD<CR><LF>
- /FLT 0077 IAD-LAX<CR><LF>
LAX KLAX 111224<CR><LF>
111155<CR><LF>
111150Z 00000KT 9SM FEW014 18/16 A2991 RMK AO2 SLP124 <CR><LF>
  T01780156 10189 20178 53001 <CR><LF>
END DATA <CR><LF>
<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX><EOT>
FLoc=294980079 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:24:43
DL MsgLen= 24 DBI= 5 DlIndicator= 1 DlNumStns= 1
BepStnName = PHLC2 SSV=45 (0x2D)
<SOH>2.N644AAS_<DEL><STX>S55AAA0077<ETX>
FLoc=294980392 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:24:43
DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1
BepStnName = BWIB2 SSV=48 (0x30)
<SOH>2.N644AAS_<DEL><STX>S55AAA0077<ETX>
FLoc=294980447 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:24:43
DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1
BepStnName = RICA2 SSV=50 (0x32)
<SOH>2.N644AAS_<DEL><STX>S55AAA0077<ETX>
FLoc=294991037 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:24:44
DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1
BepStnName = PHLA2 SSV=49 (0x31)
```

<SOH>2.N644AAS_<STX>S55AAA0077<ETX>

FLoc=294998600 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:24:45 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA2 SSV=62 (0x3E) <SOH>2.N644AAS_<STX>S55AAA0077<ETX>

FLoc=295024589 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:24:48 UL MsgLen= 235 Stn= IADA2 StnDelivType= 1 Tail= .N644AA Fid= AA0077
<SOH>2.N644AA<NAK>C1T<STX>Y 1240 0437<CR><LF> LAYED 1251 0424<CR><LF> HNN 1253 0422<CR><LF> FLM 1308 0405<CR><LF> GBEES 1313 0398<CR><LF> GBEES 1313 0398<CR><LF> CAROL 1339 0369<CR><LF> STL 1349 0357<CR><LF> ELSTO 1400 0344<CR><LF> SCAWT 1414 <ETB>

FLoc=295054341 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:24:51 DL MsgLen= 24 DBI= 6 DlIndicator= 1 DlNumStns= 1 BepStnName = BWIB2 SSV=53 (0x35) <SOH>2.N644AAT_<STX>S56AAA0077<ETX>

FLoc=295054396 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:24:51 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = RICA2 SSV=47 (0x2F) <SOH>2.N644AAT_<STX>S56AAA0077<ETX>

FLoc=295066393 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:24:52 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIA2 SSV=57 (0x39) <SOH>2.N644AAT_<STX>S56AAA0077<ETX>

FLoc=295082737 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:24:53 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA2 SSV=63 (0x3F) <SOH>2.N644AAT_<STX>S56AAA0077<ETX>

FLoc=295112419 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:24:56 UL MsgLen= 235 Stn= IADA2 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>C1U<STX>0329<CR><LF> BUM 1417 0326<CR><LF> FRACA 1433 0308<CR><LF> PEABO 1436 0304<CR><LF> GCK 1459 0279<CR><LF> ALS 1535 0240<CR><LF> FMN 1552 0222<CR><LF> 1615 TBC 0198<CR><LF> PGS 1632 0180<CR><LF> RUSTT 1707 0150<CR><LF> CIVET <ETB>

```
FLoc=295151723 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:24:59
DL MsgLen= 24 DBI= 7 DlIndicator= 1 DlNumStns= 1
BepStnName = BWIB2 SSV=56 (0x38)
<SOH>2.N644AAU_<DEL><STX>S57AAA0077<ETX>
FLoc=295151778 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:24:59
DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = RICA2 SSV=51 (0x33)
<SOH>2.N644AAU_<DEL><STX>S57AAA0077<ETX>
FLoc=295175443 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:01
DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1
BepStnName = IADA2 SSV=62 (0x3E)
<SOH>2.N644AAU_<DEL><STX>S57AAA0077<ETX>
FLoc=295176499 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:25:01
DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 2
BepStnName = DCAA2 SSV=59 (0x3B)
BepStnName = BWIA2 SSV=56 (0x38)
<SOH>2.N644AAU_<DEL><STX>S57AAA0077<ETX>
FLoc=295197236 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:25:04
UL MsgLen= 235 Stn= IADA2 StnDelivType= 1
Tail= .N644AA Fid= AA0077
<SOH>2.N644AA<NAK>C1V<STX>1709 0149<CR><LF>
 ON 1720
           0141<CR><LF>
 IN 1727
           0139<CR><LF>
           <CR><LF>
- FLT 0077 IAD-LAX SKD ARR 1036L<CR><LF>
         PLN 1027L<CR><LF>
 OUT 1209 0494<CR><LF>
 OFF 1220<ETB>
FLoc=295226627 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:07
DL MsgLen= 24 DBI= 8 DlIndicator= 1 DlNumStns= 1
BepStnName = PHLC2 SSV=45 (0x2D)
<SOH>2.N644AAV_<DEL><STX>S58AAA0077<ETX>
FLoc=295227599 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:07
DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1
BepStnName = BWIB2 SSV=53 (0x35)
<SOH>2.N644AAV <DEL><STX>S58AAA0077<ETX>
```

FLoc=295238933 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:08

DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1

BepStnName = BWIA2 SSV=56 (0x38) <SOH>2.N644AAV_<STX>S58AAA0077<ETX>

FLoc=295247358 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:09 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA2 SSV=62 (0x3E) <SOH>2.N644AAV_<STX>S58AAA0077<ETX>

FLoc=295276826 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:25:12 UL MsgLen= 235 Stn= IADA2 StnDelivType= 1 Tail= .N644AA Fid= AA0077
<SOH>2.N644AA<NAK>C1W<STX> 0490<CR><LF> LDN 1228 0474<CR><LF> COLNS 1236 0452<CR><LF> STEVY 1240 0437<CR><LF> LAYED 1251 0424<CR><LF> HNN 1253 0422<CR><LF> FLM 1308 0405<CR><LF> GBEES 1313 0398<CR><LF> JUDDI 1322 0388<CR><LF> O388<CR><LF>

0369<CR><LF>

CAROL 1339

S<ETB>

FLoc=295310015 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:15 DL MsgLen= 24 DBI= 9 DlIndicator= 1 DlNumStns= 1 BepStnName = PHLC2 SSV=44 (0x2C) <SOH>2.N644AAW_<STX>S59AAA0077<ETX>

FLoc=295310131 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:15 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB2 SSV=52 (0x34) <SOH>2.N644AAW_<STX>S59AAA0077<ETX>

FLoc=295310241 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:15 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = RICA2 SSV=53 (0x35) <SOH>2.N644AAW <STX>S59AAA0077<ETX>

FLoc=295323778 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:16 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = PHLA2 SSV=48 (0x30) <SOH>2.N644AAW_<STX>S59AAA0077<ETX>

FLoc=295332001 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:17 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA2 SSV=62 (0x3E) <SOH>2.N644AAW_<STX>S59AAA0077<ETX>

FLoc=295358780 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:25:20 UL MsgLen= 235 Stn= IADA2 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>C1X<STX>TL 1349 0357<CR><LF> ELSTO 1400 0344<CR><LF> SCAWT 1414 0329<CR><LF> BUM 1417 0326<CR><LF> FRACA 1433 0308<CR><LF> SCAWS STANDER ST

```
PEABO 1436
             0304<CR><LF>
GCK 1459 0279<CR><LF>
ALS 1535
            0240<CR><LF>
FMN
     1552
            0222<CR><LF>
TBC
     1615 <ETB>
FLoc=295389008 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:23
DL MsgLen= 24 DBI= 0 DlIndicator= 1 DlNumStns= 1
BepStnName = BWIB2 SSV=56 (0x38)
<SOH>2.N644AAX_<DEL><STX>S60AAA0077<ETX>
FLoc=295389173 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:23
DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1
BepStnName = RICA2 SSV=54 (0x36)
<SOH>2.N644AAX_<DEL><STX>S60AAA0077<ETX>
FLoc=295403181 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:25:24
DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 2
BepStnName = DCAA2 SSV=59 (0x3B)
BepStnName = BWIA2 SSV=56 (0x38)
<SOH>2.N644AAX_<DEL><STX>S60AAA0077<ETX>
FLoc=295427554 AJPSBcnt= 211 ULBLK S=31 D=21 BEPts=20010911 12:25:28
UL MsgLen= 170 Stn= IADA2 StnDelivType= 1
Tail= .N644AA Fid= AA0077
<SOH>2.N644AA<NAK>C1Y<STX> 0198<CR><LF>
PGS 1632
           0180<CR><LF>
RUSTT 1707
             0150<CR><LF>
CIVET 1709
            0149<CR><LF>
 ON 1720
           0141<CR><LF>
 IN 1727
          0139<CR><LF>
          <CR><LF>
<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<ETX>
FLoc=295449873 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:30
DL MsgLen= 24 DBI= 1 DlIndicator= 1 DlNumStns= 1
BepStnName = BWIB2 SSV=52 (0x34)
<SOH>2.N644AAY_<DEL><STX>S61AAA0077<ETX>
FLoc=295449928 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:30
DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1
BepStnName = RICA2 SSV=60 (0x3C)
<SOH>2.N644AAY_<DEL><STX>S61AAA0077<ETX>
FLoc=295449983 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:30
DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1
BepStnName = RDUB2 SSV=44 (0x2C)
<SOH>2.N644AAY_<DEL><STX>S61AAA0077<ETX>
FLoc=295463753 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:32
```

DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1

```
BepStnName = IADA2 SSV=62 (0x3E)
<SOH>2.N644AAY_<DEL><STX>S61AAA0077<ETX>
```

<LF> <LF> <ETX>

FLoc=295465225 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:25:32 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 2 BepStnName = DCAA2 SSV=60 (0x3C) BepStnName = BWIA2 SSV=57 (0x39) <SOH>2.N644AAY_<STX>S61AAA0077<ETX>

FLoc=295482081 AJPSBcnt= 271 ULBLK S=31 D=21 BEPts=20010911 12:25:35 UL MsgLen= 230 Stn= IADA2 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>C1Z<STX>.TULDDAA 111224 FROM <CR><LF> AGM<CR><LF> AN N644AA/GL IAD<CR><LF> - /FLT 0077 IAD-LAX<CR><LF> LAX KLAX 111224<CR><LF> 111155<CR><LF> 111150Z 00000KT 9SM FEW014 18/16 A2991 RMK AO2 SLP124 <CR><LF> T01780156 10189 20178 53001 <CR><LF> END DATA <CR><LF> <CR><LF> <| F> <CR><LF>

FLoc=295507421 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:38 DL MsgLen= 24 DBI= 2 DlIndicator= 1 DlNumStns= 1 BepStnName = BWIB2 SSV=56 (0x38) <SOH>2.N644AAZ <STX>S62AAA0077<ETX>

FLoc=295507531 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:38 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = RICA2 SSV=56 (0x38) <SOH>2.N644AAZ <STX>S62AAA0077<ETX>

FLoc=295530913 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:25:40 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 2 BepStnName = DCAA2 SSV=62 (0x3E) BepStnName = BWIA2 SSV=57 (0x39) <SOH>2.N644AAZ <STX>S62AAA0077<ETX>

FLoc=295538187 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:25:41 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA2 SSV=62 (0x3E) <SOH>2.N644AAZ_<STX>S62AAA0077<ETX>

FLoc=297198055 AJPSBcnt= 216 DLBLK S=31 D=21 BEPts=20010911 12:28:30 DL MsgLen= 185 DBI= 3 DlIndicator= 1 DlNumStns= 1 BepStnName = BWIB2 SSV=42 (0x2A) <SOH>2.N644AA<NAK>H1<STX>F005AA0000#M1APWDA350STEVYHVQ39LAYEDH<TSTRET> NN YRK13FLM CVG25GBEESMOSEYJUDDICAROLJIGSYSTL TRAKEELSTOSC<TSTRET> AWTBUM FRACAPEABOGCK ALS FMN COCANTBC PGS ETINEABREEDIK<TSTRET> ESEMMEYCONDR<ETX>

FLoc=297198271 AJPSBcnt= 309 DLMSG S=31 D=21 BEPts=20010911 12:28:30 ADNS MsgLen= 269 Tail Number= .N644AA SMI= FML FltId= AA0000 AgyNum= 1 (0x0001) <CR><LF> <SOH>QU RURDLXA DCABFXA DCAGFXA TULDDAA <CR><LF> .DDLXCXA 111228 < CR> < LF> <STX> FML < CR> < LF> FI AA0/AN N644AA < CR> < LF> DT DDL BWI 111228 F005 < CR> < LF>

- PWDA350STEVYHVQ39LAYEDHNN YRK13FLM CVG25GBEESMOSEYJUDDICA<TSTRET> ROLJIGSYSTL TRAKEELSTOSCAWTBUM FRACAPEABOGCK ALS FMN COC<TSTRET> ANTBC PGS ETINEABREEDIKESEMMEYCONDR<CR><LF> <ETX><FOT>

FLoc=297198580 AJPSBcnt= 216 DLBLK S=31 D=21 BEPts=20010911 12:28:30 DL MsgLen= 185 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = RICA2 SSV=52 (0x34) <SOH>2.N644AA<NAK>H1<STX>F005AA0000#M1APWDA350STEVYHVQ39LAYEDH<TSTRET>

<SOH>2.N644AA<NAK>H1<STX>F005AA0000#M1APWDA350STEVYHVQ39LAYEDH<TSTRET> NN YRK13FLM CVG25GBEESMOSEYJUDDICAROLJIGSYSTL TRAKEELSTOSC<TSTRET> AWTBUM FRACAPEABOGCK ALS FMN COCANTBC PGS ETINEABREEDIK<TSTRET> ESEMMEYCONDR<ETX>

FLoc=297198796 AJPSBcnt= 216 DLBLK S=31 D=21 BEPts=20010911 12:28:30 DL MsgLen= 185 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB2 SSV=51 (0x33) <SOH>>2.N644AA<NAK>H1<STX>F005AA0000#M1APWDA350STEVYHVQ39LAYEDH<TSTRET> NN YRK13FLM CVG25GBEESMOSEYJUDDICAROLJIGSYSTL TRAKEELSTOSC<TSTRET> AWTBUM FRACAPEABOGCK ALS FMN COCANTBC PGS ETINEABREEDIK<TSTRET>

FLoc=297219264 AJPSBcnt= 216 DLBLK S=31 D=21 BEPts=20010911 12:28:32 DL MsgLen= 185 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = ROAA2 SSV=53 (0x35) <SOH>2.N644AA<NAK>H1<STX>F005AA0000#M1APWDA350STEVYHVQ39LAYEDH<TSTRET>

ESEMMEYCONDR<ETX>

<SOH>2.N644AA<NAK>H1<STX>F005AA0000#M1APWDA350STEVYHVQ39LAYEDH<TSTRET>
NN YRK13FLM CVG25GBEESMOSEYJUDDICAROLJIGSYSTL TRAKEELSTOSC<TSTRET>
AWTBUM FRACAPEABOGCK ALS FMN COCANTBC PGS ETINEABREEDIK<TSTRET>
ESEMMEYCONDR<ETX>

FLoc=297219706 AJPSBcnt= 222 DLBLK S=31 D=21 BEPts=20010911 12:28:32 DL MsgLen= 185 DBI= 3 DlIndicator= 2 DlNumStns= 2 BepStnName = CRWA2 SSV=52 (0x34) BepStnName = ORFA2 SSV=39 (0x27) <SOH>2.N644AA<NAK>H1<STX>F005AA0000#M1APWDA350STEVYHVQ39LAYEDH<TSTRET> NN YRK13FLM CVG25GBEESMOSEYJUDDICAROLJIGSYSTL TRAKEELSTOSC<TSTRET> AWTBUM FRACAPEABOGCK ALS FMN COCANTBC PGS ETINEABREEDIK<TSTRET> ESEMMEYCONDR<ETX>

FLoc=297228800 AJPSBcnt= 341 ULMSG S=31 D=21 BEPts=20010911 12:28:33 ADNS MsgLen= 284 Org Addr= TULDDAA Org TimeStamp= 20010911 12:28:00 Smi= FML AgyNum= 65535 Tail Number= .N644AA FltId= AA0077 Target Stn= IAD<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111228 FROM <CR><LF>

<STX>FML<CR><LF>

AN N644AA/GL IAD<CR><LF>

- PWD/ERSTEVY288029LAYED295031HNN 303031FLM 309032GBEES30903<TSTRET> 2MOSEY309032JUDDI305033CAROL300036JIGSY300036STL 294035TRAKE<TSTRET> 284034ELSTO272034SCAWT267034BUM 263034FRACA261033PEABO258035<TSTRET> GCK 254037ALS 2710442459<ETX><EOT>

8ABREE232053DIKES232053EMMEY232053CONDR230045C4B2<ETX><EOT>

- PWD/DW180199028FCCF<ETX><EOT>

FLoc=297232075 AJPSBcnt= 216 DLBLK S=31 D=21 BEPts=20010911 12:28:33 DL MsgLen= 185 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIA2 SSV=58 (0x3A)

<SOH>2.N644AA<NAK>H1<STX>F005AA0000#M1APWDA350STEVYHVQ39LAYEDH<TSTRET>NN YRK13FLM CVG25GBEESMOSEYJUDDICAROLJIGSYSTL TRAKEELSTOSC<TSTRET>AWTBUM FRACAPEABOGCK ALS FMN COCANTBC PGS ETINEABREEDIK<TSTRET>ESEMMEYCONDR<ETX>

FLoc=297244656 AJPSBcnt= 269 ULBLK S=31 D=21 BEPts=20010911 12:28:35 UL MsgLen= 228 Stn= DCAA2 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA3H1A<STX>- #M1PWD/ERSTEVY288029LAYED295031HNN 30<TSTRET> 3031FLM 309032GBEES309032MOSEY309032JUDDI305033CAROL300036JI<TSTRET> GSY300036STL 294035TRAKE284034ELSTO272034SCAWT267034BUM 263<TSTRET> 034FRACA261033PEABO258035GCK 254037ALS 2710442459<ETX>

FLoc=297345035 AJPSBcnt= 269 ULBLK S=31 D=21 BEPts=20010911 12:28:45 UL MsgLen= 228 Stn= DCAA2 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA3H1A<STX>- #M1PWD/ERSTEVY288029LAYED295031HNN 30<TSTRET> 2021ELM 2000320 PEFE 200032MOSE V200032 ULD D1205032 CAPOL 200036 UST TETTET>

3031FLM 309032GBEES309032MOSEY309032JUDDI305033CAROL300036JI<TSTRET>
GSY300036STL 294035TRAKE284034ELSTO272034SCAWT267034BUM 263<TSTRET>
034FRACA261033PEABO258035GCK 254037ALS 2710442459<ETX>

FLoc=297374105 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:28:48 DL MsgLen= 39 DBI= 4 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC2 SSV=56 (0x38) <SOH>2.N644AAAQ7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297375294 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:28:48 DL MsgLen= 39 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = RICA2 SSV=54 (0x36) <SOH>2.N644AAAQ7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297375364 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:28:48 DL MsgLen= 39 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB2 SSV=52 (0x34) <SOH>2.N644AAAQ7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297383785 AJPSBcnt= 82 DLBLK S=31 D=21 BEPts=20010911 12:28:49 DL MsgLen= 39 DBI= 4 DlIndicator= 2 DlNumStns= 3 BepStnName = ROAA2 SSV=54 (0x36) BepStnName = ACYA2 SSV=42 (0x2A) BepStnName = AVPA2 SSV=27 (0x1B) <SOH>2.N644AAAQ7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297390739 AJPSBcnt= 88 DLBLK S=31 D=21 BEPts=20010911 12:28:50 DL MsgLen= 39 DBI= 4 DlIndicator= 2 DlNumStns= 4 BepStnName = IADA2 SSV=60 (0x3C) BepStnName = CRWA2 SSV=53 (0x35) BepStnName = PITA2 SSV=53 (0x35) BepStnName = ORFA2 SSV=33 (0x21) <SOH>2.N644AAAQ7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297396893 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:28:51 DL MsgLen= 39 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = DCAA2 SSV=59 (0x3B) <SOH>2.N644AAAQ7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297414372 AJPSBcnt= 170 ULBLK S=31 D=21 BEPts=20010911 12:28:53 UL MsgLen= 129 Stn= DCAA2 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA4H1B<STX>- #M1PWD/ERFMN 273043COCAN266042TBC 25<TSTRET> 8045PGS 242045ETINE237048ABREE232053DIKES232053EMMEY232053CO<TSTRET> NDR230045C4B2<ETX>

FLoc=297514916 AJPSBcnt= 170 ULBLK S=31 D=21 BEPts=20010911 12:29:03 UL MsgLen= 129 Stn= DCAA2 StnDelivType= 1

Tail= .N644AA Fid= AA0077 <SOH>2.N644AA4H1B<STX>- #M1PWD/ERFMN 273043COCAN266042TBC 25<TSTRET> 8045PGS 242045ETINE237048ABREE232053DIKES232053EMMEY232053CO<TSTRET> NDR230045C4B2<ETX>

FLoc=297573455 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:29:09 DL MsgLen= 39 DBI= 4 DlIndicator= 3 DlNumStns= 1 BepStnName = PITC2 SSV=56 (0x38) <SOH>2.N644AA<NAK>Q7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297573580 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:29:09 DL MsgLen= 39 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB2 SSV=43 (0x2B) <SOH>2.N644AA<NAK>Q7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297573650 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:29:09 DL MsgLen= 39 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = RICA2 SSV=55 (0x37) <SOH>2.N644AA<NAK>Q7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297573720 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:29:09 DL MsgLen= 39 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB2 SSV=52 (0x34) <SOH>2.N644AA<NAK>Q7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297583521 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:29:10 DL MsgLen= 39 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = ROAA2 SSV=53 (0x35) <SOH>2.N644AA<NAK>Q7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297584659 AJPSBcnt= 82 DLBLK S=31 D=21 BEPts=20010911 12:29:10 DL MsgLen= 39 DBI= 4 DIIndicator= 2 DINumStns= 3 BepStnName = CRWA2 SSV=54 (0x36) BepStnName = ORDA2 SSV=41 (0x29) BepStnName = ORFA2 SSV=36 (0x24) <SOH>2.N644AA<NAK>Q7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297585202 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:29:10 DL MsgLen= 39 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA2 SSV=45 (0x2D) <SOH>2.N644AA<NAK>Q7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297591226 AJPSBcnt= 76 DLBLK S=31 D=21 BEPts=20010911 12:29:11 DL MsgLen= 39 DBI= 4 DlIndicator= 2 DlNumStns= 2 BepStnName = DCAA2 SSV=59 (0x3B) BepStnName = BWIA2 SSV=58 (0x3A) <SOH>2.N644AA<NAK>Q7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297604972 AJPSBcnt= 170 ULBLK S=31 D=21 BEPts=20010911 12:29:13 UL MsgLen= 129 Stn= DCAA2 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA4H1B<STX>- #M1PWD/ERFMN 273043COCAN266042TBC 25<TSTRET> 8045PGS 242045ETINE237048ABREE232053DIKES232053EMMEY232053CO<TSTRET> NDR230045C4B2<ETX>

FLoc=297625117 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:29:15

DL MsgLen= 39 DBI= 4 DlIndicator= 2 DlNumStns= 1
BepStnName = PHLC2 SSV=52 (0x34)
<SOH>2.N644AA<NAK>Q7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297625856 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:29:15 DL MsgLen= 39 DBI= 4 DIIndicator= 2 DINumStns= 1 BepStnName = PITC2 SSV=56 (0x38) <SOH>2.N644AA<NAK>Q7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297626360 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:29:15 DL MsgLen= 39 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB2 SSV=44 (0x2C) <SOH>2.N644AA<NAK>Q7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297626430 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:29:15 DL MsgLen= 39 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = RICA2 SSV=52 (0x34) <SOH>2.N644AA<NAK>Q7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297626500 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:29:15 DL MsgLen= 39 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB2 SSV=52 (0x34) <SOH>2.N644AA<NAK>Q7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297648206 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:29:17 DL MsgLen= 39 DBI= 4 DlIndicator= 3 DlNumStns= 1 BepStnName = IADA2 SSV=59 (0x3B) <SOH>2.N644AA<NAK>Q7<STX>M62AAA0077OS LAX /EON1700<ETX>

FLoc=297701780 AJPSBcnt= 170 ULBLK S=31 D=21 BEPts=20010911 12:29:23 UL MsgLen= 129 Stn= DCAA2 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA4H1B<STX>- #M1PWD/ERFMN 273043COCAN266042TBC 25<TSTRET> 8045PGS 242045ETINE237048ABREE232053DIKES232053EMMEY232053CO<TSTRET> NDR230045C4B2<ETX>

FLoc=297728195 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:29:25 DL MsgLen= 24 DBI= 5 DlIndicator= 1 DlNumStns= 1 BepStnName = PHLC2 SSV=51 (0x33) <SOH>2.N644AAB_<STX>S63AAA0077<ETX>

FLoc=297730387 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:29:26 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = GSOA2 SSV=38 (0x26) <SOH>2.N644AAB_<STX>S63AAA0077<ETX>

FLoc=297730442 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:29:26 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = RICA2 SSV=53 (0x35) <SOH>2.N644AAB_<STX>S63AAA0077<ETX>

FLoc=297730497 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:29:26 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB2 SSV=44 (0x2C) <SOH>2.N644AAB_<STX>S63AAA0077<ETX>

FLoc=297730607 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:29:26 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB2 SSV=50 (0x32) <SOH>2.N644AAB_<STX>S63AAA0077<ETX>

FLoc=297733665 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:29:26 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = ROAA2 SSV=52 (0x34) <SOH>2.N644AAB_<STX>S63AAA0077<ETX>

FLoc=297736995 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:29:26 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA2 SSV=47 (0x2F) <SOH>2.N644AAB_<STX>S63AAA0077<ETX>

FLoc=297744842 AJPSBcnt= 67 DLBLK S=31 D=21 BEPts=20010911 12:29:27 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 3 BepStnName = DCAA2 SSV=59 (0x3B) BepStnName = BWIA2 SSV=56 (0x38) BepStnName = PHLA2 SSV=52 (0x34) <SOH>2.N644AAB <STX>S63AAA0077<ETX>

FLoc=297746040 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:29:27 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 2 BepStnName = CRWA2 SSV=55 (0x37) BepStnName = ORFA2 SSV=44 (0x2C) <SOH>2.N644AAB_<STX>S63AAA0077<ETX>

FLoc=297766786 AJPSBcnt= 80 ULBLK S=31 D=21 BEPts=20010911 12:29:30 UL MsgLen= 39 Stn= DCAA2 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>H1C<STX>- #M1PWD/DW180199028FCCF<ETX>

FLoc=297787966 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:29:32 DL MsgLen= 24 DBI= 6 DlIndicator= 1 DlNumStns= 1 BepStnName = PHLC2 SSV=51 (0x33) <SOH>2.N644AAC <STX>S64AAA0077<ETX>

FLoc=297788021 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:29:32 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = PITC2 SSV=56 (0x38) <SOH>2.N644AAC_<STX>S64AAA0077<ETX>

FLoc=297788814 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:29:32 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB2 SSV=47 (0x2F) <SOH>2.N644AAC_<STX>S64AAA0077<ETX>

FLoc=297788869 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:29:32 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = GSOA2 SSV=41 (0x29) <SOH>2.N644AAC_<STX>S64AAA0077<ETX>

FLoc=297788924 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:29:32 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = RICA2 SSV=55 (0x37)

<SOH>2.N644AAC_<STX>S64AAA0077<ETX>

FLoc=297795272 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:29:33 DL MsgLen= 24 DBI= 6 DIIndicator= 2 DINumStns= 1 BepStnName = ROAA2 SSV=52 (0x34) <SOH>2.N644AAC_<STX>S64AAA0077<ETX>

FLoc=297796276 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:29:33 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DINumStns= 2 BepStnName = HTSA2 SSV=47 (0x2F) BepStnName = CMHA2 SSV=35 (0x23) <SOH>2.N644AAC_<STX>S64AAA0077<ETX>

FLoc=297802012 AJPSBcnt= 73 DLBLK S=31 D=21 BEPts=20010911 12:29:34 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 4 BepStnName = IADA2 SSV=59 (0x3B) BepStnName = CRWA2 SSV=56 (0x38) BepStnName = PITA2 SSV=56 (0x38) BepStnName = ORFA2 SSV=43 (0x2B) <SOH>2.N644AAC_<STX>S64AAA0077<ETX>

FLoc=297807235 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:29:34 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 2 BepStnName = DCAA2 SSV=59 (0x3B) BepStnName = PHLA2 SSV=53 (0x35) <SOH>2.N644AAC_<STX>S64AAA0077<ETX>

FLoc=300150303 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:33:33 DL MsgLen= 24 DBI= 7 DlIndicator= 1 DlNumStns= 1 BepStnName = PHLC2 SSV=49 (0x31) <SOH>2.N644AA<NAK>QO<STX>S65AAA0077<ETX>

FLoc=300150358 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:33:33 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = PITC2 SSV=59 (0x3B) <SOH>2.N644AA<NAK>QO<STX>S65AAA0077<ETX>

FLoc=300150718 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:33:33 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = GSOA2 SSV=45 (0x2D) <SOH>2.N644AA<NAK>QO<STX>S65AAA0077<ETX>

FLoc=300150773 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:33:33 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB2 SSV=56 (0x38) <SOH>2.N644AA<NAK>Q0<STX>S65AAA0077<ETX>

FLoc=300150828 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:33:33 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB2 SSV=47 (0x2F) <SOH>2.N644AA<NAK>Q0<STX>S65AAA0077<ETX>

FLoc=300150883 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:33:33 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = RICA2 SSV=57 (0x39) <SOH>2.N644AA<NAK>Q0<STX>S65AAA0077<ETX>

FLoc=300150938 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:33:33 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = CLEB2 SSV=39 (0x27) <SOH>2.N644AA<NAK>Q0<STX>S65AAA0077<ETX>

FLoc=300156636 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:33:34 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 2 BepStnName = ROAA2 SSV=56 (0x38) BepStnName = ACYA2 SSV=41 (0x29) <SOH>2.N644AA<NAK>Q0<STX>S65AAA0077<ETX>

FLoc=300157668 AJPSBcnt= 67 DLBLK S=31 D=21 BEPts=20010911 12:33:34 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DINumStns= 3 BepStnName = HTSA2 SSV=52 (0x34) BepStnName = CMHA2 SSV=40 (0x28) BepStnName = LCKA2 SSV=40 (0x28) <SOH>2.N644AA<NAK>QO<STX>S65AAA0077<ETX>

FLoc=300160500 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:33:34 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = CAKA2 SSV=40 (0x28) <SOH>2.N644AA<NAK>QO<STX>S65AAA0077<ETX>

FLoc=300169679 AJPSBcnt= 67 DLBLK S=31 D=21 BEPts=20010911 12:33:35 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 3 BepStnName = BWIA2 SSV=56 (0x38) BepStnName = PHLA2 SSV=51 (0x33) BepStnName = CLEA2 SSV=33 (0x21) <SOH>2.N644AA<NAK>Q0<STX>S65AAA0077<ETX>

FLoc=300189048 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:33:38 UL MsgLen= 14 Stn= PITC2 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA7_D<ETX>

FLoc=302721074 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:37:39 DL MsgLen= 24 DBI= 8 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC2 SSV=60 (0x3C) <SOH>2.N644AA<NAK>Q0<STX>S66AAA0077<ETX>

FLoc=302721312 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:37:39 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB2 SSV=44 (0x2C) <SOH>2.N644AA<NAK>Q0<STX>S66AAA0077<ETX>

FLoc=302721367 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:37:39 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = GSOA2 SSV=42 (0x2A) <SOH>2.N644AA<NAK>Q0<STX>S66AAA0077<ETX>

FLoc=302721422 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:37:39 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = RICA2 SSV=56 (0x38) <SOH>2.N644AA<NAK>Q0<STX>S66AAA0077<ETX>

FLoc=302721477 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:37:39 DL MsgLen= 24 DBI= 8 DIIndicator= 2 DINumStns= 1 BepStnName = RDUB2 SSV=53 (0x35) <SOH>2.N644AA<NAK>Q0<STX>S66AAA0077<ETX>

FLoc=302721532 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:37:39 DL MsgLen= 24 DBI= 8 DIIndicator= 2 DINumStns= 1 BepStnName = CLEB2 SSV=44 (0x2C) <SOH>2.N644AA<NAK>Q0<STX>S66AAA0077<ETX>

FLoc=302732326 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:37:40 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 2 BepStnName = ROAA2 SSV=59 (0x3B) BepStnName = AVPA2 SSV=26 (0x1A) <SOH>2.N644AA<NAK>Q0<STX>S66AAA0077<ETX>

FLoc=302732660 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:37:40 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = CAKA2 SSV=37 (0x25) <SOH>2.N644AA<NAK>QO<STX>S66AAA0077<ETX>

FLoc=302734289 AJPSBcnt= 79 DLBLK S=31 D=21 BEPts=20010911 12:37:40 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DINumStns= 5 BepStnName = HTSA2 SSV=57 (0x39) BepStnName = LCKA2 SSV=49 (0x31) BepStnName = CMHA2 SSV=48 (0x30) BepStnName = DAYA2 SSV=42 (0x2A) BepStnName = LEXA2 SSV=42 (0x2A) <SOH>2.N644AA<NAK>QO<STX>S66AAA0077<ETX>

FLoc=302748300 AJPSBcnt= 67 DLBLK S=31 D=21 BEPts=20010911 12:37:41 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DINumStns= 3 BepStnName = DCAA2 SSV=53 (0x35) BepStnName = BWIA2 SSV=50 (0x32) BepStnName = CLEA2 SSV=38 (0x26) <SOH>2.N644AA<NAK>QO<STX>S66AAA0077<ETX>

FLoc=302777773 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:37:44 UL MsgLen= 14 Stn= PITC2 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA8_E<ETX>

FLoc=304549879 AJPSBcnt= 62 ULBLK S=31 D=21 BEPts=20010911 12:40:22 UL MsgLen= 21 Stn= PITC2 StnDelivType= 12 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>:;F<STX>136800<ETX>

FLoc=304637654 AJPSBcnt= 62 ULBLK S=31 D=21 BEPts=20010911 12:40:32 UL MsgLen= 21 Stn= PITC2 StnDelivType= 12 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>:;F<STX>136800<ETX>

FLoc=304738442 AJPSBcnt= 62 ULBLK S=31 D=21 BEPts=20010911 12:40:42 UL MsgLen= 21 Stn= PITC2 StnDelivType= 12 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>:;F<STX>136800<ETX>

FLoc=304749376 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:40:42 DL MsgLen= 24 DBI= 9 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC2 SSV=59 (0x3B) <SOH>2.N644AAF_<STX>S67AAA0077<ETX> FLoc=304749431 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:40:42 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA2 SSV=43 (0x2B) <SOH>2.N644AAF_<STX>S67AAA0077<ETX> FLoc=304749596 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:40:42 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = GSOA2 SSV=43 (0x2B) <SOH>2.N644AAF_<STX>S67AAA0077<ETX> FLoc=304749651 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:40:42 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB2 SSV=45 (0x2D) <SOH>2.N644AAF_<STX>S67AAA0077<ETX> FLoc=304749761 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:40:42 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = RICA2 SSV=51 (0x33) <SOH>2.N644AAF_<STX>S67AAA0077<ETX> FLoc=304749926 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:40:42 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = CLEB2 SSV=51 (0x33) <SOH>2.N644AAF_<STX>S67AAA0077<ETX> FLoc=304749981 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:40:42 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB2 SSV=52 (0x34) <SOH>2.N644AAF_<STX>S67AAA0077<ETX> FLoc=304754255 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:40:43 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 2 BepStnName = ROAA2 SSV=52 (0x34) BepStnName = AVPA2 SSV=29 (0x1D) <SOH>2.N644AAF_<STX>S67AAA0077<ETX> FLoc=304757039 AJPSBcnt= 67 DLBLK S=31 D=21 BEPts=20010911 12:40:43 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 3 BepStnName = CMHA2 SSV=50 (0x32) BepStnName = LCKA2 SSV=47 (0x2F) BepStnName = DAYA2 SSV=43 (0x2B) <SOH>2.N644AAF_<STX>S67AAA0077<ETX> FLoc=304763660 AJPSBcnt= 79 DLBLK S=31 D=21 BEPts=20010911 12:40:44 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 5

BepStnName = CRWA2 SSV=62 (0x3E) BepStnName = IADA2 SSV=55 (0x37) BepStnName = TRIA2 SSV=44 (0x2C) BepStnName = CAKA2 SSV=42 (0x2A) BepStnName = TOLA2 SSV=36 (0x24)

<SOH>2.N644AAF <STX>S67AAA0077<ETX>

FLoc=304767697 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:40:44 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 2 BepStnName = BWIA2 SSV=51 (0x33) BepStnName = DTWB2 SSV=50 (0x32) <SOH>2.N644AAF_<STX>S67AAA0077<ETX>

FLoc=304770209 AJPSBcnt= 71 DLBLK S=31 D=21 BEPts=20010911 12:40:45 DL MsgLen= 40 DBI= 0 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=63 (0x3F) <SOH>2.N644AA<NAK>10<STX>M63AAA0077OS LAX /FQY36800<ETX>

FLoc=304770433 AJPSBcnt= 71 DLBLK S=31 D=21 BEPts=20010911 12:40:45 DL MsgLen= 40 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=42 (0x2A) <SOH>2.N644AA<NAK>10<STX>M63AAA0077OS LAX /FQY36800<ETX>

FLoc=304770504 AJPSBcnt= 71 DLBLK S=31 D=21 BEPts=20010911 12:40:45 DL MsgLen= 40 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB6 SSV=53 (0x35) <SOH>2.N644AA<NAK>10<STX>M63AAA0077OS LAX /FQY36800<ETX>

FLoc=304774870 AJPSBcnt= 71 DLBLK S=31 D=21 BEPts=20010911 12:40:45 DL MsgLen= 40 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=53 (0x35) <SOH>2.N644AA<NAK>10<STX>M63AAA0077OS LAX /FQY36800<ETX>

FLoc=304780225 AJPSBcnt= 71 DLBLK S=31 D=21 BEPts=20010911 12:40:46 DL MsgLen= 40 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=62 (0x3E) <SOH>2.N644AA<NAK>10<STX>M63AAA0077OS LAX /FQY36800<ETX>

FLoc=304785767 AJPSBcnt= 77 DLBLK S=31 D=21 BEPts=20010911 12:40:46 DL MsgLen= 40 DBI= 0 DlIndicator= 2 DlNumStns= 2 BepStnName = BWIA6 SSV=58 (0x3A) BepStnName = RDUA6 SSV=50 (0x32) <SOH>2.N644AA<NAK>10<STX>M63AAA0077OS LAX /FQY36800<ETX>

FLoc=304813636 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:40:50 UL MsgLen= 14 Stn= PITC6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA0_G<ETX>

FLoc=307254727 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:44:51 DL MsgLen= 24 DBI= 1 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=76 (0x4C) <SOH>2.N644AA<NAK>Q0<STX>S68AAA0077<ETX>

FLoc=307254782 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:44:51 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = DTWA6 SSV=48 (0x30) <SOH>2.N644AA<NAK>QO<STX>S68AAA0077<ETX>

FLoc=307254837 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:44:51 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = IADC6 SSV=56 (0x38) <SOH>2.N644AA<NAK>Q0<STX>S68AAA0077<ETX>

FLoc=307254892 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:44:51 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=47 (0x2F) <SOH>2.N644AA<NAK>Q0<STX>S68AAA0077<ETX>

FLoc=307257754 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:44:52 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB6 SSV=49 (0x31) <SOH>2.N644AA<NAK>Q0<STX>S68AAA0077<ETX>

FLoc=307257809 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:44:52 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = CLTB6 SSV=41 (0x29) <SOH>2.N644AA<NAK>Q0<STX>S68AAA0077<ETX>

FLoc=307257864 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:44:52 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB6 SSV=48 (0x30) <SOH>2.N644AA<NAK>Q0<STX>S68AAA0077<ETX>

FLoc=307261179 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:44:52 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=57 (0x39) <SOH>2.N644AA<NAK>Q0<STX>S68AAA0077<ETX>

FLoc=307268286 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:44:53 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=62 (0x3E) <SOH>2.N644AA<NAK>Q0<STX>S68AAA0077<ETX>

FLoc=307270631 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:44:53 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 2 BepStnName = BWIA6 SSV=54 (0x36) BepStnName = CVGB6 SSV=49 (0x31) <SOH>2.N644AA<NAK>QO<STX>S68AAA0077<ETX>

FLoc=307290482 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:44:56 UL MsgLen= 14 Stn= PITC6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA1_H<ETX>

FLoc=308168541 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:46:24 DL MsgLen= 39 DBI= 2 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=63 (0x3F) <SOH>2.N644AA<NAK>Q7<STX>M64AAA0077OS LAX /EON1650<ETX>

FLoc=308168611 AJPSBcnt= 152 DLMSG S=31 D=21 BEPts=20010911 12:46:24 ADNS MsgLen= 112 Tail Number= .N644AA SMI= DLA FltId= AA0077 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA TULDDAA <CR><LF>
.DDLXCXA 111246<CR><LF>
<STX>DLA<CR><LF>
FI AA77/AN N644AA<CR><LF>
DT DDL PIT 111246 M64A<CR><LF>
- OS LAX /EON1650<CR><LF>
<ETX><ETX><EOT>

FLoc=308168763 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:46:24 DL MsgLen= 39 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = IADC6 SSV=51 (0x33) <SOH>2.N644AA<NAK>Q7<STX>M64AAA0077OS LAX /EON1650<ETX>

FLoc=308168833 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:46:24 DL MsgLen= 39 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=50 (0x32) <SOH>2.N644AA<NAK>Q7<STX>M64AAA0077OS LAX /EON1650<ETX>

FLoc=308169078 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:46:24 DL MsgLen= 39 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB6 SSV=44 (0x2C) <SOH>2.N644AA<NAK>Q7<STX>M64AAA0077OS LAX /EON1650<ETX>

FLoc=308169148 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:46:24 DL MsgLen= 39 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB6 SSV=48 (0x30)

<SOH>2.N644AA<NAK>Q7<STX>M64AAA0077OS LAX /EON1650<ETX>

FLoc=308169218 AJPSBcnt= 70 DLBLK S=31 D=21 BEPts=20010911 12:46:24 DL MsgLen= 39 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = CLTB6 SSV=41 (0x29) <SOH>2.N644AA<NAK>Q7<STX>M64AAA0077OS LAX /EON1650<ETX>

FLoc=308178880 AJPSBcnt= 76 DLBLK S=31 D=21 BEPts=20010911 12:46:25 DL MsgLen= 39 DBI= 2 DlIndicator= 2 DlNumStns= 2 BepStnName = HTSA6 SSV=57 (0x39) BepStnName = LEXA6 SSV=44 (0x2C) <SOH>2.N644AA<NAK>Q7<STX>M64AAA0077OS LAX /EON1650<ETX>

FLoc=308186254 AJPSBcnt= 82 DLBLK S=31 D=21 BEPts=20010911 12:46:26 DL MsgLen= 39 DBI= 2 DlIndicator= 2 DlNumStns= 3 BepStnName = CRWA6 SSV=64 (0x40) BepStnName = IADA6 SSV=54 (0x36) BepStnName = TRIA6 SSV=51 (0x33) <SOH>2.N644AA<NAK>Q7<STX>M64AAA0077OS LAX /EON1650<ETX>

FLoc=308187408 AJPSBcnt= 88 DLBLK S=31 D=21 BEPts=20010911 12:46:26

DL MsgLen= 39 DBI= 2 DlIndicator= 2 DlNumStns= 4 BepStnName = BWIA6 SSV=52 (0x34)

BepStnName = CVGB6 SSV=50 (0x32)

BepStnName = RDUA6 SSV=44 (0x2C) BepStnName = CLTA6 SSV=43 (0x2B)

<SOH>2.N644AA<NAK>Q7<STX>M64AAA0077OS LAX /EON1650<ETX>

FLoc=308219838 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:46:29 UL MsqLen= 14 Stn= PITC6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA2 I<ETX>

FLoc=308410131 AJPSBcnt= 77 DLBLK S=31 D=21 BEPts=20010911 12:46:46 DL MsgLen= 46 DBI= 3 DlIndicator= 1 DlNumStns= 1 BepStnName = CVGA6 SSV=49 (0x31) <SOH>2.N644AA<NAK>B9<STX>M65AAA0077/KLAX.TI2/039KLAXC47C1<ETX>

FLoc=308410208 AJPSBcnt= 161 DLMSG S=31 D=21 BEPts=20010911 12:46:46 ADNS MsgLen= 121 Tail Number= .N644AA SMI= RAI FltId= AA0077 AgyNum= 1 (0x0001) <CR><LF> <SOH>QU RURDLXA ATSAAXA TULDDAA <CR><LF> .DDLXCXA 111246<CR><LF> <STX>RAI<CR><LF> FI AA77/AN N644AA<CR><LF> DT DDL CVG 111246 M65A<CR><LF> - TI2/039KLAXC47C1<CR><LF> <ETX><EOT>

FLoc=308410534 AJPSBcnt= 77 DLBLK S=31 D=21 BEPts=20010911 12:46:46 DL MsgLen= 46 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = CLTB6 SSV=41 (0x29) <SOH>2.N644AA<NAK>B9<STX>M65AAA0077/KLAX.TI2/039KLAXC47C1<ETX>

FLoc=308410611 AJPSBcnt= 77 DLBLK S=31 D=21 BEPts=20010911 12:46:46 DL MsgLen= 46 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB6 SSV=49 (0x31) <SOH>2.N644AA<NAK>B9<STX>M65AAA0077/KLAX.TI2/039KLAXC47C1<ETX>

FLoc=308410688 AJPSBcnt= 77 DLBLK S=31 D=21 BEPts=20010911 12:46:46 DL MsgLen= 46 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = IADC6 SSV=49 (0x31) <SOH>2.N644AA<NAK>B9<STX>M65AAA0077/KLAX.TI2/039KLAXC47C1<ETX>

FLoc=308420450 AJPSBcnt= 83 DLBLK S=31 D=21 BEPts=20010911 12:46:47 DL MsgLen= 46 DBI= 3 DlIndicator= 2 DlNumStns= 2 BepStnName = BWIA6 SSV=50 (0x32) BepStnName = CLTA6 SSV=44 (0x2C) <SOH>2.N644AA<NAK>B9<STX>M65AAA0077/KLAX.TI2/039KLAXC47C1<ETX>

FLoc=308420594 AJPSBcnt= 77 DLBLK S=31 D=21 BEPts=20010911 12:46:47 DL MsgLen= 46 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=57 (0x39) <SOH>2.N644AA<NAK>B9<STX>M65AAA0077/KLAX.TI2/039KLAXC47C1<ETX>

FLoc=308421080 AJPSBcnt= 77 DLBLK S=31 D=21 BEPts=20010911 12:46:47

DL MsgLen= 46 DBI= 3 DIIndicator= 2 DINumStns= 1
BepStnName = TRIA6 SSV=49 (0x31)
<SOH>2.N644AA<NAK>B9<STX>M65AAA0077/KLAX.Ti2/039KLAXC47C1<ETX>

FLoc=308434545 AJPSBcnt= 581 ULMSG S=31 D=21 BEPts=20010911 12:46:49 ADNS MsgLen= 524 Org Addr= ATSAAXA Org TimeStamp= 20010911 12:46:00 Smi= DAI AgyNum= 65535 Tail Number= .N644AA FltId= AA0077 Target Stn= <00><00><00><00> Target Method= 0 <CR><I F> <SOH>QU DDLXCXA<CR><LF> .ATSAAXA 111246<CR><LF> <STX>DAI<CR><LF> AN N644AA<CR><LF> - /ATSAAXA.TI2/KLAX ARR ATIS S<CR><LF> 1150Z LAX ATIS INFO S 1150Z. 00000KT 9SM<CR><LF> FEW014 18/16 A2991 (TWO NINER NINER<CR><LF> ONE). ILS APCHS ARE IN PROG TO RY 6R, <CR><LF> OR VCTR FOR VISUAL APCH WILL BE<CR><LF> PROVIDED, OPP DIRECTION TFC DEPG RY 25.<CR><LF> NOTAMS... RWYS 24R, 6L CLSD, RWYS 25L, <CR><LF> 7R CLSD. READBACK ALL RWY HOLD SHORT<CR><LF> INSTRUCTIONS. GC FREQ FOR ALL RWYS IS<CR><LF> 121.75. TWR FREQ FOR ALL RWYS IS<CR><LF> 120.95. UPON RECEIPT OF YOUR ATC CLNC<CR><LF> READBACK ONLY SQUAWK CODE. ...ADVS YOU<CR><LF> HAVE INFO S.90E8<CR><LF> <FTX><FOT>

FLoc=308453284 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:46:51 UL MsgLen= 235 Stn= PITC6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA3A9J<STX>/ATSAAXA.TI2/KLAX ARR ATIS S<CR><LF>1150Z LAX ATIS INFO S 1150Z. 00000KT 9SM<CR><LF>FEW014 18/16 A2991 (TWO NINER NINER<CR><LF>ONE). ILS APCHS ARE IN PROG TO RY 6R,<CR><LF>OR VCTR FOR VISUAL APCH WILL BE<CR><LF>PROVIDED, OPP DIRECTION TFC DEPG RY 25.<

FLoc=308557559 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:47:01 UL MsgLen= 235 Stn= PITC6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA3A9J<STX>/ATSAAXA.TI2/KLAX ARR ATIS S<CR><LF>1150Z LAX ATIS INFO S 1150Z. 00000KT 9SM<CR><LF>FEW014 18/16 A2991 (TWO NINER NINER<CR><LF>ONE). ILS APCHS ARE IN PROG TO RY 6R,<CR><LF>PROVIDED, OPP DIRECTION TFC DEPG RY 25.

FLoc=308573970 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:47:02 DL MsgLen= 24 DBI= 4 DlIndicator= 1 DlNumStns= 1 BepStnName = DTWA6 SSV=50 (0x32) <SOH>2.N644AAJ_<STX>S69AAA0077<ETX>

FLoc=308574025 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:47:02 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DINumStns= 1

BepStnName = CVGA6 SSV=50 (0x32) <SOH>2.N644AAJ_<STX>S69AAA0077<ETX>

FLoc=308589132 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:47:04 DL MsgLen= 24 DBI= 4 DIIndicator= 2 DINumStns= 2 BepStnName = CRWA6 SSV=65 (0x41) BepStnName = TRIA6 SSV=50 (0x32) <SOH>2.N644AAJ_<STX>S69AAA0077<ETX>

FLoc=308593903 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:47:04 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGB6 SSV=51 (0x33) <SOH>2.N644AAJ <STX>S69AAA0077<ETX>

FLoc=308602127 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:47:05 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=58 (0x3A) <SOH>2.N644AAJ_<STX>S69AAA0077<ETX>

FLoc=308613654 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:47:07 UL MsgLen= 235 Stn= PITC6 StnDelivType= 1 Tail= .N644AA Fid= AA0077
<SOH>2.N644AA<NAK>A9K<STX><CR><LF> NOTAMS... RWYS 24R, 6L CLSD, RWYS 25L,<CR><LF> 7R CLSD. READBACK ALL RWY HOLD SHORT<CR><LF> INSTRUCTIONS. GC FREQ FOR ALL RWYS IS<CR><LF> 121.75. TWR FREQ FOR ALL RWYS IS<CR><LF> 120.95. UPON RECEIPT OF YOUR ATC CLNC<CR><LF> READBACK ONLY SQUAWK CODE. .<ETB>

FLoc=308638807 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:47:09 DL MsgLen= 24 DBI= 5 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=47 (0x2F) <SOH>2.N644AAK_<STX>S70AAA0077<ETX>

FLoc=308638862 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:47:09 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=50 (0x32) <SOH>2.N644AAK_<STX>S70AAA0077<ETX>

FLoc=308639027 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:47:09 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB6 SSV=47 (0x2F) <SOH>2.N644AAK_<STX>S70AAA0077<ETX>

FLoc=308653201 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:47:10 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 2 BepStnName = CRWA6 SSV=65 (0x41) BepStnName = TRIA6 SSV=50 (0x32) <SOH>2.N644AAK_<STX>S70AAA0077<ETX>

FLoc=308654121 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:47:10 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 2 BepStnName = HTSA6 SSV=58 (0x3A) BepStnName = LEXA6 SSV=44 (0x2C) <SOH>2.N644AAK_<STX>S70AAA0077<ETX>

FLoc=308659573 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:47:11 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUA6 SSV=43 (0x2B) <SOH>2.N644AAK <STX>S70AAA0077<ETX>

FLoc=308678606 AJPSBcnt= 86 ULBLK S=31 D=21 BEPts=20010911 12:47:14 UL MsgLen= 45 Stn= PITC6 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>A9L<STX>..ADVS YOU<CR><LF>HAVE INFO S.90E8<CR><LF><ETX>

FLoc=308761455 AJPSBcnt= 86 ULBLK S=31 D=21 BEPts=20010911 12:47:24 UL MsgLen= 45 Stn= PITC6 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>A9L<STX>..ADVS YOU<CR><LF>HAVE INFO S.90E8<CR><LF><ETX>

FLoc=308851452 AJPSBcnt= 86 ULBLK S=31 D=21 BEPts=20010911 12:47:34 UL MsgLen= 45 Stn= PITC6 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>A9L<STX>..ADVS YOU<CR><LF> HAVE INFO S.90E8<CR><LF> <ETX>

FLoc=308948087 AJPSBcnt= 86 ULBLK S=31 D=21 BEPts=20010911 12:47:44 UL MsgLen= 45 Stn= PITC6 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>A9L<STX>..ADVS YOU<CR><LF> HAVE INFO S.90E8<CR><LF> <ETX>

FLoc=308970430 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:47:45 DL MsgLen= 24 DBI= 6 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=61 (0x3D) <SOH>2.N644AAL <STX>S71AAA0077<ETX>

FLoc=308970485 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:47:45 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = IADC6 SSV=49 (0x31) <SOH>2.N644AAL_<STX>S71AAA0077<ETX>

FLoc=308970540 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:47:45 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=50 (0x32) <SOH>2.N644AAL_<STX>S71AAA0077<ETX>

FLoc=308970823 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:47:45 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = CLTB6 SSV=43 (0x2B) <SOH>2.N644AAL_<STX>S71AAA0077<ETX>

FLoc=308970878 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:47:45 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1

FLoc=308980818 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:47:46 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 2 BepStnName = CRWA6 SSV=65 (0x41) BepStnName = TRIA6 SSV=51 (0x33) <SOH>2.N644AAL <STX>S71AAA0077<ETX>

FLoc=308982816 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:47:46 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 2 BepStnName = HTSA6 SSV=58 (0x3A) BepStnName = LEXA6 SSV=44 (0x2C) <SOH>2.N644AAL_<STX>S71AAA0077<ETX>

FLoc=308989347 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:47:47 DL MsgLen= 24 DBI= 6 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIA6 SSV=48 (0x30) <SOH>2.N644AAL_<STX>S71AAA0077<ETX>

FLoc=311267923 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:51:44 DL MsgLen= 24 DBI= 7 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=42 (0x2A) <SOH>2.N644AA<NAK>Q0<STX>S72AAA0077<ETX>

FLoc=311269303 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:51:44 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=53 (0x35) <SOH>2.N644AA<NAK>Q0<STX>S72AAA0077<ETX>

FLoc=311269864 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:51:44 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB6 SSV=43 (0x2B) <SOH>2.N644AA<NAK>Q0<STX>S72AAA0077<ETX>

FLoc=311276647 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:51:45 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = LEXA6 SSV=44 (0x2C) <SOH>2.N644AA<NAK>Q0<STX>S72AAA0077<ETX>

FLoc=311284219 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:51:46 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 2 BepStnName = CRWA6 SSV=64 (0x40) BepStnName = TRIA6 SSV=50 (0x32) <SOH>2.N644AA<NAK>QO<STX>S72AAA0077<ETX>

FLoc=311296575 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:51:47 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 2 BepStnName = DTWB6 SSV=55 (0x37) BepStnName = CVGB6 SSV=55 (0x37) <SOH>2.N644AA<NAK>Q0<STX>S72AAA0077<ETX>

FLoc=311314631 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:51:49 UL MsgLen= 14 Stn= PITC6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA7_M<ETX>

FLoc=312107590 AJPSBcnt= 532 ULMSG S=31 D=21 BEPts=20010911 12:52:58 ADNS MsgLen= 475 Org Addr= ATSAAXA Org TimeStamp= 20010911 12:52:00 Smi= DAI AgyNum= 65535 Tail Number= .N644AA FltId= AA0077 Target Stn= <00><00><00><00> Target Method= 0 <CR><I F> <SOH>QU DDLXCXA<CR><LF> .ATSAAXA 111252<CR><LF> <STX>DAI<CR><LF> AN N644AA<CR><LF> - /ATSAAXA.TI2/KLAX ARR ATIS T<CR><LF> 1250Z LAX ATIS INFO T 1250Z. 09003KT 9SM<CR><LF> FEW014 17/15 A2991 (TWO NINER NINER<CR><LF> ONE). ILS APCHS ARE IN PROG TO RY 6R, <CR><LF> OR VCTR FOR VISUAL APCH WILL BE<CR><LF> PROVIDED, OPP DIRECTION TFC DEPG RY 25.<CR><LF> READBACK ALL RWY HOLD SHORT<CR><LF> INSTRUCTIONS. GC FREQ FOR ALL RWYS IS<CR><LF> 121.75. TWR FREQ FOR ALL RWYS IS<CR><LF> 120.95. UPON RECEIPT OF YOUR ATC CLNC<CR><LF> READBACK ONLY SQUAWK CODE. ...ADVS YOU<CR><LF> HAVE INFO T.3236<CR><LF> <ETX><EOT>

FLoc=312108122 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:52:58 UL MsgLen= 235 Stn= PITC6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA</BANCSTX>/ATSAAXA.TI2/KLAX ARR ATIS T<CR><LF>1250Z LAX ATIS INFO T 1250Z. 09003KT 9SM<CR><LF>FEW014 17/15 A2991 (TWO NINER NINER<CR><LF>ONE). ILS APCHS ARE IN PROG TO RY 6R,<CR><LF>OR VCTR FOR VISUAL APCH WILL BE<CR><LF>PROVIDED, OPP DIRECTION TFC DEPG RY 25.</br>

FLoc=312198647 AJPSBcnt= 276 ULBLK S=31 D=21 BEPts=20010911 12:53:08 UL MsgLen= 235 Stn= PITC6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>A9N<STX>/ATSAAXA.TI2/KLAX ARR ATIS T<CR><LF>1250Z LAX ATIS INFO T 1250Z. 09003KT 9SM<CR><LF>FEW014 17/15 A2991 (TWO NINER NINER<CR><LF>ONE). ILS APCHS ARE IN PROG TO RY 6R,<CR><LF>OR VCTR FOR VISUAL APCH WILL BE<CR><LF>PROVIDED, OPP DIRECTION TFC DEPG RY 25.<

FLoc=312223494 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:53:09 DL MsgLen= 24 DBI= 8 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=63 (0x3F) <SOH>2.N644AAN_<STX>S73AAA0077<ETX>

FLoc=312223604 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:53:09 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=60 (0x3C) <SOH>2.N644AAN_<STX>S73AAA0077<ETX>

FLoc=312234570 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:53:10

DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = LEXA6 SSV=44 (0x2C) <SOH>2.N644AAN <STX>S73AAA0077<ETX>

FLoc=312247668 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:53:11 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=63 (0x3F) <SOH>2.N644AAN <STX>S73AAA0077<ETX>

FLoc=312252382 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:53:12 DL MsgLen= 24 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGB6 SSV=55 (0x37) <SOH>2.N644AAN_<STX>S73AAA0077<ETX>

FLoc=312275601 AJPSBcnt= 257 ULBLK S=31 D=21 BEPts=20010911 12:53:14 UL MsgLen= 216 Stn= PITC6 StnDelivType= 1
Tail= .N644AA Fid= AA0077
<SOH>2.N644AA<NAK>A9O<STX><CR><LF>
READBACK ALL RWY HOLD SHORT<CR><LF>
INSTRUCTIONS. GC FREQ FOR ALL RWYS IS<CR><LF>
121.75. TWR FREQ FOR ALL RWYS IS<CR><LF>
120.95. UPON RECEIPT OF YOUR ATC CLNC<CR><LF>
READBACK ONLY SQUAWK CODE. ...ADVS YOU<CR><LF>
HAVE INFO T.3236<CR><LF>
<ETX>

FLoc=312288944 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:53:15 DL MsgLen= 24 DBI= 9 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=63 (0x3F) <SOH>2.N644AAO_<STX>S74AAA0077<ETX>

FLoc=312289654 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:53:15 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB6 SSV=44 (0x2C) <SOH>2.N644AAO_<STX>S74AAA0077<ETX>

FLoc=312290023 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:53:15 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=60 (0x3C) <SOH>2.N644AAO_<STX>S74AAA0077<ETX>

FLoc=312295223 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:53:16 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=63 (0x3F) <SOH>2.N644AAO_<STX>S74AAA0077<ETX>

FLoc=312298032 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:53:16 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 2 BepStnName = HTSA6 SSV=57 (0x39) BepStnName = LEXA6 SSV=44 (0x2C) <SOH>2.N644AAO_<STX>S74AAA0077<ETX>

FLoc=312306159 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:53:17 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 2 BepStnName = CVGB6 SSV=55 (0x37) BepStnName = RDUA6 SSV=44 (0x2C)

<SOH>2.N644AAO_<STX>S74AAA0077<ETX>

FLoc=315023828 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:57:15 DL MsgLen= 24 DBI= 0 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=60 (0x3C) <SOH>2.N644AA<NAK>Q0<STX>S75AAA0077<ETX>

FLoc=315023883 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:57:15 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=60 (0x3C) <SOH>2.N644AA<NAK>Q0<STX>S75AAA0077<ETX>

FLoc=315023938 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:57:15 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = BNAC6 SSV=50 (0x32) <SOH>2.N644AA<NAK>Q0<STX>S75AAA0077<ETX>

FLoc=315032220 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:57:16 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=63 (0x3F) <SOH>2.N644AA<NAK>Q0<STX>S75AAA0077<ETX>

FLoc=315033215 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:57:16 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 2 BepStnName = HTSA6 SSV=66 (0x42) BepStnName = LEXA6 SSV=45 (0x2D)

<SOH>2.N644AA<NAK>Q0<STX>S75AAA0077<ETX> FLoc=315075084 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:57:20

UL MsgLen= 14 Stn= HTSA6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA0_P<ETX>

FLoc=315247677 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:57:36 DL MsgLen= 24 DBI= 0 DlIndicator= 3 DlNumStns= 1 BepStnName = CVGA6 SSV=60 (0x3C) <SOH>2.N644AA<NAK>Q0<STX>S75AAA0077<ETX>

FLoc=315247732 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:57:36 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1

BepStnName = DTWA6 SSV=48 (0x30) <SOH>2.N644AA<NAK>Q0<STX>S75AAA0077<ETX>

FLoc=315247787 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:57:36 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = BNAC6 SSV=50 (0x32) <SOH>2.N644AA<NAK>Q0<STX>S75AAA0077<ETX>

FLoc=315248025 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:57:36 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DINumStns= 1 BepStnName = CLTB6 SSV=41 (0x29) <SOH>2.N644AA<NAK>Q0<STX>S75AAA0077<ETX>

FLoc=315261412 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:57:37 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = LEXA6 SSV=45 (0x2D)

<SOH>2.N644AA<NAK>Q0<STX>S75AAA0077<ETX>

FLoc=315261467 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:57:37 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=62 (0x3E) <SOH>2.N644AA<NAK>QO<STX>S75AAA0077<ETX>

FLoc=315263807 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:57:37 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGB6 SSV=61 (0x3D) <SOH>2.N644AA<NAK>Q0<STX>S75AAA0077<ETX>

FLoc=315297684 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 12:57:41 UL MsgLen= 14 Stn= HTSA6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA0_Q<ETX>

FLoc=316754422 AJPSBcnt= 219 ULMSG S=31 D=21 BEPts=20010911 12:59:45 ADNS MsgLen= 162 Org Addr= TULDDAA Org TimeStamp= 20010911 12:59:00 Smi= AGM AgyNum= 65535 Tail Number= .N644AA FltId= AA0077 Target Stn= CRW<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111259 FROM EQP6 <CR><LF> <STX>AGM<CR><LF> AN N644AA/GL CRW<CR><LF> - /<CR><LF> CONTACT IND CENTER ON 120.27<CR><LF> FTWDP JIM MCDONALD<CR><LF> PLZ ACK MSG NO. 5926<CR><LF> END<CR><LF> <LF> <CR><LF> <LF> <LF> <ETX><EOT>

FLoc=316754641 AJPSBcnt= 200 ULBLK S=31 D=21 BEPts=20010911 12:59:45 UL MsgLen= 159 Stn= HTSA6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>C1R<STX>.TULDDAA 111259 FROM EQP6 CR><LF> AGM<CR><LF> AN N644AA/GL CRW<CR><LF> - /<CR><LF> CONTACT IND CENTER ON 120.27<CR><LF> FTWDP JIM MCDONALD<CR><LF> PLZ ACK MSG NO. 5926<CR><LF> END<CR><LF> <LF> <CR><LF> <LF> <LF> <ETX>

FLoc=316790946 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:59:48

DL MsgLen= 24 DBI= 1 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=60 (0x3C) <SOH>2.N644AAR_<STX>S76AAA0077<ETX>

FLoc=316791001 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:59:48 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=60 (0x3C) <SOH>2.N644AAR <STX>S76AAA0077<ETX>

FLoc=316791056 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:59:48 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = BNAC6 SSV=49 (0x31) <SOH>2.N644AAR_<STX>S76AAA0077<ETX>

FLoc=316791346 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:59:48 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB6 SSV=43 (0x2B) <SOH>2.N644AAR_<STX>S76AAA0077<ETX>

FLoc=316791494 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:59:48 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = CLTB6 SSV=41 (0x29) <SOH>2.N644AAR_<STX>S76AAA0077<ETX>

FLoc=316796288 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:59:48 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=66 (0x42) <SOH>2.N644AAR_<STX>S76AAA0077<ETX>

FLoc=316807517 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 12:59:49 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DINumStns= 1 BepStnName = TRIA6 SSV=54 (0x36) <SOH>2.N644AAR_<STX>S76AAA0077<ETX>

FLoc=316812528 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 12:59:49 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 2 BepStnName = CVGB6 SSV=58 (0x3A) BepStnName = DTWB6 SSV=52 (0x34) <SOH>2.N644AAR_<STX>S76AAA0077<ETX>

FLoc=317618155 AJPSBcnt= 205 DLBLK S=31 D=21 BEPts=20010911 13:00:53 DL MsgLen= 174 DBI= 2 DlIndicator= 1 DlNumStns= 1 BepStnName = BNAC6 SSV=47 (0x2F) <SOH>2.N644AA<NAK>H1<STX>D006AA0077#DFBEDA/E1445,477,344,E7C,,<TSTRET> 58257E,52A525,4D64D6,21620C,042054,37F28F,3<CR><LF> 82336,190070,28C428C4,243,0E50EA,547545,0CE33064E64D,00A,000,1<TSTRET> ,42D435<CR><LF> ,0D001A<ETX>

FLoc=317618360 AJPSBcnt= 307 DLMSG S=31 D=21 BEPts=20010911 13:00:53 ADNS MsgLen= 267 Tail Number= .N644AA SMI= DFD FltId= AA0077 AgyNum= 1 (0x0001) <CR><LF> <SOH>QU RURDLXA ABZDS8X BDROOXA DCABFXA TULDDAA <CR><LF> .DDLXCXA 111300<CR><LF> <STX>DFD<CR><LF> <

FI AA77/AN N644AA<CR><LF>
DT DDL BNA 111300 D006<CR><LF>
- EDA/E1445,477,344,E7C,,58257E,52A525,4D64D6,21620C,042054,3<TSTRET>
7F28F,3<CR><LF>
82336,190070,28C428C4,243,0E50EA,547545,0CE33064E64D,00A,000,1<TSTRET>
,42D435<CR><LF>
,0D001A<CR><LF>
<ETX><EOT>

FLoc=317620939 AJPSBcnt= 205 DLBLK S=31 D=21 BEPts=20010911 13:00:53 DL MsgLen= 174 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = CLTB6 SSV=41 (0x29) <SOH>2.N644AA<NAK>H1<STX>D006AA0077#DFBEDA/E1445,477,344,E7C,,<TSTRET> 58257E,52A525,4D64D6,21620C,042054,37F28F,3<CR><LF> 82336,190070,28C428C4,243,0E50EA,547545,0CE33064E64D,00A,000,1<TSTRET> ,42D435<CR><LF> ,0D001A<ETX>

FLoc=317621144 AJPSBcnt= 205 DLBLK S=31 D=21 BEPts=20010911 13:00:53 DL MsgLen= 174 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB6 SSV=47 (0x2F) <SOH>2.N644AA<NAK>H1<STX>D006AA0077#DFBEDA/E1445,477,344,E7C,,<TSTRET> 58257E,52A525,4D64D6,21620C,042054,37F28F,3<CR><LF> 82336,190070,28C428C4,243,0E50EA,547545,0CE33064E64D,00A,000,1<TSTRET> ,42D435<CR><LF> ,0D001A<ETX>

FLoc=317635236 AJPSBcnt= 205 DLBLK S=31 D=21 BEPts=20010911 13:00:54 DL MsgLen= 174 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = TRIA6 SSV=56 (0x38) <SOH>2.N644AA<NAK>H1<STX>D006AA0077#DFBEDA/E1445,477,344,E7C,,<TSTRET> 58257E,52A525,4D64D6,21620C,042054,37F28F,3<CR><LF> 82336,190070,28C428C4,243,0E50EA,547545,0CE33064E64D,00A,000,1<TSTRET> ,42D435<CR><LF> .0D001A<ETX>

FLoc=317640789 AJPSBcnt= 211 DLBLK S=31 D=21 BEPts=20010911 13:00:54 DL MsgLen= 174 DBI= 2 DlIndicator= 2 DlNumStns= 2 BepStnName = HTSA6 SSV=67 (0x43) BepStnName = LEXA6 SSV=44 (0x2C) <SOH>2.N644AA<NAK>H1<STX>D006AA0077#DFBEDA/E1445,477,344,E7C,,<TSTRET> 58257E,52A525,4D64D6,21620C,042054,37F28F,3<CR><LF> 82336,190070,28C428C4,243,0E50EA,547545,0CE33064E64D,00A,000,1<TSTRET> ,42D435<CR><LF> ,0D001A<ETX>

FLoc=317650360 AJPSBcnt= 217 DLBLK S=31 D=21 BEPts=20010911 13:00:55 DL MsgLen= 174 DBI= 2 DIIndicator= 2 DINumStns= 3 BepStnName = CVGB6 SSV=58 (0x3A) BepStnName = RDUA6 SSV=48 (0x30) BepStnName = CLTA6 SSV=46 (0x2E) <SOH>2.N644AA<NAK>H1<STX>D006AA0077#DFBEDA/E1445,477,344,E7C,,<TSTRET>58257E,52A525,4D64D6,21620C,042054,37F28F,3<CR><LF>82336,190070,28C428C4,243,0E50EA,547545,0CE33064E64D,00A,000,1<TSTRET>,42D435<CR><LF>,0D001A<ETX>

FLoc=317678235 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:00:58 UL MsgLen= 14 Stn= HTSA6 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA2_S<ETX>

FLoc=317908374 AJPSBcnt= 214 ULMSG S=31 D=21 BEPts=20010911 13:01:17 ADNS MsgLen= 157 Org Addr= TULDDAA Org TimeStamp= 20010911 13:01:00 Smi= AGM AgyNum= 65535 Tail Number= .N644AA FltId= AA0077 Target Stn= CVG<00><00> Target Method= 2 <CR>><LF> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111301 FROM FD23 <CR><LF> <STX>AGM<CR><LF> AN N644AA/GL CVG<CR><LF> - <CR><LF> ATC WANTS YOU ON FREQ 120.27<CR><LF> DON....DESK 23<CR><LF> PLZ ACK MSG NO. 0119<CR><LF> END<CR><LF> <LF> <CR><LF> <LF> <LF> <ETX><EOT>

FLoc=317908588 AJPSBcnt= 195 ULBLK S=31 D=21 BEPts=20010911 13:01:17 UL MsgLen= 154 Stn= HTSA6 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>C1T<STX>.TULDDAA 111301 FROM FD23 CR><LF> AGM<CR><LF> AN N644AA/GL CVG<CR><LF> - <CR><LF> ATC WANTS YOU ON FREQ 120.27<CR><LF> DON....DESK 23<CR><LF> PLZ ACK MSG NO. 0119<CR><LF> END<CR><LF> <LF> <CR><LF> <LF> <LF> <ETX>

FLoc=317943815 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:01:19 DL MsgLen= 24 DBI= 3 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=61 (0x3D) <SOH>2.N644AAT <STX>S77AAA0077<ETX>

FLoc=317943870 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:01:19 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = DTWA6 SSV=48 (0x30) <SOH>2.N644AAT <STX>S77AAA0077<ETX>

FLoc=317943925 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:01:19 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DINumStns= 1

BepStnName = CVGA6 SSV=53 (0x35) <SOH>2.N644AAT <STX>S77AAA0077<ETX>

FLoc=317944427 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:01:19 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = BNAC6 SSV=44 (0x2C) <SOH>2.N644AAT_<STX>S77AAA0077<ETX>

FLoc=317945031 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:01:19 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = CLTB6 SSV=43 (0x2B) <SOH>2.N644AAT_<STX>S77AAA0077<ETX>

FLoc=317945086 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:01:19 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB6 SSV=47 (0x2F) <SOH>2.N644AAT_<STX>S77AAA0077<ETX>

FLoc=317954958 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 13:01:20 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 2 BepStnName = HTSA6 SSV=66 (0x42) BepStnName = LEXA6 SSV=44 (0x2C) <SOH>2.N644AAT_<STX>S77AAA0077<ETX>

FLoc=317963594 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 13:01:21 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 2 BepStnName = CRWA6 SSV=65 (0x41) BepStnName = TRIA6 SSV=54 (0x36) <SOH>2.N644AAT_<STX>S77AAA0077<ETX>

FLoc=317964477 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 13:01:21 DL MsgLen= 24 DBI= 3 DlIndicator= 2 D!NumStns= 2 BepStnName = RDUA6 SSV=48 (0x30) BepStnName = CLTA6 SSV=46 (0x2E) <SOH>2.N644AAT_<STX>S77AAA0077<ETX>

FLoc=318881999 AJPSBcnt= 219 ULMSG S=31 D=21 BEPts=20010911 13:02:33 ADNS MsgLen= 162 Org Addr= TULDDAA Org TimeStamp= 20010911 13:02:00 Smi= AGM AgyNum= 65535 Tail Number= .N644AA FltId= AA0077 Target Stn= CVG<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111302 FROM EQP6 <CR><LF> <STX>AGM<CR><LF> AN N644AA/GL CVG<CR><LF> - /<CR><LF> CONTACT IND CENTER ON 120.27<CR><LF> FTWDP JIM MCDONALD<CR><LF> PLZ ACK MSG NO. 0212<CR><LF> <BEL>END<CR><LF> <LF> <CR><LF> <LF> <| F> <ETX><EOT>

FLoc=318882218 AJPSBcnt= 200 ULBLK S=31 D=21 BEPts=20010911 13:02:33 UL MsgLen= 159 Stn= HTSA6 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>C1U<STX>.TULDDAA 111302 FROM EQP6 <CR><LF> AGM<CR><LF> AN N644AA/GL CVG<CR><LF> - /<CR><LF> CONTACT IND CENTER ON 120.27<CR><LF> FTWDP JIM MCDONALD<CR><LF> PLZ ACK MSG NO. 0212<CR><LF> <BEL>END<CR><LF> <| F> <CR><LF> <LF> <LF> <ETX>

FLoc=318927993 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:36 DL MsgLen= 24 DBI= 4 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=60 (0x3C) <SOH>2.N644AAU_<STX>S78AAA0077<ETX>

FLoc=318928048 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:36 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = DTWA6 SSV=47 (0x2F) <SOH>2.N644AAU_<STX>S78AAA0077<ETX>

FLoc=318928323 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:36 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = CLTB6 SSV=41 (0x29) <SOH>2.N644AAU_<STX>S78AAA0077<ETX>

FLoc=318928378 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:36 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB6 SSV=49 (0x31) <SOH>2.N644AAU_<STX>S78AAA0077<ETX>

FLoc=318943936 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:02:37 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=66 (0x42) <SOH>2.N644AAU_<STX>S78AAA0077<ETX>

FLoc=318945818 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 13:02:37 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 2 BepStnName = HTSA6 SSV=65 (0x41) BepStnName = LEXA6 SSV=44 (0x2C) <SOH>2.N644AAU_<STX>S78AAA0077<ETX>

FLoc=318960787 AJPSBcnt= 73 DLBLK S=31 D=21 BEPts=20010911 13:02:38 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 4 BepStnName = CVGB6 SSV=55 (0x37) BepStnName = DTWB6 SSV=49 (0x31) BepStnName = RDUA6 SSV=49 (0x31) BepStnName = CLTA6 SSV=44 (0x2C) <SOH>2.N644AAU_<STX>S78AAA0077<ETX>

FLoc=320484772 AJPSBcnt= 155 ULMSG S=31 D=21 BEPts=20010911 13:04:40 ADNS MsgLen= 98 Org Addr= TULDDAA Org TimeStamp= 20010911 13:04:00 Smi= DFD AgyNum= 65535 Tail Number= .N644AA FltId= AA0077 Target Stn= CVG<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111304 FROM FD04 <CR><LF> <STX>DFD<CR><LF> AN N644AA/GL CVG<CR><LF> XRP 150 0<CR><LF> <LF> <CR><LF> <LF> <LF> <EOT> 590<ETX><EOT> FLoc=320484927 AJPSBcnt= 137 ULBLK S=31 D=21 BEPts=20010911 13:04:40 UL MsgLen= 96 Stn= HTSA6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>H1V<STX>.TULDDAA 111304 FROM FD04 CR><LF> DFD<CR><LF> AN N644AA/GL CVG<CR><LF> - #DFXRP 150 0<CR><LF> <LF> <CR><LF> <LF> <LF> 590<ETX> FLoc=320602655 AJPSBcnt= 137 ULBLK S=31 D=21 BEPts=20010911 13:04:50 UL MsgLen= 96 Stn= HTSA6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA<NAK>H1V<STX>.TULDDAA 111304 FROM FD04 CR><LF> DFD<CR><LF> AN N644AA/GL CVG<CR><LF> - #DFXRP 150 0<CR><LF> <LF> <CR><LF> <LF> <LF> 590<ETX> FLoc=320630608 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:04:52 DL MsgLen= 24 DBI= 5 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=60 (0x3C) <SOH>2.N644AAV_<STX>S79AAA0077<ETX> FLoc=320630884 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:04:52 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=50 (0x32) <SOH>2.N644AAV_<STX>S79AAA0077<ETX>

FLoc=320631724 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:04:52

DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1

BepStnName = RDUB6 SSV=44 (0x2C) <SOH>2.N644AAV <STX>S79AAA0077<ETX>

FLoc=320646435 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 13:04:53

DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 2

BepStnName = HTSA6 SSV=62 (0x3E) BepStnName = LEXA6 SSV=44 (0x2C)

<SOH>2.N644AAV_<STX>S79AAA0077<ETX>

FLoc=320647917 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 13:04:53

DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 2

BepStnName = CVGB6 SSV=51 (0x33)

BepStnName = CLTA6 SSV=43 (0x2B)

<SOH>2.N644AAV_<STX>S79AAA0077<ETX>

FLoc=320649241 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:04:53

DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1

BepStnName = TRIA6 SSV=52 (0x34)

<SOH>2.N644AAV_<STX>S79AAA0077<ETX>

FLoc=320678105 AJPSBcnt= 124 DLBLK S=31 D=21 BEPts=20010911 13:04:56

DL MsgLen= 93 DBI= 6 DlIndicator= 1 DlNumStns= 1

BepStnName = CVGA6 SSV=50 (0x32)

<SOH>2.N644AA<NAK>H1<STX>D007AA0077#DFB/TULDDAA.ERROR 114 REPO<TSTRET>

RT NOT FOUND<CR><LF>

XRP ><150 0 590<CR><LF>

XX <ETX>

FLoc=320678400 AJPSBcnt= 217 DLMSG S=31 D=21 BEPts=20010911 13:04:56

ADNS MsgLen= 177 Tail Number= .N644AA SMI= DFD

FltId= AA0077 AgyNum= 1 (0x0001)

<CR><LF>

<SOH>QU RURDLXA TULDDAA ABZDS8X BDROOXA DCABFXA <CR><LF>

.DDLXCXA 111304<CR><LF>

<STX>DFD<CR><LF>

FI AA77/AN N644AA<CR><LF>

DT DDL CVG 111304 D007<CR><LF>

- ERROR 114 REPORT NOT FOUND<CR><LF>

XRP ><150 0 590<CR><LF>

XX <CR><LF>

<ETX><EOT>

FLoc=320680253 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:04:57

UL MsgLen= 14 Stn= HTSA6 StnDelivType= 1

Tail= .N644AA Fid= AA0077

<SOH>2.N644AA6 W<ETX>

FLoc=320692260 AJPSBcnt= 124 DLBLK S=31 D=21 BEPts=20010911 13:04:58

DL MsgLen= 93 DBI= 6 DlIndicator= 2 DlNumStns= 1

BepStnName = CRWA6 SSV=70 (0x46)

<SOH>2.N644AA<NAK>H1<STX>D007AA0077#DFB/TULDDAA.ERROR 114 REPO<TSTRET>

RT NOT FOUND<CR><LF>

XRP ><150 0 590<CR><LF>

XX <ETX>

FLoc=320693394 AJPSBcnt= 124 DLBLK S=31 D=21 BEPts=20010911 13:04:58

```
DL MsgLen= 93 DBI= 6 DlIndicator= 2 DlNumStns= 1
BepStnName = HTSA6 SSV=62 (0x3E)
<SOH>2.N644AA<NAK>H1<STX>D007AA0077#DFB/TULDDAA.ERROR 114 REPO<TSTRET>
RT NOT FOUND<CR><LF>
XRP ><150 0
              590<CR><LF>
XX <ETX>
FLoc=320705013 AJPSBcnt= 130 DLBLK S=31 D=21 BEPts=20010911 13:04:59
DL MsgLen= 93 DBI= 6 DlIndicator= 2 DlNumStns= 2
BepStnName = CVGB6 SSV=51 (0x33)
BepStnName = DTWB6 SSV=46 (0x2E)
<SOH>2.N644AA<NAK>H1<STX>D007AA0077#DFB/TULDDAA.ERROR 114 REPO<TSTRET>
RT NOT FOUND<CR><LF>
XRP ><150 0
               590<CR><LF>
XX <ETX>
FLoc=320738883 AJPSBcnt= 155 ULMSG S=31 D=21 BEPts=20010911 13:05:02
ADNS MsgLen= 98 Org Addr= TULDDAA Org TimeStamp= 20010911 13:04:00
Smi= DFD AgyNum= 65535
Tail Number= .N644AA FltId= AA0077
Target Stn= CVG<00><00> Target Method= 2
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111304 FROM
                          <CR><LF>
<STX>DFD<CR><LF>
AN N644AA/GL CVG<CR><LF>
- XRP 150 0<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<EOT> 608<ETX><EOT>
FLoc=320739038 AJPSBcnt= 137 ULBLK S=31 D=21 BEPts=20010911 13:05:02
UL MsgLen= 96 Stn= HTSA6 StnDelivType= 1
Tail= .N644AA Fid= AA0077
<SOH>2.N644AA<NAK>H1X<STX>.TULDDAA 111304 FROM
                                                        <CR><LF>
DFD<CR><LF>
AN N644AA/GL CVG<CR><LF>
- #DFXRP 150 0<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
608<ETX>
FLoc=320763248 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:05:04
DL MsgLen= 24 DBI= 7 DlIndicator= 1 DlNumStns= 1
BepStnName = PITC6 SSV=60 (0x3C)
<SOH>2.N644AAX_<DEL><STX>S80AAA0077<ETX>
FLoc=320763358 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:05:04
DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1
```

BepStnName = BNAC6 SSV=43 (0x2B)

<SOH>2.N644AAX_<STX>S80AAA0077<ETX>

FLoc=320766933 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:05:05 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = CLTB6 SSV=41 (0x29) <SOH>2.N644AAX <STX>S80AAA0077<ETX>

FLoc=320766988 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:05:05 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB6 SSV=47 (0x2F) <SOH>2.N644AAX_<STX>S80AAA0077<ETX>

FLoc=320774308 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:05:05 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=62 (0x3E) <SOH>2.N644AAX_<STX>S80AAA0077<ETX>

FLoc=320782308 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:05:06 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=69 (0x45) <SOH>2.N644AAX_<STX>S80AAA0077<ETX>

FLoc=320784027 AJPSBcnt= 67 DLBLK S=31 D=21 BEPts=20010911 13:05:06 DL MsgLen= 24 DBI= 7 DlIndicator= 2 DlNumStns= 3 BepStnName = CVGB6 SSV=52 (0x34) BepStnName = RDUA6 SSV=47 (0x2F) BepStnName = CLTA6 SSV=43 (0x2B) <SOH>2.N644AAX_<STX>S80AAA0077<ETX>

FLoc=320815193 AJPSBcnt= 124 DLBLK S=31 D=21 BEPts=20010911 13:05:09 DL MsgLen= 93 DBI= 8 DlIndicator= 1 DlNumStns= 1 BepStnName = CVGA6 SSV=51 (0x33) <SOH>2.N644AA<NAK>H1<STX>D008AA0077#DFB/TULDDAA.ERROR 114 REPO<TSTRET> RT NOT FOUND<CR><LF> XRP ><150 0 608<CR><LF> XX <ETX>

FLoc=320815317 AJPSBcnt= 217 DLMSG S=31 D=21 BEPts=20010911 13:05:09 ADNS MsgLen= 177 Tail Number= .N644AA SMI= DFD FltId= AA0077 AgyNum= 1 (0x0001)
<CR><LF>
<SOH>QU RURDLXA TULDDAA ABZDS8X BDROOXA DCABFXA <CR><LF>
.DDLXCXA 111305<CR><LF>
<STX>DFD<CR><LF>
FI AA77/AN N644AA<CR><LF>
DT DDL CVG 111305 D008<CR><LF>
- ERROR 114 REPORT NOT FOUND<CR><LF>
XRP ><150 0 608<CR><LF>
XX <CR><LF>
<ETX><ETX><ETX><ETX><ETX><ETX><ETX><ETX<<ET>

FLoc=320816855 AJPSBcnt= 124 DLBLK S=31 D=21 BEPts=20010911 13:05:09 DL MsgLen= 93 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB6 SSV=44 (0x2C) <SOH>2.N644AA<NAK>H1<STX>D008AA0077#DFB/TULDDAA.ERROR 114 REPO<TSTRET> RT NOT FOUND<CR><LF> XRP ><150 0 608<CR><LF> XX <ETX>

FLoc=320832000 AJPSBcnt= 124 DLBLK S=31 D=21 BEPts=20010911 13:05:10 DL MsgLen= 93 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=62 (0x3E) <SOH>2.N644AA<NAK>H1<STX>D008AA0077#DFB/TULDDAA.ERROR 114 REPO<TSTRET> RT NOT FOUND<CR><LF> XRP ><150 0 608<CR><LF> XX <ETX>

FLoc=320841657 AJPSBcnt= 124 DLBLK S=31 D=21 BEPts=20010911 13:05:11 DL MsgLen= 93 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=68 (0x44) <SOH>2.N644AA<NAK>H1<STX>D008AA0077#DFB/TULDDAA.ERROR 114 REPO<TSTRET> RT NOT FOUND<CR><LF> XRP ><150 0 608<CR><LF> XX <ETX>

FLoc=320846371 AJPSBcnt= 130 DLBLK S=31 D=21 BEPts=20010911 13:05:11 DL MsgLen= 93 DBI= 8 DlIndicator= 2 DlNumStns= 2 BepStnName = CVGB6 SSV=52 (0x34) BepStnName = RDUA6 SSV=46 (0x2E) <SOH>2.N644AA<NAK>H1<STX>D008AA0077#DFB/TULDDAA.ERROR 114 REPO<TSTRET> RT NOT FOUND<CR><LF> XRP ><150 0 608<CR><LF> XX <ETX>

FLoc=320873073 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:05:14 UL MsgLen= 14 Stn= HTSA6 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA8_Y<ETX>

FLoc=320978750 AJPSBcnt= 124 DLBLK S=31 D=21 BEPts=20010911 13:05:23 DL MsgLen= 93 DBI= 8 DlIndicator= 3 DlNumStns= 1 BepStnName = RDUB6 SSV=44 (0x2C) <SOH>2.N644AA<NAK>H1<STX>D008AA0077#DFB/TULDDAA.ERROR 114 REPO<TSTRET> RT NOT FOUND<CR><LF> XRP ><150 0 608<CR><LF> XX <ETX>

FLoc=320991242 AJPSBcnt= 124 DLBLK S=31 D=21 BEPts=20010911 13:05:24 DL MsgLen= 93 DBI= 8 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=62 (0x3E) <SOH>2.N644AA<NAK>H1<STX>D008AA0077#DFB/TULDDAA.ERROR 114 REPO<TSTRET> RT NOT FOUND<CR><LF> XRP ><150 0 608<CR><LF> XX <ETX>

FLoc=320996801 AJPSBcnt= 124 DLBLK S=31 D=21 BEPts=20010911 13:05:25 DL MsgLen= 93 DBI= 8 DlIndicator= 2 DINumStns= 1 BepStnName = TRIA6 SSV=52 (0x34)
<SOH>2.N644AA<NAK>H1<STX>D008AA0077#DFB/TULDDAA.ERROR 114 REPO<TSTRET> RT NOT FOUND<CR><LF> XRP ><150 0 608<CR><LF> XX <ETX>

FLoc=321006005 AJPSBcnt= 130 DLBLK S=31 D=21 BEPts=20010911 13:05:26

DL MsgLen= 93 DBI= 8 DlIndicator= 2 DlNumStns= 2
BepStnName = DTWB6 SSV=46 (0x2E)
BepStnName = RDUA6 SSV=46 (0x2E)
<SOH>2.N644AA<NAK>H1<STX>D008AA0077#DFB/TULDDAA.ERROR 114 REPO<TSTRET>
RT NOT FOUND<CR><LF>
XRP ><150 0 608<CR><LF>
XX <ETX>

FLoc=321027560 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:05:28 UL MsgLen= 14 Stn= HTSA6 StnDelivType= 1 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA8_Z<ETX>

FLoc=323844726 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:09:29 DL MsgLen= 24 DBI= 9 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=42 (0x2A) <SOH>2.N644AA<NAK>Q0<STX>S81AAA0077<ETX>

FLoc=323844859 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:09:29 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=43 (0x2B) <SOH>2.N644AA<NAK>Q0<STX>S81AAA0077<ETX>

FLoc=323845420 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:09:29 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB6 SSV=50 (0x32) <SOH>2.N644AA<NAK>Q0<STX>S81AAA0077<ETX>

FLoc=323852864 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:09:30 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=66 (0x42) <SOH>2.N644AA<NAK>Q0<STX>S81AAA0077<ETX>

FLoc=323864808 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 13:09:31 DL MsgLen= 24 DBI= 9 DlIndicator= 2 DlNumStns= 2 BepStnName = CVGB6 SSV=48 (0x30) BepStnName = RDUA6 SSV=46 (0x2E) <SOH>2.N644AA<NAK>Q0<STX>S81AAA0077<ETX>

FLoc=323865899 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:09:31 DL MsgLen= 24 DBI= 9 DIIndicator= 2 DINumStns= 1 BepStnName = HTSA6 SSV=58 (0x3A) <SOH>2.N644AA<NAK>Q0<STX>S81AAA0077<ETX>

FLoc=323890123 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:09:34 UL MsgLen= 14 Stn= CRWA6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA9 A<ETX>

FLoc=326724814 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:13:35 DL MsgLen= 24 DBI= 0 DlIndicator= 1 DlNumStns= 1 BepStnName = PITC6 SSV=63 (0x3F) <SOH>2.N644AA<NAK>Q0<STX>S82AAA0077<ETX>

FLoc=326724869 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:13:35 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DINumStns= 1

BepStnName = CVGA6 SSV=43 (0x2B) <SOH>2.N644AA<NAK>Q0<STX>S82AAA0077<ETX>

FLoc=326725203 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:13:35 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB6 SSV=47 (0x2F) <SOH>2.N644AA<NAK>Q0<STX>S82AAA0077<ETX>

FLoc=326725313 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:13:35 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB6 SSV=44 (0x2C) <SOH>2.N644AA<NAK>QO<STX>S82AAA0077<ETX>

FLoc=326739144 AJPSBcnt= 67 DLBLK S=31 D=21 BEPts=20010911 13:13:36 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DINumStns= 3 BepStnName = CRWA6 SSV=66 (0x42) BepStnName = IADA6 SSV=53 (0x35) BepStnName = TRIA6 SSV=46 (0x2E) <SOH>2.N644AA<NAK>Q0<STX>S82AAA0077<ETX>

FLoc=326740360 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:13:36 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=55 (0x37) <SOH>2.N644AA<NAK>QO<STX>S82AAA0077<ETX>

FLoc=326746877 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 13:13:37 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 2 BepStnName = BWIA6 SSV=51 (0x33) BepStnName = RDUA6 SSV=48 (0x30) <SOH>2.N644AA<NAK>QO<STX>S82AAA0077<ETX>

FLoc=326773403 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:13:40 UL MsgLen= 14 Stn= CRWA6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA0_B<ETX>

FLoc=326903808 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:13:49 DL MsgLen= 24 DBI= 0 DlIndicator= 3 DlNumStns= 1 BepStnName = PITC6 SSV=63 (0x3F) <SOH>2.N644AA<NAK>Q0<STX>S82AAA0077<ETX>

FLoc=326903918 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:13:49 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=42 (0x2A) <SOH>2.N644AA<NAK>Q0<STX>S82AAA0077<ETX>

FLoc=326924925 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 13:13:50 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 2 BepStnName = RDUA6 SSV=47 (0x2F) BepStnName = CVGB6 SSV=47 (0x2F) <SOH>2.N644AA<NAK>QO<STX>S82AAA0077<ETX>

FLoc=326929514 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:13:51 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=55 (0x37) <SOH>2.N644AA<NAK>Q0<STX>S82AAA0077<ETX>

FLoc=326932647 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 13:13:51 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 2 BepStnName = CRWA6 SSV=66 (0x42) BepStnName = IADA6 SSV=54 (0x36) <SOH>2.N644AA<NAK>Q0<STX>S82AAA0077<ETX>

FLoc=326960072 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:13:54 UL MsgLen= 14 Stn= CRWA6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA0_C<ETX>

FLoc=327089671 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:14:04 DL MsgLen= 24 DBI= 0 DlIndicator= 3 DlNumStns= 1 BepStnName = IADC6 SSV=56 (0x38) <SOH>2.N644AA<NAK>Q0<STX>S82AAA0077<ETX>

FLoc=327090922 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:14:04 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB6 SSV=47 (0x2F) <SOH>2.N644AA<NAK>Q0<STX>S82AAA0077<ETX>

FLoc=327091046 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:14:04 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB6 SSV=48 (0x30) <SOH>2.N644AA<NAK>Q0<STX>S82AAA0077<ETX>

FLoc=327091101 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:14:04 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = PITC6 SSV=62 (0x3E) <SOH>2.N644AA<NAK>QO<STX>S82AAA0077<ETX>

FLoc=327091481 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:14:04 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = CVGA6 SSV=41 (0x29) <SOH>2.N644AA<NAK>Q0<STX>S82AAA0077<ETX>

FLoc=327104807 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:14:05 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=66 (0x42) <SOH>2.N644AA<NAK>Q0<STX>S82AAA0077<ETX>

FLoc=327111135 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:14:06 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=55 (0x37) <SOH>2.N644AA<NAK>Q0<STX>S82AAA0077<ETX>

FLoc=327119405 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:14:06 DL MsgLen= 24 DBI= 0 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUA6 SSV=48 (0x30) <SOH>2.N644AA<NAK>Q0<STX>S82AAA0077<ETX>

FLoc=327146415 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:14:09 UL MsgLen= 14 Stn= CRWA6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA0 D<ETX>

FLoc=330094798 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:18:11 DL MsgLen= 24 DBI= 1 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=56 (0x38) <SOH>2.N644AA<NAK>Q0<STX>S83AAA0077<ETX> FLoc=330096834 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:18:11 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB6 SSV=60 (0x3C) <SOH>2.N644AA<NAK>Q0<STX>S83AAA0077<ETX> FLoc=330096999 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:18:11 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB6 SSV=51 (0x33) <SOH>2.N644AA<NAK>Q0<STX>S83AAA0077<ETX> FLoc=330113571 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:18:12 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=53 (0x35) <SOH>2.N644AA<NAK>Q0<STX>S83AAA0077<ETX> FLoc=330125627 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:18:13 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=63 (0x3F) <SOH>2.N644AA<NAK>Q0<STX>S83AAA0077<ETX> FLoc=330143842 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 13:18:14 DL MsgLen= 24 DBI= 1 DlIndicator= 2 DlNumStns= 2 BepStnName = BWIA6 SSV=52 (0x34) BepStnName = RDUA6 SSV=51 (0x33) <SOH>2.N644AA<NAK>Q0<STX>S83AAA0077<ETX> FLoc=330161344 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:18:16 UL MsgLen= 14 Stn= CRWA6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA1 E<ETX> FLoc=332967834 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:22:18 DL MsgLen= 24 DBI= 2 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=56 (0x38) <SOH>2.N644AA<NAK>Q0<STX>S84AAA0077<ETX> FLoc=332967961 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:22:18 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB6 SSV=53 (0x35) <SOH>2.N644AA<NAK>Q0<STX>S84AAA0077<ETX> FLoc=332972826 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:22:18

FLoc=332972826 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:22: DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=48 (0x30) <SOH>2.N644AA<NAK>Q0<STX>S84AAA0077<ETX>

FLoc=332980292 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:22:19 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=59 (0x3B) <SOH>2.N644AA<NAK>QO<STX>S84AAA0077<ETX>

FLoc=332982947 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 13:22:19 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 2 BepStnName = RDUA6 SSV=51 (0x33) BepStnName = BWIA6 SSV=50 (0x32) <SOH>2.N644AA<NAK>Q0<STX>S84AAA0077<ETX>

FLoc=333021174 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:22:23 UL MsgLen= 14 Stn= CRWA6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA2_F<ETX>

FLoc=333268568 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:22:40 DL MsgLen= 24 DBI= 2 DlIndicator= 3 DlNumStns= 1 BepStnName = PITC6 SSV=60 (0x3C) <SOH>2.N644AA<NAK>Q0<STX>S84AAA0077<ETX>

FLoc=333269705 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:22:40 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB6 SSV=60 (0x3C) <SOH>2.N644AA<NAK>Q0<STX>S84AAA0077<ETX>

FLoc=333273876 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:22:41 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = RDUB6 SSV=51 (0x33) <SOH>2.N644AA<NAK>Q0<STX>S84AAA0077<ETX>

FLoc=333283937 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:22:42 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = HTSA6 SSV=48 (0x30) <SOH>2.N644AA<NAK>QO<STX>S84AAA0077<ETX>

FLoc=333285653 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:22:42 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 1 BepStnName = CRWA6 SSV=58 (0x3A) <SOH>2.N644AA<NAK>Q0<STX>S84AAA0077<ETX>

FLoc=333287681 AJPSBcnt= 61 DLBLK S=31 D=21 BEPts=20010911 13:22:42 DL MsgLen= 24 DBI= 2 DlIndicator= 2 DlNumStns= 2 BepStnName = BWIA6 SSV=52 (0x34) BepStnName = RDUA6 SSV=51 (0x33) <SOH>2.N644AA<NAK>QO<STX>S84AAA0077<ETX>

FLoc=333318519 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:22:45 UL MsgLen= 14 Stn= PITC6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA2_G<ETX>

FLoc=336185637 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:26:47 DL MsgLen= 24 DBI= 3 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=56 (0x38) <SOH>2.N644AA<NAK>Q0<STX>S85AAA0077<ETX>

FLoc=336185692 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:26:47 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB6 SSV=60 (0x3C)

<SOH>2.N644AA<NAK>Q0<STX>S85AAA0077<ETX>

FLoc=336208837 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:26:49 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIA6 SSV=57 (0x39) <SOH>2.N644AA<NAK>Q0<STX>S85AAA0077<ETX>

FLoc=336222271 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:26:50 DL MsgLen= 24 DBI= 3 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=65 (0x41) <SOH>2.N644AA<NAK>Q0<STX>S85AAA0077<ETX>

FLoc=336240460 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:26:52 UL MsgLen= 14 Stn= IADA6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA3 H<ETX>

FLoc=338957412 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:30:54 DL MsgLen= 24 DBI= 4 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=70 (0x46) <SOH>2.N644AA<NAK>Q0<STX>S86AAA0077<ETX>

FLoc=338957980 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:30:54 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB6 SSV=63 (0x3F) <SOH>2.N644AA<NAK>Q0<STX>S86AAA0077<ETX>

FLoc=338974142 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:30:56 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=65 (0x41) <SOH>2.N644AA<NAK>QO<STX>S86AAA0077<ETX>

FLoc=338983741 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:30:57 DL MsgLen= 24 DBI= 4 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIA6 SSV=62 (0x3E) <SOH>2.N644AA<NAK>Q0<STX>S86AAA0077<ETX>

FLoc=338999163 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:30:59 UL MsgLen= 14 Stn= IADC6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA4_I<ETX>

FLoc=341861094 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:34:59 DL MsgLen= 24 DBI= 5 DlIndicator= 1 DlNumStns= 1 BepStnName = IADC6 SSV=70 (0x46) <SOH>2.N644AA<NAK>QO<STX>S87AAA0077<ETX>

FLoc=341861369 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:34:59 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = BWIB6 SSV=60 (0x3C) <SOH>2.N644AA<NAK>QO<STX>S87AAA0077<ETX>

FLoc=341883363 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:35:01 DL MsgLen= 24 DBI= 5 DlIndicator= 2 DlNumStns= 1 BepStnName = IADA6 SSV=68 (0x44) <SOH>2.N644AA<NAK>Q0<STX>S87AAA0077<ETX>

FLoc=341887832 AJPSBcnt= 55 DLBLK S=31 D=21 BEPts=20010911 13:35:02 DL MsgLen= 24 DBI= 5 DIIndicator= 2 DINumStns= 1 BepStnName = BWIA6 SSV=63 (0x3F) <SOH>2.N644AA<NAK>Q0<STX>S87AAA0077<ETX>

FLoc=341909477 AJPSBcnt= 55 ULBLK S=31 D=21 BEPts=20010911 13:35:04 UL MsgLen= 14 Stn= IADC6 StnDelivType= 2 Tail= .N644AA Fid= AA0077 <SOH>2.N644AA5_J<ETX>

FLoc=359262552 AJPSBcnt= 610 ULMSG S=31 D=21 BEPts=20010911 14:00:58 ADNS MsgLen= 553 Org Addr= ATSAAXA Org TimeStamp= 20010911 14:00:00 Smi= DAI AgyNum= 65535 Tail Number= .N644AA FltId= <FF><00><00><00><00><00> Target Stn= <00><00><00><00> Target Method= 0 <CR>><LF> <SOH>QU DDLXCXA<CR><LF> .ATSAAXA 111400<CR><LF> <STX>DAI<CR><LF> AN N644AA<CR><LF> - /ATSAAXA.TI2/KLAX ARR ATIS U<CR><LF> 1350Z LAX ATIS INFO U 1350Z. 09004KT 8SM<CR><LF> FEW012 SCT065 BKN220 17/14 A2992 (TWO<CR><LF> NINER NINER TWO) RMK CCSL OHD AND S.<CR><LF> ILS APCHS IN PROG TO RY 24R AND 25L, OR<CR><LF> VCTR FOR VISUAL APCH WILL BE PROVIDED, <CR><LF> SIMUL VISUAL APCHS TO ALL RWYS ARE IN<CR><LF> PROG, SIMUL INSTR DEP IN PROG RWYS 24<CR><LF> AND 25. GROUND STOP TO ALL AIRPORTS<CR><LF> UNTIL FURTHER NOTICE. READBACK ALL RWY<CR><LF> HOLD SHORT INSTRUCTIONS. UPON RECEIPT<CR><LF> OF YOUR ATC CLNC READBACK ONLY SQUAWK<CR><LF> CODE. ...ADVS YOU HAVE INFO U.95E4<CR><LF> <ETX><EOT>

FLoc=359263162 AJPSBcnt= 608 ICPUL S=31 D=21 BEPts=20010911 14:00:58 Intercept MsgLen=553 Addressee= .N644AA Num MediaTypes=1 Blk Num=1 UI Code=0

***IcpHdr: Reason Code= 231 AgyNum= 65535

***IcpHdr: Tail Number= .N644AA

***IcpHdr: FltId= <FF><00><00><00><00>

Dumping Media type #1 of 1 Media Type = 0 Num Stns= 0 Num History= 0

<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.ATSAAXA 111400<CR><LF>
.STX>DAI<CR><LF>
<STX>DAI<CR><LF>
AN N644AA<CR><LF>
- /ATSAAXA.TI2/KLAX ARR ATIS U<CR><LF>
1350Z LAX ATIS INFO U 1350Z. 09004KT 8SM<CR><LF>
FEW012 SCT065 BKN220 17/14 A2992 (TWO<CR><LF>

NINER NINER TWO) RMK CCSL OHD AND S.<CR><LF>ILS APCHS IN PROG TO RY 24R AND 25L, OR<CR><LF>VCTR FOR VISUAL APCH WILL BE PROVIDED, CR><LF>SIMUL VISUAL APCHS TO ALL RWYS ARE IN<CR><LF>PROG, SIMUL INSTR DEP IN PROG RWYS 24<CR><LF>AND 25. GROUND STOP TO ALL AIRPORTS<CR><LF>UNTIL FURTHER NOTICE. READBACK ALL RWY<CR><LF>HOLD SHORT INSTRUCTIONS. UPON RECEIPT<CR><LF>OF YOUR ATC CLNC READBACK ONLY SQUAWK<CR><LF>CODE. ...ADVS YOU HAVE INFO U.95E4<CR><LF><ETX><EOT>

FLoc=373657791 AJPSBcnt= 155 ULMSG S=31 D=21 BEPts=20010911 14:41:19 ADNS MsgLen= 98 Org Addr= TULDDAA Org TimeStamp= 20010911 14:41:00 Smi= DFD AgyNum= 65535 Tail Number= .N644AA FltId= <FF><00><00><00><00><00> Target Stn= ICT<00><00> Target Method= 2 <CR><LF> <SOH>QU DDLXCXA<CR><LF> .TULDDAA 111441 FROM FD04 <CR><LF> <STX>DFD<CR><LF> AN N644AA/GL ICT<CR><LF> XRP 150 0<CR><LF> <LF> <CR><LF> <LF> <LF> <EOT> 201<ETX><EOT>

FLoc=373690912 AJPSBcnt= 137 ULBLK S=31 D=21 BEPts=20010911 14:41:29 UL MsgLen= 96 Stn= ICTA6 StnDelivType= 4
Tail= .N644AA Fid= <FF><00><00><00><00><
SOH>2.N644AA<NAK>H1L<STX>.TULDDAA 111441 FROM FD04 <CR><LF>DFD<CR><LF>
AN N644AA/GL ICT<CR><LF>
- #DFXRP 150 0<CR><LF>
<LF>
<CR><LF>
<CR><LF>
<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<LF>
<1.F>
<1.F >
<1.F

FLoc=373722835 AJPSBcnt= 174 ICPUL S=31 D=21 BEPts=20010911 14:41:39

```
Intercept MsgLen=98 Addressee= .N644AA Num MediaTypes=1
Blk Num=1 UI Code=0
***IcpHdr: Reason Code= 311 AgyNum= 65535
***IcpHdr: Tail Number= .N644AA
***lcpHdr: FltId= <FF><00><00><00><00>
Dumping Media type #1 of 1
 Media Type = 0 Num Stns= 1 Num History= 2
 Stn Score Card # 1 of 1; EntryType= 4 (0x0004) Stn= ICTA6
History Card # 1 of 2; Reason= 311 (0x0137) Stn= ICTA6
 History Card # 2 of 2; Reason= 311 (0x0137) Stn= ICTA6
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 111441 FROM FD04
                               <CR><LF>
<STX>DFD<CR><LF>
AN N644AA/GL ICT<CR><LF>
- XRP 150 0<CR><LF>
<| F>
<CR><LF>
<LF>
<LF>
<EOT> 201<ETX><EOT>
FLoc=408033210 AJPSBcnt= 155 ULMSG S=32 D=21 BEPts=20010911 21:20:42
ADNS MsgLen= 98 Org Addr= TULDDAA Org TimeStamp= 20010911 21:20:00
Smi= DFD AgyNum= 65535
Tail Number= .N644AA FltId= <FF><00><00><00><00><00>
Target Stn= LAX<00><00> Target Method= 1
<CR><LF>
<SOH>QU DDLXCXA<CR><LF>
.TULDDAA 112120 FROM FD28
                               <CR><LF>
<STX>DFD<CR><LF>
AN N644AA/AP LAX<CR><LF>
- XRP 150 0<CR><LF>
<LF>
<CR><LF>
<LF>
<LF>
<EOT> 244<ETX><EOT>
FLoc=408033365 AJPSBcnt= 153 ICPUL S=32 D=21 BEPts=20010911 21:20:42
Intercept MsgLen=98 Addressee= .N644AA Num MediaTypes=1
Blk Num=1 Ul Code=0
***IcpHdr: Reason Code= 231 AgyNum= 65535
***IcpHdr: Tail Number= .N644AA
***IcpHdr: FltId= <FF><00><00><00><00>
Dumping Media type #1 of 1
```

Media Type = 0 Num Stns= 0 Num History= 0

<CR><LF>