

higher authority requires stronger evidence

higher

Level 5

Commitment-boundary awareness

Knows what it can decide, what must escalate, and why.

Level 4

Evidence and calibration awareness

Tracks uncertainty, proxy mismatch, and fidelity;
records rejected alternatives.

Level 3

Tool and environment awareness

Compiles, runs, profiles, simulates, and interprets tool failures.

Level 2

Performance-model awareness

Reasons about locality, bandwidth, parallelism, pipelines, and data movement.

Level 1

Constraint awareness

Uses power, area, memory, latency, precision, reliability, and process limits.

Level 0

Vocabulary awareness

Names ISA, cache, vector, accelerator, SoC, compiler, and EDA concepts.

lower

Assessment: what can it change, what feedback supports it, and what can reject it?