

shared ontology

task → representation → environment → method → evidence → accountable decision

fast software

feedback: fast
commitment: low
reject: tests



workload + DSE

feedback: staged
commitment: mid
reject: coverage



co-design + fleet

feedback: noisy
commitment: high
reject: telemetry



RTL / physical

feedback: slow
commitment: very high
reject: signoff

higher commitment means more critique, evidence, and approval

—————→
feedback latency and evidence burden increase; acceptable autonomy narrows