

Stopping Phases: Phase 1: Linear Reaction Drift ($v_0 \cdot \Delta t$) Phase 2: Quadratic Kinetic Braking ($v_0^2/2a_{\max}$)

