



(a) Commanded Control Torque $u(t)$ [Nm]



(b) Torque Rate of Change $\dot{u}(t) \propto \ddot{q}(t)$ (Actuator Jerk) [Nm/s]



(c) Actuator Phase Current $i(t)$ [A] & Gearbox Backlash Stress

