


(a) Unsafe Shared-Bus Architecture: Direct Motor Authority without Hardware Isolation (Single Point of Failure)



(b) Privileged Enforcer & Control Multiplexer Architecture: Register Isolation Behind Deterministic Invariant Checks

