


TEC steady-state temperature versus signed PWM



Recorded temperature ranges are treated as steady-state observations; points are range midpoints and error bars show the recorded min-max range, not statistical uncertainty. The table does not document a settling-time or drift criterion.