

Matched-initial-state interventions: H=2.5 s, D1=10, D2=100, B5=1 pu
Remote internal phase change [turns]
Remote total Pcap [pu]
Remote mean frequency deviation [Hz]
All line active-power losses [pu]
Time after clearing [s]
Time after clearing [s]
Baseline
R56 = 75%
R56 = 50%
R56 = 25%
R56 = 0
Keep line 4-5
All line R = 0
X56 = 50%