
XpuInit : E_PROGRESS
Execute : Bool
Execute
FALSE
_eState := E_PROGRESS.PROGRESS_INIT
TRUE
E_PROGRESS.PROGRESS_INIT:
XpuCtrl.Cmd := E_XPU_CTRL.XTS_CMD_NULL
_eState := PROGRESS_BUSY
_eState
E_PROGRESS.PROGRESS_BUSY:
XpuCtrl.Cmd := E_XPU_CTRL.XTS_CMD_INIT
XpuState.State
PROGRESS_ERROR
f_GetProgress(XpuState.State)
PROGRESS_DONE
_eState
E_PROGRESS.PROGRESS_PREPARE:
XpuCtrl.Cmd := E_XPU_CTRL.XTS_CMD_IDLE
PROGRESS_ERROR
f_GetProgress(XpuState.State)
PROGRESS_WORKING
_eState
E_PROGRESS.PROGRESS_STARTUP:
PROGRESS_ERROR
XpuState.Check
E_XPU_CHECK.MOVER_ID_SIMULATION
E_XPU_CHECK:MOVER_ID_STANDARD
E_XPU_CHECK:MOVER_ID_DETECTION_VALID
_eState
E_PROGRESS.PROGRESS_DONE:
XpuInit := _eState