

**GVL\_XTS.XpuCtrl**

**GVL\_XTS.XpuState**

Ctrl.eCmd := E\_XPU\_CTRL.XTS\_IDLE

State

**GVL\_XTS.Xpu**

Check()

FALSE

**RETURN**

TRUE

\_eCmd := Ctrl.eCmd

(\_eCmd <> \_eCmdOld)

TRUE

\_eState := Cmd(\_eCmd)

E\_XPU\_STATE.XTS\_IDLE:  
\_eResult := SUPER^.Cycle(true, \_eCheck)

FALSE

**State.Check := \_eCheck**

TRUE

**State.Check := DetectMoverId(true)**

State.State := \_eState + \_eResult  
State.Init := \_eInit  
State.DcLink := AllModulesDcLink