




- 1. Table of Contents (This Page) Created on Mon Apr 9 22:19:34 2012
- 2. component
- 3. solder
- 4. outline
- 5. plated-drill
- 6. unplated-drill
- 7. componentmask
- 8. soldermask
- 9. topsilk
- 10. bottomsilk
- 11. toppaste
- 12. bottompaste
- 13. topassembly
- 14. bottomassembly
- 15. fab

































There are 14 different drill sizes used in this layout, 709 holes total

Symbol	Diam. (Inch)	Count	<u>Plated?</u>	
٧	0.013	150	YES	
+	0.014	49	YES	
×	0.016	10	YES	
۰	0.019	31	YES	
	0.020	274	YES	
φ	0.030	4	YES	
#	0.038	18	YES	
×	0.039	8	YES	
0	0.041	2	YES	
	0.042	150	YES	
\$	0.062	1	YES	Title: (unknown) - Fabrication Drawing
-	0.066	4	YES	Author: Mark Haun
	0.094	4	YES	Date: Tue 10 Apr 2012 05:19:34 AM GMT UTC
0	0.130	4	NO	



Board outline is the centerline of this path