

# FusionSolar Troubleshooting Report

**Date:** 22-05-2026  
**Generated At:** 22-05-2026 22:30:08  
**Prepared By:** TERA SPMS

## Executive Summary

| Metric                           | Value |
|----------------------------------|-------|
| Total low-performing plants      | 4     |
| Total low-performing inverters   | 0     |
| Total low-performing strings     | 75    |
| Total alarms                     | 70    |
| Total high-temperature inverters | 50    |
| Unsuccessful task sections       | 0     |

## Low-performing Plants

| Plant Name                      | Plant PSH | City Average PSH | Deviation |
|---------------------------------|-----------|------------------|-----------|
| Kossan Rubber Industries Berhad | 0.00      | 1.87             | -100.00   |
| LIAN FOO POULTRY FARM SDN BHD   | 0.00      | 0.00             | nan       |
| MAJOR ENGINEERING Lot 8         | 1.44      | 3.80             | -62.16    |
| QL FARM SDN BHD                 | 0.00      | 0.00             | nan       |

## Low-performing Inverters

| Plant Name                        | Inverter Name | Inverter SN | Inverter PSH | Benchmark PSH | Deviation |
|-----------------------------------|---------------|-------------|--------------|---------------|-----------|
| No low-performing inverters found | -             | -           | -            | -             | -         |

## Low-performing Strings

| Plant Name                    | Inverter Name      | Inverter SN | String Name           | Total Current | Benchmark | Deviation |
|-------------------------------|--------------------|-------------|-----------------------|---------------|-----------|-----------|
| BJC FOOD (MALAYSIA) SDN. BHD. | 100KTL-M1(COM1-1)  | NE=50476040 | PV11 input current(A) | 510.480       | 809.670   | 36.95     |
| BJC FOOD (MALAYSIA) SDN. BHD. | 100KTL-M1(COM1-1)  | NE=50476040 | PV13 input current(A) | 536.780       | 809.670   | 33.70     |
| BJC FOOD (MALAYSIA) SDN. BHD. | 100KTL-M1(COM1-1)  | NE=50476040 | PV15 input current(A) | 537.340       | 809.670   | 33.63     |
| BJC FOOD (MALAYSIA) SDN. BHD. | 100KTL-M1(COM1-1)  | NE=50476040 | PV17 input current(A) | 396.880       | 809.670   | 50.98     |
| BJC FOOD (MALAYSIA) SDN. BHD. | 100KTL-M1(COM1-1)  | NE=50476040 | PV19 input current(A) | 457.930       | 809.670   | 43.44     |
| BJC FOOD (MALAYSIA) SDN. BHD. | 100KTL-M1(COM1-1)  | NE=50476040 | PV7 input current(A)  | 493.850       | 809.670   | 39.01     |
| BJC FOOD (MALAYSIA) SDN. BHD. | 100KTL-M1(COM1-1)  | NE=50476040 | PV9 input current(A)  | 602.360       | 809.670   | 25.60     |
| DSG MALAYSIA SDN. BHD         | 100KTL-M1(COM1-15) | NE=50412011 | PV2 input current(A)  | 379.350       | 498.530   | 23.91     |
| DSG MALAYSIA SDN. BHD         | 100KTL-M1(COM1-17) | NE=50412012 | PV1 input current(A)  | 387.330       | 588.240   | 34.15     |
| DSG MALAYSIA SDN. BHD         | 100KTL-M1(COM1-17) | NE=50412012 | PV2 input current(A)  | 390.850       | 588.240   | 33.56     |
| DSG MALAYSIA SDN. BHD         | 100KTL-M1(COM1-17) | NE=50412012 | PV3 input current(A)  | 418.340       | 588.240   | 28.88     |
| DSG MALAYSIA SDN. BHD         | 100KTL-M1(COM1-17) | NE=50412012 | PV5 input current(A)  | 429.610       | 588.240   | 26.97     |
| DSG MALAYSIA SDN. BHD         | 100KTL-M1(COM1-17) | NE=50412012 | PV7 input current(A)  | 469.440       | 588.240   | 20.20     |
| DSG MALAYSIA SDN. BHD         | 100KTL-M1(COM1-18) | NE=50412014 | PV1 input current(A)  | 397.900       | 547.360   | 27.31     |
| DSG MALAYSIA SDN. BHD         | 100KTL-M1(COM1-18) | NE=50412014 | PV11 input current(A) | 431.120       | 547.360   | 21.24     |
| DSG MALAYSIA SDN. BHD         | 100KTL-M1(COM1-18) | NE=50412014 | PV2 input current(A)  | 385.240       | 547.360   | 29.62     |

| Plant Name                             | Inverter Name                  | Inverter SN | String Name           | Total Current | Benchmark | Deviation |
|----------------------------------------|--------------------------------|-------------|-----------------------|---------------|-----------|-----------|
| DSG MALAYSIA SDN. BHD                  | 100KTL-M1(COM1-19)             | NE=50411994 | PV1 input current(A)  | 401.950       | 558.450   | 28.02     |
| DSG MALAYSIA SDN. BHD                  | 100KTL-M1(COM1-19)             | NE=50411994 | PV2 input current(A)  | 384.950       | 558.450   | 31.07     |
| DSG MALAYSIA SDN. BHD                  | 100KTL-M1(COM1-19)             | NE=50411994 | PV3 input current(A)  | 433.710       | 558.450   | 22.34     |
| DSG MALAYSIA SDN. BHD                  | 100KTL-M1(COM1-19)             | NE=50411994 | PV7 input current(A)  | 437.490       | 558.450   | 21.66     |
| DSG MALAYSIA SDN. BHD                  | 100KTL-M1(COM1-19)             | NE=50411994 | PV9 input current(A)  | 438.090       | 558.450   | 21.55     |
| DSG MALAYSIA SDN. BHD                  | 100KTL-M1(COM1-20)             | NE=50412016 | PV1 input current(A)  | 410.400       | 554.880   | 26.04     |
| DSG MALAYSIA SDN. BHD                  | 100KTL-M1(COM1-20)             | NE=50412016 | PV2 input current(A)  | 372.940       | 554.880   | 32.79     |
| KWANG HUA PERSENDIRIAN METER 2-3-4-5-6 | Block C - Inverter 7 - Meter 2 | NE=51163025 | PV1 input current(A)  | 306.540       | 603.460   | 49.20     |
| KWANG HUA PERSENDIRIAN METER 2-3-4-5-6 | Block C - Inverter 7 - Meter 2 | NE=51163025 | PV3 input current(A)  | 278.680       | 603.460   | 53.82     |
| PKT 12 WAVES                           | Inverter 1                     | NE=56003099 | PV1 input current(A)  | 464.300       | 756.020   | 38.59     |
| PKT 12 WAVES                           | Inverter 1                     | NE=56003099 | PV16 input current(A) | -50.330       | 756.020   | 106.66    |
| PKT 12 WAVES                           | Inverter 1                     | NE=56003099 | PV2 input current(A)  | 422.370       | 756.020   | 44.13     |
| PKT 12 WAVES                           | Inverter 10                    | NE=56003102 | PV11 input current(A) | 472.150       | 774.160   | 39.01     |
| PKT 12 WAVES                           | Inverter 10                    | NE=56003102 | PV12 input current(A) | 457.510       | 774.160   | 40.90     |
| PKT 12 WAVES                           | Inverter 10                    | NE=56003102 | PV15 input current(A) | 500.960       | 774.160   | 35.29     |
| PKT 12 WAVES                           | Inverter 10                    | NE=56003102 | PV16 input current(A) | 452.890       | 774.160   | 41.50     |
| PKT 12 WAVES                           | Inverter 10                    | NE=56003102 | PV17 input current(A) | 1.960         | 774.160   | 99.75     |
| PKT 12 WAVES                           | Inverter 10                    | NE=56003102 | PV19 input current(A) | 460.960       | 774.160   | 40.46     |
| PKT 12 WAVES                           | Inverter 10                    | NE=56003102 | PV20 input current(A) | 483.200       | 774.160   | 37.58     |
| PKT 12 WAVES                           | Inverter 10                    | NE=56003102 | PV6 input current(A)  | -10.130       | 774.160   | 101.31    |

| Plant Name   | Inverter Name | Inverter SN | String Name           | Total Current | Benchmark | Deviation |
|--------------|---------------|-------------|-----------------------|---------------|-----------|-----------|
| PKT 12 WAVES | Inverter 2    | NE=56003098 | PV1 input current(A)  | 494.010       | 725.240   | 31.88     |
| PKT 12 WAVES | Inverter 2    | NE=56003098 | PV2 input current(A)  | 417.060       | 725.240   | 42.49     |
| PKT 12 WAVES | Inverter 3    | NE=56003101 | PV1 input current(A)  | 458.280       | 717.060   | 36.09     |
| PKT 12 WAVES | Inverter 3    | NE=56003101 | PV16 input current(A) | -5.570        | 717.060   | 100.78    |
| PKT 12 WAVES | Inverter 3    | NE=56003101 | PV2 input current(A)  | 423.930       | 717.060   | 40.88     |
| PKT 12 WAVES | Inverter 4    | NE=56003104 | PV10 input current(A) | 446.640       | 770.050   | 42.00     |
| PKT 12 WAVES | Inverter 4    | NE=56003104 | PV11 input current(A) | 503.270       | 770.050   | 34.64     |
| PKT 12 WAVES | Inverter 4    | NE=56003104 | PV12 input current(A) | 463.430       | 770.050   | 39.82     |
| PKT 12 WAVES | Inverter 4    | NE=56003104 | PV7 input current(A)  | 524.050       | 770.050   | 31.95     |
| PKT 12 WAVES | Inverter 4    | NE=56003104 | PV8 input current(A)  | 425.010       | 770.050   | 44.81     |
| PKT 12 WAVES | Inverter 4    | NE=56003104 | PV9 input current(A)  | 501.330       | 770.050   | 34.90     |
| PKT 12 WAVES | Inverter 5    | NE=56003103 | PV1 input current(A)  | 424.660       | 710.130   | 40.20     |
| PKT 12 WAVES | Inverter 5    | NE=56003103 | PV2 input current(A)  | 463.730       | 710.130   | 34.70     |
| PKT 12 WAVES | Inverter 6    | NE=56003095 | PV1 input current(A)  | 450.240       | 702.570   | 35.92     |
| PKT 12 WAVES | Inverter 6    | NE=56003095 | PV16 input current(A) | -14.880       | 702.570   | 102.12    |
| PKT 12 WAVES | Inverter 6    | NE=56003095 | PV2 input current(A)  | 400.930       | 702.570   | 42.93     |
| PKT 12 WAVES | Inverter 7    | NE=56003100 | PV1 input current(A)  | 459.530       | 699.650   | 34.32     |
| PKT 12 WAVES | Inverter 7    | NE=56003100 | PV2 input current(A)  | 407.490       | 699.650   | 41.76     |
| PKT 12 WAVES | Inverter 8    | NE=56003096 | PV19 input current(A) | 440.190       | 708.060   | 37.83     |
| PKT 12 WAVES | Inverter 8    | NE=56003096 | PV20 input current(A) | 423.190       | 708.060   | 40.23     |
| PKT 12 WAVES | Inverter 8    | NE=56003096 | PV6 input current(A)  | -15.960       | 708.060   | 102.25    |
| PKT 12 WAVES | Inverter 9    | NE=56003097 | PV1 input current(A)  | 463.720       | 782.460   | 40.74     |
| PKT 12 WAVES | Inverter 9    | NE=56003097 | PV16 input current(A) | -49.410       | 782.460   | 106.31    |
| PKT 12 WAVES | Inverter 9    | NE=56003097 | PV2 input current(A)  | 472.460       | 782.460   | 39.62     |
| PKT 12 WAVES | Inverter 9    | NE=56003097 | PV3 input current(A)  | 444.110       | 782.460   | 43.24     |

| Plant Name   | Inverter Name | Inverter SN | String Name           | Total Current | Benchmark | Deviation |
|--------------|---------------|-------------|-----------------------|---------------|-----------|-----------|
| PKT 12 WAVES | Inverter 9    | NE=56003097 | PV4 input current(A)  | 506.580       | 782.460   | 35.26     |
| QL FOODS     | INVERTER_5 R1 | NE=54942978 | PV12 input current(A) | -31.710       | 988.930   | 103.21    |
| QL FOODS     | INVERTER_5 R1 | NE=54942978 | PV16 input current(A) | -44.280       | 988.930   | 104.48    |
| QL FOODS     | INVERTER_5 R1 | NE=54942978 | PV6 input current(A)  | -14.800       | 988.930   | 101.50    |
| QL FOODS     | INVERTER_10   | NE=53679611 | PV4 input current(A)  | 1.400         | 833.330   | 99.83     |
| QL FOODS     | INVERTER_10   | NE=53679611 | PV7 input current(A)  | 552.160       | 833.330   | 33.74     |
| QL FOODS     | INVERTER_10   | NE=53679611 | PV8 input current(A)  | 536.990       | 833.330   | 35.56     |
| QL FOODS     | INVERTER_13   | NE=53679495 | PV16 input current(A) | -20.720       | 888.490   | 102.33    |
| QL FOODS     | INVERTER_14   | NE=53679493 | PV17 input current(A) | 791.620       | 1006.240  | 21.33     |
| QL FOODS     | INVERTER_14   | NE=53679493 | PV19 input current(A) | 716.830       | 1006.240  | 28.76     |
| QL FOODS     | INVERTER_15   | NE=53679053 | PV4 input current(A)  | 1.040         | 818.560   | 99.87     |
| QL FOODS     | INVERTER_7    | NE=53676713 | PV7 input current(A)  | 18.710        | 803.730   | 97.67     |
| QL FOODS     | INVERTER_9    | NE=53679667 | PV19 input current(A) | 537.980       | 877.520   | 38.69     |
| QL FOODS     | INVERTER_9    | NE=53679667 | PV20 input current(A) | 490.120       | 877.520   | 44.15     |

## Active Alarms

| Plant Name                          | Device Name         | Device SN    | Alarm Name                         | Severity | Occurrence Time  |
|-------------------------------------|---------------------|--------------|------------------------------------|----------|------------------|
| BOILERMECH LOT 873                  | Logger-102516002824 | 102516002824 | Network Connection Error           | Major    | 19-05-2026 06:35 |
| C0172_ATRIA SOUTH                   | Logger-102256528212 | 102256528212 | Network Connection Error           | Major    | 18-05-2026 12:57 |
| C0176_GETHA                         | Logger-102256528260 | 102256528260 | Network Connection Error           | Major    | 28-04-2026 21:09 |
| Fibertex Phase 2                    | Inverter 2 L3 Old   | 6T2379019735 | Upgrade Failed or Version Mismatch | Minor    | 18-07-2025 15:24 |
| IOI Mall Puchong (New Wing) Phase 2 | Inverter 3          | GR2569071111 | String Loss                        | Warning  | 20-05-2026 15:30 |
| IOI Mall Puchong (New Wing) Phase 2 | Inverter 4          | GR2569071069 | String Loss                        | Warning  | 20-05-2026 10:32 |
| IOI Mall Puchong (New Wing) Phase 2 | Inverter 3          | GR2569071111 | String Loss                        | Warning  | 20-05-2026 10:32 |
| IOI Mall Puchong (New Wing) Phase 2 | Inverter 3          | GR2569071111 | String Loss                        | Warning  | 20-05-2026 10:32 |

| Plant Name                          | Device Name          | Device SN    | Alarm Name                         | Severity | Occurrence Time  |
|-------------------------------------|----------------------|--------------|------------------------------------|----------|------------------|
| IOI Mall Puchong (New Wing) Phase 2 | Inverter 4           | GR2569071069 | String Loss                        | Warning  | 17-05-2026 13:39 |
| IOI Mall Puchong (Old Wing)         | Inverter 21 R1-TERA  | 6T2599057796 | Upgrade Failed or Version Mismatch | Minor    | 18-04-2026 00:46 |
| IOI Mall Puchong (Old Wing)         | Inverter 3 R1 - TERA | BN2521059950 | Upgrade Failed or Version Mismatch | Minor    | 18-04-2026 00:46 |
| IOI Mall Puchong (Old Wing)         | Inverter 12 - TERA   | BN2461066801 | Upgrade Failed or Version Mismatch | Minor    | 18-04-2026 00:46 |
| IOI Mall Puchong (Old Wing)         | Inverter 2 - TERA    | BN2461066770 | Upgrade Failed or Version Mismatch | Minor    | 18-04-2026 00:46 |
| IOI Mall Puchong (Old Wing)         | Inverter 7 - TERA    | 6T2479017524 | Upgrade Failed or Version Mismatch | Minor    | 18-04-2026 00:46 |
| IOI Mall Puchong (Old Wing)         | Inverter 10 - TERA   | 6T2469039407 | Upgrade Failed or Version Mismatch | Minor    | 18-04-2026 00:46 |
| IOI Mall Puchong (Old Wing)         | Inverter 4 - TERA    | 6T2479017517 | Upgrade Failed or Version Mismatch | Minor    | 18-04-2026 00:46 |
| IOI Mall Puchong (Old Wing)         | Inverter 1 - TERA    | BN2461065466 | Upgrade Failed or Version Mismatch | Minor    | 18-04-2026 00:46 |
| IOI Mall Puchong (Old Wing)         | Inverter 5 - TERA    | BN2461066760 | Upgrade Failed or Version Mismatch | Minor    | 18-04-2026 00:46 |
| IOI Mall Puchong (Old Wing)         | Inverter 6 - TERA    | BN2461066754 | Upgrade Failed or Version Mismatch | Minor    | 18-04-2026 00:46 |
| IOI Mall Puchong (Old Wing)         | Inverter 11 - TERA   | BN2461066739 | Upgrade Failed or Version Mismatch | Minor    | 18-04-2026 00:46 |
| IOI Mall Puchong (Old Wing)         | Inverter 8 - TERA    | BN2461065428 | Upgrade Failed or Version Mismatch | Minor    | 18-04-2026 00:46 |
| IOI Mall Puchong (Old Wing)         | Inverter 9 - TERA    | 6T2479017523 | Upgrade Failed or Version Mismatch | Minor    | 18-04-2026 00:46 |
| KILANG BATU BATA                    | Dongle-TA2510047367  | TA2510047367 | Network Connection Error           | Major    | 21-05-2026 12:16 |
| LIAN FOO POULTRY FARM SDN BHD       | Dongle-BT2541519026  | BT2541519026 | Network Connection Error           | Major    | 30-04-2026 18:40 |
| LIAN FOO POULTRY FARM SDN BHD       | INV-ES2550000030     | ES2550000030 | Grid Loss                          | Major    | 30-04-2026 17:55 |
| LIAN FOO POULTRY FARM SDN BHD       | INV-ES25C0125116     | ES25C0125116 | Grid Loss                          | Major    | 30-04-2026 17:54 |
| LIAN FOO POULTRY FARM SDN BHD       | INV-ES25C0125117     | ES25C0125117 | Grid Loss                          | Major    | 30-04-2026 17:54 |
| Lian Teck Seng Lot 11               | Dongle-BT24C0060275  | BT24C0060275 | Network Connection Error           | Major    | 29-01-2026 15:54 |
| MARINE GOLD SDN BHD                 | Dongle-TA2340293153  | TA2340293153 | Network Connection Error           | Major    | 26-03-2026 15:55 |
| MARINE GOLD SDN BHD                 | Dongle-TA2340293476  | TA2340293476 | Network Connection Error           | Major    | 26-03-2026 15:55 |
| MARINE GOLD SDN BHD                 | Dongle-TA2340291437  | TA2340291437 | Network Connection Error           | Major    | 26-03-2026 15:55 |
| MARINE GOLD SDN BHD                 | Dongle-HV2310776105  | HV2310776105 | Network Connection Error           | Major    | 26-03-2026 14:56 |
| MARINE GOLD SDN BHD                 | Dongle-HV2310776109  | HV2310776109 | Network Connection Error           | Major    | 26-03-2026 14:55 |

| Plant Name                     | Device Name         | Device SN    | Alarm Name                         | Severity | Occurrence Time  |
|--------------------------------|---------------------|--------------|------------------------------------|----------|------------------|
| MARINE GOLD SDN BHD            | Dongle-HV2310773587 | HV2310773587 | Network Connection Error           | Major    | 26-03-2026 14:54 |
| MENARA PKNS PJ                 | Logger-102466288020 | 102466288020 | Network Connection Error           | Major    | 10-05-2026 01:00 |
| MAIW FRESH                     | VASOLAR INV 1       | NS2331625509 | Grid Loss                          | Major    | 20-05-2026 11:38 |
| PKT 12 WAVES                   | Inverter 4          | ES2470045168 | Upgrade Failed or Version Mismatch | Minor    | 15-05-2026 20:32 |
| PKT 12 WAVES                   | Inverter 5          | 6T2459004824 | Upgrade Failed or Version Mismatch | Minor    | 15-05-2026 20:32 |
| PKT 12 WAVES                   | Inverter 3          | 6T2449041406 | Upgrade Failed or Version Mismatch | Minor    | 15-05-2026 20:32 |
| PKT 12 WAVES                   | Inverter 7          | 6T2449033633 | Upgrade Failed or Version Mismatch | Minor    | 15-05-2026 20:32 |
| PKT 12 WAVES                   | Inverter 8          | 6T2459004809 | Upgrade Failed or Version Mismatch | Minor    | 15-05-2026 20:32 |
| PKT 12 WAVES                   | Inverter 6          | ES2470045204 | Upgrade Failed or Version Mismatch | Minor    | 15-05-2026 20:32 |
| PKT 12 WAVES                   | Inverter 10         | 6T2449041556 | Upgrade Failed or Version Mismatch | Minor    | 15-05-2026 20:30 |
| PKT 12 WAVES                   | Inverter 1          | 6T2459004867 | Upgrade Failed or Version Mismatch | Minor    | 15-05-2026 20:30 |
| PKT 12 WAVES                   | Inverter 2          | 6T2459004831 | Upgrade Failed or Version Mismatch | Minor    | 15-05-2026 20:30 |
| PKT 12 WAVES                   | Inverter 9          | 6T2449032075 | Upgrade Failed or Version Mismatch | Minor    | 15-05-2026 20:30 |
| PKT THE SHIP                   | Inverter_7          | 6T2379019759 | Upgrade Failed or Version Mismatch | Minor    | 15-05-2026 20:32 |
| PKT THE SHIP                   | Inverter_3          | 6T2379019623 | Upgrade Failed or Version Mismatch | Minor    | 15-05-2026 20:32 |
| PKT THE SHIP                   | Inverter_5          | 6T2379019768 | Upgrade Failed or Version Mismatch | Minor    | 15-05-2026 20:32 |
| PKT THE SHIP                   | Inverter_1          | 6T2379018298 | Upgrade Failed or Version Mismatch | Minor    | 15-05-2026 20:32 |
| PKT THE SHIP                   | Inverter_4          | 6T2379019776 | Upgrade Failed or Version Mismatch | Minor    | 15-05-2026 20:32 |
| PKT THE SHIP                   | Inverter_2 R1       | BN2531021024 | Upgrade Failed or Version Mismatch | Minor    | 15-05-2026 20:32 |
| PKT THE SHIP                   | Inverter_6          | 6T2379019622 | Upgrade Failed or Version Mismatch | Minor    | 15-05-2026 20:32 |
| Pengerang Independent Terminal | Dongle-LAB          | TA23B0087782 | Network Connection Error           | Major    | 20-04-2026 13:52 |
| Pleasure Latex Phase 2         | Logger-102347282208 | 102347282208 | Network Connection Error           | Major    | 19-02-2026 03:00 |
| QL ENDAU MARINE                | Logger-HV24C0331342 | HV24C0331342 | Network Connection Error           | Major    | 21-05-2026 18:56 |
| QL FARM SDN BHD                | Logger-102466853213 | 102466853213 | Network Connection Error           | Major    | 24-04-2026 10:56 |
| QL FARM SDN BHD                | Inverter 1          | ES2580051653 | Grid Loss                          | Major    | 24-04-2026 10:07 |

| Plant Name                | Device Name                 | Device SN            | Alarm Name                                      | Severity | Occurrence Time  |
|---------------------------|-----------------------------|----------------------|-------------------------------------------------|----------|------------------|
| QL FARM SDN BHD           | Inverter 2                  | ES2580051643         | Grid Loss                                       | Major    | 24-04-2026 10:07 |
| QL FARM SDN BHD           | Inverter3                   | ES2490076207         | Grid Loss                                       | Major    | 24-04-2026 10:07 |
| REDANG LAGOON RESORT      | Dongle-2102312EHS10N9115979 | 2102312EHS10N9115979 | Network Connection Error                        | Major    | 30-01-2026 19:29 |
| REDANG LAGOON RESORT      | INV-ES22A0089681            | ES22A0089681         | Grid Loss                                       | Major    | 30-01-2026 07:23 |
| SIME KANSAI PAINT SDN BHD | INV-ES2550146111            | ES2550146111         | Upgrade Failed or Version Mismatch              | Minor    | 19-11-2025 21:35 |
| SINCERELY DYEING          | Dongle Roof C               | BT2540023458         | Network Connection Error                        | Major    | 20-05-2026 11:54 |
| THP MEDICAL               | VASOLAR INV 3               | 6T2279009018         | Upgrade Failed or Version Mismatch              | Minor    | 15-02-2026 20:22 |
| THP MEDICAL               | VASOLAR INV 2               | 6T2279008977         | Upgrade Failed or Version Mismatch              | Minor    | 15-02-2026 20:22 |
| THP MEDICAL               | VASOLAR INV 1               | 6T2279009011         | Upgrade Failed or Version Mismatch              | Minor    | 15-02-2026 20:22 |
| VINDA PHASE 4 (MSB 3-2)   | Inverter7 Phase4 R1         | ES2580051502         | Grid Loss                                       | Major    | 19-05-2026 14:42 |
| VINDA PHASE 4 (MSB 3-2)   | Inverter7 Phase4 R1         | ES2580051502         | The PV string is short-circuited to the ground. | Major    | 19-05-2026 08:49 |
| VINDA PHASE 4 (MSB 3-2)   | Inverter7 Phase4 R1         | ES2580051502         | AC Overcurrent                                  | Major    | 19-05-2026 08:49 |

## High-temperature Inverters

| Plant Name                      | Inverter Name        | Inverter SN  | Temperature |
|---------------------------------|----------------------|--------------|-------------|
| AFI BRAKE MANUFACTURING SDN BHD | INV 4 - GROUND FLOOR | HV22B0337098 | 77.9        |
| AFI BRAKE MANUFACTURING SDN BHD | INV 5 - FIRST FLOOR  | HV22B0337097 | 82.1        |
| AFI BRAKE MANUFACTURING SDN BHD | INV 6 - SECOND FLOOR | HV22A0405534 | 78.4        |
| AFI BRAKE MANUFACTURING SDN BHD | INV 7 - THIRD FLOOR  | HV22B0337096 | 74.0        |
| Apex Uniparts                   | VASOLAR_INV_1        | ES2420001215 | 80.3        |
| BP PLASTICS HQ                  | Inverter_11          | 6T2499023013 | 70.4        |
| BP PLASTICS HQ                  | Inverter_2           | ES2440060550 | 74.5        |
| BP PLASTICS HQ                  | Inverter_6           | 6T2499021622 | 76.8        |
| C0102_QL batang kali            | 150K-MG0(COM3-2)     | GR2479026710 | 75.7        |



| Plant Name                               | Inverter Name        | Inverter SN  | Temperature |
|------------------------------------------|----------------------|--------------|-------------|
| C0102_QL batang kali                     | 150K-MG0(COM3-3)     | GR2479026770 | 73.8        |
| C0149_VERTEX MISSION                     | HV21B0210137         | HV21B0210137 | 70.9        |
| CHAN KAH WHYE                            | INV-NS249G082061     | NS249G082061 | 79.0        |
| Durasafe Sdn. Bhd.                       | INV 1-6T2479002464   | 6T2479002464 | 75.2        |
| Durasafe Sdn. Bhd.                       | INV 2-6T2469038783   | 6T2469038783 | 72.0        |
| FDP AND MTB INDUSTRIES SDN BHD           | TERA FDP INV 1       | 6T2569054829 | 76.3        |
| FDP AND MTB INDUSTRIES SDN BHD           | TERA FDP INV 2       | ES2580087345 | 83.3        |
| FDP AND MTB INDUSTRIES SDN BHD           | TERA MTB INV 3       | 6T2569054834 | 73.9        |
| FDP AND MTB INDUSTRIES SDN BHD           | TERA MTB INV 4       | ES2580087312 | 82.4        |
| Farm Fresh Taiping (Factory)             | 50KTL-M3(COM1-12)    | 6T22A9038815 | 76.8        |
| GLASS PLASTIC PACKAGING                  | INV 2 - (No.23)      | 6T2489010546 | 82.5        |
| GLASS PLASTIC PACKAGING                  | INV 3 - (Lot 65999)  | 6T2489010635 | 77.8        |
| GLASS PLASTIC PACKAGING                  | INV 4 - (Lot 65999)  | 6T2489010593 | 80.1        |
| IOI Mall Puchong (New Wing)              | Inverter 16 - TERA   | 6T2449030262 | 73.1        |
| Jebsen And Jessen Malaysia Sdn Bhd (MHE) | Inverter 2 - Tera    | 6T2489031215 | 72.9        |
| Kamma Klang Enterprise                   | Inverter 2           | HV22A0153968 | 74.8        |
| Kiara Bay                                | Inverter 2 - TERA    | ES2330110574 | 72.7        |
| Kiara Bay                                | Inverter 3 - TERA    | 6T2449022934 | 77.2        |
| Kiara Bay                                | Inverter 4 - TERA    | 6T2449023252 | 73.8        |
| Kiara Bay                                | Inverter 6 - TERA    | ES2350101155 | 70.1        |
| Kiara Bay                                | Inverter 9 - TERA    | ES2350101147 | 70.4        |
| Mitsui Copper Foil P3                    | Inverter 3 (AREA A)  | 6T24A9009773 | 71.2        |
| Multi Choice (M) Sdn Bhd                 | TERA INV 3           | ES2560208616 | 79.3        |
| QL ENDAU DEEP SEA FISHING                | Inverter 1 (COM1-12) | GR2479028683 | 80.4        |
| QL ENDAU DEEP SEA FISHING                | Inverter 2 (COM3-13) | 6T2519005200 | 79.2        |

| Plant Name                                    | Inverter Name        | Inverter SN  | Temperature |
|-----------------------------------------------|----------------------|--------------|-------------|
| QL ENDAU DEEP SEA FISHING                     | Inverter 3 (COM3-14) | GR2479020699 | 77.7        |
| QL ENDAU DEEP SEA FISHING                     | Inverter 5 (COM3-16) | GR2479028681 | 80.0        |
| QL FOODS                                      | INVERTER_10          | 6T2449032177 | 73.5        |
| RS POLY INDUSTRY                              | VASOLAR INV 1        | ES2420000999 | 76.3        |
| RS POLY INDUSTRY                              | VASOLAR INV 2        | ES2420001084 | 73.2        |
| SABAH CHINESE HIGH SCHOOL (TAK YUEN BUILDING) | 50KTL-M3(COM1-2)     | ES22A0076308 | 83.6        |
| SCENT PUR MANUFACTURING SDN BHD NO.35         | INV-TA2470078151     | TA2470078151 | 71.5        |
| SCENT PUR MANUFACTURING SDN BHD NO.37         | INV-NS245G038275     | NS245G038275 | 80.6        |
| SJK (C) WU TECK                               | INV 1                | 6T25B9000135 | 72.9        |
| SWH INDUSTRIES (PLOT 132113)                  | VASOLAR INV 1        | 6T2379015928 | 71.7        |
| SWH INDUSTRIES (PLOT 132113)                  | VASOLAR INV 4        | 6T2379019753 | 71.6        |
| SWH INDUSTRIES (PLOT 132113)                  | VASOLAR INV 6        | 6T22A9048188 | 74.2        |
| TOMEI                                         | INV-(12-1)           | HV2330348462 | 71.3        |
| TOMEI                                         | INV-(16-1)           | HV2330348376 | 73.9        |
| Teong Huat Medical                            | TERA INV 1           | 6T2539003818 | 71.4        |
| Teong Huat Medical                            | TERA INV 3 R1        | 6T2599029908 | 79.4        |