

FusionSolar Troubleshooting Report

Date: 22-05-2026
Generated At: 22-05-2026 09:53:06
Prepared By: TERA SPMS

Task Status Warnings

Task	Status Message
Low-PSH Plants	This low-PSH plant detection task for 22-05-2026 was unsuccessful.
Low-performing Inverters	This low-performing inverter detection task for 22-05-2026 was unsuccessful.
Low-performing Strings	This low-performing string detection task for 22-05-2026 was unsuccessful.
Active Alarms	This alarm polling task for 22-05-2026 was unsuccessful.
High-temperature Inverters	This high-temperature inverter sync task for 22-05-2026 was unsuccessful.

Executive Summary

Metric	Value
Total low-performing plants	0
Total low-performing inverters	0
Total low-performing strings	0
Total alarms	0
Total high-temperature inverters	0
Unsuccessful task sections	5

Low-performing Plants

Plant Name	Plant PSH	City Average PSH	Deviation
This low-PSH plant detection task for 22-05-2026 was unsuccessful.	-	-	-

Low-performing Inverters

Plant Name	Inverter Name	Inverter SN	Inverter PSH	Benchmark PSH	Deviation
This low-performing inverter detection task for 22-05-2026 was unsuccessful.	-	-	-	-	-

Low-performing Strings

Plant Name	Inverter Name	Inverter SN	String Name	Total Current	Benchmark	Deviation
This low-performing string detection task for 22-05-2026 was unsuccessful.	-	-	-	-	-	-

Active Alarms

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
This alarm polling task for 22-05-2026 was unsuccessful.	-	-	-	-	-

High-temperature Inverters

Plant Name	Inverter Name	Inverter SN	Temperature
This high-temperature inverter sync task for 22-05-2026 was unsuccessful.	-	-	-