

FusionSolar Troubleshooting Report

Date: 06-05-2026
Generated At: 06-05-2026 20:30:07
Prepared By: TERA SPMS

Executive Summary

Metric	Value
Total low-performing plants	31
Total alarms	56
Total high-temperature inverters	55

Low-performing Plants

Plant Name	Plant PSH	City Average PSH	Deviation
ASHITA COMMUNICATION	0.00	2.27	-100.00
BIMB Bdr Penawar - 1st Floor	0.00	1.21	-100.00
BJC FOOD (MALAYSIA) SDN. BHD.	2.21	2.70	-18.23
BOILERMECH LOT 873	0.00	1.38	-100.00
BP PLASTICS HQ	3.52	4.09	-13.87
DSG Malaysia Sdn. Bhd	2.29	2.78	-17.53
Dong Sing Food Link Sdn Bhd	0.00	2.39	-100.00
IOI Mall Puchong (New Wing) Phase 2	2.09	2.75	-24.05
IOI Mall Puchong (Old Wing)	2.34	2.75	-14.96
Jaya Nets	1.97	2.20	-10.59
KISWIRE CORD PHASE 1 (DATA)	0.00	1.32	-100.00
KOSSAN PAINT SDN BHD	0.62	2.27	-72.66
Kwang Hua Persendirian meter 2-3-4-5-6	1.88	2.27	-17.11

Plant Name	Plant PSH	City Average PSH	Deviation
Lau and Tan Pharmacy (G.Floor)	2.90	3.47	-16.55
Lian Teck Seng Lot 11	0.00	2.27	-100.00
MAJOR ENGINEERING Lot 10	1.97	2.27	-13.14
MAJOR ENGINEERING Lot 8	0.55	2.27	-75.75
MARINE GOLD SDN BHD	0.00	2.35	-100.00
MENARA PKNS PJ	0.00	1.84	-100.00
Menara PJD	2.28	2.61	-12.76
PKT 12 WAVES	2.57	2.86	-10.24
Perbadanan Pengurusan Villa Raintree II	2.65	3.08	-14.05
Pleasure Latex Phase 2	0.00	1.42	-100.00
QL FARM SDN BHD	0.00	1.53	-100.00
REDANG LAGOON RESORT	0.00	2.78	-100.00
SWEE CHEONG WATCH SDN BHD (Meter 2)	3.75	4.51	-16.91
THOR SPECIALTIES	0.00	2.70	-100.00
TIMURIKAN TRENGGANU MARINE PRODUCTS SDN BHD	0.79	2.89	-72.66
Teong Huat Medical	3.00	3.41	-12.11
WASCO PIPE SDN BHD (COATING)	0.09	1.12	-92.00
WEIDA MARKETING SDN. BHD.	2.75	3.20	-13.93

Active Alarms

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
BIMB Bdr Penawar - 1st Floor	Dongle- INV1	BT24C0060244	Network Connection Error	Major	15-04-2026 18:07
BOILERMECH LOT 873	Logger-102516002824	102516002824	Network Connection Error	Major	02-05-2026 00:57
C0176_GETHA	Logger-102256528260	102256528260	Network Connection Error	Major	28-04-2026 21:09

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
Dong Sing Food Link Sdn Bhd	Inverter(COM2-1)	ES2570023845	Grid Loss	Major	06-05-2026 06:48
Fibertex Phase 2	Inverter 2 L3 Old	6T2379019735	Upgrade Failed or Version Mismatch	Minor	18-07-2025 15:24
GUH METER 1	VASOLAR_INV_1	6T2379018351	Abnormal External Fan	Major	06-05-2026 08:06
IOI Mall Puchong (New Wing)	Inverter 14 - TERA	ES2470053866	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing)	Inverter 17 - TERA	6T2479017623	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing)	Inverter 13 - TERA	6T2479017534	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing) Phase 2	Inverter 4	GR2569071069	Grid Loss	Major	16-04-2026 09:37
IOI Mall Puchong (New Wing) Phase 2	Inverter(COM1-1)	GR2569071128	Grid Loss	Major	10-04-2026 16:33
IOI Mall Puchong (Old Wing)	Inverter 21 R1-TERA	6T2599057796	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 3 R1 - TERA	BN2521059950	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 12 - TERA	BN2461066801	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 2 - TERA	BN2461066770	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 7 - TERA	6T2479017524	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 10 - TERA	6T2469039407	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 4 - TERA	6T2479017517	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 1 - TERA	BN2461065466	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 5 - TERA	BN2461066760	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 6 - TERA	BN2461066754	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 11 - TERA	BN2461066739	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 8 - TERA	BN2461065428	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 9 - TERA	6T2479017523	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
KILANG BATU BATA	Dongle-TA2510047367	TA2510047367	Network Connection Error	Major	02-05-2026 11:29
LIAN FOO POULTRY FARM SDN BHD	Dongle-BT2541519026	BT2541519026	Network Connection Error	Major	30-04-2026 18:40

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
LIAN FOO POULTRY FARM SDN BHD	INV-ES2550000030	ES2550000030	Grid Loss	Major	30-04-2026 17:55
LIAN FOO POULTRY FARM SDN BHD	INV-ES25C0125116	ES25C0125116	Grid Loss	Major	30-04-2026 17:54
LIAN FOO POULTRY FARM SDN BHD	INV-ES25C0125117	ES25C0125117	Grid Loss	Major	30-04-2026 17:54
Lian Teck Seng Lot 11	Dongle-BT24C0060275	BT24C0060275	Network Connection Error	Major	29-01-2026 15:54
MARINE GOLD SDN BHD	Dongle-TA2340293153	TA2340293153	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-TA2340293476	TA2340293476	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-TA2340291437	TA2340291437	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-HV2310776105	HV2310776105	Network Connection Error	Major	26-03-2026 14:56
MARINE GOLD SDN BHD	Dongle-HV2310776109	HV2310776109	Network Connection Error	Major	26-03-2026 14:55
MARINE GOLD SDN BHD	Dongle-HV2310773587	HV2310773587	Network Connection Error	Major	26-03-2026 14:54
Pengerang Independent Terminal	Dongle-LAB	TA23B0087782	Network Connection Error	Major	20-04-2026 13:52
Pleasure Latex Phase 2	Logger-102347282208	102347282208	Network Connection Error	Major	19-02-2026 03:00
QL FARM SDN BHD	Logger-102466853213	102466853213	Network Connection Error	Major	24-04-2026 10:56
QL FARM SDN BHD	Inverter 1	ES2580051653	Grid Loss	Major	24-04-2026 10:07
QL FARM SDN BHD	Inverter 2	ES2580051643	Grid Loss	Major	24-04-2026 10:07
QL FARM SDN BHD	Inverter3	ES2490076207	Grid Loss	Major	24-04-2026 10:07
QL TAWAU FEEDMILL	Inverter 1	6T2489021082	Grid Loss	Major	06-05-2026 10:09
REDANG LAGOON RESORT	Dongle-2102312EHS10N9115979	2102312EHS10N9115979	Network Connection Error	Major	30-01-2026 19:29
REDANG LAGOON RESORT	INV-ES22A0089681	ES22A0089681	Grid Loss	Major	30-01-2026 07:23
SABAH CHINESE HIGH SCHOOL (TAK YUEN BUILDING)	20KTL-M5(COM1-1)	NS2311057237	Grid Loss	Major	06-05-2026 09:16
SABAH CHINESE HIGH SCHOOL (TAK YUEN BUILDING)	50KTL-M3(COM1-2)	ES22A0076308	Grid Loss	Major	06-05-2026 09:16

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
SIME KANSAI PAINT SDN BHD	INV-ES2550146111	ES2550146111	Upgrade Failed or Version Mismatch	Minor	19-11-2025 21:35
THP MEDICAL	VASOLAR INV 3	6T2279009018	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
THP MEDICAL	VASOLAR INV 2	6T2279008977	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
THP MEDICAL	VASOLAR INV 1	6T2279009011	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
Telewiring	VASOLAR_INV_1	HV2330869769	Grid Loss	Major	04-05-2026 08:17
VINDA PHASE 4 (MSB 3-2)	MASTER LOG HT P4	102595350697	Southbound Device Communication Abnormal	Minor	29-04-2026 15:30
WASCO PIPE SDN BHD (COATING)	Inverter 3	HV2570122057	Grid Loss	Major	06-05-2026 10:03
WASCO PIPE SDN BHD (COATING)	Inverter 2	6T24B9016590	Grid Loss	Major	06-05-2026 10:03
WASCO PIPE SDN BHD (MILL)	Inverter 5	ES2540189908	Grid Loss	Major	05-05-2026 15:11

High-temperature Inverters

Plant Name	Inverter Name	Inverter SN	Temperature
AFI BRAKE MANUFACTURING SDN BHD	INV 4 - GROUND FLOOR	HV22B0337098	79.3
AFI BRAKE MANUFACTURING SDN BHD	INV 5 - FIRST FLOOR	HV22B0337097	82.0
AFI BRAKE MANUFACTURING SDN BHD	INV 6 - SECOND FLOOR	HV22A0405534	79.5
AFI BRAKE MANUFACTURING SDN BHD	INV 7 - THIRD FLOOR	HV22B0337096	78.0
C0102_QL batang kali	150K-MG0(COM3-2)	GR2479026710	73.1
CHAN KAH WHYE	INV-NS249G082061	NS249G082061	85.8
Durasafe Sdn. Bhd.	INV 1-6T2479002464	6T2479002464	79.1
Durasafe Sdn. Bhd.	INV 2-6T2469038783	6T2469038783	72.7
Farm Fresh Taiping (Factory)	50KTL-M3(COM1-12)	6T22A9038815	76.9
GLASS PLASTIC PACKAGING	INV 2 - (No.23)	6T2489010546	72.8
GLASS PLASTIC PACKAGING	INV 4 - (Lot 65999)	6T2489010593	72.0
IOI City Mall Inc. Feeder 1	Inverter 1.1 - TERA	6T22C9025521	70.2

Plant Name	Inverter Name	Inverter SN	Temperature
IOI City Mall Inc. Feeder 1	Inverter 2.1 - TERA	6T22C9011475	71.8
IOI City Mall Inc. Feeder 1	Inverter 2.12 R1	6T2599029683	72.3
IOI City Mall Inc. Feeder 1	Inverter 2.2 - TERA	6T22B9036192	72.1
IOI City Mall Inc. Feeder 1	Inverter 2.3 - TERA	6T22C9011508	70.1
IOI City Mall Inc. Feeder 1	Inverter 2.5 - TERA	6T22C9011507	72.8
IOI City Mall Inc. Feeder 1	Inverter 2.6 - TERA	6T22C9011480	74.4
IOI City Mall Inc. Feeder 1	Inverter 2.7 - TERA	6T22C9011519	70.4
Jiann Lih safety product	40KTL-M3(COM1-15)	ES2290059762	82.2
Jiann Lih safety product	40KTL-M3(COM1-16)	ES2290059727	85.0
KUASA BAKTI (PETRON SETIA ALAM)	INV-6T2489035314	6T2489035314	70.2
Kiara Bay	Inverter 3 - TERA	6T2449022934	79.1
Kiara Bay	Inverter 4 - TERA	6T2449023252	80.7
Kiara Bay	Inverter 6 - TERA	ES2350101155	76.9
Kiara Bay	Inverter 8 - TERA	ES2470045868	71.1
Kiara Bay	Inverter 9 - TERA	ES2350101147	74.1
Komplex PKNS Bangi	40KTL-M3(COM1-13)	ES22A0040484	71.1
Marbach Asia Pacific Lot17	INV-6T2489012207	6T2489012207	74.6
Marbach Asia Pacific lot 15	INV-6T2489012205	6T2489012205	70.6
Mitsui Copper Foil P3	Inverter 3 (AREA A)	6T24A9009773	70.0
Mitsui Copper Foil P3	Inverter 4 (AREA A)	6T24A9013004	71.1
Multi Choice (M) Sdn Bhd	TERA INV 1	GR2489029065	71.4
Multi Choice (M) Sdn Bhd	TERA INV 2	GR2489029048	72.9
Multi Choice (M) Sdn Bhd	TERA INV 3	ES2560208616	82.3
P.A Food Sdn Bhd 2ATKT	INV-ES2420001275	ES2420001275	70.5

Plant Name	Inverter Name	Inverter SN	Temperature
Pengerang Independent Terminal	VASOLAR INV 3 CP 1	ES2340146417	73.4
Pengerang Independent Terminal	VASOLAR INV 4 CP 2	6T23A9016705	74.1
Pengerang Independent Terminal	VASOLAR INV7 MC	ES2340146422	84.8
Pengerang Independent Terminal	VASOLAR INV8 LCS304	ES2410011406	71.5
Pengerang Independent Terminal	VASOLAR INV9 LCS304	ES2410011693	70.1
QL ENDAU DEEP SEA FISHING	Inverter 2 (COM3-13)	6T2519005200	79.4
QL ENDAU DEEP SEA FISHING	Inverter 3 (COM3-14)	GR2479020699	76.0
QL ENDAU DEEP SEA FISHING	Inverter 4 (COM3-15)	GR2479020734	76.5
QL ENDAU DEEP SEA FISHING	Inverter 5 (COM3-16)	GR2479028681	78.3
QL ENDAU MARINE	TERA - INV 2	6T24C9071297	74.9
QL ENDAU MARINE	TERA - INV 4	GR2479026771	71.7
QL PAJAM PHASE 2	INV 5	6T2559006722	73.5
QI Lot 14	INV-ES24A0149129	ES24A0149129	72.4
QI Lot 16	INV-ES24A0149130	ES24A0149130	71.8
SCENT PUR MANUFACTURING SDN BHD NO.37	INV-NS245G038275	NS245G038275	79.3
SJK ■ C ■ PIN HWA 1	INVERTER-2	ES2560208642	74.2
SP Logistics Sdn Bhd	INV-6T23B9005457	6T23B9005457	75.6
Succesfuel Sdn. Bhd.	INVERTER 1 R1	6T24C9072224	75.9
TOMEI	INV-(16-1)	HV2330348376	72.6