

FusionSolar Troubleshooting Report

Date: 08-05-2026
Generated At: 08-05-2026 20:30:07
Prepared By: TERA SPMS

Executive Summary

Metric	Value
Total low-performing plants	44
Total low-performing inverters	0
Total alarms	58
Total high-temperature inverters	95

Low-performing Plants

Plant Name	Plant PSH	City Average PSH	Deviation
AMEBA MGMT	0.81	0.94	-13.68
AMT PC DISTRIBUTORS SDN. BHD.	0.59	0.70	-15.20
ASHITA COMMUNICATION	0.00	0.70	-100.00
BIMB Bdr Penawar - 1st Floor	0.00	1.26	-100.00
BJC FOOD (MALAYSIA) SDN. BHD.	0.54	0.87	-37.98
BOILERMECH LOT 873	0.00	0.48	-100.00
BP PLASTICS HQ	2.49	2.78	-10.54
C0149_VERTEX MISSION	0.80	0.92	-13.36
C0172_ATRIA SOUTH	0.00	0.78	-100.00
Dong Sing Food Link Sdn Bhd	0.00	1.65	-100.00
FUJI M1	0.46	0.58	-21.37
Hoon Yuen Furniture	0.61	0.70	-12.32

Plant Name	Plant PSH	City Average PSH	Deviation
IOI Mall Puchong (New Wing) Phase 2	0.81	0.94	-13.68
IOI Mayang Development	1.28	1.69	-24.46
Jaya Nets	0.79	0.92	-13.66
KISWIRE CORD PHASE 1 (DATA)	0.00	1.48	-100.00
KOSSAN PAINT SDN BHD	0.39	0.70	-43.94
Kwang Hua Persendirian meter 2-3-4-5-6	0.46	0.70	-33.88
LEAN GIAP ENTERPRISE SDN BHD	3.35	3.86	-13.14
LKW FROZEN SDN BHD	1.17	1.69	-30.95
Lau and Tan Pharmacy (1st Floor)	0.81	1.61	-49.85
Lian Teck Seng Lot 11	0.00	0.70	-100.00
MAJOR ENGINEERING Lot 8	0.43	0.70	-38.19
MARINE GOLD SDN BHD	0.00	0.89	-100.00
MENARA PKNS PJ	0.00	0.65	-100.00
MIAW FRESH	0.00	0.70	-100.00
Menara PJD	1.13	1.31	-13.52
Pleasure Latex Phase 2	0.00	0.36	-100.00
QL FARM SDN BHD	0.00	2.08	-100.00
QL FOODS	3.04	3.79	-19.86
REDANG LAGOON RESORT	0.00	2.71	-100.00
SABAH CHINESE HIGH SCHOOL (CANTEEN)	1.65	2.08	-20.67
SABAH CHINESE HIGH SCHOOL (CULTURE AND EDUCATION)	1.69	2.08	-18.75
SAWIPAC SDN BHD	1.69	1.90	-11.05
SWEE CHEONG WATCH SDN BHD (Meter 2)	3.51	4.06	-13.55
THOR SPECIALTIES	0.00	0.87	-100.00

Plant Name	Plant PSH	City Average PSH	Deviation
TIMURIKAN TRENGGANU MARINE PRODUCTS SDN BHD	0.59	1.43	-58.89
Teong Huat Medical	3.73	4.15	-10.05
UCS_Block A	1.42	1.69	-16.20
UCS_Block B	1.51	1.69	-10.89
UCS_Block C	1.49	1.69	-12.07
Vinda Phase 1 and 2 (MSB 2)	0.61	0.70	-12.32
WASCO PIPE SDN BHD (COATING)	1.03	1.34	-23.42
WEIDA MARKETING SDN. BHD.	1.92	2.24	-14.29

Low-performing Inverters

Plant Name	Inverter	SN	Inverter PSH	Highest PSH	Deviation	Reason
No low-performing inverters found	-	-	-	-	-	-

Active Alarms

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
BIMB Bdr Penawar - 1st Floor	Dongle- INV1	BT24C0060244	Network Connection Error	Major	15-04-2026 18:07
BJC FOOD (MALAYSIA) SDN. BHD.	60KTL-M0(COM1-3)	ES2180084797	Low Insulation Resistance	Major	08-05-2026 07:40
BOILERMECH LOT 873	Logger-102516002824	102516002824	Network Connection Error	Major	02-05-2026 00:57
C0172_ATRIA SOUTH	Logger-102256528212	102256528212	Network Connection Error	Major	08-05-2026 01:02
C0176_GETHA	Logger-102256528260	102256528260	Network Connection Error	Major	28-04-2026 21:09
Dong Sing Food Link Sdn Bhd	Inverter(COM2-1)	ES2570023845	Grid Loss	Major	08-05-2026 06:49
Fibertex Phase 2	Inverter 2 L3 Old	6T2379019735	Upgrade Failed or Version Mismatch	Minor	18-07-2025 15:24
IOI Mall Puchong (New Wing)	Inverter 14 - TERA	ES2470053866	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing)	Inverter 17 - TERA	6T2479017623	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
IOI Mall Puchong (New Wing)	Inverter 13 - TERA	6T2479017534	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing) Phase 2	Inverter 4	GR2569071069	Grid Loss	Major	16-04-2026 09:37
IOI Mall Puchong (New Wing) Phase 2	Inverter(COM1-1)	GR2569071128	Grid Loss	Major	10-04-2026 16:33
IOI Mall Puchong (Old Wing)	Inverter 21 R1-TERA	6T2599057796	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 3 R1 - TERA	BN2521059950	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 12 - TERA	BN2461066801	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 2 - TERA	BN2461066770	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 7 - TERA	6T2479017524	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 10 - TERA	6T2469039407	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 4 - TERA	6T2479017517	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 1 - TERA	BN2461065466	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 5 - TERA	BN2461066760	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 6 - TERA	BN2461066754	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 11 - TERA	BN2461066739	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 8 - TERA	BN2461065428	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 9 - TERA	6T2479017523	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
KILANG BATU BATA	Dongle-TA2510047367	TA2510047367	Network Connection Error	Major	02-05-2026 11:29
Kwang Hua Persendirian meter 2-3-4-5-6	Block C - Inverter 7 - Meter 2	6T21C9024903	Low Insulation Resistance	Major	08-05-2026 07:56
LIAN FOO POULTRY FARM SDN BHD	Dongle-BT2541519026	BT2541519026	Network Connection Error	Major	30-04-2026 18:40
LIAN FOO POULTRY FARM SDN BHD	INV-ES2550000030	ES2550000030	Grid Loss	Major	30-04-2026 17:55
LIAN FOO POULTRY FARM SDN BHD	INV-ES25C0125116	ES25C0125116	Grid Loss	Major	30-04-2026 17:54
LIAN FOO POULTRY FARM SDN BHD	INV-ES25C0125117	ES25C0125117	Grid Loss	Major	30-04-2026 17:54

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
Lian Teck Seng Lot 11	Dongle-BT24C0060275	BT24C0060275	Network Connection Error	Major	29-01-2026 15:54
MARINE GOLD SDN BHD	Dongle-TA2340293153	TA2340293153	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-TA2340293476	TA2340293476	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-TA2340291437	TA2340291437	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-HV2310776105	HV2310776105	Network Connection Error	Major	26-03-2026 14:56
MARINE GOLD SDN BHD	Dongle-HV2310776109	HV2310776109	Network Connection Error	Major	26-03-2026 14:55
MARINE GOLD SDN BHD	Dongle-HV2310773587	HV2310773587	Network Connection Error	Major	26-03-2026 14:54
MAIAW FRESH	VASOLAR INV 1	NS2331625509	Grid Loss	Major	07-05-2026 12:49
Pengerang Independent Terminal	Dongle-LAB	TA23B0087782	Network Connection Error	Major	20-04-2026 13:52
Pleasure Latex Phase 2	Logger-102347282208	102347282208	Network Connection Error	Major	19-02-2026 03:00
QL AGROVENTURE	ES2190052996	ES2190052996	Grid Loss	Major	07-05-2026 09:05
QL AGROVENTURE	6T21A9013577	6T21A9013577	Grid Loss	Major	07-05-2026 09:05
QL AGROVENTURE	ES2170034957	ES2170034957	Grid Loss	Major	07-05-2026 09:05
QL AGROVENTURE	ES2170034958	ES2170034958	Grid Loss	Major	07-05-2026 09:05
QL FARM SDN BHD	Logger-102466853213	102466853213	Network Connection Error	Major	24-04-2026 10:56
QL FARM SDN BHD	Inverter 1	ES2580051653	Grid Loss	Major	24-04-2026 10:07
QL FARM SDN BHD	Inverter 2	ES2580051643	Grid Loss	Major	24-04-2026 10:07
QL FARM SDN BHD	Inverter3	ES2490076207	Grid Loss	Major	24-04-2026 10:07
REDANG LAGOON RESORT	Dongle-2102312EHS10N9115979	2102312EHS10N9115979	Network Connection Error	Major	30-01-2026 19:29
REDANG LAGOON RESORT	INV-ES22A0089681	ES22A0089681	Grid Loss	Major	30-01-2026 07:23
SIME KANSAI PAINT SDN BHD	INV-ES2550146111	ES2550146111	Upgrade Failed or Version Mismatch	Minor	19-11-2025 21:35
THOR SPECIALTIES	Dongle-BT2541519069	BT2541519069	Network Connection Error	Major	07-05-2026 14:48
THP MEDICAL	VASOLAR INV 3	6T2279009018	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
THP MEDICAL	VASOLAR INV 2	6T2279008977	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
THP MEDICAL	VASOLAR INV 1	6T2279009011	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
Telewiring	VASOLAR_INV_1	HV2330869769	Grid Loss	Major	04-05-2026 08:17
VINDA PHASE 4 (MSB 3-2)	MASTER LOG HT P4	102595350697	Southbound Device Communication Abnormal	Minor	29-04-2026 15:30

High-temperature Inverters

Plant Name	Inverter Name	Inverter SN	Temperature
AFI BRAKE MANUFACTURING SDN BHD	INV 4 - GROUND FLOOR	HV22B0337098	76.0
AFI BRAKE MANUFACTURING SDN BHD	INV 5 - FIRST FLOOR	HV22B0337097	79.8
AFI BRAKE MANUFACTURING SDN BHD	INV 6 - SECOND FLOOR	HV22A0405534	77.7
AFI BRAKE MANUFACTURING SDN BHD	INV 7 - THIRD FLOOR	HV22B0337096	76.3
AMEBA MGMT	INV-HV2290878023	HV2290878023	70.3
AMT PC DISTRIBUTORS SDN. BHD.	INV-6T22B9024620	6T22B9024620	75.2
ASIA WIRE STEEL MESH MANUFACTURERS SDN BHD	Inverter(COM3-12)	ES2550064320	75.8
ASIA WIRE STEEL MESH MANUFACTURERS SDN BHD	Inverter(COM3-13)	ES2550064305	76.7
ASIA WIRE STEEL MESH MANUFACTURERS SDN BHD	Inverter(COM3-14)	ES2550064253	72.4
ASIA WIRE STEEL MESH MANUFACTURERS SDN BHD	Inverter(COM3-15)	ES2550064258	79.6
ATS AIR SOLUTION	INV-HV22A0242778	HV22A0242778	72.8
C0102_QL batang kali	150K-MG0(COM3-2)	GR2479026710	74.5
C0149_VERTEX MISSION	HV21B0210137	HV21B0210137	75.3
C0172_ATRIA SOUTH	Inverter 4(COM2-1)	HV22A0105615	74.9
C150_VERTEX MISSION	Inverter-1	6T2159040800	70.2
CHAN KAH WHYIE	INV-NS249G082061	NS249G082061	89.1
CIC CONTRACT SDN BHD	INV-HV22A0242777	HV22A0242777	70.0
Durasafe Sdn. Bhd.	INV 1-6T2479002464	6T2479002464	81.8

Plant Name	Inverter Name	Inverter SN	Temperature
Durasafe Sdn. Bhd.	INV 2-6T2469038783	6T2469038783	74.1
Farm Fresh Taiping (Factory)	50KTL-M3(COM1-12)	6T22A9038815	71.7
Fibertex Phase 2	Inverter 1 L3	6T23A9016283	72.1
Fibertex Phase 2	Inverter 8 L3	6T2379019736	72.3
Fibertex Phase 2	Inverter 9 L3	6T2379019637	70.8
Fibertex Phase 2	Roof 2C Bridge R1	6T2469046697	72.2
Fungiculture	Inverter 1 (M3)	ES22B0022997	72.8
Fungiculture	Inverter 1 (M4)	ES22B0007042	77.1
Fungiculture	Inverter 2 (M3)	HV22B0337400	80.1
Fungiculture	Inverter 2 (M4)	HV22B0004571	76.7
Fungiculture	Inveter 2 (M1)	HV22B0337398	78.1
GLASS PLASTIC PACKAGING	INV 2 - (No.23)	6T2489010546	70.0
IOI City Mall Inc. Feeder 1	Inverter 2.6 - TERA	6T22C9011480	71.4
IOI Mall Puchong (New Wing)	Inverter 15 - TERA	ES2330107601	72.2
IOI Mall Puchong (New Wing)	Inverter 16 - TERA	6T2449030262	76.3
IOI Mall Puchong (New Wing) Phase 2	Inverter 7	GR2569071081	70.6
IOI Mall Puchong (New Wing) Phase 2	Inverter 9	GR2569094300	71.5
IOI Mall Puchong (Old Wing)	Inverter 20 - TERA	6T24C9047414	70.9
Jiann Lih safety product	40KTL-M3(COM1-15)	ES2290059762	84.3
Jiann Lih safety product	40KTL-M3(COM1-16)	ES2290059727	86.5
KB AIS SDN. BHD.	Inverter-1	6T21C9025324	70.6
KUASA BAKTI (PETRON SETIA ALAM)	INV-6T2489035314	6T2489035314	74.5
Kamma Klang Enterprise	Inverter 1	ES22A0088766	76.1
Kamma Klang Enterprise	Inverter 2	HV22A0153968	77.8

Plant Name	Inverter Name	Inverter SN	Temperature
Kiara Bay	Inverter 2 - TERA	ES2330110574	71.7
Kiara Bay	Inverter 3 - TERA	6T2449022934	77.5
Kiara Bay	Inverter 4 - TERA	6T2449023252	72.4
Kiara Bay	Inverter 6 - TERA	ES2350101155	76.6
Kiara Bay	Inverter 9 - TERA	ES2350101147	72.6
Komplex PKNS Bangi	40KTL-M3(COM1-13)	ES22A0040484	78.5
Kwang Hua Persendirian meter 2-3-4-5-6	Block B2-Inverter 6 - Meter 6	6T21C9025214	73.7
LAM SOON EDIBLE OILS	INV-2	6T2449022953	72.4
Marbach Asia Pacific Lot17	INV-6T2489012207	6T2489012207	83.2
Marbach Asia Pacific lot 15	INV-6T2489012205	6T2489012205	79.4
Menara PJD	Inverter 50ktl(COM1-12)	6T22A9046122	72.9
Mitsui Copper Foil P3	Inverter 1 (AREA A)	GR2459039442	72.0
Mitsui Copper Foil P3	Inverter 2 (AREA A)	GR2459039444	73.9
Mitsui Copper Foil P3	Inverter 3 (AREA A)	6T24A9009773	79.5
Mitsui Copper Foil P3	Inverter 4 (AREA A)	6T24A9013004	81.1
Mitsui Copper Foil P3	Inverter 5 (AREA B)	6T2519017589	74.5
Multi Choice (M) Sdn Bhd	TERA INV 1	GR2489029065	74.6
Multi Choice (M) Sdn Bhd	TERA INV 2	GR2489029048	75.5
Multi Choice (M) Sdn Bhd	TERA INV 3	ES2560208616	82.9
New Age 160	INV 1	6T2469012777	74.2
New Age 160	Inverter 2 R1	6T23B9005979	80.1
New Age 160	Inverter 3-36ktl m3	6T2489036764	76.5
P.A Food Sdn Bhd 2ATKT	INV-ES2420001275	ES2420001275	78.3
PKT 8 WAVES	Inverter_2	6T2439012020	71.4

Plant Name	Inverter Name	Inverter SN	Temperature
PKT THE SHIP	Inverter_8 R1	ES24C0173071	72.3
Pengerang Independent Terminal	VASOLAR INV 3 CP 1	ES2340146417	71.5
Pengerang Independent Terminal	VASOLAR INV 4 CP 2	6T23A9016705	72.5
Pengerang Independent Terminal	VASOLAR INV7 MC	ES2340146422	73.9
QL FOODS	INVERTER_10	6T2449032177	76.0
QL FOODS	INVERTER_7	6T22A9046723	71.2
RS POLY INDUSTRY	VASOLAR INV 1	ES2420000999	71.9
RS POLY INDUSTRY	VASOLAR INV 2	ES2420001084	70.6
SABAH CHINESE HIGH SCHOOL (TAK YUEN BUILDING)	50KTL-M3(COM1-2)	ES22A0076308	85.6
SCENT PUR MANUFACTURING SDN BHD NO.35	INV-TA2470078151	TA2470078151	71.7
SCENT PUR MANUFACTURING SDN BHD NO.37	INV-NS245G038275	NS245G038275	80.1
SJK (C) WU TECK	INV 1	6T25B9000135	74.8
SJK ■ C ■ PIN HWA 1	INVERTER-2	ES2560208642	74.1
SM Chung Chung Hua (PSDN) Klang	60KTL-M0(COM1-4)	ES2190080965	72.7
SP Logistics Sdn Bhd	INV-6T23B9005457	6T23B9005457	79.4
SWH INDUSTRIES (PLOT6311)	INVERTER 2	6T2499021680	70.4
Succesfuel Sdn. Bhd.	INVERTER 1 R1	6T24C9072224	73.7
TOMEI	INV-(12-1)	HV2330348462	82.0
TOMEI	INV-(16-1)	HV2330348376	83.5
TOMEI	INV-(4-1)	HV2330348450	78.9
TOMEI	INV-(4-2)	HV2330348386	78.4
TOMEI	INV-(4-3)	HV2330348461	74.8
TOMEI	INV-(6-1)	HV2330348465	77.2
TOMEI	INV-(8)	HV2330348453	78.0

Plant Name	Inverter Name	Inverter SN	Temperature
TOMEI	INV-(8-2)	HV2330348466	76.9
TOMEI	INV-(8-3)	HV2330348451	76.5
VISKO INDUSTRIES SDN BHD	VASOLAR_INV_8	ES2180084993	70.7
Vinda Phase 1 and 2 (MSB 2)	Inverter 7 - Phase 1	6T21C9025215	73.2
WCS UNIT 6	INVERTER UNIT 6	HV2290931617	73.5