

FusionSolar Troubleshooting Report

Date: 09-05-2026
Generated At: 09-05-2026 20:30:08
Prepared By: TERA SPMS

Executive Summary

Metric	Value
Total low-performing plants	2
Total low-performing inverters	0
Total alarms	55
Total high-temperature inverters	80

Low-performing Plants

Plant Name	Plant PSH	City Average PSH	Deviation
MAJOR ENGINEERING Lot 10	2.51	3.20	-21.66
MAJOR ENGINEERING Lot 8	0.94	3.20	-70.66

Low-performing Inverters

Plant Name	Inverter	SN	Inverter PSH	Highest PSH	Deviation	Reason
No low-performing inverters found	-	-	-	-	-	-

Active Alarms

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
AMEBA MGMT	Dongle-HV2350290717	HV2350290717	Network Connection Error	Major	09-05-2026 10:28
BIMB Bdr Penawar - 1st Floor	Dongle- INV1	BT24C0060244	Network Connection Error	Major	15-04-2026 18:07
BOILERMECH LOT 873	Logger-102516002824	102516002824	Network Connection Error	Major	02-05-2026 00:57

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
BRC INDUSTRIES	Dongle-TA2340258607	TA2340258607	Network Connection Error	Major	09-05-2026 03:47
C0172_ATRIA SOUTH	Logger-102256528212	102256528212	Network Connection Error	Major	08-05-2026 01:02
C0176_GETHA	Logger-102256528260	102256528260	Network Connection Error	Major	28-04-2026 21:09
Dong Sing Food Link Sdn Bhd	Inverter(COM2-1)	ES2570023845	Grid Loss	Major	09-05-2026 06:52
Fibertex Phase 2	Inverter 2 L3 Old	6T2379019735	Upgrade Failed or Version Mismatch	Minor	18-07-2025 15:24
IOI Mall Puchong (New Wing)	Inverter 14 - TERA	ES2470053866	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing)	Inverter 17 - TERA	6T2479017623	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing)	Inverter 13 - TERA	6T2479017534	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing) Phase 2	Inverter(COM1-1)	GR2569071128	Grid Loss	Major	08-05-2026 16:11
IOI Mall Puchong (New Wing) Phase 2	Inverter 4	GR2569071069	Grid Loss	Major	16-04-2026 09:37
IOI Mall Puchong (Old Wing)	Inverter 21 R1-TERA	6T2599057796	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 3 R1 - TERA	BN2521059950	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 12 - TERA	BN2461066801	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 2 - TERA	BN2461066770	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 7 - TERA	6T2479017524	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 10 - TERA	6T2469039407	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 4 - TERA	6T2479017517	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 1 - TERA	BN2461065466	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 5 - TERA	BN2461066760	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 6 - TERA	BN2461066754	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 8 - TERA	BN2461065428	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 11 - TERA	BN2461066739	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 9 - TERA	6T2479017523	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
KILANG BATU BATA	Dongle-TA2510047367	TA2510047367	Network Connection Error	Major	09-05-2026 09:26

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
LIAN FOO POULTRY FARM SDN BHD	Dongle-BT2541519026	BT2541519026	Network Connection Error	Major	30-04-2026 18:40
LIAN FOO POULTRY FARM SDN BHD	INV-ES2550000030	ES2550000030	Grid Loss	Major	30-04-2026 17:55
LIAN FOO POULTRY FARM SDN BHD	INV-ES25C0125116	ES25C0125116	Grid Loss	Major	30-04-2026 17:54
LIAN FOO POULTRY FARM SDN BHD	INV-ES25C0125117	ES25C0125117	Grid Loss	Major	30-04-2026 17:54
Lian Teck Seng Lot 11	Dongle-BT24C0060275	BT24C0060275	Network Connection Error	Major	29-01-2026 15:54
MARINE GOLD SDN BHD	Dongle-TA2340293153	TA2340293153	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-TA2340293476	TA2340293476	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-TA2340291437	TA2340291437	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-HV2310776105	HV2310776105	Network Connection Error	Major	26-03-2026 14:56
MARINE GOLD SDN BHD	Dongle-HV2310776109	HV2310776109	Network Connection Error	Major	26-03-2026 14:55
MARINE GOLD SDN BHD	Dongle-HV2310773587	HV2310773587	Network Connection Error	Major	26-03-2026 14:54
MIAW FRESH	VASOLAR INV 1	NS2331625509	Grid Loss	Major	07-05-2026 12:49
Pengerang Independent Terminal	Dongle-LAB	TA23B0087782	Network Connection Error	Major	20-04-2026 13:52
Pleasure Latex Phase 2	Logger-102347282208	102347282208	Network Connection Error	Major	19-02-2026 03:00
QL AGROVENTURE	ES2170034957	ES2170034957	Abnormal Residual Current	Major	09-05-2026 10:26
QL FARM SDN BHD	Logger-102466853213	102466853213	Network Connection Error	Major	24-04-2026 10:56
QL FARM SDN BHD	Inverter 2	ES2580051643	Grid Loss	Major	24-04-2026 10:07
QL FARM SDN BHD	Inverter 1	ES2580051653	Grid Loss	Major	24-04-2026 10:07
QL FARM SDN BHD	Inverter3	ES2490076207	Grid Loss	Major	24-04-2026 10:07
REDANG LAGOON RESORT	Dongle-2102312EHS10N9115979	2102312EHS10N9115979	Network Connection Error	Major	30-01-2026 19:29
REDANG LAGOON RESORT	INV-ES22A0089681	ES22A0089681	Grid Loss	Major	30-01-2026 07:23
SIME KANSAI PAINT SDN BHD	INV-ES2550146111	ES2550146111	Upgrade Failed or Version Mismatch	Minor	19-11-2025 21:35

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
THOR SPECIALTIES	Dongle-BT2541519069	BT2541519069	Network Connection Error	Major	07-05-2026 14:48
THP MEDICAL	VASOLAR INV 3	6T2279009018	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
THP MEDICAL	VASOLAR INV 2	6T2279008977	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
THP MEDICAL	VASOLAR INV 1	6T2279009011	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
Telewiring	VASOLAR_INV_1	HV2330869769	Grid Loss	Major	04-05-2026 08:17
VINDA PHASE 4 (MSB 3-2)	MASTER LOG HT P4	102595350697	Southbound Device Communication Abnormal	Minor	29-04-2026 15:30

High-temperature Inverters

Plant Name	Inverter Name	Inverter SN	Temperature
AFI BRAKE MANUFACTURING SDN BHD	INV 4 - GROUND FLOOR	HV22B0337098	81.3
AFI BRAKE MANUFACTURING SDN BHD	INV 5 - FIRST FLOOR	HV22B0337097	83.9
AFI BRAKE MANUFACTURING SDN BHD	INV 6 - SECOND FLOOR	HV22A0405534	83.0
AFI BRAKE MANUFACTURING SDN BHD	INV 7 - THIRD FLOOR	HV22B0337096	76.6
AMT PC DISTRIBUTORS SDN. BHD.	INV-6T22B9024620	6T22B9024620	76.8
ASIA WIRE STEEL MESH MANUFACTURERS SDN BHD	Inverter(COM3-12)	ES2550064320	72.1
ASIA WIRE STEEL MESH MANUFACTURERS SDN BHD	Inverter(COM3-13)	ES2550064305	70.8
ASIA WIRE STEEL MESH MANUFACTURERS SDN BHD	Inverter(COM3-14)	ES2550064253	73.4
ASIA WIRE STEEL MESH MANUFACTURERS SDN BHD	Inverter(COM3-15)	ES2550064258	73.6
C0102_QL batang kali	150K-MG0(COM3-2)	GR2479026710	76.4
C0102_QL batang kali	150K-MG0(COM3-3)	GR2479026770	74.5
C0149_VERTEX MISSION	HV21B0210137	HV21B0210137	76.4
CHAN KAH WHYIE	INV-NS249G082061	NS249G082061	75.8
Durasafe Sdn. Bhd.	INV 1-6T2479002464	6T2479002464	71.8
FDP AND MTB INDUSTRIES SDN BHD	TERA FDP INV 1	6T2569054829	75.2

Plant Name	Inverter Name	Inverter SN	Temperature
FDP AND MTB INDUSTRIES SDN BHD	TERA FDP INV 2	ES2580087345	84.4
FDP AND MTB INDUSTRIES SDN BHD	TERA MTB INV 3	6T2569054834	72.9
FDP AND MTB INDUSTRIES SDN BHD	TERA MTB INV 4	ES2580087312	83.5
FOX ONE LOT 8	TERA INVERTER 2	6T25B9000067	73.2
Fibertex Phase 2	Inv. CarPark Roof A	ES2420001055	72.2
Fibertex Phase 2	Inverter 1 L3	6T23A9016283	77.1
Fibertex Phase 2	Inverter 4 L3	6T2379019613	72.0
Fibertex Phase 2	Inverter 8 L3	6T2379019736	71.3
Fibertex Phase 2	Inverter 9 L3	6T2379019637	71.3
Fibertex Phase 2	Roof 2C Bridge R1	6T2469046697	75.6
Fungiculture	Inverter 1 (M4)	ES22B0007042	76.4
Fungiculture	Inverter 2 (M3)	HV22B0337400	82.6
Fungiculture	Inverter 2 (M4)	HV22B0004571	77.4
Fungiculture	Inveter 2 (M1)	HV22B0337398	79.8
GLASS PLASTIC PACKAGING	INV 2 - (No.23)	6T2489010546	80.6
GLASS PLASTIC PACKAGING	INV 3 - (Lot 65999)	6T2489010635	75.1
GLASS PLASTIC PACKAGING	INV 4 - (Lot 65999)	6T2489010593	78.1
IOI Mall Puchong (New Wing)	Inverter 16 - TERA	6T2449030262	72.1
Jiann Lih safety product	40KTL-M3(COM1-15)	ES2290059762	75.1
Jiann Lih safety product	40KTL-M3(COM1-16)	ES2290059727	76.6
KUASA BAKTI (PETRON SETIA ALAM)	INV-6T2489035314	6T2489035314	75.7
Kamma Klang Enterprise	Inverter 1	ES22A0088766	75.5
Kamma Klang Enterprise	Inverter 2	HV22A0153968	81.3
Kiara Bay	Inverter 3 - TERA	6T2449022934	73.6

Plant Name	Inverter Name	Inverter SN	Temperature
Kiara Bay	Inverter 4 - TERA	6T2449023252	71.9
Komplex PKNS Bangi	40KTL-M3(COM1-13)	ES22A0040484	77.9
Komplex PKNS Bangi	50KTL-M3(COM1-14)	6T22A9024868	72.0
Marbach Asia Pacific Lot17	INV-6T2489012207	6T2489012207	72.4
Marbach Asia Pacific lot 15	INV-6T2489012205	6T2489012205	70.9
Mitsui Copper Foil P3	Inverter 3 (AREA A)	6T24A9009773	73.7
Mitsui Copper Foil P3	Inverter 4 (AREA A)	6T24A9013004	76.3
Multi Choice (M) Sdn Bhd	TERA INV 3	ES2560208616	71.0
New Age 160	INV 1	6T2469012777	73.1
New Age 160	Inverter 2 R1	6T23B9005979	76.6
New Age 160	Inverter 3-36ktl m3	6T2489036764	74.9
P.A Food Sdn Bhd 2ATKT	INV-ES2420001275	ES2420001275	80.7
P.A Food Sdn Bhd Lot 10	INV-6T2449029469	6T2449029469	80.8
P.A Food Sdn Bhd Lot 12	INV-6T2449029471	6T2449029471	82.7
P.A. Food Warehouse No. 9	INV-HV2290797189	HV2290797189	75.1
PKT 8 WAVES	Inverter_2	6T2439012020	70.2
QL FOODS	INVERTER_10	6T2449032177	74.8
QL FOODS	INVERTER_7	6T22A9046723	72.8
QL FOODS	TERA INV2_HOSTEL	6T2599013072	72.3
QL PAJAM PHASE 2	INV 5	6T2559006722	78.8
QI Lot 14	INV-ES24A0149129	ES24A0149129	72.2
QI Lot 16	INV-ES24A0149130	ES24A0149130	70.6
SCENT PUR MANUFACTURING SDN BHD NO.35	INV-TA2470078151	TA2470078151	71.4
SCENT PUR MANUFACTURING SDN BHD NO.37	INV-NS245G038275	NS245G038275	80.3

Plant Name	Inverter Name	Inverter SN	Temperature
SP Logistics Sdn Bhd	INV-6T23B9005457	6T23B9005457	78.5
San Soon Seng Food Industries Sdn Bhd	Inv 02 (Racking WH)	6T2549057201	78.5
San Soon Seng Food Industries Sdn Bhd	Inv 04 (GP 2B)	ES24A0060037	71.3
San Soon Seng Food Industries Sdn Bhd	Inv 06 (GP 2)	ES2480078460	71.5
San Soon Seng Food Industries Sdn Bhd	Inv 09 (GP 2-Soya1)	ES2480078899	71.6
Succesfuel Sdn. Bhd.	INVERTER 1 R1	6T24C9072224	81.6
TOMEI	INV-(12-1)	HV2330348462	80.7
TOMEI	INV-(16-1)	HV2330348376	81.8
TOMEI	INV-(4-1)	HV2330348450	77.9
TOMEI	INV-(4-2)	HV2330348386	78.6
TOMEI	INV-(4-3)	HV2330348461	74.2
TOMEI	INV-(6-1)	HV2330348465	75.6
TOMEI	INV-(8)	HV2330348453	77.2
TOMEI	INV-(8-2)	HV2330348466	76.2
TOMEI	INV-(8-3)	HV2330348451	76.6
Vinda Phase 1 and 2 (MSB 2)	Inverter 7 - Phase 1	6T21C9025215	71.3
WCS UNIT 6	INVERTER UNIT 6	HV2290931617	73.7