

FusionSolar Troubleshooting Report

Date: 10-05-2026
Generated At: 10-05-2026 20:30:08
Prepared By: TERA SPMS

Executive Summary

Metric	Value
Total low-performing plants	2
Total low-performing inverters	0
Total alarms	63
Total high-temperature inverters	75

Low-performing Plants

Plant Name	Plant PSH	City Average PSH	Deviation
MAJOR ENGINEERING Lot 10	1.80	2.81	-35.99
MAJOR ENGINEERING Lot 8	0.69	2.81	-75.46

Low-performing Inverters

Plant Name	Inverter	SN	Inverter PSH	Highest PSH	Deviation	Reason
No low-performing inverters found	-	-	-	-	-	-

Active Alarms

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
BIMB Bdr Penawar - 1st Floor	Dongle- INV1	BT24C0060244	Network Connection Error	Major	15-04-2026 18:07
BOILERMECH LOT 873	Logger-102516002824	102516002824	Network Connection Error	Major	02-05-2026 00:57
BRC INDUSTRIES	Dongle-TA2340258607	TA2340258607	Network Connection Error	Major	09-05-2026 03:47

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
C0172_ATRIA SOUTH	Logger-102256528212	102256528212	Network Connection Error	Major	08-05-2026 01:02
C0176_GETHA	Logger-102256528260	102256528260	Network Connection Error	Major	28-04-2026 21:09
Dong Sing Food Link Sdn Bhd	Inverter(COM2-1)	ES2570023845	Grid Loss	Major	10-05-2026 06:50
Fibertex Phase 2	Inverter 2 L3 Old	6T2379019735	Upgrade Failed or Version Mismatch	Minor	18-07-2025 15:24
GLASS PLASTIC PACKAGING	Dongle - (No.23A)	TA24C0271931	Network Connection Error	Major	10-05-2026 07:24
GLASS PLASTIC PACKAGING	Dongle - (No.23)	TA24C0272100	Network Connection Error	Major	10-05-2026 07:22
GLASS PLASTIC PACKAGING	Dongle - (No.6)	TA24C0272130	Network Connection Error	Major	10-05-2026 07:22
IOI Mall Puchong (New Wing)	Inverter 14 - TERA	ES2470053866	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing)	Inverter 17 - TERA	6T2479017623	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing)	Inverter 13 - TERA	6T2479017534	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing) Phase 2	Logger-102516002835	102516002835	Network Connection Error	Major	10-05-2026 01:18
IOI Mall Puchong (New Wing) Phase 2	Inverter(COM1-1)	GR2569071128	Grid Loss	Major	08-05-2026 16:11
IOI Mall Puchong (New Wing) Phase 2	Inverter 4	GR2569071069	Grid Loss	Major	16-04-2026 09:37
IOI Mall Puchong (Old Wing)	Inverter 21 R1-TERA	6T2599057796	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 3 R1 - TERA	BN2521059950	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 12 - TERA	BN2461066801	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 2 - TERA	BN2461066770	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 7 - TERA	6T2479017524	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 10 - TERA	6T2469039407	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 4 - TERA	6T2479017517	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 1 - TERA	BN2461065466	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 5 - TERA	BN2461066760	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 6 - TERA	BN2461066754	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 8 - TERA	BN2461065428	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
IOI Mall Puchong (Old Wing)	Inverter 11 - TERA	BN2461066739	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 9 - TERA	6T2479017523	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
KILANG BATU BATA	Dongle-TA2510047367	TA2510047367	Network Connection Error	Major	09-05-2026 09:26
LIAN FOO POULTRY FARM SDN BHD	Dongle-BT2541519026	BT2541519026	Network Connection Error	Major	30-04-2026 18:40
LIAN FOO POULTRY FARM SDN BHD	INV-ES2550000030	ES2550000030	Grid Loss	Major	30-04-2026 17:55
LIAN FOO POULTRY FARM SDN BHD	INV-ES25C0125116	ES25C0125116	Grid Loss	Major	30-04-2026 17:54
LIAN FOO POULTRY FARM SDN BHD	INV-ES25C0125117	ES25C0125117	Grid Loss	Major	30-04-2026 17:54
Lian Teck Seng Lot 11	Dongle-BT24C0060275	BT24C0060275	Network Connection Error	Major	29-01-2026 15:54
MARINE GOLD SDN BHD	Dongle-TA2340293153	TA2340293153	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-TA2340293476	TA2340293476	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-TA2340291437	TA2340291437	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-HV2310776105	HV2310776105	Network Connection Error	Major	26-03-2026 14:56
MARINE GOLD SDN BHD	Dongle-HV2310776109	HV2310776109	Network Connection Error	Major	26-03-2026 14:55
MARINE GOLD SDN BHD	Dongle-HV2310773587	HV2310773587	Network Connection Error	Major	26-03-2026 14:54
MENARA PKNS PJ	Logger-102466288020	102466288020	Network Connection Error	Major	10-05-2026 01:00
MIAW FRESH	VASOLAR INV 1	NS2331625509	Grid Loss	Major	07-05-2026 12:49
Pengerang Independent Terminal	Dongle-LAB	TA23B0087782	Network Connection Error	Major	20-04-2026 13:52
Pleasure Latex Phase 2	Logger-102347282208	102347282208	Network Connection Error	Major	19-02-2026 03:00
QL FARM SDN BHD	Logger-102466853213	102466853213	Network Connection Error	Major	24-04-2026 10:56
QL FARM SDN BHD	Inverter 2	ES2580051643	Grid Loss	Major	24-04-2026 10:07
QL FARM SDN BHD	Inverter 1	ES2580051653	Grid Loss	Major	24-04-2026 10:07
QL FARM SDN BHD	Inverter3	ES2490076207	Grid Loss	Major	24-04-2026 10:07

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
REDANG LAGOON RESORT	Dongle-2102312EHS10N9115979	2102312EHS10N9115979	Network Connection Error	Major	30-01-2026 19:29
REDANG LAGOON RESORT	INV-ES22A0089681	ES22A0089681	Grid Loss	Major	30-01-2026 07:23
SIME KANSAI PAINT SDN BHD	INV-ES2550146111	ES2550146111	Upgrade Failed or Version Mismatch	Minor	19-11-2025 21:35
SWH INDUSTRIES (PLOT 132113)	Dongle-BT2590184507	BT2590184507	Network Connection Error	Major	09-05-2026 18:41
THOR SPECIALTIES	Dongle-BT2541519069	BT2541519069	Network Connection Error	Major	07-05-2026 14:48
THP MEDICAL	VASOLAR INV 3	6T2279009018	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
THP MEDICAL	VASOLAR INV 2	6T2279008977	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
THP MEDICAL	VASOLAR INV 1	6T2279009011	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
TS United Metal	Dongle-TA2340289794	TA2340289794	Network Connection Error	Major	10-05-2026 04:08
Telewiring	VASOLAR_INV_1	HV2330869769	Grid Loss	Major	04-05-2026 08:17
VINDA PHASE 4 (MSB 3-2)	Inverter13 Phase4 R1	ES2580050563	Grid Loss	Major	09-05-2026 15:53
VINDA PHASE 4 (MSB 3-2)	Inverter13 Phase4 R1	ES2580050563	AC Overcurrent	Major	09-05-2026 12:24
VINDA PHASE 4 (MSB 3-2)	Inverter13 Phase4 R1	ES2580050563	The PV string is short-circuited to the ground.	Major	09-05-2026 12:24
VINDA PHASE 4 (MSB 3-2)	MASTER LOG HT P4	102595350697	Southbound Device Communication Abnormal	Minor	29-04-2026 15:30

High-temperature Inverters

Plant Name	Inverter Name	Inverter SN	Temperature
AFI BRAKE MANUFACTURING SDN BHD	INV 7 - THIRD FLOOR	HV22B0337096	70.1
AMT PC DISTRIBUTORS SDN. BHD.	INV-6T22B9024620	6T22B9024620	76.0
BP PLASTICS BP9	INVERTER 5 (AREA C)	6T24A9018015	73.5
BP PLASTICS HQ	Inverter_11	6T2499023013	72.3
BP PLASTICS HQ	Inverter_2	ES2440060550	77.8
BP PLASTICS HQ	Inverter_3	6T2489015626	71.5

Plant Name	Inverter Name	Inverter SN	Temperature
BP PLASTICS HQ	Inverter_6	6T2499021622	74.2
BP PLASTICS HQ	Inverter_8	6T2499021624	73.5
BREMFIELD SDN BHD	INV 1	ES2320221246	72.4
BUNCHO (M) SDN BHD	INV-6T2519005159	6T2519005159	70.1
C0102_QL batang kali	150K-MG0(COM3-2)	GR2479026710	70.4
C0149_VERTEX MISSION	HV21B0210137	HV21B0210137	73.9
CHAN KAH WHYE	INV-NS249G082061	NS249G082061	90.1
CIC CONTRACT SDN BHD	INV-HV22A0242777	HV22A0242777	71.7
FOX ONE LOT 8	TERA INVERTER 2	6T25B9000067	75.0
Fibertex Phase 2	Inv. CarPark Roof A	ES2420001055	71.0
Fungiculture	Inverter 1 (M1)	ES22B0022924	71.5
Fungiculture	Inverter 1 (M4)	ES22B0007042	73.2
Fungiculture	Inverter 2 (M3)	HV22B0337400	75.9
Fungiculture	Inveter 2 (M1)	HV22B0337398	75.6
IOI Mall Puchong (New Wing)	Inverter 16 - TERA	6T2449030262	72.4
IOI Mall Puchong (Old Wing)	Inverter 20 - TERA	6T24C9047414	70.8
Jiann Lih safety product	40KTL-M3(COM1-15)	ES2290059762	80.9
Jiann Lih safety product	40KTL-M3(COM1-16)	ES2290059727	82.5
KISWIRE CORD SDN BHD	VASOLAR_INV_10	6T2269040723	71.4
KISWIRE CORD SDN BHD	VASOLAR_INV_12	HV22A0243263	73.4
Kamma Klang Enterprise	Inverter 2	HV22A0153968	76.9
Kiara Bay	Inverter 3 - TERA	6T2449022934	70.8
Komplex PKNS Bangi	40KTL-M3(COM1-13)	ES22A0040484	77.4
Kwang Hua Persendirian meter 2-3-4-5-6	Block B2-Inverter 6 - Meter 6	6T21C9025214	71.2

Plant Name	Inverter Name	Inverter SN	Temperature
LAM SOON EDIBLE OILS	INV-2	6T2449022953	76.6
Marbach Asia Pacific Lot17	INV-6T2489012207	6T2489012207	75.7
Marbach Asia Pacific lot 15	INV-6T2489012205	6T2489012205	75.5
Mitsui Copper Foil P3	Inverter 2 (AREA A)	GR2459039444	71.4
Mitsui Copper Foil P3	Inverter 3 (AREA A)	6T24A9009773	77.5
Mitsui Copper Foil P3	Inverter 4 (AREA A)	6T24A9013004	79.6
Mitsui Copper Foil P3	Inverter 5 (AREA B)	6T2519017589	72.3
P.A Food Sdn Bhd 2ATKT	INV-ES2420001275	ES2420001275	81.3
P.A Food Sdn Bhd Lot 10	INV-6T2449029469	6T2449029469	77.6
P.A Food Sdn Bhd Lot 12	INV-6T2449029471	6T2449029471	78.7
P.A. Food Warehouse No. 9	INV-HV2290797189	HV2290797189	72.6
Pengerang Independent Terminal	VASOLAR INV 2 CP 1	ES2330104289	70.9
Pengerang Independent Terminal	VASOLAR INV 3 CP 1	ES2340146417	73.7
Pengerang Independent Terminal	VASOLAR INV 4 CP 2	6T23A9016705	74.7
Pengerang Independent Terminal	VASOLAR INV7 MC	ES2340146422	80.9
Pengerang Independent Terminal	VASOLAR INV8 LCS304	ES2410011406	70.0
QL ENDAU DEEP SEA FISHING	Inverter 1 (COM1-12)	GR2479028683	77.4
QL ENDAU DEEP SEA FISHING	Inverter 2 (COM3-13)	6T2519005200	77.6
QL ENDAU DEEP SEA FISHING	Inverter 3 (COM3-14)	GR2479020699	72.3
QL ENDAU DEEP SEA FISHING	Inverter 5 (COM3-16)	GR2479028681	74.4
QL ENDAU MARINE	TERA - INV 1	6T2449018663	72.2
QL ENDAU MARINE	TERA - INV 2	6T24C9071297	79.2
QL ENDAU MARINE	TERA - INV 4	GR2479026771	73.5
QL PAJAM PHASE 2	INV 4	6T2549059627	70.4

Plant Name	Inverter Name	Inverter SN	Temperature
RS POLY INDUSTRY	VASOLAR INV 1	ES2420000999	76.8
RS POLY INDUSTRY	VASOLAR INV 2	ES2420001084	76.4
SCENT PUR MANUFACTURING SDN BHD NO.35	INV-TA2470078151	TA2470078151	75.1
SCENT PUR MANUFACTURING SDN BHD NO.37	INV-NS245G038275	NS245G038275	85.1
SJK (C) WU TECK	INV 1	6T25B9000135	75.4
SJK ■ C ■ PIN HWA 1	INVERTER-2	ES2560208642	71.2
SP Logistics Sdn Bhd	INV-6T23B9005457	6T23B9005457	78.9
TOMEI	INV-(12-1)	HV2330348462	73.2
TOMEI	INV-(16-1)	HV2330348376	80.0
TOMEI	INV-(4-1)	HV2330348450	71.1
TOMEI	INV-(4-2)	HV2330348386	76.1
TOMEI	INV-(4-3)	HV2330348461	72.0
TOMEI	INV-(6-1)	HV2330348465	71.1
TOMEI	INV-(8)	HV2330348453	75.5
TOMEI	INV-(8-2)	HV2330348466	73.5
TOMEI	INV-(8-3)	HV2330348451	72.8
UCS_Block B	10KTL-M1(COM1-12)	BT2240736599	72.1
VISKO INDUSTRIES SDN BHD	VASOLAR_INV_8	ES2180084993	70.1
Vinda Phase 1 and 2 (MSB 2)	Inverter 7 - Phase 1	6T21C9025215	70.4
WCS UNIT 6	INVERTER UNIT 6	HV2290931617	72.1
WCS UNIT 7	INVERTER UNIT 7	HV22A0404241	70.3