

FusionSolar Troubleshooting Report

Date: 11-05-2026
Generated At: 11-05-2026 20:30:09
Prepared By: TERA SPMS

Executive Summary

Metric	Value
Total low-performing plants	1
Total low-performing inverters	31
Total low-performing strings	0
Total alarms	60
Total high-temperature inverters	65

Low-performing Plants

Plant Name	Plant PSH	City Average PSH	Deviation
MAJOR ENGINEERING Lot 8	1.28	3.46	-62.98

Low-performing Inverters

Plant Name	Inverter	SN	Inverter PSH	Benchmark PSH	Deviation
BJC FOOD (MALAYSIA) SDN. BHD.	100KTL-M1(COM1-1)	NE=50476040	1.948	2.367	17.70
BP PLASTICS HQ	Inverter_1	NE=55632738	2.721	3.837	29.09
BP PLASTICS HQ	Inverter_10	NE=55632735	2.978	3.837	22.39
BP PLASTICS HQ	Inverter_2	NE=55632739	2.954	3.837	23.01
BP PLASTICS HQ	Inverter_3	NE=55632740	2.894	3.837	24.58
BP PLASTICS HQ	Inverter_4	NE=55632734	2.923	3.837	23.82
BP PLASTICS HQ	Inverter_5	NE=55632733	2.863	3.837	25.38

Plant Name	Inverter	SN	Inverter PSH	Benchmark PSH	Deviation
BP PLASTICS HQ	Inverter_7	NE=55632736	1.950	3.837	49.18
BP PLASTICS HQ	Inverter_9	NE=55632737	2.918	3.837	23.95
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-1)	NE=50412148	1.538	1.952	21.21
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-10)	NE=50412130	1.530	1.952	21.62
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-2)	NE=50412133	1.532	1.952	21.52
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-3)	NE=50412147	1.526	1.952	21.82
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-4)	NE=50412150	1.528	1.952	21.72
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-5)	NE=50412131	1.529	1.952	21.67
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-6)	NE=50412146	1.530	1.952	21.62
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-7)	NE=50412143	1.531	1.952	21.57
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-8)	NE=50412144	1.533	1.952	21.47
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-9)	NE=50412145	1.531	1.952	21.57
KWANG HUA PERSENDIRIAN METER 2-3-4-5-6	Block B2-Inverter 6 - Meter 6	NE=51163027	2.539	2.866	11.41
KWANG HUA PERSENDIRIAN METER 2-3-4-5-6	Block C - Inverter 7 - Meter 2	NE=51163025	2.206	2.866	23.03
PKT 12 WAVES	Inverter 1	NE=56003099	2.843	3.528	19.42
PKT 12 WAVES	Inverter 10	NE=56003102	2.856	3.528	19.05
PKT 12 WAVES	Inverter 2	NE=56003098	2.850	3.528	19.22
PKT 12 WAVES	Inverter 3	NE=56003101	2.858	3.528	18.99
PKT 12 WAVES	Inverter 4	NE=56003104	2.834	3.528	19.67
PKT 12 WAVES	Inverter 5	NE=56003103	2.824	3.528	19.95
PKT 12 WAVES	Inverter 6	NE=56003095	2.830	3.528	19.78
PKT 12 WAVES	Inverter 7	NE=56003100	2.829	3.528	19.81
PKT 12 WAVES	Inverter 8	NE=56003096	2.829	3.528	19.81
PKT 12 WAVES	Inverter 9	NE=56003097	2.841	3.528	19.47

Low-performing Strings

Plant Name	Inverter	SN	String	Total Current	Benchmark	Deviation
No low-performing strings found	-	-	-	-	-	-

Active Alarms

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
BIMB Bdr Penawar - 1st Floor	Dongle- INV1	BT24C0060244	Network Connection Error	Major	15-04-2026 18:07
BOILERMECH LOT 873	Logger-102516002824	102516002824	Network Connection Error	Major	02-05-2026 00:57
BP PLASTICS BP9	Logger-102556511876	102556511876	Network Connection Error	Major	10-05-2026 16:38
C0172_ATRIA SOUTH	Logger-102256528212	102256528212	Network Connection Error	Major	08-05-2026 01:02
C0176_GETHA	Logger-102256528260	102256528260	Network Connection Error	Major	28-04-2026 21:09
CHYE JOO HIANG SDN. BHD. (Meter 1)	INV-TA2470005979	TA2470005979	Abnormal Residual Current	Major	11-05-2026 10:28
Dong Sing Food Link Sdn Bhd	Inverter(COM2-1)	ES2570023845	Grid Loss	Major	11-05-2026 06:57
Fibertex Phase 2	Inverter 2 L3 Old	6T2379019735	Upgrade Failed or Version Mismatch	Minor	18-07-2025 15:24
GUH METER 1	VASOLAR_INV_1	6T2379018351	Abnormal External Fan	Major	11-05-2026 08:04
IOI Mall Puchong (New Wing)	Inverter 14 - TERA	ES2470053866	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing)	Inverter 17 - TERA	6T2479017623	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing)	Inverter 13 - TERA	6T2479017534	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing) Phase 2	Logger-102516002835	102516002835	Network Connection Error	Major	10-05-2026 01:18
IOI Mall Puchong (New Wing) Phase 2	Inverter(COM1-1)	GR2569071128	Grid Loss	Major	08-05-2026 16:11
IOI Mall Puchong (New Wing) Phase 2	Inverter 4	GR2569071069	Grid Loss	Major	16-04-2026 09:37
IOI Mall Puchong (Old Wing)	Inverter 21 R1-TERA	6T2599057796	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 3 R1 - TERA	BN2521059950	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 12 - TERA	BN2461066801	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 2 - TERA	BN2461066770	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
IOI Mall Puchong (Old Wing)	Inverter 7 - TERA	6T2479017524	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 10 - TERA	6T2469039407	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 4 - TERA	6T2479017517	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 1 - TERA	BN2461065466	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 5 - TERA	BN2461066760	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 6 - TERA	BN2461066754	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 8 - TERA	BN2461065428	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 11 - TERA	BN2461066739	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 9 - TERA	6T2479017523	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
KILANG BATU BATA	Dongle-TA2510047367	TA2510047367	Network Connection Error	Major	09-05-2026 09:26
LIAN FOO POULTRY FARM SDN BHD	Dongle-BT2541519026	BT2541519026	Network Connection Error	Major	30-04-2026 18:40
LIAN FOO POULTRY FARM SDN BHD	INV-ES2550000030	ES2550000030	Grid Loss	Major	30-04-2026 17:55
LIAN FOO POULTRY FARM SDN BHD	INV-ES25C0125116	ES25C0125116	Grid Loss	Major	30-04-2026 17:54
LIAN FOO POULTRY FARM SDN BHD	INV-ES25C0125117	ES25C0125117	Grid Loss	Major	30-04-2026 17:54
Lian Teck Seng Lot 11	Dongle-BT24C0060275	BT24C0060275	Network Connection Error	Major	29-01-2026 15:54
MARINE GOLD SDN BHD	Dongle-TA2340293153	TA2340293153	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-TA2340293476	TA2340293476	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-TA2340291437	TA2340291437	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-HV2310776105	HV2310776105	Network Connection Error	Major	26-03-2026 14:56
MARINE GOLD SDN BHD	Dongle-HV2310776109	HV2310776109	Network Connection Error	Major	26-03-2026 14:55
MARINE GOLD SDN BHD	Dongle-HV2310773587	HV2310773587	Network Connection Error	Major	26-03-2026 14:54
MENARA PKNS PJ	Logger-102466288020	102466288020	Network Connection Error	Major	10-05-2026 01:00
MAIAW FRESH	VASOLAR INV 1	NS2331625509	Grid Loss	Major	07-05-2026 12:49
Pengerang Independent Terminal	Dongle-LAB	TA23B0087782	Network Connection Error	Major	20-04-2026 13:52
Pleasure Latex Phase 2	Logger-102347282208	102347282208	Network Connection Error	Major	19-02-2026 03:00

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
QL FARM SDN BHD	Logger-102466853213	102466853213	Network Connection Error	Major	24-04-2026 10:56
QL FARM SDN BHD	Inverter 1	ES2580051653	Grid Loss	Major	24-04-2026 10:07
QL FARM SDN BHD	Inverter 2	ES2580051643	Grid Loss	Major	24-04-2026 10:07
QL FARM SDN BHD	Inverter3	ES2490076207	Grid Loss	Major	24-04-2026 10:07
REDANG LAGOON RESORT	Dongle-2102312EHS10N9115979	2102312EHS10N9115979	Network Connection Error	Major	30-01-2026 19:29
REDANG LAGOON RESORT	INV-ES22A0089681	ES22A0089681	Grid Loss	Major	30-01-2026 07:23
SIME KANSAI PAINT SDN BHD	INV-ES2550146111	ES2550146111	Upgrade Failed or Version Mismatch	Minor	19-11-2025 21:35
THOR SPECIALTIES	Dongle-BT2541519069	BT2541519069	Network Connection Error	Major	07-05-2026 14:48
THP MEDICAL	VASOLAR INV 3	6T2279009018	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
THP MEDICAL	VASOLAR INV 2	6T2279008977	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
THP MEDICAL	VASOLAR INV 1	6T2279009011	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
Telewiring	VASOLAR_INV_1	HV2330869769	Grid Loss	Major	04-05-2026 08:17
VINDA PHASE 4 (MSB 3-2)	Inverter13 Phase4 R1	ES2580050563	Grid Loss	Major	09-05-2026 15:53
VINDA PHASE 4 (MSB 3-2)	Inverter13 Phase4 R1	ES2580050563	AC Overcurrent	Major	09-05-2026 12:24
VINDA PHASE 4 (MSB 3-2)	Inverter13 Phase4 R1	ES2580050563	The PV string is short-circuited to the ground.	Major	09-05-2026 12:24
VINDA PHASE 4 (MSB 3-2)	MASTER LOG HT P4	102595350697	Southbound Device Communication Abnormal	Minor	29-04-2026 15:30

High-temperature Inverters

Plant Name	Inverter Name	Inverter SN	Temperature
-	INV 5	-	80.6
Apex Uniparts	VASOLAR_INV_1	ES2420001215	76.2
BREMFIELD SDN BHD	INV 1	ES2320221246	72.3
BREMFIELD SDN BHD	INV 3	6T22A9048280	70.3
C0102_QL batang kali	150K-MG0(COM3-2)	GR2479026710	72.3

Plant Name	Inverter Name	Inverter SN	Temperature
C0149_VERTEX MISSION	HV21B0210137	HV21B0210137	72.2
CHAN KAH WHYE	INV-NS249G082061	NS249G082061	82.4
Durasafe Sdn. Bhd.	INV 1-6T2479002464	6T2479002464	81.7
Durasafe Sdn. Bhd.	INV 2-6T2469038783	6T2469038783	73.8
FDP AND MTB INDUSTRIES SDN BHD	TERA FDP INV 2	ES2580087345	75.4
FDP AND MTB INDUSTRIES SDN BHD	TERA MTB INV 4	ES2580087312	74.4
FOX ONE LOT 8	TERA INVERTER 2	6T25B9000067	77.1
Farm Fresh Taiping (Factory)	50KTL-M3(COM1-12)	6T22A9038815	72.1
Fibertex Phase 2	Roof 2C Bridge R1	6T2469046697	70.1
Fungiculture	Inverter 2 (M4)	HV22B0004571	70.0
GLASS PLASTIC PACKAGING	INV 2 - (No.23)	6T2489010546	74.2
GLASS PLASTIC PACKAGING	INV 4 - (Lot 65999)	6T2489010593	71.8
IOI Mall Puchong (New Wing)	Inverter 15 - TERA	ES2330107601	72.4
IOI Mall Puchong (New Wing)	Inverter 16 - TERA	6T2449030262	74.3
IOI Mall Puchong (Old Wing)	Inverter 20 - TERA	6T24C9047414	71.8
KB AIS SDN. BHD.	Inverter-1	6T21C9025324	70.3
Kiara Bay	Inverter 2 - TERA	ES2330110574	72.8
Kiara Bay	Inverter 3 - TERA	6T2449022934	75.9
Kiara Bay	Inverter 4 - TERA	6T2449023252	72.0
Marbach Asia Pacific Lot17	INV-6T2489012207	6T2489012207	72.6
Menara PJD	Inverter 50ktl(COM1-12)	6T22A9046122	70.7
Multi Choice (M) Sdn Bhd	TERA INV 1	GR2489029065	70.1
Multi Choice (M) Sdn Bhd	TERA INV 2	GR2489029048	71.8
Multi Choice (M) Sdn Bhd	TERA INV 3	ES2560208616	81.3
P.A Food Sdn Bhd 2ATKT	INV-ES2420001275	ES2420001275	78.1

Plant Name	Inverter Name	Inverter SN	Temperature
P.A Food Sdn Bhd Lot 10	INV-6T2449029469	6T2449029469	74.2
P.A Food Sdn Bhd Lot 12	INV-6T2449029471	6T2449029471	75.8
P.A. Food Warehouse No. 9	INV-HV2290797189	HV2290797189	75.5
Pengerang Independent Terminal	VASOLAR INV 2 CP 1	ES2330104289	74.4
Pengerang Independent Terminal	VASOLAR INV 3 CP 1	ES2340146417	74.9
Pengerang Independent Terminal	VASOLAR INV 4 CP 2	6T23A9016705	73.7
Pengerang Independent Terminal	VASOLAR INV7 MC	ES2340146422	83.2
QL ENDAU DEEP SEA FISHING	Inverter 1 (COM1-12)	GR2479028683	74.0
QL ENDAU DEEP SEA FISHING	Inverter 2 (COM3-13)	6T2519005200	75.4
QL ENDAU DEEP SEA FISHING	Inverter 3 (COM3-14)	GR2479020699	72.1
QL ENDAU DEEP SEA FISHING	Inverter 4 (COM3-15)	GR2479020734	74.6
QL ENDAU DEEP SEA FISHING	Inverter 5 (COM3-16)	GR2479028681	74.3
QL ENDAU MARINE	TERA - INV 2	6T24C9071297	76.9
QL ENDAU MARINE	TERA - INV 4	GR2479026771	71.7
QL FOODS	INVERTER_10	6T2449032177	70.7
QL PAJAM PHASE 2	INV 3	6T2549059593	73.2
QL PAJAM PHASE 2	INV 4	6T2549059627	74.0
RS POLY INDUSTRY	VASOLAR INV 1	ES2420000999	70.1
SABAH CHINESE HIGH SCHOOL (TAK YUEN BUILDING)	50KTL-M3(COM1-2)	ES22A0076308	81.9
SCENT PUR MANUFACTURING SDN BHD NO.35	INV-TA2470078151	TA2470078151	71.8
SCENT PUR MANUFACTURING SDN BHD NO.37	INV-NS245G038275	NS245G038275	79.8
SP Logistics Sdn Bhd	INV-6T23B9005457	6T23B9005457	76.1
San Soon Seng Food Industries Sdn Bhd	Inv 02 (Racking WH)	6T2549057201	72.4
TOMEI	INV-(12-1)	HV2330348462	77.5
TOMEI	INV-(16-1)	HV2330348376	79.2

Plant Name	Inverter Name	Inverter SN	Temperature
TOMEI	INV-(4-1)	HV2330348450	74.9
TOMEI	INV-(4-2)	HV2330348386	75.5
TOMEI	INV-(4-3)	HV2330348461	72.0
TOMEI	INV-(6-1)	HV2330348465	74.2
TOMEI	INV-(8)	HV2330348453	74.3
TOMEI	INV-(8-2)	HV2330348466	72.8
TOMEI	INV-(8-3)	HV2330348451	72.4
Tembikar Wei Khing	Inverter 8 - TERA	6T2469033043	71.0
WCS UNIT 6	INVERTER UNIT 6	HV2290931617	72.8
YAN JIAN 2	INV-6T2529005668	6T2529005668	74.3