

FusionSolar Troubleshooting Report

Date: 12-05-2026
Generated At: 12-05-2026 20:30:09
Prepared By: TERA SPMS

Executive Summary

Metric	Value
Total low-performing plants	33
Total low-performing inverters	54
Total low-performing strings	0
Total alarms	57
Total high-temperature inverters	89

Low-performing Plants

Plant Name	Plant PSH	City Average PSH	Deviation
AFI METAL	0.08	1.32	-93.94
ASHITA COMMUNICATION	0.00	3.94	-100.00
BIMB Bdr Penawar - 1st Floor	0.00	1.04	-100.00
BJC FOOD (MALAYSIA) SDN. BHD.	3.42	4.00	-14.59
BOILERMECH LOT 873	0.00	2.09	-100.00
BP PLASTICS BP9	2.96	3.90	-24.17
C0172_ATRIA SOUTH	0.00	2.47	-100.00
DSG Malaysia Sdn. Bhd	2.91	3.90	-25.38
Dong Sing Food Link Sdn Bhd	1.97	3.44	-42.65
FUJI M3	3.37	3.85	-12.35
IOI Mall Puchong (New Wing) Phase 2	3.53	4.04	-12.66

Plant Name	Plant PSH	City Average PSH	Deviation
IOI Mall Puchong (Old Wing)	3.26	4.04	-19.34
KISWIRE CORD PHASE 1 (DATA)	0.00	1.43	-100.00
Kiara Bay	2.41	3.20	-24.61
Kwang Hua Persendirian meter 2-3-4-5-6	3.18	3.94	-19.22
Lau and Tan Pharmacy (G.Floor)	2.89	3.33	-13.21
Lian Teck Seng Lot 11	0.00	3.94	-100.00
MAJOR ENGINEERING Lot 10	3.43	3.94	-12.87
MAJOR ENGINEERING Lot 8	1.58	3.94	-59.86
MARINE GOLD SDN BHD	0.00	3.16	-100.00
MENARA PKNS PJ	0.00	2.48	-100.00
MAIW FRESH	0.00	3.94	-100.00
Pleasure Latex Phase 2	0.00	2.19	-100.00
QL FARM SDN BHD	0.00	1.95	-100.00
REDANG LAGOON RESORT	0.00	1.32	-100.00
SJK (C) TSHING NIAN	3.85	4.33	-11.12
SWEE CHEONG WATCH SDN BHD (Meter 2)	2.83	3.56	-20.43
THOR SPECIALTIES	0.00	4.00	-100.00
TIMURIKAN TRENGGANU MARINE PRODUCTS SDN BHD	0.70	2.06	-65.94
TOMEI	3.45	3.94	-12.36
Teong Huat Medical	3.08	3.83	-19.51
WASCO PIPE SDN BHD (COATING)	0.84	1.23	-31.71
WEIDA MARKETING SDN. BHD.	3.87	4.54	-14.66

Low-performing Inverters

Plant Name	Inverter	SN	Inverter PSH	Benchmark PSH	Deviation
BJC FOOD (MALAYSIA) SDN. BHD.	100KTL-M1(COM1-1)	NE=50476040	1.950	2.376	17.93
BP PLASTICS BP9	INVERTER 1 (AREA C)	NE=60208482	2.507	2.881	12.98
BP PLASTICS BP9	INVERTER 2 (AREA C)	NE=60208484	2.543	2.881	11.73
BP PLASTICS BP9	INVERTER 3 (AREA C)	NE=60208483	2.580	2.881	10.45
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-1)	NE=50412148	1.734	2.037	14.87
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-10)	NE=50412130	1.736	2.037	14.78
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-2)	NE=50412133	1.728	2.037	15.17
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-3)	NE=50412147	1.712	2.037	15.95
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-4)	NE=50412150	1.729	2.037	15.12
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-5)	NE=50412131	1.725	2.037	15.32
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-6)	NE=50412146	1.724	2.037	15.37
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-7)	NE=50412143	1.735	2.037	14.83
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-8)	NE=50412144	1.733	2.037	14.92
DSG MALAYSIA SDN. BHD	100KTL-M1(COM1-9)	NE=50412145	1.725	2.037	15.32
IOI MALL PUCHONG (NEW WING) PHASE 2	Inverter 4	NE=82071817	0.187	2.530	92.61
IOI MALL PUCHONG (OLD WING)	Inverter 1 - TERA	NE=57818394	1.780	2.825	36.99
IOI MALL PUCHONG (OLD WING)	Inverter 10 - TERA	NE=57818392	1.977	2.825	30.02
IOI MALL PUCHONG (OLD WING)	Inverter 11 - TERA	NE=57818399	1.951	2.825	30.94
IOI MALL PUCHONG (OLD WING)	Inverter 12 - TERA	NE=57818390	1.935	2.825	31.50
IOI MALL PUCHONG (OLD WING)	Inverter 18 - TERA	NE=57818401	1.674	2.825	40.74
IOI MALL PUCHONG (OLD WING)	Inverter 2 - TERA	NE=57818389	1.985	2.825	29.73
IOI MALL PUCHONG (OLD WING)	Inverter 3 R1 - TERA	NE=60013298	1.969	2.825	30.30
IOI MALL PUCHONG (OLD WING)	Inverter 4 - TERA	NE=57818393	1.831	2.825	35.19
IOI MALL PUCHONG (OLD WING)	Inverter 5 - TERA	NE=57818395	1.902	2.825	32.67
IOI MALL PUCHONG (OLD WING)	Inverter 6 - TERA	NE=57818396	1.955	2.825	30.80

Plant Name	Inverter	SN	Inverter PSH	Benchmark PSH	Deviation
IOI MALL PUCHONG (OLD WING)	Inverter 7 - TERA	NE=57818391	1.926	2.825	31.82
IOI MALL PUCHONG (OLD WING)	Inverter 8 - TERA	NE=57818397	1.921	2.825	32.00
IOI MALL PUCHONG (OLD WING)	Inverter 9 - TERA	NE=57818400	1.938	2.825	31.40
KIARA BAY	Inverter 1 - TERA	NE=55735156	2.003	2.287	12.42
KIARA BAY	Inverter 10 - TERA	NE=55735154	1.232	2.287	46.13
KIARA BAY	Inverter 11 - TERA	NE=55735153	1.274	2.287	44.29
KIARA BAY	Inverter 3 - TERA	NE=55735162	1.807	2.287	20.99
KIARA BAY	Inverter 4 - TERA	NE=55735161	1.683	2.287	26.41
KIARA BAY	Inverter 5 - TERA	NE=55735155	1.826	2.287	20.16
KIARA BAY	Inverter 6 - TERA	NE=55735160	1.248	2.287	45.43
KIARA BAY	Inverter 7 - TERA	NE=55735157	1.474	2.287	35.55
KIARA BAY	Inverter 8 - TERA	NE=55735158	1.426	2.287	37.65
KIARA BAY	Inverter 9 - TERA	NE=55735159	1.180	2.287	48.40
KWANG HUA PERSENDIRIAN METER 2-3-4-5-6	Block B2-Inverter 6 - Meter 6	NE=51163027	1.675	2.121	21.03
KWANG HUA PERSENDIRIAN METER 2-3-4-5-6	Block C - Inverter 7 - Meter 2	NE=51163025	1.458	2.121	31.26
QL FOODS	INVERTER_10	NE=53679611	1.926	2.460	21.71
QL FOODS	INVERTER_15	NE=53679053	2.099	2.460	14.67
QL FOODS	INVERTER_3	NE=53678487	2.194	2.460	10.81
QL FOODS	INVERTER_7	NE=53676713	1.979	2.460	19.55
QL FOODS	INVERTER_9	NE=53679667	2.079	2.460	15.49
TEONG HUAT MEDICAL	TERA INV 1	NE=79838602	3.012	3.402	11.46
TEONG HUAT MEDICAL	TERA INV 4	NE=79838604	3.011	3.402	11.49
TOMEI	INV-(10-2)	NE=54352010	1.500	1.855	19.14
TOMEI	INV-(10-3)	NE=54351494	1.231	1.855	33.64

Plant Name	Inverter	SN	Inverter PSH	Benchmark PSH	Deviation
TOMEI	INV-(16-2)	NE=54352004	1.392	1.855	24.96
TOMEI	INV-(4)	NE=55086008	1.594	1.855	14.07
TOMEI	INV-(4-3)	NE=54351850	1.304	1.855	29.70
TOMEI	INV-(6-3)	NE=54351644	1.443	1.855	22.21
TOMEI	INV-(8-3)	NE=54351578	1.331	1.855	28.25

Low-performing Strings

Plant Name	Inverter	SN	String	Total Current	Benchmark	Deviation
No low-performing strings found	-	-	-	-	-	-

Active Alarms

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
AFI METAL	Dongle-TA2340291486	TA2340291486	Network Connection Error	Major	12-05-2026 09:29
BIMB Bdr Penawar - 1st Floor	Dongle- INV1	BT24C0060244	Network Connection Error	Major	15-04-2026 18:07
BOILERMECH LOT 873	Logger-102516002824	102516002824	Network Connection Error	Major	02-05-2026 00:57
BP PLASTICS BP9	Logger-102556511876	102556511876	Network Connection Error	Major	10-05-2026 16:38
C0172_ATRIA SOUTH	Logger-102256528212	102256528212	Network Connection Error	Major	08-05-2026 01:02
C0176_GETHA	Logger-102256528260	102256528260	Network Connection Error	Major	28-04-2026 21:09
Dong Sing Food Link Sdn Bhd	Inverter(COM2-1)	ES2570023845	Grid Loss	Major	12-05-2026 06:52
Fibertex Phase 2	Inverter 2 L3 Old	6T2379019735	Upgrade Failed or Version Mismatch	Minor	18-07-2025 15:24
IOI Mall Puchong (New Wing)	Inverter 14 - TERA	ES2470053866	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing)	Inverter 17 - TERA	6T2479017623	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing)	Inverter 13 - TERA	6T2479017534	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing) Phase 2	Inverter 4	GR2569071069	Grid Loss	Major	12-05-2026 09:13
IOI Mall Puchong (New Wing) Phase 2	Inverter(COM1-1)	GR2569071128	Grid Loss	Major	08-05-2026 16:11

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
IOI Mall Puchong (Old Wing)	Inverter 21 R1-TERA	6T2599057796	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 3 R1 - TERA	BN2521059950	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 12 - TERA	BN2461066801	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 2 - TERA	BN2461066770	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 7 - TERA	6T2479017524	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 10 - TERA	6T2469039407	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 4 - TERA	6T2479017517	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 1 - TERA	BN2461065466	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 5 - TERA	BN2461066760	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 6 - TERA	BN2461066754	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 11 - TERA	BN2461066739	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 8 - TERA	BN2461065428	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 9 - TERA	6T2479017523	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
LIAN FOO POULTRY FARM SDN BHD	Dongle-BT2541519026	BT2541519026	Network Connection Error	Major	30-04-2026 18:40
LIAN FOO POULTRY FARM SDN BHD	INV-ES2550000030	ES2550000030	Grid Loss	Major	30-04-2026 17:55
LIAN FOO POULTRY FARM SDN BHD	INV-ES25C0125116	ES25C0125116	Grid Loss	Major	30-04-2026 17:54
LIAN FOO POULTRY FARM SDN BHD	INV-ES25C0125117	ES25C0125117	Grid Loss	Major	30-04-2026 17:54
Lian Teck Seng Lot 11	Dongle-BT24C0060275	BT24C0060275	Network Connection Error	Major	29-01-2026 15:54
MARINE GOLD SDN BHD	Dongle-TA2340293153	TA2340293153	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-TA2340293476	TA2340293476	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-TA2340291437	TA2340291437	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-HV2310776105	HV2310776105	Network Connection Error	Major	26-03-2026 14:56
MARINE GOLD SDN BHD	Dongle-HV2310776109	HV2310776109	Network Connection Error	Major	26-03-2026 14:55
MARINE GOLD SDN BHD	Dongle-HV2310773587	HV2310773587	Network Connection Error	Major	26-03-2026 14:54
MENARA PKNS PJ	Logger-102466288020	102466288020	Network Connection Error	Major	10-05-2026 01:00

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
MAIAW FRESH	VASOLAR INV 1	NS2331625509	Grid Loss	Major	07-05-2026 12:49
Pengerang Independent Terminal	Dongle-LAB	TA23B0087782	Network Connection Error	Major	20-04-2026 13:52
Pleasure Latex Phase 2	Logger-102347282208	102347282208	Network Connection Error	Major	19-02-2026 03:00
QL FARM SDN BHD	Logger-102466853213	102466853213	Network Connection Error	Major	24-04-2026 10:56
QL FARM SDN BHD	Inverter 2	ES2580051643	Grid Loss	Major	24-04-2026 10:07
QL FARM SDN BHD	Inverter 1	ES2580051653	Grid Loss	Major	24-04-2026 10:07
QL FARM SDN BHD	Inverter3	ES2490076207	Grid Loss	Major	24-04-2026 10:07
REDANG LAGOON RESORT	Dongle-2102312EHS10N9115979	2102312EHS10N9115979	Network Connection Error	Major	30-01-2026 19:29
REDANG LAGOON RESORT	INV-ES22A0089681	ES22A0089681	Grid Loss	Major	30-01-2026 07:23
SIME KANSAI PAINT SDN BHD	INV-ES2550146111	ES2550146111	Upgrade Failed or Version Mismatch	Minor	19-11-2025 21:35
THOR SPECIALTIES	Dongle-BT2541519069	BT2541519069	Network Connection Error	Major	07-05-2026 14:48
THP MEDICAL	VASOLAR INV 3	6T2279009018	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
THP MEDICAL	VASOLAR INV 2	6T2279008977	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
THP MEDICAL	VASOLAR INV 1	6T2279009011	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
Telewiring	VASOLAR_INV_1	HV2330869769	Grid Loss	Major	04-05-2026 08:17
VINDA PHASE 4 (MSB 3-2)	Inverter13 Phase4 R1	ES2580050563	Grid Loss	Major	09-05-2026 15:53
VINDA PHASE 4 (MSB 3-2)	Inverter13 Phase4 R1	ES2580050563	The PV string is short-circuited to the ground.	Major	09-05-2026 12:24
VINDA PHASE 4 (MSB 3-2)	Inverter13 Phase4 R1	ES2580050563	AC Overcurrent	Major	09-05-2026 12:24
VINDA PHASE 4 (MSB 3-2)	MASTER LOG HT P4	102595350697	Southbound Device Communication Abnormal	Minor	29-04-2026 15:30

High-temperature Inverters

Plant Name	Inverter Name	Inverter SN	Temperature
-	-	-	70.1
AMT PC DISTRIBUTORS SDN. BHD.	INV-6T22B9024620	6T22B9024620	79.8

Plant Name	Inverter Name	Inverter SN	Temperature
ATS AIR SOLUTION	INV-HV22A0242778	HV22A0242778	76.2
Advance Vi Tech Lot 1629	INVERTER 2 - TERA	ES2330108240	72.9
Advance Vi Tech Lot 1629	INVERTER 3 - TERA	6T24B9059721	70.9
Apex Uniparts	VASOLAR_INV_1	ES2420001215	74.7
BJC FOOD (MALAYSIA) SDN. BHD.	60KTL-M0(COM1-3)	ES2180084797	70.4
BP PLASTICS BP9	INVERTER 2 (AREA C)	BN24A1084697	73.7
BP PLASTICS BP9	INVERTER 3 (AREA C)	BN24A1081068	70.6
BP PLASTICS BP9	INVERTER 5 (AREA C)	6T24A9018015	75.7
BP PLASTICS HQ	Inverter_11	6T2499023013	75.0
BP PLASTICS HQ	Inverter_2	ES2440060550	79.4
BP PLASTICS HQ	Inverter_3	6T2489015626	73.4
BP PLASTICS HQ	Inverter_6	6T2499021622	80.3
BP PLASTICS HQ	Inverter_8	6T2499021624	76.3
C0102_QL batang kali	150K-MG0(COM3-2)	GR2479026710	72.7
C0102_QL batang kali	150K-MG0(COM3-3)	GR2479026770	71.9
CHAN KAH WHYE	INV-NS249G082061	NS249G082061	83.1
CIC CONTRACT SDN BHD	INV-HV22A0242777	HV22A0242777	70.1
Durasafe Sdn. Bhd.	INV 1-6T2479002464	6T2479002464	72.6
Durasafe Sdn. Bhd.	INV 2-6T2469038783	6T2469038783	70.3
FDP AND MTB INDUSTRIES SDN BHD	TERA FDP INV 2	ES2580087345	78.8
FDP AND MTB INDUSTRIES SDN BHD	TERA MTB INV 4	ES2580087312	77.4
Farm Fresh Taiping (Factory)	50KTL-M3(COM1-12)	6T22A9038815	71.4
Fibertex Phase 2	Inv. CarPark Roof A	ES2420001055	75.5
Fibertex Phase 2	Inverter 1 L3	6T23A9016283	74.7
Fibertex Phase 2	Inverter 4 L3	6T2379019613	70.0

Plant Name	Inverter Name	Inverter SN	Temperature
Fibertex Phase 2	Inverter 8 L3	6T2379019736	70.2
Fibertex Phase 2	Roof 2C Bridge R1	6T2469046697	72.9
Fungiculture	Inverter 2 (M3)	HV22B0337400	71.4
GLASS PLASTIC PACKAGING	INV 2 - (No.23)	6T2489010546	75.3
GLASS PLASTIC PACKAGING	INV 3 - (Lot 65999)	6T2489010635	70.4
GLASS PLASTIC PACKAGING	INV 4 - (Lot 65999)	6T2489010593	72.1
Hoon Yuen Furniture	Inverter 1	ES22B0024091	71.4
IOI City Mall Inc. Feeder 1	Inverter 1.1 - TERA	6T22C9025521	70.7
IOI City Mall Inc. Feeder 1	Inverter 2.1 - TERA	6T22C9011475	70.9
IOI City Mall Inc. Feeder 1	Inverter 2.12 R1	6T2599029683	71.8
IOI City Mall Inc. Feeder 1	Inverter 2.2 - TERA	6T22B9036192	71.5
IOI City Mall Inc. Feeder 1	Inverter 2.5 - TERA	6T22C9011507	71.9
IOI City Mall Inc. Feeder 1	Inverter 2.6 - TERA	6T22C9011480	73.2
IOI City Mall Inc. Feeder 1	Inverter 2.7 - TERA	6T22C9011519	70.1
IOI City Mall Inc. Feeder 2	Inverter 4.1 - TERA	6T22B9036278	71.7
IOI Mall Puchong (New Wing)	Inverter 16 - TERA	6T2449030262	73.9
Jiann Lih safety product	40KTL-M3(COM1-15)	ES2290059762	74.2
Jiann Lih safety product	40KTL-M3(COM1-16)	ES2290059727	75.5
KUASA BAKTI (PETRON SETIA ALAM)	INV-6T2489035314	6T2489035314	76.6
Kwang Hua Persendirian meter 2-3-4-5-6	Block B2-Inverter 6 - Meter 6	6T21C9025214	70.7
LAM SOON EDIBLE OILS	INV-1	6T24A9018029	72.5
LAM SOON EDIBLE OILS	INV-2	6T2449022953	85.5
MEWAH OILS SDN BHD	Inverter 1(COM2-13)	6T2519016741	70.3
Marbach Asia Pacific Lot17	INV-6T2489012207	6T2489012207	71.0
Menara PJD	Inverter 50ktl(COM1-12)	6T22A9046122	74.2

Plant Name	Inverter Name	Inverter SN	Temperature
Mitsui Copper Foil P3	Inverter 1 (AREA A)	GR2459039442	75.4
Mitsui Copper Foil P3	Inverter 2 (AREA A)	GR2459039444	78.0
Mitsui Copper Foil P3	Inverter 3 (AREA A)	6T24A9009773	83.2
Mitsui Copper Foil P3	Inverter 4 (AREA A)	6T24A9013004	85.6
Mitsui Copper Foil P3	Inverter 5 (AREA B)	6T2519017589	77.3
Multi Choice (M) Sdn Bhd	TERA INV 2	GR2489029048	70.3
Multi Choice (M) Sdn Bhd	TERA INV 3	ES2560208616	80.6
New Age 160	INV 1	6T2469012777	73.8
New Age 160	Inverter 2 R1	6T23B9005979	76.9
New Age 160	Inverter 3-36ktl m3	6T2489036764	74.0
P.A Food Sdn Bhd 2ATKT	INV-ES2420001275	ES2420001275	71.8
P.A Food Sdn Bhd Lot 10	INV-6T2449029469	6T2449029469	76.1
P.A Food Sdn Bhd Lot 12	INV-6T2449029471	6T2449029471	78.3
PKT 8 WAVES	Inverter_2	6T2439012020	74.9
PKT THE SHIP	Inverter_8 R1	ES24C0173071	70.2
Pengerang Independent Terminal	VASOLAR INV 2 CP 1	ES2330104289	73.5
Pengerang Independent Terminal	VASOLAR INV 3 CP 1	ES2340146417	74.5
Pengerang Independent Terminal	VASOLAR INV 4 CP 2	6T23A9016705	73.5
Pengerang Independent Terminal	VASOLAR INV7 MC	ES2340146422	86.8
Pengerang Independent Terminal	VASOLAR INV8 LCS304	ES2410011406	70.2
Pengerang Independent Terminal	VASOLAR INV9 LCS304	ES2410011693	70.8
QL ENDAU DEEP SEA FISHING	Inverter 2 (COM3-13)	6T2519005200	73.9
QL PAJAM PHASE 2	INV 4	6T2549059627	73.8
QI Lot 14	INV-ES24A0149129	ES24A0149129	75.1
RS POLY INDUSTRY	VASOLAR INV 1	ES2420000999	75.8

Plant Name	Inverter Name	Inverter SN	Temperature
RS POLY INDUSTRY	VASOLAR INV 2	ES2420001084	73.8
SABAH CHINESE HIGH SCHOOL (TAK YUEN BUILDING)	50KTL-M3(COM1-2)	ES22A0076308	73.8
SCENT PUR MANUFACTURING SDN BHD NO.35	INV-TA2470078151	TA2470078151	73.5
SCENT PUR MANUFACTURING SDN BHD NO.37	INV-NS245G038275	NS245G038275	83.9
SJK (C) WU TECK	INV 1	6T25B9000135	78.8
SJK ■ C ■ PIN HWA 1	INVERTER-2	ES2560208642	82.0
SM Chung Chung Hua (PSDN) Klang	60KTL-M0(COM1-4)	ES2190080965	70.7
SP Logistics Sdn Bhd	INV-6T23B9005457	6T23B9005457	79.8
Succesfuel Sdn. Bhd.	INVERTER 1 R1	6T24C9072224	75.8
VINDA PHASE 4 (MSB 3-2)	Phase4 Inverter 9 R1	6T2489040944	70.1
VISKO INDUSTRIES SDN BHD	VASOLAR_INV_8	ES2180084993	71.3
YAN JIAN 2	INV-6T2529005668	6T2529005668	76.4