

FusionSolar Troubleshooting Report

Date: 22-04-2026
Generated At: 22-04-2026 17:26:47
Prepared By: TERA SPMS

Executive Summary

Metric	Value
Total plant analysed	26
Total low-performing plants	26
Total alarms	43
Total high-temperature inverters	28

Low-performing Plants

Plant Name	Plant PSH	City Average PSH	Deviation
ASHITA COMMUNICATION	0.00	1.01	-100.00
BIMB Bdr Penawar - 1st Floor	0.00	1.02	-100.00
BJC FOOD (MALAYSIA) SDN. BHD.	0.97	1.24	-21.86
BP PLASTICS HQ	1.11	1.61	-31.06
BRC INDUSTRIES	0.00	0.79	-100.00
IOI Mall Puchong (New Wing) Phase 2	0.00	1.14	-100.00
IOI Mayang Development	1.15	1.73	-33.57
Jaya Nets	0.87	0.97	-10.77
KISWIRE CORD PHASE 1 (DATA)	0.00	0.86	-100.00
Kwang Hua Persendirian meter 2-3-4-5-6	0.89	1.01	-11.60
Lau and Tan Pharmacy (G.Floor)	1.08	1.28	-15.62
Lian Teck Seng Lot 11	0.00	1.01	-100.00

Plant Name	Plant PSH	City Average PSH	Deviation
MAJOR ENGINEERING Lot 8	0.17	1.01	-83.11
MARINE GOLD SDN BHD	0.00	1.47	-100.00
MENARA PKNS PJ	0.00	0.77	-100.00
P.A. Food Warehouse No. 9	1.60	1.83	-12.57
Pleasure Latex Phase 2	0.00	0.48	-100.00
QL TAWAU FEEDMILL	0.19	0.57	-66.81
REDANG LAGOON RESORT	0.00	1.12	-100.00
SABAH CHINESE HIGH SCHOOL (TAK YUEN BUILDING)	0.00	0.57	-100.00
SUPERMICRO COMPUTER SDN BHD	1.29	1.51	-14.57
SWEE CHEONG WATCH SDN BHD (Meter 1)	1.66	1.92	-13.69
SWEE CHEONG WATCH SDN BHD (Meter 2)	1.56	1.92	-18.89
TIMURIKAN TRENGGANU MARINE PRODUCTS SDN BHD	0.33	1.16	-71.43
Teong Huat Medical	1.28	1.47	-12.73
WEIDA MARKETING SDN. BHD.	1.74	2.17	-19.63

Active Alarms

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
BIMB Bdr Penawar - 1st Floor	Dongle- INV1	BT24C0060244	Network Connection Error	Major	15-04-2026 18:07
BRC INDUSTRIES	Dongle-TA2340258607	TA2340258607	Network Connection Error	Major	22-04-2026 03:43
Fibertex Phase 2	Inverter 2 L3 Old	6T2379019735	Upgrade Failed or Version Mismatch	Minor	18-07-2025 15:24
IOI Mall Puchong (New Wing)	Inverter 14 - TERA	ES2470053866	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing)	Inverter 17 - TERA	6T2479017623	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing)	Inverter 13 - TERA	6T2479017534	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing) Phase 2	Logger-102516002835	102516002835	Network Connection Error	Major	19-04-2026 00:57

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
IOI Mall Puchong (New Wing) Phase 2	Inverter 4	GR2569071069	Grid Loss	Major	16-04-2026 09:37
IOI Mall Puchong (Old Wing)	Inverter 3 R1 - TERA	BN2521059950	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 12 - TERA	BN2461066801	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 2 - TERA	BN2461066770	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 7 - TERA	6T2479017524	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 10 - TERA	6T2469039407	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 4 - TERA	6T2479017517	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 1 - TERA	BN2461065466	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 5 - TERA	BN2461066760	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 6 - TERA	BN2461066754	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 11 - TERA	BN2461066739	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 8 - TERA	BN2461065428	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 9 - TERA	6T2479017523	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
Lian Teck Seng Lot 11	Dongle-BT24C0060275	BT24C0060275	Network Connection Error	Major	29-01-2026 15:54
MARINE GOLD SDN BHD	Dongle-TA2340293153	TA2340293153	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-TA2340293476	TA2340293476	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-TA2340291437	TA2340291437	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-HV2310776105	HV2310776105	Network Connection Error	Major	26-03-2026 14:56
MARINE GOLD SDN BHD	Dongle-HV2310776109	HV2310776109	Network Connection Error	Major	26-03-2026 14:55
MARINE GOLD SDN BHD	Dongle-HV2310773587	HV2310773587	Network Connection Error	Major	26-03-2026 14:54
MENARA PKNS PJ	Logger-102466288020	102466288020	Network Connection Error	Major	11-04-2026 01:01
Pengerang Independent Terminal	Dongle-LAB	TA23B0087782	Network Connection Error	Major	20-04-2026 13:52
Pleasure Latex Phase 2	Logger-102347282208	102347282208	Network Connection Error	Major	19-02-2026 03:00
REDANG LAGOON RESORT	Dongle-2102312EHS10N9115979	2102312EHS10N9115979	Network Connection Error	Major	30-01-2026 19:29

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
REDANG LAGOON RESORT	INV-ES22A0089681	ES22A0089681	Grid Loss	Major	30-01-2026 07:23
SABAH CHINESE HIGH SCHOOL (TAK YUEN BUILDING)	Logger-102297461092	102297461092	Network Connection Error	Major	21-04-2026 18:17
SIME KANSAI PAINT SDN BHD	INV-ES2550146111	ES2550146111	Upgrade Failed or Version Mismatch	Minor	19-11-2025 21:35
THP MEDICAL	VASOLAR INV 3	6T2279009018	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
THP MEDICAL	VASOLAR INV 2	6T2279008977	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
THP MEDICAL	VASOLAR INV 1	6T2279009011	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
VINDA PHASE 4 (MSB 3-2)	MASTER LOG HT P4	102595350697	Network Connection Error	Major	19-04-2026 09:24
WASCO PIPE SDN BHD (COATING)	Logger-102516002786	102516002786	Network Connection Error	Major	14-04-2026 16:31
WASCO PIPE SDN BHD (MILL)	Inverter 4	GR2459039441	Grid Loss	Major	19-03-2026 12:46
WASCO PIPE SDN BHD (MILL)	Inverter 1	GR2569103020	Grid Loss	Major	19-03-2026 12:45
WASCO PIPE SDN BHD (MILL)	Inverter 2	GR2569101664	Grid Loss	Major	19-03-2026 12:45
WASCO PIPE SDN BHD (MILL)	Inverter 3	GR2569101626	Grid Loss	Major	19-03-2026 12:44

High-temperature Inverters

Plant Name	Inverter Name	Inverter SN	Temperature
AFI BRAKE MANUFACTURING SDN BHD	INV 4 - GROUND FLOOR	HV22B0337098	78.0
AFI BRAKE MANUFACTURING SDN BHD	INV 5 - FIRST FLOOR	HV22B0337097	78.8
AFI BRAKE MANUFACTURING SDN BHD	INV 7 - THIRD FLOOR	HV22B0337096	71.8
BJC FOOD (MALAYSIA) SDN. BHD.	60KTL-M0(COM1-3)	ES2180084797	71.7
C0156_DENIM CODE	60KTL-M0(COM1-1)	ES2180085464	71.6
CHAN KAH WHYE	INV-NS249G082061	NS249G082061	70.7
Durasafe Sdn. Bhd.	INV 1-6T2479002464	6T2479002464	72.9
Durasafe Sdn. Bhd.	INV 2-6T2469038783	6T2469038783	71.5
Fungiculture	Inverter 1 (M4)	ES22B0007042	71.7

Plant Name	Inverter Name	Inverter SN	Temperature
IOI Mall Puchong (New Wing)	Inverter 16 - TERA	6T2449030262	74.2
KB AIS SDN. BHD.	Inverter-1	6T21C9025324	71.8
Kamma Klang Enterprise	Inverter 2	HV22A0153968	70.9
Kiara Bay	Inverter 4 - TERA	6T2449023252	70.7
Kwang Hua Persendirian meter 2-3-4-5-6	Block B2-Inverter 6 - Meter 6	6T21C9025214	70.6
Marbach Asia Pacific Lot17	INV-6T2489012207	6T2489012207	70.3
P.A Food Sdn Bhd 2ATKT	INV-ES2420001275	ES2420001275	73.2
P.A Food Sdn Bhd Lot 12	INV-6T2449029471	6T2449029471	71.5
RS POLY INDUSTRY	VASOLAR INV 1	ES2420000999	79.4
RS POLY INDUSTRY	VASOLAR INV 2	ES2420001084	72.9
SCENT PUR MANUFACTURING SDN BHD NO.37	INV-NS245G038275	NS245G038275	75.1
SWEE CHEONG WATCH SDN BHD (Meter 1)	INV-TA2470383341	TA2470383341	78.2
SWEE CHEONG WATCH SDN BHD (Meter 2)	INV-TA2470383489	TA2470383489	71.5
SWH INDUSTRIES (PLOT 132113)	VASOLAR INV 6	6T22A9048188	71.5
TOMEI	INV-(12-1)	HV2330348462	71.8
TOMEI	INV-(16-1)	HV2330348376	74.6
TOMEI	INV-(4-1)	HV2330348450	70.3
TOMEI	INV-(4-2)	HV2330348386	70.4
UCS_Block B	10KTL-M1(COM1-12)	BT2240736599	70.2