

FusionSolar Troubleshooting Report

Date: 23-04-2026
Generated At: 23-04-2026 13:58:21
Prepared By: TERA SPMS

Executive Summary

Metric	Value
Total low-performing plants	33
Total alarms	45
Total high-temperature inverters	109

Low-performing Plants

Plant Name	Plant PSH	City Average PSH	Deviation
ASHITA COMMUNICATION	0.00	2.20	-100.00
Advance Vi Tech Lot 1629	1.63	2.20	-26.07
BIMB Bdr Penawar - 1st Floor	0.00	1.35	-100.00
BJC FOOD (MALAYSIA) SDN. BHD.	1.94	2.65	-26.87
BP PLASTICS HQ	1.31	2.42	-45.79
C0172_ATRIA NORTH	0.47	1.71	-72.46
DSG Malaysia Sdn. Bhd	1.99	2.34	-15.08
Dong Sing Food Link Sdn Bhd	2.04	2.38	-14.20
FUJI M3	1.95	2.31	-15.49
IOI Mall Puchong (New Wing) Phase 2	0.00	1.98	-100.00
IOI Mayang Development	1.64	2.40	-31.73
KISWIRE CORD PHASE 1 (DATA)	0.00	1.56	-100.00
KOSSAN PAINT SDN BHD	0.05	2.20	-97.73

Plant Name	Plant PSH	City Average PSH	Deviation
Kwang Hua Persendirian meter 2-3-4-5-6	1.98	2.20	-10.20
Lau and Tan Pharmacy (G.Floor)	1.71	2.12	-19.53
Lian Teck Seng Lot 11	0.00	2.20	-100.00
MAJOR ENGINEERING Lot 10	1.90	2.20	-13.83
MAJOR ENGINEERING Lot 8	0.20	2.20	-90.93
MARINE GOLD SDN BHD	0.00	2.03	-100.00
MENARA PKNS PJ	0.00	1.40	-100.00
Pleasure Latex Phase 2	0.00	1.01	-100.00
QL FARM SDN BHD	0.00	1.04	-100.00
QL FOODS	1.68	2.32	-27.59
Ql Lot 16	2.38	2.65	-10.29
REDANG LAGOON RESORT	0.00	1.72	-100.00
ROYAL KLANG CLUB	1.94	2.20	-12.01
SABAH CHINESE HIGH SCHOOL (TAK YUEN BUILDING)	0.00	1.04	-100.00
SUPERMICRO COMPUTER SDN BHD	1.76	2.00	-12.00
SWEE CHEONG WATCH SDN BHD (Meter 2)	2.68	3.04	-11.94
TIMURIKAN TRENGGANU MARINE PRODUCTS SDN BHD	0.42	1.71	-75.44
Teong Huat Medical	1.51	1.97	-23.48
UCS_Block A	2.12	2.40	-11.75
WEIDA MARKETING SDN. BHD.	2.29	2.75	-16.73

Active Alarms

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
BIMB Bdr Penawar - 1st Floor	Dongle- INV1	BT24C0060244	Network Connection Error	Major	15-04-2026 18:07

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
C0172_ATRIA NORTH	Logger-102140066456	102140066456	Network Connection Error	Major	23-04-2026 10:33
CK PACKAGING AND PLASTIC INDUSTRIES	Logger-102595350776	102595350776	Network Connection Error	Major	23-04-2026 11:08
Fibertex Phase 2	Inverter 2 L3 Old	6T2379019735	Upgrade Failed or Version Mismatch	Minor	18-07-2025 15:24
IOI Mall Puchong (New Wing)	Inverter 14 - TERA	ES2470053866	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing)	Inverter 17 - TERA	6T2479017623	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing)	Inverter 13 - TERA	6T2479017534	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing) Phase 2	Logger-102516002835	102516002835	Network Connection Error	Major	19-04-2026 00:57
IOI Mall Puchong (New Wing) Phase 2	Inverter 4	GR2569071069	Grid Loss	Major	16-04-2026 09:37
IOI Mall Puchong (Old Wing)	Inverter 21 R1-TERA	6T2599057796	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 3 R1 - TERA	BN2521059950	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 12 - TERA	BN2461066801	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 2 - TERA	BN2461066770	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 7 - TERA	6T2479017524	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 10 - TERA	6T2469039407	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 4 - TERA	6T2479017517	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 1 - TERA	BN2461065466	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 5 - TERA	BN2461066760	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 6 - TERA	BN2461066754	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 8 - TERA	BN2461065428	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 11 - TERA	BN2461066739	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 9 - TERA	6T2479017523	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
KILANG BATU BATA	Dongle-TA2510047367	TA2510047367	Network Connection Error	Major	22-04-2026 18:08
Lian Teck Seng Lot 11	Dongle-BT24C0060275	BT24C0060275	Network Connection Error	Major	29-01-2026 15:54
MARINE GOLD SDN BHD	Dongle-TA2340293153	TA2340293153	Network Connection Error	Major	26-03-2026 15:55

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
MARINE GOLD SDN BHD	Dongle-TA2340293476	TA2340293476	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-TA2340291437	TA2340291437	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-HV2310776105	HV2310776105	Network Connection Error	Major	26-03-2026 14:56
MARINE GOLD SDN BHD	Dongle-HV2310776109	HV2310776109	Network Connection Error	Major	26-03-2026 14:55
MARINE GOLD SDN BHD	Dongle-HV2310773587	HV2310773587	Network Connection Error	Major	26-03-2026 14:54
MENARA PKNS PJ	Logger-102466288020	102466288020	Network Connection Error	Major	11-04-2026 01:01
Maxtwo Engineering (Factory)	Dongle-TA2510349523	TA2510349523	Network Connection Error	Major	23-04-2026 11:23
Pengerang Independent Terminal	Dongle-LAB	TA23B0087782	Network Connection Error	Major	20-04-2026 13:52
Pleasure Latex Phase 2	Logger-102347282208	102347282208	Network Connection Error	Major	19-02-2026 03:00
QL PAJAM PHASE 2	INV 5	6T2559006722	Grid Loss	Major	23-04-2026 07:42
QL PAJAM PHASE 2	INV 4	6T2549059627	Grid Loss	Major	23-04-2026 07:42
REDANG LAGOON RESORT	Dongle-2102312EHS10N9115979	2102312EHS10N9115979	Network Connection Error	Major	30-01-2026 19:29
REDANG LAGOON RESORT	INV-ES22A0089681	ES22A0089681	Grid Loss	Major	30-01-2026 07:23
SABAH CHINESE HIGH SCHOOL (TAK YUEN BUILDING)	Logger-102297461092	102297461092	Network Connection Error	Major	21-04-2026 18:17
SIME KANSAI PAINT SDN BHD	INV-ES2550146111	ES2550146111	Upgrade Failed or Version Mismatch	Minor	19-11-2025 21:35
THP MEDICAL	VASOLAR INV 3	6T2279009018	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
THP MEDICAL	VASOLAR INV 2	6T2279008977	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
THP MEDICAL	VASOLAR INV 1	6T2279009011	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
VINDA PHASE 4 (MSB 3-2)	MASTER LOG HT P4	102595350697	Network Connection Error	Major	19-04-2026 09:24
WASCO PIPE SDN BHD (COATING)	Logger-102516002786	102516002786	Network Connection Error	Major	14-04-2026 16:31

High-temperature Inverters

Plant Name	Inverter Name	Inverter SN	Temperature
AFI BRAKE MANUFACTURING SDN BHD	INV 4 - GROUND FLOOR	HV22B0337098	78.8
AFI BRAKE MANUFACTURING SDN BHD	INV 6 - SECOND FLOOR	HV22A0405534	78.3
AFI BRAKE MANUFACTURING SDN BHD	INV 7 - THIRD FLOOR	HV22B0337096	78.1
AMEBA MGMT	INV-HV2290878023	HV2290878023	73.2
AMT PC DISTRIBUTORS SDN. BHD.	INV-6T22B9024620	6T22B9024620	76.6
ATS AIR SOLUTION	INV-HV22A0242778	HV22A0242778	75.5
Apex Uniparts	VASOLAR_INV_1	ES2420001215	75.4
BP PLASTICS BP9	INVERTER 1 (AREA A)	BN24A1093025	70.0
BP PLASTICS BP9	INVERTER 2 (AREA A)	BN24A1093027	72.8
BP PLASTICS BP9	INVERTER 2 (AREA C)	BN24A1084697	73.6
BP PLASTICS BP9	INVERTER 3 (AREA A)	BN24A1093038	72.2
BP PLASTICS BP9	INVERTER 3 (AREA C)	BN24A1081068	72.3
BP PLASTICS BP9	INVERTER 4 (AREA D)	6T24A9018003	73.2
BP PLASTICS BP9	INVERTER 5 (AREA A)	BN24A1092953	70.1
BP PLASTICS BP9	INVERTER 5 (AREA C)	6T24A9018015	78.8
BP PLASTICS BP9	INVERTER 6 (AREA A)	BN24A1093023	71.1
BP PLASTICS BP9	INVERTER 7 (AREA A)	BN24A1093033	71.0
BP PLASTICS BP9	INVERTER 8 (AREA A)	BN24A1093030	70.7
BP PLASTICS BP9	INVERTER 9 (AREA A)	ES24A0149486	82.2
BP PLASTICS BP9	Inverter 1(AREA E)	BN24A1093029	71.3
BP PLASTICS BP9	Inverter 3(AREA E)	BN24A1092994	70.8
BP PLASTICS HQ	Inverter_2	ES2440060550	71.6
BREMFIELD SDN BHD	INV 1	ES2320221246	73.3
BUNCHO (M) SDN BHD	INV-6T2519005159	6T2519005159	74.8

Plant Name	Inverter Name	Inverter SN	Temperature
C0149_VERTEX MISSION	HV21B0210137	HV21B0210137	71.8
C0172_ATRIA SOUTH	Inverter 4(COM2-1)	HV22A0105615	76.8
CHAN KAH WHYE	INV-NS249G082061	NS249G082061	78.4
CIC CONTRACT SDN BHD	INV-HV22A0242777	HV22A0242777	76.0
FOX ONE LOT 8	TERA INVERTER 2	6T25B9000067	74.6
Farm Fresh Taiping (Factory)	50KTL-M3(COM1-12)	6T22A9038815	74.9
Fibertex Phase 2	Inv. CarPark Roof A	ES2420001055	71.8
Fibertex Phase 2	Inverter 1 L3	6T23A9016283	71.3
Fibertex Phase 2	Roof 2C Bridge R1	6T2469046697	73.1
Fungiculture	Inverter 1 (M4)	ES22B0007042	70.3
Fungiculture	Inverter 2 (M3)	HV22B0337400	75.2
Fungiculture	Inverter 2 (M4)	HV22B0004571	71.6
Fungiculture	Inveter 2 (M1)	HV22B0337398	72.3
GLASS PLASTIC PACKAGING	INV 2 - (No.23)	6T2489010546	73.3
GLASS PLASTIC PACKAGING	INV 3 - (Lot 65999)	6T2489010635	74.6
GLASS PLASTIC PACKAGING	INV 4 - (Lot 65999)	6T2489010593	73.5
Hoon Yuen Furniture	Inverter 1	ES22B0024091	71.1
IOI City Mall Inc. Feeder 1	Inverter 2.6 - TERA	6T22C9011480	70.4
IOI Mall Puchong (New Wing)	Inverter 15 - TERA	ES2330107601	72.1
IOI Mall Puchong (New Wing)	Inverter 16 - TERA	6T2449030262	77.2
IOI Mall Puchong (Old Wing)	Inverter 20 - TERA	6T24C9047414	71.8
IOI Mall Puchong (Old Wing)	Inverter 6 - TERA	BN2461066754	70.7
IOI Mall Puchong (Old Wing)	Inverter 7 - TERA	6T2479017524	71.0
IOI Mall Puchong (Old Wing)	Inverter 9 - TERA	6T2479017523	70.5

Plant Name	Inverter Name	Inverter SN	Temperature
Jebsen And Jessen Malaysia Sdn Bhd (MHE)	Inverter 2 - Tera	6T2489031215	70.7
Jiann Lih safety product	40KTL-M3(COM1-15)	ES2290059762	85.3
Jiann Lih safety product	40KTL-M3(COM1-16)	ES2290059727	88.3
KB AIS SDN. BHD.	Inverter-1	6T21C9025324	70.4
KUASA BAKTI (PETRON SETIA ALAM)	INV-6T2489035314	6T2489035314	77.7
Kamma Klang Enterprise	Inverter 1	ES22A0088766	76.6
Kamma Klang Enterprise	Inverter 2	HV22A0153968	78.8
Kiara Bay	Inverter 3 - TERA	6T2449022934	71.9
Kwang Hua Persendirian meter 2-3-4-5-6	Block B2-Inverter 6 - Meter 6	6T21C9025214	72.3
LKW FROZEN SDN BHD	VASOLAR_INV_1	6T22A9046185	71.1
Marbach Asia Pacific Lot17	INV-6T2489012207	6T2489012207	75.7
Marbach Asia Pacific lot 15	INV-6T2489012205	6T2489012205	76.5
Mitsui Copper Foil P3	Inverter 1 (AREA A)	GR2459039442	77.8
Mitsui Copper Foil P3	Inverter 2 (AREA A)	GR2459039444	78.0
Mitsui Copper Foil P3	Inverter 3 (AREA A)	6T24A9009773	83.5
Mitsui Copper Foil P3	Inverter 4 (AREA A)	6T24A9013004	84.4
Mitsui Copper Foil P3	Inverter 5 (AREA B)	6T2519017589	76.8
Multi Choice (M) Sdn Bhd	TERA INV 3	ES2560208616	78.6
New Age 160	INV 1	6T2469012777	73.6
New Age 160	Inverter 2 R1	6T23B9005979	79.4
New Age 160	Inverter 3-36ktl m3	6T2489036764	76.9
P.A Food Sdn Bhd 2ATKT	INV-ES2420001275	ES2420001275	78.2
P.A Food Sdn Bhd Lot 10	INV-6T2449029469	6T2449029469	74.0
P.A Food Sdn Bhd Lot 12	INV-6T2449029471	6T2449029471	74.5

Plant Name	Inverter Name	Inverter SN	Temperature
P.A. Food Warehouse No. 9	INV-HV2290797189	HV2290797189	74.9
PKT THE SHIP	Inverter_1	6T2379018298	72.3
PKT THE SHIP	Inverter_2 R1	BN2531021024	71.3
PKT THE SHIP	Inverter_3	6T2379019623	72.5
PKT THE SHIP	Inverter_6	6T2379019622	70.6
PKT THE SHIP	Inverter_8 R1	ES24C0173071	74.7
Pengerang Independent Terminal	VASOLAR INV 4 CP 2	6T23A9016705	73.4
Pengerang Independent Terminal	VASOLAR INV7 MC	ES2340146422	83.2
QL ENDAU DEEP SEA FISHING	Inverter 1 (COM1-12)	GR2479028683	79.5
QL ENDAU DEEP SEA FISHING	Inverter 2 (COM3-13)	6T2519005200	81.0
QL ENDAU DEEP SEA FISHING	Inverter 3 (COM3-14)	GR2479020699	75.5
QL ENDAU DEEP SEA FISHING	Inverter 4 (COM3-15)	GR2479020734	74.4
QL ENDAU DEEP SEA FISHING	Inverter 5 (COM3-16)	GR2479028681	80.1
QL ENDAU MARINE	TERA - INV 1	6T2449018663	70.8
QL ENDAU MARINE	TERA - INV 2	6T24C9071297	80.3
QL ENDAU MARINE	TERA - INV 4	GR2479026771	76.0
QI Lot 14	INV-ES24A0149129	ES24A0149129	75.8
QI Lot 16	INV-ES24A0149130	ES24A0149130	75.7
ROYAL KLANG CLUB	Inverter 1	6T2559006760	73.2
RS POLY INDUSTRY	VASOLAR INV 1	ES2420000999	80.7
RS POLY INDUSTRY	VASOLAR INV 2	ES2420001084	76.4
SCENT PUR MANUFACTURING SDN BHD NO.37	INV-NS245G038275	NS245G038275	76.9
SJK ■ C ■ PIN HWA 1	INVERTER-2	ES2560208642	81.5
SP Logistics Sdn Bhd	INV-6T23B9005457	6T23B9005457	73.4

Plant Name	Inverter Name	Inverter SN	Temperature
SWEE CHEONG WATCH SDN BHD (Meter 1)	INV-TA2470383341	TA2470383341	72.0
SWEE CHEONG WATCH SDN BHD (Meter 2)	INV-TA2470383489	TA2470383489	70.4
Succesfuel Sdn. Bhd.	INVERTER 1 R1	6T24C9072224	76.7
THOR SPECIALTIES	INV-ES25C0123936	ES25C0123936	80.4
TOMEI	INV-(16-1)	HV2330348376	80.9
TOMEI	INV-(4-3)	HV2330348461	74.9
VINDA PHASE 4 (MSB 3-2)	Inverter11 - Phase 4	GR2479020739	70.8
VINDA PHASE 4 (MSB 3-2)	Inverter13 Phase4 R1	ES2580050563	72.9
VINDA PHASE 4 (MSB 3-2)	Inverter14 - Phase 4	6T24C9071357	72.6
VINDA PHASE 4 (MSB 3-2)	Phase4 Inverter 8 R1	6T2489038090	75.3
VINDA PHASE 4 (MSB 3-2)	Phase4 Inverter 9 R1	6T2489040944	73.4
Vinda Phase 1 and 2 (MSB 2)	Inverter 7 - Phase 1	6T21C9025215	71.4
WCS UNIT 6	INVERTER UNIT 6	HV2290931617	72.6