

FusionSolar Troubleshooting Report

Date: 27-04-2026
Generated At: 27-04-2026 16:15:41
Prepared By: TERA SPMS

Executive Summary

Metric	Value
Total low-performing plants	30
Total alarms	53
Total high-temperature inverters	69

Low-performing Plants

Plant Name	Plant PSH	City Average PSH	Deviation
ASHITA COMMUNICATION	0.00	2.71	-100.00
BIMB Bdr Penawar - 1st Floor	0.00	1.76	-100.00
BJC FOOD (MALAYSIA) SDN. BHD.	2.37	3.43	-30.82
BM COCO PALM	1.80	2.06	-12.62
Dong Sing Food Link Sdn Bhd	0.00	2.85	-100.00
FUJI M3	2.56	3.01	-15.02
IOI City Mall Inc. Feeder 1	0.00	2.27	-100.00
IOI Mall Puchong (New Wing) Phase 2	0.00	2.70	-100.00
KISWIRE CORD PHASE 1 (DATA)	0.00	1.54	-100.00
KOSSAN PAINT SDN BHD	0.77	2.71	-71.57
Kwang Hua Persendirian meter 2-3-4-5-6	2.31	2.71	-14.71
LAM SOON EDIBLE OILS	0.00	1.85	-100.00
LEAN GIAP ENTERPRISE SDN BHD	2.22	2.70	-17.68

Plant Name	Plant PSH	City Average PSH	Deviation
Lian Teck Seng Lot 11	0.00	2.71	-100.00
MAJOR ENGINEERING Lot 8	0.81	2.71	-70.09
MARINE GOLD SDN BHD	0.00	2.49	-100.00
MENARA PKNS PJ	0.00	1.97	-100.00
Menara PJD	0.00	2.24	-100.00
Pleasure Latex Phase 2	0.00	1.50	-100.00
QL FARM SDN BHD	0.00	1.16	-100.00
REDANG LAGOON RESORT	0.00	1.43	-100.00
SABAH CHINESE HIGH SCHOOL (TAK YUEN BUILDING)	0.00	1.16	-100.00
SP Logistics Sdn Bhd	0.79	2.71	-70.83
SWEE CHEONG WATCH SDN BHD (Meter 2)	3.07	3.54	-13.20
TIMURIKAN TRENGGANU MARINE PRODUCTS SDN BHD	0.51	2.25	-77.33
UCS_Block A	0.00	2.30	-100.00
UCS_Block B	0.00	2.30	-100.00
UCS_Block C	0.00	2.30	-100.00
WASCO PIPE SDN BHD (MILL)	0.60	1.00	-40.30
WEIDA MARKETING SDN. BHD.	3.25	3.87	-16.02

Active Alarms

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
BIMB Bdr Penawar - 1st Floor	Dongle- INV1	BT24C0060244	Network Connection Error	Major	15-04-2026 18:07
BJC FOOD (MALAYSIA) SDN. BHD.	60KTL-M0(COM1-3)	ES2180084797	Low Insulation Resistance	Major	27-04-2026 07:36
Dong Sing Food Link Sdn Bhd	Inverter(COM2-1)	ES2570023845	Grid Loss	Major	27-04-2026 06:50
Fibertex Phase 2	Inverter 2 L3 Old	6T2379019735	Upgrade Failed or Version Mismatch	Minor	18-07-2025 15:24

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
IOI Mall Puchong (New Wing)	Inverter 14 - TERA	ES2470053866	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing)	Inverter 17 - TERA	6T2479017623	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing)	Inverter 13 - TERA	6T2479017534	Upgrade Failed or Version Mismatch	Minor	17-04-2026 23:52
IOI Mall Puchong (New Wing) Phase 2	Logger-102516002835	102516002835	Network Connection Error	Major	19-04-2026 00:57
IOI Mall Puchong (New Wing) Phase 2	Inverter 4	GR2569071069	Grid Loss	Major	16-04-2026 09:37
IOI Mall Puchong (Old Wing)	Inverter 21 R1-TERA	6T2599057796	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 3 R1 - TERA	BN2521059950	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 12 - TERA	BN2461066801	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 2 - TERA	BN2461066770	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 7 - TERA	6T2479017524	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 10 - TERA	6T2469039407	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 4 - TERA	6T2479017517	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 1 - TERA	BN2461065466	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 5 - TERA	BN2461066760	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 6 - TERA	BN2461066754	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 11 - TERA	BN2461066739	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 8 - TERA	BN2461065428	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
IOI Mall Puchong (Old Wing)	Inverter 9 - TERA	6T2479017523	Upgrade Failed or Version Mismatch	Minor	18-04-2026 00:46
LAM SOON EDIBLE OILS	Dongle-BT24C0060212	BT24C0060212	Network Connection Error	Major	26-04-2026 20:51
LIAN FOO POULTRY FARM SDN BHD	Dongle-BT2541519026	BT2541519026	Network Connection Error	Major	26-04-2026 15:20
Lian Teck Seng Lot 11	Dongle-BT24C0060275	BT24C0060275	Network Connection Error	Major	29-01-2026 15:54
MARINE GOLD SDN BHD	Dongle-TA2340293153	TA2340293153	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-TA2340293476	TA2340293476	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-TA2340291437	TA2340291437	Network Connection Error	Major	26-03-2026 15:55

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
MARINE GOLD SDN BHD	Dongle-HV2310776105	HV2310776105	Network Connection Error	Major	26-03-2026 14:56
MARINE GOLD SDN BHD	Dongle-HV2310776109	HV2310776109	Network Connection Error	Major	26-03-2026 14:55
MARINE GOLD SDN BHD	Dongle-HV2310773587	HV2310773587	Network Connection Error	Major	26-03-2026 14:54
MENARA PKNS PJ	Logger-102466288020	102466288020	Network Connection Error	Major	11-04-2026 01:01
Menara PJD	Logger-102347282182	102347282182	Network Connection Error	Major	25-04-2026 01:26
Pengerang Independent Terminal	Dongle-LAB	TA23B0087782	Network Connection Error	Major	20-04-2026 13:52
Pleasure Latex Phase 2	Logger-102347282208	102347282208	Network Connection Error	Major	19-02-2026 03:00
QL FARM SDN BHD	Logger-102466853213	102466853213	Network Connection Error	Major	24-04-2026 10:56
QL FARM SDN BHD	Inverter 2	ES2580051643	Grid Loss	Major	24-04-2026 10:07
QL FARM SDN BHD	Inverter 1	ES2580051653	Grid Loss	Major	24-04-2026 10:07
QL FARM SDN BHD	Inverter3	ES2490076207	Grid Loss	Major	24-04-2026 10:07
REDANG LAGOON RESORT	Dongle-2102312EHS10N9115979	2102312EHS10N9115979	Network Connection Error	Major	30-01-2026 19:29
REDANG LAGOON RESORT	INV-ES22A0089681	ES22A0089681	Grid Loss	Major	30-01-2026 07:23
SABAH CHINESE HIGH SCHOOL (TAK YUEN BUILDING)	Logger-102297461092	102297461092	Network Connection Error	Major	21-04-2026 18:17
SIME KANSAI PAINT SDN BHD	INV-ES2550146111	ES2550146111	Upgrade Failed or Version Mismatch	Minor	19-11-2025 21:35
SP Logistics Sdn Bhd	INV-6T23B9005457	6T23B9005457	The PV string is short-circuited to the ground.	Major	27-04-2026 06:45
THP MEDICAL	VASOLAR INV 3	6T2279009018	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
THP MEDICAL	VASOLAR INV 2	6T2279008977	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
THP MEDICAL	VASOLAR INV 1	6T2279009011	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
UCS_Block A	Logger-1	102140066592	Network Connection Error	Major	26-04-2026 19:09
UCS_Block B	10KTL-M1(COM1-12)	BT2240736599	Grid Loss	Major	26-04-2026 18:40
UCS_Block B	100KTL-M1(COM1-13)	6T2159043021	Grid Loss	Major	26-04-2026 18:40
UCS_Block C	100KTL-M1(COM1-12)	6T2159043011	Grid Loss	Major	26-04-2026 18:59

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
UCS_Block C	60KTL-M0(COM1-13)	6T2159040503	Grid Loss	Major	26-04-2026 18:59
WASCO PIPE SDN BHD (COATING)	Logger-102516002786	102516002786	Network Connection Error	Major	14-04-2026 16:31

High-temperature Inverters

Plant Name	Inverter Name	Inverter SN	Temperature
AFI BRAKE MANUFACTURING SDN BHD	INV 4 - GROUND FLOOR	HV22B0337098	72.9
AFI BRAKE MANUFACTURING SDN BHD	INV 5 - FIRST FLOOR	HV22B0337097	76.5
AFI BRAKE MANUFACTURING SDN BHD	INV 6 - SECOND FLOOR	HV22A0405534	72.4
AFI BRAKE MANUFACTURING SDN BHD	INV 7 - THIRD FLOOR	HV22B0337096	72.5
AMT PC DISTRIBUTORS SDN. BHD.	INV-6T22B9024620	6T22B9024620	70.7
ASIA WIRE STEEL MESH MANUFACTURERS SDN BHD	Inverter(COM3-13)	ES2550064305	70.7
ASIA WIRE STEEL MESH MANUFACTURERS SDN BHD	Inverter(COM3-14)	ES2550064253	71.0
ASIA WIRE STEEL MESH MANUFACTURERS SDN BHD	Inverter(COM3-15)	ES2550064258	74.1
BREMFIELD SDN BHD	INV 1	ES2320221246	71.5
C0172_ATRIA SOUTH	Inverter 4(COM2-1)	HV22A0105615	72.0
CHAN KAH WHYE	INV-NS249G082061	NS249G082061	86.6
Durasafe Sdn. Bhd.	INV 1-6T2479002464	6T2479002464	72.6
FOX ONE LOT 8	TERA INVERTER 2	6T25B9000067	77.2
Fibertex Phase 2	Inverter 1 L3	6T23A9016283	72.6
Fibertex Phase 2	Roof 2C Bridge R1	6T2469046697	70.0
GLASS PLASTIC PACKAGING	INV 2 - (No.23)	6T2489010546	76.1
GLASS PLASTIC PACKAGING	INV 3 - (Lot 65999)	6T2489010635	71.5
GLASS PLASTIC PACKAGING	INV 4 - (Lot 65999)	6T2489010593	75.2
IOI Knowledge Vision Sdn Bhd	Tera Inverter 1	NS2481218152	71.0

Plant Name	Inverter Name	Inverter SN	Temperature
IOI Mall Puchong (New Wing)	Inverter 16 - TERA	6T2449030262	73.0
Jiann Lih safety product	40KTL-M3(COM1-15)	ES2290059762	76.2
Jiann Lih safety product	40KTL-M3(COM1-16)	ES2290059727	80.2
KISWIRE CORD SDN BHD	VASOLAR_INV_10	6T2269040723	73.1
KISWIRE CORD SDN BHD	VASOLAR_INV_11	6T21A9008894	71.0
KISWIRE CORD SDN BHD	VASOLAR_INV_12	HV22A0243263	73.1
KUASA BAKTI (PETRON SETIA ALAM)	INV-6T2489035314	6T2489035314	73.5
Kamma Klang Enterprise	Inverter 2	HV22A0153968	72.6
Kiara Bay	Inverter 2 - TERA	ES2330110574	74.0
Kiara Bay	Inverter 3 - TERA	6T2449022934	78.3
Kiara Bay	Inverter 4 - TERA	6T2449023252	76.1
Kiara Bay	Inverter 6 - TERA	ES2350101155	74.8
Kiara Bay	Inverter 9 - TERA	ES2350101147	74.9
Komplex PKNS Bangi	40KTL-M3(COM1-13)	ES22A0040484	75.4
Marbach Asia Pacific Lot17	INV-6T2489012207	6T2489012207	73.5
Marbach Asia Pacific lot 15	INV-6T2489012205	6T2489012205	75.9
Mitsui Copper Foil P3	Inverter 1 (AREA A)	GR2459039442	75.3
Mitsui Copper Foil P3	Inverter 2 (AREA A)	GR2459039444	76.3
Mitsui Copper Foil P3	Inverter 3 (AREA A)	6T24A9009773	82.6
Mitsui Copper Foil P3	Inverter 4 (AREA A)	6T24A9013004	82.1
Mitsui Copper Foil P3	Inverter 5 (AREA B)	6T2519017589	75.1
Multi Choice (M) Sdn Bhd	TERA INV 3	ES2560208616	76.4
New Age 160	INV 1	6T2469012777	71.1
New Age 160	Inverter 2 R1	6T23B9005979	79.3

Plant Name	Inverter Name	Inverter SN	Temperature
New Age 160	Inverter 3-36ktl m3	6T2489036764	74.9
P.A Food Sdn Bhd 2ATKT	INV-ES2420001275	ES2420001275	72.8
PKT 8 WAVES	Inverter_2	6T2439012020	70.4
QL ENDAU DEEP SEA FISHING	Inverter 1 (COM1-12)	GR2479028683	74.0
QL ENDAU DEEP SEA FISHING	Inverter 2 (COM3-13)	6T2519005200	78.6
QL ENDAU DEEP SEA FISHING	Inverter 3 (COM3-14)	GR2479020699	71.1
QL ENDAU DEEP SEA FISHING	Inverter 4 (COM3-15)	GR2479020734	74.8
QL ENDAU DEEP SEA FISHING	Inverter 5 (COM3-16)	GR2479028681	76.7
QL ENDAU MARINE	TERA - INV 2	6T24C9071297	80.5
QL ENDAU MARINE	TERA - INV 4	GR2479026771	74.2
QL FOODS	INVERTER_7	6T22A9046723	70.3
QL PAJAM PHASE 2	INV 5	6T2559006722	72.0
QI Lot 14	INV-ES24A0149129	ES24A0149129	76.7
QI Lot 16	INV-ES24A0149130	ES24A0149130	75.6
ROYAL KLANG CLUB	Inverter 1	6T2559006760	74.8
SCENT PUR MANUFACTURING SDN BHD NO.37	INV-NS245G038275	NS245G038275	76.5
SJK (C) WU TECK	INV 1	6T25B9000135	80.7
SJK ■ C ■ PIN HWA 1	INVERTER-1	ES2550146112	70.4
SJK ■ C ■ PIN HWA 1	INVERTER-2	ES2560208642	82.9
SM Chung Chung Hua (PSDN) Klang	60KTL-M0(COM1-4)	ES2190080965	72.9
SM Chung Chung Hua (PSDN) Klang	60KTL-M0(COM1-5)	ES2190075672	70.4
San Soon Seng Food Industries Sdn Bhd	Inv 02 (Racking WH)	6T2549057201	74.0
Succesfuel Sdn. Bhd.	INVERTER 1 R1	6T24C9072224	74.6
THOR SPECIALTIES	INV-ES25C0123936	ES25C0123936	73.8

Plant Name	Inverter Name	Inverter SN	Temperature
TOMEI	INV-(16-1)	HV2330348376	73.7
WCS UNIT 6	INVERTER UNIT 6	HV2290931617	71.4