

D-ATIS(Chinese) 127.0
D-ATIS(English) 128.6
Delivery01 121.95(DCL AVBL)
Delivery02 122.175(DCL AVBL)


GND(East one)	121.75 (122.125)
GND(East two)	121.6 (122.125)
GND(East three)	121.55 (122.125)
GND(West one)	121.85 (122.125)
GND(West two)	121.65 (122.125)

APN(East one) 121.825(121.975)
APN(East two) 121.625(121.7)
APN(East three) 121.7(121.625)
APN(West) 121.775(121.975)

TWR(01L/19R)	118.8(118.875)
TWR(01R/19L)	118.325(118.875)
TWR(02L/20R)	123.55(118.875)
TWR(02R/20L)	118.25(118.875)
TWR(03/21)	118.1(118.875)

Taxiing Routes Chart (RWY01L Arrival)

1. Controllers shall direct arriving aircraft to join other taxiways at intermediate nodes or endpoints of standard taxi routes based on their parking stands.
2. When controllers instruct an aircraft to join another taxiway at an intermediate node of the standard taxi route, it indicates the cancellation of the remaining portion of the previously issued standard taxi route.
3. For GREEN7 route: After Taxiway N, ensure correct entry to Taxiway T12. Crews must observe surface markings to avoid incorrect taxiing.



ID	Description	Runway
GREEN 7	N-T12-H-H2-E-T3-(turn left to join)B-B2-Q-T64	RWY01L

Changes: Adjust construction area and APN(East one).