PN	Description	Manual Ref	Symbol Ref
8A3115/8A1782	3rd stage disk	Task # 72-53-30-440-001 1 A &B (1)	H or with number
8A2154/8A1783	3rd stage Support	Task # 72-53-30-440-001 1 A &B (2)	H or <equation-block> with number</equation-block>
8A1013/8A2167	3rd stage Airseal	Task # 72-53-30-440-001 1 A &B (3)	H or with number
8A3119/8A2910/8A2137/8A1024/8A1534	4th Stg Disk	Task # 72-53-40-440-001 1 A & B (1)	H or <equation-block> with number</equation-block>
8A2094/8A1014/8A1805/8A2139/8A2140	4th Stg Airseal	Task # 72-53-40-440-001 1 A & B (2)	H or with number
8A3116/8A1025/8A2138	5th Stg Disk	Task # 72-53-50-440-001 1 A & B (1)	H or 🛆 with number
8A2095/8A1015/8A1806/8A2141/8A2142	5th Stg Airseal	Task # 72-53-50-440-001 1 A & B (2)	H or with number
8A3058/8A1046/8A3064/A8A1046	6th Stg Disk	Task # 72-53-60-440-001 1 A & B (1)	H or 🛆 with number
8A2806	6th Stg Airseal	Task # 72-53-60-440-001 1 A & B (2)	H or with number
8A3059/8A2166/8A2151/8A2150/8A1047/8A1027	7th Stg Disk	Task # 72-53-70-440-001 1 A & B (1)	H or with number
8A2807/8A2097/A8A2097/A8A1808/A8A1017	7th Stg Airseal	Task # 72-53-70-440-001 1 A & B (2)	H or Wwith number

Usually there should not be multiple markings on the same part. But it is possible that the highpoint "wanders" when working on the flange so that the old highpoint could be crossed.

If there is a marking available already, MTU relies on that marking. No need to issue a new one.

Highpoint will be noted on 8130

^{**}Start date for High Point 8130s after December 2020 to add the above specific requirement to PO's moving forward