



Unison Industries LLC 2070 Heller Road Alpha, OH 45301-0217 Ph: 937-490-7428

Notwithstanding the standard statement on SkyWest Work Orders, Unison Industries LLC is authorized to perform the following repair listed below using data produced or obtained by Unison Industries LLC.

Item	Repair Number	Data Producer	Repair Classification/ M-337A Required
Anti-Ice Inlet Tube PN 14C0710001	Repair Log 079 Dated 3-30-2007 Rev 00	Unison Industries LLC	Minor/No
Tube Repair PN's 14E0146001, 14E0228001, 15E2146001, 15E2147001, 15E2148001, 15E2149001, 15E2150001, 15E2151001, 15E2001, 15E2153001	Repair Log 081 Dated 1-23-2020 Rev E	Unison Industries LLC	Minor/No
**Pneumatic Air Tube Repair PN's 14E0904001, 15E0103003, 15E0158001, 15E0903001, 15E2121001	Repair Log 076 Dated 8-18-2017 Rev C	Unison Industries LLC	Minor/No
*Anti-Ice Tubes PN's 14E0163003, 14E0164005	Repair Log 77 Dated 8-14-2006 Rev IR	Unison Industries LLC	Minor/No
*Support Links PN's 14E0114001, 14E0115016, 15E0115006, 15E0115009	Repair Log 91 Dated 3-02-2012 Rev IR	Unison Industries LLC	Minor/No

^{*}Addition this letter

If you desire to use any other repairs for maintenance on SkyWest components, please contact us in advance for approval. SkyWest requires that we review the data prior to giving approval to use the data. Repair overhaul vendors are required to possess or be capable of accessing the data as approved on SkyWest's letter. SkyWest will not share this data as it may be proprietary to the data developer.

If you have any questions or concerns don't hesitate to contact me.

Sincerely,

SkyWest Airlines

Jim Thompson, Engineering Coordinator

435-634-3849

jthompson@skywest.com

Cc: Unison Industries LLC.

^{**}Revision this letter