

Customer Requirements			
Revision Date:	November 10, 2022	Previous Revision Date:	August 3, 2021
Division #:	1, 7, 11	Customer #:	21559 & 856
# of Pages:	1	QC Approved By:	Andy Sanders
United Parcel Service (UPS)			

Certification Requirements

UPS requires a Certified True Copy Spit Stamp for any quantity reductions.

PW2000 Fan Blades E.O. / AD Requirement

Require UPS E.O. noted on the Airworthiness Release Certificate (ARC) <u>and</u> the Dirty Fingerprints (DFP) for single blades <u>and</u> blade set/pair.

When an AD is present/applicable, AD must be noted on single blade ARC/DFP **and** blade set/pair ARC/DFP.

Example of UPS EO: C-7200-5057-K

All Orders

E.O. Not Required on New, Factory New, Repairable, and As-Is part conditions.

All other UPS Orders will require narrative instructions per below:

- *E.O. Required* Copy of E.O. should be scanned against the order and QC to verify that E.O. is noted on the ARC Form.
- *E.O. Not Required* No need for QC to verify E.O. compliance on ARC.
- *No Narrative Instructions* = Non-Conformance Report (NCR)