

Customer Requirements			
Revision Date:	10/5/11	Previous Revision Date:	8/25/10
Division #:	11	Customer #:	99226
# of Pages:	1	QC Approved By:	Bill Petersen

Snecma America Engine Services (SAMES)

- Traceability must go back to the last Airline operator.
- An 8130-3 and/or an EASA Form One must be supplied on all new material.
- SAMES requires a dual release on overhauled and serviceable parts. These certificates must have been issued within the past 12 months for LLPs and 24 months for non-LLPs.
- SAMES requires a certified true copy stamp (reflecting the quantity being supplied) if the 8130-3 quantity is split. This applies even if they are purchasing the remaining quantity and are being provided with the original 8130-3.
- SAMES cannot accept PMA parts.
- SAMES cannot accept FAA DER repairs.