

Customer Requirements			
<b>Revision Date:</b>	9/19/2011	<b>Previous Revision Date:</b>	8/11/11
Division #:	11	Customer #:	73870
# of Pages:	1	QC Approved By:	Bill Petersen

## **Evergreen Aviation Tech (EGAT)**

- No thermal shields (P/N 9315M41P20) will be accepted with S/N prefix "BTA"
- EGAT will not accept repair code GE or GR22 for CF6-80C HPT 1 & 2 blades
- EGAT will not accept Lufthansa Technik repaired airfoils if repaired under the Advanced Recontouring Process ARP.