Approving Civil / Authority/Countr FAA/United Stat	y:	2011년 2015년 - 1211년 -	RELEASE CERTII	3. Form Tracking Number: Q.A1694-668-2015				
4. Organization Na	me and Address:				5. Work Order/Contract/Invoice Number: 2015E-668			
6. Item: 7. De:	scription:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:			
1.	ENGINE	CFM56-	5B2/P 1EA.	575744	REPAIRED			
3. ENGINE WAS I 4. ENGINE BORE 5. ENGINE OIL AN 6. PRIOR TO ENG	SCOPE CHECK CARRIED OUT. ID FUEL SYSTEMS PRESERVE INE TEST RUN ON A/C, THE EI	STED AS REQUIRED IN ACCORDANCE WITH ENGI- I.A.W. ENGINE SHOP MANUAL P/N: CFMI-TP.NT.11 D FOR 365 DAYS I.A.W ESM ESM TASK 72-00-00-50 NGINE AND ENGINE DRIVEN COMPONENTS SHOU OLLOWING Q.E.C. INSTALLATION.	REV.38 NOV 30, 2011. 00-001-0. EXPIRY DATE DEC 30, 20	016.				
13a. Certifies the I	ems identified above were manu	factured in conformity to:	14a. 🛛 14 CFR 43.9 Return	to Service Other regulat	ion specified in Block 12			
1000	ad design data and are in a condi proyed design data specified in B	AND CONTRACTOR OF THE PROPERTY	Certifies that unless otherwise described in Block 12 was acc Regulations, part 43 and i	dentified in Block 11 and de 14, Code of Federal approved for return to service.				
13b. Authorized S	gnature:	13c Approval/Authorization No.;	14b. Authorized Signature		14c. Approval/Certificate No.:			
13d. Name (Type	or Printed):	13e. Date (dd/mmm/yyyy):	14d. Name (Typed or Printed):		14e. Date (dd/mmm/yyyy):			
					03/JAN/2016			
		User / Insta	aller Responsibilities					
Where the user/in specified in Block of the country spe Statements in Block	estaller performs work in accordant 1, it is essential that the user/instactified in Block 1.	nis document alone does not automatically constitute ance with the national regulations of an airworthiness autaller ensures that his/her airworthiness authority acceptions installation certification. In all cases, aircraft maintenater/installer before the aircraft may be flown.	thority different than the airworthinesepts aircraft engine(s)/propeller(s)/artic	s authority of the country cle(s) from the airworthiness auth	nority			

FAA From 8130-3 (02-14) NSN: 0052-00-012-9005

FAA CRS No. MK1 Y325K EASA APPROVAL No. 145.0029 C.A.A.I - 01

LIFE LIMITED PARTS FOR A CFM56-5B2/P ENGINE

ENGINE S/N:

575744

OWNER/CUSTOMER:

DATE: TIME LIMITS MANUAL:

ENGINE WORK RECORD NO.

NOV.30,2015 SM.9 REV 66. 2015E-668

FIRST LIMITATION CYC. FAN DISK. 10003 CYC.

TSN: 23148:00 CSN: 19,997 TSLSV: 00 0

CSLSV:

			TOTAL	TOTAL		T	OTAL CYC	LES			CYCLES LIMIT		MIT			REMAINING C'		YCLES		
DESCRIPTION	PART NO	SER NO.	HOURS	CYCLES	3B1	5B2/P	5B6/P	5B4/P	5C4	5B2/P	5B6/P	5B4/P	5C4	B not/P	5B2/P	5B6/P	5B4/P	5C4	B not/P	REMARKS
FAN & BOOSTER MOD.		21X75744	23148:00	19,997						10/22 1 1 1 1 1 2						99.1				
FAN DISK	338-001-504-0	BC061631	23148:00	19,997	0	0	19997			30,000	30,000	30,000	-	-	10,003	10,003	10,003	-		
BOOSTER SPOOL	338-001-906-0	BB962897	23148:00	19,997	0	0	19997			30,000	30,000	30,000	-		10,003	10,003	10,003	**	-	
FAN SHAFT	338-010-601-0	DC548436	23148:00	19,997	0	0	19997			30,000	30,000	30,000		- 2	10,003	10,003	10,003	140	-	
HPC. ROTOR MOD.		31X75744	23148:00	19,997			350 1110											200	Jan Lie	
COMP. ROT. FRONT SHAFT	1386M56P03	NCU28185	NEW	NEW	0	0	0	0	0	20,000	20,000	20,000	-	-	20,000	20,000	20,000			
COMP. ROT. 1-2 SPOOL STG.	1558M31G07	FGB0A6EN	NEW	NEW	0	0	0	0	0	20,000	20,000	20,000	-		20,000	20,000	20,000			SB72-0655 C/W
COMP. ROT. DISK 3RD STG.	2116M23P01	XAEDV139	NEW	NEW	0	0	0	0	0	20,000	20,000	20,000		-	20,000	20,000	20,000			SB72-0654 C/W
COMP. ROT. SPOOL 4-9 STG.	2048M20G04	GWNOWNMG	NEW	NEW	0	0	0	0	0	20,000	20,000	20,000	-	15	20,000	20,000	20,000	-		SB72-0652 C/W
REAR COMP. (CDP) AIR SEAL	2116M25P01	GFF5J3KP	NEW	NEW	0	0	0	0	0	20,000	20,000	20,000	-	-	20,000	20,000	20,000	-		SB72-0652 C/W
HPT. ROTOR MOD.		52X75744	23148:00	19,997			- 2010						-						1928	
HPT. FRONT SHAFT	2048M21P03	FCV02V54	NEW	NEW.	0	0	0	0	0	20,000	20,000	20,000			20,000	20,000	20,000		-	
HPT. FRONT AIR SEAL	2116M20P02	TMT3T905	NEW	NEW	0	0	0	0	0	20,000	20,000	20,000	-		20,000	20,000	20,000	-		SB72-0652 C/W
HPT. DISK	1498M43P07	GWN0WN22	NEW	NEW	0	0	0	0	0	20,000	20,000	20,000			20,000	20,000	20,000			SB72-0652 C/W
HPT. REAR SHAFT	1864M90P04	TMTD1589	NEW	NEW	0	0	0	0	0	20,000	20,000	20,000	-	18	20,000	20,000	20,000			SB72-0652 C/W
LPT. ROTOR MOD.			23148:00	19,997			600	955- 1-3	100	100						001				
LPT DISK 1ST. STG.	336-001-804-0	PC304348	NEW	NEW	0	0	0	0	0	25,000	25,000	25,000			25,000	25,000	25,000			
LPT DISK 2ND STG.	336-001-909-0	PC308001	NEW	NEW	0	0	0	0	0	25,000	25,000	25,000		=	25,000	25,000	25,000	**	-	
LPT DISK 3RD STG.	336-002-006-0	PC315039	NEW	NEW	0	0	0	0	0	25,000	25,000	25,000	-		25,000	25,000	25,000		-	
LPT DISK 4TH STG.	336-002-105-0	PC302608	NEW	NEW	0	0	0	0	0	25,000	25,000	25,000	-		25,000	25,000	25,000		-	
CONICAL SUPPORT	340-301-702-0	DK266393	NEW	NEW	0	0	0	0	0	25,000	25,000	25,000	-	-	25,000	25,000	25,000			
LPT CASE	338-117-455-0	DC503877	23148:00	19,997	0	0	19,997	0	0	N/L	N/L	N/L	-							SB72-589 & 706 C/W
LPT SHAFT	338-010-005-0	PC268135	NEW	NEW	0	0	0	0	0	25,000	25,000	25,000			25,000	25,000	25,000			
LPT REAR FRAME	338-171-703-0	LA113047	23148:00	100000000000000000000000000000000000000	0	0	19,997	0	0		25000**	-			-	5,003			-	SB.72-0521 C/W

Remark:

ENG. RECORD NO.2015E-668 DATED:30/11/2015 REPAIRED & TESTED AT ENG. TSN.:23148:00 CSN.:19997.LLP's REPLACED:HPC ROTOR LLP's,HPT ROTOR LLP's,LPT ROTOR LLP's,LPT SHAFT[NEW].

**NOTE: THIS IS LIMIT FOR INSPECTION ONLY.

0 3 -01- 2016